

ASS. REC. BY:

REF: CS/SMA18007057/Arb72

Special Instruction:

VIVEJOY

Action.

ASSIGNMENT (Office)

From (Person):

Groble Ted

of

SMA

Date/Time:

17042018 938am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 2717K

Insured:

SGJ 7011L

at Workshop m/s

JEC Auto

Tel:

92327457

of

1 Kuki Bukit Ave 6 #02-11

Policy No:

Claim No:

CMTD1801657/GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A

12042018

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

17042018 959am

Person Contacted:

Ah Xian

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 2717K - X
	SGJ 7011L - NAI / AIG U8015600/el
	Def: 17032008
	Revert thru email
	Confirm LIS \$1100 @ 3 days (Def: 86608.98, 86/.)

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

/	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or No

GIA / PR Seen: _____ Consistent? : **Yes** or No

Est. Repairs: _____ days Res.: **Yes** or No

Lum Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SKZ2717K Yr Regn: 2016 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Axio c.c. 1496

Colour: Gold A/C: **Insured / Std / NI / NA**

Sp. Reading: 146488 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: NRE1610011233

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or _____

Brake: **Inorder** / Jammed / Leaked / Burnt or _____

Modi: **Nil** / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dayton

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 17/04/18

Survey held at JFC

Des. of Damages: **Frnt / Rear / O/S / N/S / U/C / Rooftop** or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Samp.</u>
	<u>RECEIVED</u>

Date/Time, File Pass to? : Preli. Report

1) typist : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: TP

Lump Sum / ~~Est.~~ (\$) 1100

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ \$ + RS _____ \$

Photos _____

Others _____

TOTAL 250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18007087/Arb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 17-04-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 7011L	Veh. Inspected	SKZ 2717K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801607/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	17/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/04/2018	Inspection Date	17/04/2018
Survey held at	JEC AUTOMOTIVE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1801607/GPL
Our Ref: CS/SMO18007087/Arb

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PTE LTD

Without Prejudice


Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKZ 2717K .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/04/2018 at the premises of M/s JEC AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 7,708.98 .
Revised Estimate Amount	: S\$ 1,372.95 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:
The vehicle sustained damages
at the rear o/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

ADRIAN
Automotive Assessor

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 17 April, 2018 9:38 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Cindy Tan; Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: CMTD1801607/GPL - SUV(LKK)/ SGJ 7011L & SKZ2717K ACC ON 12.04.18 \ref: KSG/4644/2018/S/ct
Attachments: clt's GIA.PDF

Our Reference: CMTD1801607/GPL

Dear LKK AUTO/ MARCUS,

Please make arrangement to conduct the survey for SKZ2717K.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]
Sent: Tuesday, April 17, 2018 8:51 AM
To: Ye, Yong Kang Melvin
Cc: Gnoh, Pau Loong; Teo, Grace
Subject: RE: YRef: SGJ 7011L Oref: KSG/4644/2018/S/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

RE: PROPERTY DAMAGE CLAIM
CLAIMANT: SINGAPURA LEASING PRIVATE LIMITED
ACCIDENT INVOLVING VEH NO. SKZ 2717K & SGJ 7011L ALONG HUME AVENUE ON 12 APRIL 2018 AT 1855 HRS
PRE-REPAIR INSPECTION NOTICE

We refer to the above matter and to your email of even date.

We are instructed to propose using Mr Marcus Chua from LKK Auto Consultants as the single joint expert as listed in your said email.

Kindly contact Ah Xian – 9232 7457 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253

FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Monday, 16 April, 2018 5:41 PM
To: Cindy Tan
Cc: Gnoh, Pau Loong; Teo, Grace
Subject: RE: YRef: SGJ 7011L Oref: KSG/4644/2018/S/ct

Our Reference: CMTD1801607/GPL
Your Reference: KSG/4644/2018/S/ct

Without Prejudice

Date: 16 April 2018

Attention:
M/S KANNAN SG

Dear Cindy,

ACCIDENT INVOLVING SKZ 2717K & SGL 7011L ON 12.04.2018

We refer to your Notice of Accident dated 16/04/2018.

Please be informed that Mr Gnoh Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Cindy Tan [<mailto:cindy.tan@kannansg.com.sg>]

Sent: Monday, 16 April, 2018 3:38 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: YRef: SGJ 7011L Oref: KSG/4644/2018/S/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

**RE: PROPERTY DAMAGE CLAIM
CLAIMANT: SINGAPURA LEASING PRIVATE LIMITED
ACCIDENT INVOLVING VEH NO. SKZ 2717K & SGJ 7011L ALONG HUME AVENUE ON 12 APRIL 2018 AT 1855
HRS
PRE-REPAIR INSPECTION NOTICE**

We act for M/s Singapura Leasing Private Limited, the owner of motor vehicle No. SKZ 2717K, which was involved in the aforesaid accident. A copy of the Singapore Accident Statement filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-

Place: M/s JEC Auto Service
1 Kaki Bukit Avenue 6
#02-11 Autobay@Kaki Bukit
Singapore 417883

Contact Person: Ah Xian – 9232 7457

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253

FAX: (+65) 6223 1660

IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2018 14:10
Date Of Accident	12/04/2018 18:55
Exact Location Of Accident	HUME AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ2717K
Insured/Policyholder	
Name Of Registered Owner	SINGAPURA LEASING PRIVATE LIMITED
Co Reg No	201528975D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98579617
Alternative Phone No	OFFICE-98579617

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099773499
Cover Note Number	

Driver

Name of Driver	TAN WEI BENG EDEN
NRIC No	S8103932A
Date Of Birth	09/02/1981
Occupation	OUTDOOR
Date Of Driving Pass	12/09/2008
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98579617
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 711 JURONG WEST STREET 71 #04-19
Postcode	640711
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ7011L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN WEI BENG EDEN
Approximate Age	

Injuries Sustain

Injured person in which vehicle?

SKZ2717K

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

APT BLK 711 JURONG WEST STREET 71
#04-19

Postcode

640711

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:



JEC AUTO SERVICE

1 Kaki Bukit Ave 6 #02-11 Autobay, Singapore 417883.
 Hp : 9232 7457 Tel : 6509 6585
 Email : jecautoservice@yahoo.com.sg

Fax : 6509 6584

TP Sampo Jenice.
 NRE1610011233

Vehicle No : SKZ 2717K

Model : Toyota Axio

Qty	List Price	Price
1	Rear Boot Lock <i>Not New</i>	\$ 167.40 X
2	Rear Tailamps @ \$512.55 <i>RH included</i>	\$ 1,025.10 374
1	Rear End Panel <i>Not New</i>	\$ 669.78 X
1	Rear End Panel Inner Garnish <i>Not New</i>	\$ 177.70 X
1	Rear Bumper <i>Not New</i>	\$ 1,485.90 580.60
2	Rear Bumper side Retainers R/L @ \$131.00 <i>RH new</i>	\$ 262.00 95
1	Rear Exhaust Silencer <i>Not New</i>	\$ 720.10 X 1150.60
2	Rear Exhaust Mountings @ \$97.00	\$ 194.00 X 862.95
2	Rear Bumper Reflectors @ \$91.00 <i>RH included</i>	\$ 182.00 91
Subtotal :		\$ 4,883.98

Special Nett Items :

1 Set	Rear Bumper Clip <i>Not New</i>	\$ 45.00 30
1 Set	Rear Reverse Sensor <i>Not New</i>	\$ 350.00 X 30
1	Rear Number Plate With Holder <i>Not New</i>	\$ 50.00 X
Subtotal :		\$ 445.00

Labour Charges :

To Remove , Damaged Lamps And Check Up Rear Wiring	\$ 80.00 30
To Remove , Refix Rear Reverse Sensor	\$ 150.00 50
To Remove , Refix And Replace Exhaust Silencer And Mountings	\$ 150.00 X
To Apply Undercoating	\$ 200.00 X
Panel Beating	\$ 1,000.00 200
To Respray Painting	\$ 800.00 200 480.
Subtotal :	\$ 2,380.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 7,708.98

total: 1372.95
 1/5: 1.1K.
 030up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18007087/Arbn2

50 RAFFLES PLACE
#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 08-06-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 7011L	Veh. Inspected	SKZ 2717K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801607/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	17/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NRE1610011233	Colour	GOLD
Odometer	146488	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	DAYTON	6 mm
L/H Front Tyre	185/60 R15	DAYTON	6 mm
R/H Rear Tyre	185/60 R15	DAYTON	6 mm
L/H Rear Tyre	185/60 R15	DAYTON	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/04/2018	Inspection Date	17/04/2018
Survey held at	JEC AUTOMOTIVE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 2717K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LOCK	NOT NECESSARY	167.40	-
2	REAR TAILLAMPS @\$512.55	O/S CRACKED	1,025.10	374.00
1	REAR END PANEL	NOT NECESSARY	669.78	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	177.70	-
1	REAR BUMPER	TORN	1,485.90	590.60
2	REAR BUMPER SIDE RETAINER R/L @\$131.00	O/S NECESSARY	262.00	95.00
1	REAR EXHAUST SILENCER	NOT NECESSARY	720.10	-
2	REAR EXHAUST MOUNTINGS @\$97.00	NOT NECESSARY	194.00	-
2	REAR BUMPER REFLECTORS @\$91.00	O/S CRACKED	182.00	91.00
	LESS 25% DISCOUNT		-	-287.65
			4,883.98	862.95
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
1	REAR NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-
			445.00	30.00
LABOUR				
	TO REMOVE,DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	30.00
	TO REMOVE,REFIX REVERSE SENSOR.		150.00	50.00
	TO REMOVE,REFIX AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-
	PANEL BEATING.		1,000.00	200.00
	TO RESPRAY PAINTING.		800.00	200.00
			2,380.00	480.00
GRAND TOTAL			7,708.98	1,372.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS/SMO18007087/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.