



SHB 8044R  
Singer Mr: Kelvin

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimate No: \_\_\_\_\_  
 OD/TP ☒ RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Work Site No: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Except: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: \_\_\_\_\_ 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB 8044R Yr Regn: 22 Dec 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima cc 1680

Colour: Silver A/C: 6 Ins: 6 Std / NI / NA

Sp. Reading: 190602 T/Radio: Ins: 6 Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAH M414 MFS 15811

Gen. Cond: 6 Good / Fair / Poor / Burnt

Steering: 6 Inord / Jammed / Leaked / Burnt or

Brake: 6 Inord / Jammed / Leaked / Burnt or

Mod: 6 Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 12/4/8 D.O.I. 16/4/8

Survey held at Premise

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frnt n/s

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction       |
|-------------|----------------------------|
|             |                            |
|             | Uk: +800 (Res: +1,919 U/L) |
|             |                            |
|             |                            |
|             |                            |
|             |                            |
|             |                            |
|             |                            |
|             |                            |
|             |                            |

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

\$ + RS \$

Photos

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

|  |
|--|
|  |
|  |
|  |
|  |
|  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC3/III18007097/K1ea3

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 17-04-2018



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |           |               |            |
|--------------|-----------|---------------|------------|
| Insured Vch. | SHD 4944J | Vch. Insured  | SHB 8044R  |
| Policy No.   |           | Coverage (\$) | 0.00       |
| Claim No.    |           | Excess (\$)   | 0.00       |
| Assign From  |           | Assign Date   | 17/04/2018 |

## 2. Vehicle Particulars & Condition

|              |       |              |   |
|--------------|-------|--------------|---|
| Make & Model |       | c.c          | 0 |
| Engine No.   | HSDEN | Year of Reg. |   |
| Chassis No.  |       | Colour       |   |
| Odometer     | -     | Condition    |   |
| Driveline    |       | Registration |   |
| General      |       |              |   |

## 3. Condition of Tyres

|                | Size | Age | Thickness |
|----------------|------|-----|-----------|
| R/H Front Tyre |      |     | mm        |
| L/H Front Tyre |      |     | mm        |
| R/H Rear Tyre  |      |     | mm        |
| L/H Rear Tyre  |      |     | mm        |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 17/04/2018  | Inspection Date | 17/04/2018 |
| Survey held at | SHRIMATI AUTOMOTIVE CONSULTANTS PTE LTD<br>23 CHANGI SOUTH AVENUE 2 #01-22 SINGAPORE 486443 |                 |            |

## 5a. Remarks

|   |
|---|
| THIS INSPECTION WAS CONDUCTED ON A "WITH-OUT PREJUDICE" BASIS.<br>IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORIZED REPAIRS. |
|---|

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-Apr-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8044 R

|          |  |             |
|----------|--|-------------|
| 1 pc     | Front bumper                               | \$ 531.00   |
| 1 pc     | Front bumper emblem                        | \$ 44.00    |
| 1 pc     | Front bumper n/s side retainer @ \$16.00   | \$ 16.00    |
| 1 pc     | Front bumper n/s upper bracket @ \$16.00   | \$ 16.00    |
| 1 pc     | Front bumper n/s support bracket @ \$16.00 | \$ 16.00    |
| 1 pc     | Front bumper sponge                        | \$ 110.00   |
| 1 pc     | Front bumper reinforcement                 | \$ 328.00   |
| 1 pc     | Front bumper centre grille                 | \$ 174.00   |
| 1 pc     | Front bumper n/s fog lamp cover @ \$66.00  | \$ 66.00    |
| 1 pc     | Front bumper n/s protector @ \$51.00       | \$ 51.00    |
| 1 pc     | Front bumper lower lip                     | \$ 38.00    |
|          |  | \$ 1,390.00 |
| Less 10% |  | \$ 139.00   |
|          |  | \$ 1,251.00 |

### S/NETT

|       |                    |          |
|-------|--------------------|----------|
| 1 set | Front bumper clips | \$ 48.00 |
|-------|--------------------|----------|

### Sundry

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

To putty and spray painting on front bumper, bonnet grille

To apply rustproofing on the repaired and replaced panels.

|    |                   |
|----|-------------------|
| \$ | <del>50.00</del>  |
| \$ | <del>180.00</del> |
| \$ | <del>650.00</del> |
| \$ | <del>180.00</del> |
| \$ | <del>200.00</del> |
| \$ | 2,779.00          |

LKK Auto Consultants hence notify the Repairer of the following:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices to be confirmed by insurance company

• Third party settlement to be confirmed by insurance company

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Katun (UKK)

16/4/18 1340L  
2 days  
PIP Restore Panel p.k.

1/5/18  
total up \$800/24/18

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

16-Apr-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8044 R

|      |  |          |                    |
|------|--|----------|--------------------|
| 1 pc | Front bumper ✓                               | \$       | 531.00             |
| 1 pc | Front bumper emblem ✓                        | \$       | 44.00              |
| 1 pc | Front bumper n/s side retainer @ \$16.00 ✕   | \$       | 16.00              |
| 1 pc | Front bumper n/s upper bracket @ \$16.00 ✕   | \$       | 16.00              |
| 1 pc | Front bumper n/s support bracket @ \$16.00 ✕ | \$       | 16.00              |
| 1 pc | Front bumper sponge ✕                        | \$       | 110.00             |
| 1 pc | Front bumper reinforcement ✕                 | \$       | 328.00             |
| 1 pc | Front bumper centre grille ✕                 | \$       | 174.00             |
| 1 pc | Front bumper n/s fog lamp cover @ \$66.00 ✓  | \$       | 66.00              |
| 1 pc | Front bumper n/s protector @ \$51.00 ✓       | \$       | 51.00              |
| 1 pc | Front bumper lower lip ✕ <i>My</i>           | \$       | 38.00              |
|      |  | \$       | 1,390.00           |
|      |  | Less 10% | \$ 139.00          |
|      |  |          | <u>\$ 1,251.00</u> |

### S/NETT

|   |                      |           |                              |
|---|----------------------|-----------|------------------------------|
| 1 set   | Front bumper clips ✓ | \$        | 48.00                        |
| Sundry  |                      | \$        | <del>50.00</del> ✕           |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.                            |                      | \$        | <del>180.00</del> ✕          |
| To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc |                      | \$        | <del>650.00</del> <i>200</i> |
| To putty and spray painting on front bumper, bonnet grille ✕  |                      | \$        | <del>400.00</del> <i>180</i> |
| To apply rustproofing on the repaired and replaced panels.  |                      | \$        | <del>200.00</del> ✕          |
|   |                      | <u>\$</u> | <u>2,779.00</u>              |

LKK Auto Consultants hence notify  
the Repairer of the following

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

• To resurvey after spray painting

• To display damaged part(s) during resurvey

• Parts prices

• Third party

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE**

**ANY UNFORESEEN DAMAGES.**

*Kelvin LKK*

*16/4/18 1346L*

*2 days*

*PIP Before Pay p 60*

## Claim Audit

### AUDIT TRAIL

| No. | On                | Audit                 | Remarks  | By                                |
|-----|-------------------|-----------------------|--|-----------------------------------|
| 1   | 17 Apr 2018 15:58 | Cim Veh Model Changed | (204023) KIA OPTIMA 1.7 D (A).   | [A] HOW<br>MEI<br>KWAN            |
| 2   | 17 Apr 2018 15:58 | Cim Created           | Reg No: SHB8044R. Acct Date: 2018/04/12. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Premier Automotive Services Pte Ltd (HQ)                                    | [A] HOW<br>MEI<br>KWAN            |
| 3   | 17 Apr 2018 15:58 | Adj Co Assigned       | LKK Auto Consultants Pte Ltd (HQ):   | [A] HOW<br>MEI<br>KWAN            |
| 4   | 17 Apr 2018 15:58 | Adj Next Rpt Changed  | Next Rpt:Final Rpt.Due Date:2018/04/26   | [A] HOW<br>MEI<br>KWAN            |
| 5   | 17 Apr 2018 15:58 | Adj Mandate Set       | Approved:0.00.Reinsp:Adj decides.  | [A] HOW<br>MEI<br>KWAN            |
| 6   | 17 Apr 2018 15:58 | Label Added           | (30653):Direct Settlement.   | [A] HOW<br>MEI<br>KWAN            |
| 7   | 17 Apr 2018 15:58 | Adj Adjuster Assigned | [None] -> KALVIN ANG WEI KUN   | [A] HOW<br>MEI<br>KWAN            |
| 8   | 17 Apr 2018 15:59 | Adj Rpt Initiated     |  | [A] HOW<br>MEI<br>KWAN            |
| 9   | 17 Apr 2018 15:59 | Cim Dtl Modified      | Insured Name: -> COMFORT TRANSPORTATION PTE LTD.   | [A] HOW<br>MEI<br>KWAN            |
| 10  | 17 Apr 2018 15:59 | Cim Dtl Modified      | Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: -> 199303821R.  | [A] HOW<br>MEI<br>KWAN            |
| 11  | 17 Apr 2018 15:59 | Cim Dtl Modified      | JPJ Reg. Date: -> 2015/12/22.  | [A] HOW<br>MEI<br>KWAN            |
| 12  | 17 Apr 2018 15:59 | Cim Details Notified  |  | [A] HOW<br>MEI<br>KWAN            |
| 13  | 20 Apr 2018 09:23 | Adj Mandate Request   | Cur.Reg:0.00:PODS: LIABILITY: UNCLEAR REMARK: REQUEST FOR OI VIDEO   | [A] Asher<br>Sng Rong<br>Yi       |
| 14  | 23 Apr 2018 11:35 | Adj Next Rpt Changed  | Next Rpt:Final Rpt.Due Date:2018/04/26. Mandate Remarks: Dear Sir, there is no video footage for this claim.   | [I]<br>NATALIE<br>LEE             |
| 15  | 23 Apr 2018 11:35 | Adj Mandate Set       | Maintained:Dear Sir, there is no video footage for this claim.   | [I]<br>NATALIE<br>LEE             |
| 16  | 02 Aug 2018 11:37 | Adj Mandate Request   | Cur.Reg:0.00:PODS: LIABILITY: 100% REMARK: B:NIL OI MAKE A U-TURN FROM THE 2ND LANE (REFER TO TP VIDEO)  | [A] Asher<br>Sng Rong<br>Yi       |
| 17  | 02 Aug 2018 11:41 | Adj Mandate Set       | Approved:0.00.   | [I]<br>Zuhaidah<br>Bte<br>Samsuri |
| 18  | 02 Aug 2018 12:35 | Video Downloaded      | Downloaded Video - Accident (TP)   | [I]<br>Sundari<br>NagaraJan       |
| 19  | 30 Aug 2018 16:03 | Adj Mandate Request   | Cur.Reg:1141.44:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST : \$856.00 + (b) LOR : \$205.44 (2days x \$102.72) + LOI : \$80.00 (2days x \$40) Total: a+b+c = \$1,141.44 VEH MODEL: KIA OPTIMA 1685cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTI | [A] Asher<br>Sng Rong<br>Yi       |

Date From



Date To



Audit Type None

Go

### ACTIVITY

[08/07/2018 10:53] HOW MEI KWAN:  
PENDING EVIDENCE

### Merimen Billing for this case - Transaction History

| Ref No  | Bill Date        | Acc Type | Acc Name                                   | Co Name (French)                           | Ref 1    | Ref 2                | Amount |
|---------|------------------|----------|--|--|----------|----------------------|--------|
| 1779222 | 17/04/2018 15:59 | Motor    | LKK Auto Consultants Pte Ltd               | LKK Auto Consultants Pte Ltd (HQ)          | SHB8044R | SHD4944              | 10.70  |
| 1877671 | 02/08/2018 11:39 | Motor    | India International Insurance Pte Ltd (HQ) | India International Insurance Pte Ltd (HQ) | SHB8044R | Zuhaidah Bte Samsuri | xx.xx  |
| 1877759 | 02/08/2018       | Motor    | India                                      | India                                      | SHB8044R | Sundari              | xx.xx  |

## Print Received Message

This mail is associated with :

\*SHB8044R (MCT18040389)  
[SHD4944J]

TP

PREMIER TAXIS PTE LTD

Apr 12 2018 7:00PM

[COMFORT TRANSPORTATION PTE LTD]  
Premier Automotive Services Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 30/08/2018 17:34 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$1141.44) - SHB8044R - Claim Handler: NATALIE LEE

Approved:1141.44.

|                              |                                      |
|------------------------------|--------------------------------------|
| <b>PREMIER TAXI</b>          | <b>FIRER / RELIEF / SUPER RELIEF</b> |
| VEHICLE NO.                  | SHB8044R                             |
| CONTACT NO.                  | 9088 4176                            |
| NEW MAILING ADDRESS (if any) |                                      |

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S0218297A



LIM KWONG

林光

Race

CHINESE

Date of Birth

14-02-1953

Sex

M

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S0218297A

Name

LIM KWONG

Birth Date: 14 Feb 1953

Issue Date: 29 Jan 2004



NRIC No. S0218297A



Blood Group: Date of Issue

A+

21-02-1993

APT BLK 635C PUNGGOL DRIVE #06-633  
SINGAPORE 823635

NRIC No. S0218297A

Date: 28-06-2007 No: 5717657

STRAITS

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

|          |  |             |
|----------|--|-------------|
| Class 2B | Motorcycles not exceeding 200 cc   | 07 May 1977 |
| Class 2A | Motorcycles between 201 cc and 400 cc  | 07 May 1977 |
| Class 2  | Motorcycles exceeding 400 cc   | 07 May 1977 |
| Class 3  | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 08 May 1970 |

NP 428A



Land Transport Authority

VOCATIONAL LICENCE



License No : S0218297A

Name : LIM KWONG

Issue Date : 12/12/2005

Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence



Text size + -

**Enquire Transaction History****Transaction History Details**

|                                     |                                 |                     |   |
|-------------------------------------|---------------------------------|---------------------|---|
| Log Date/Time:                      | 22 Dec 2015 / 08:43:57          | Receipt No.:        | AACCK001-AX239-151222-000004                  |
| Asset Type:                         | Vehicle                         | Transaction Amount: | \$68,909.00                                   |
| Asset ID:                           | SHB8044R                        | Channel:            | AA Counterless - CYCLE & CARRIAGE KIA PTE LTD |
| Transaction Type:                   | 01.02 Register New Vehicle (AA) |                     |   |
| Business Transaction Reference No.: | 20151222084357395077            |                     |   |

|                                |   |
|--------------------------------|---|
| Vehicle No.:                   | SHB8044R                                |
| Vehicle Type:                  | H10 - Public Transport Taxi (Motor Car) |
| Vehicle Attachment 1:          | Air-Con (Taxi)                          |
| Vehicle Attachment 2:          | -                                       |
| Vehicle Attachment 3:          | -                                       |
| Vehicle Schema:                | Taxi (Company)                          |
| First Registration Date:       | 22 Dec 2015                             |
| Original Registration Date:    | 22 Dec 2015                             |
| Vehicle Make:                  | KIA                                     |
| Vehicle Model:                 | OPTIMA 1.7(A) DIESEL                    |
| Chassis No.:                   | KNAGM414MF5658068                       |
| Engine No.:                    | D4FDFH314485                            |
| Motor No.:                     | -                                       |
| Trailer Chassis No.:           | -                                       |
| Propellant:                    | Diesel                                  |
| Passenger Capacity:            | 4                                       |
| Engine Capacity:               | 1665                                    |
| Power Rating:                  | -                                       |
| Unladen Weight:                | 1584                                    |
| Maximum Laden Weight:          | 2050                                    |
| Primary Color:                 | Silver                                  |
| Secondary Color:               | -                                       |
| Manufacturing Year:            | 2015                                    |
| Open Market Value:             | \$22,359.00                             |
| Minimum PARF Benefit:          | \$13,981.00                             |
| PARF Eligibility:              | Y                                       |
| No. of Transfer:               | 0                                       |
| Effective Ownership Date/Time: | 22 Dec 2015 08:43:57                    |
| COE No.:                       | 2015122201003528R                       |
| COE Expiry Date:               | 21 Dec 2023                             |
| COE Bid Category:              | -                                       |
| Actual QP/PQP Paid Amount:     | \$45,466.00                             |
| Lifespan Expiry Date:          | 21 Dec 2023                             |

### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number** : 5095103893

**Cover** : Third Party

1. Index mark and Registration Number of Vehicle : **SHB8044R**  
Chassis Number : KNAGM414MF5658068
2. Name of Policyholder : PREMIER TAXIS PTE. LTD.
3. Effective Date of Insurance : 20 Oct 2017
4. Expiry Date of Insurance : 19 Oct 2018
5. Persons or Classes of Persons entitled to drive\*  
(a) The Policyholder.  
(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use\*  
(a) Use as a Taxi.  
(b) Use for social domestic and pleasure purposes.

**This Policy does not cover**

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

|                       |                                |
|-----------------------|--------------------------------|
| EXCESS (SECTION I)    | : N/A                          |
| EXCESS (SECTION II)   | : S\$3,500                     |
| INSURE WITH COE       | : N/A                          |
| HIRE PURCHASE COMPANY | : UNITED OVERSEAS BANK LIMITED |
| SUM INSURED           | : N/A                          |

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)  
Date of Issue : 16 Oct 2017 17:13 hrs

**For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED**

Countersigned By:



Authorised Officer



Chief Executive

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8044R/GS

**WITHOUT PREJUDICE**

11<sup>th</sup> May 2018

**(By Email Only)**

**Attn: The Motor Claims Department**

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Dear Sir/Madam

## **ACCIDENT INVOLVING SHB8044R & SHD4944J ALONG PATTERSON ROAD / WHEELLOCK PLACE ON 12.04.18**

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHB8044R, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SHD4944J at the material time of the accident with the driver of our client's vehicle, Mr Lim Kwong

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SHD4944J, our client's vehicle was damaged and we have been put to loss and damage as follows:

|   |           |                       |
|---|-----------|-----------------------|
| (1) Cost of repair                          | \$        | 856.00 (Incl. GST)    |
| (2) Loss of Rental - 2Days @\$102.72per day | \$        | 205.44                |
| (3) Loss of Income – 2Days @\$100.00per day | \$        | 200.00                |
|   | <b>\$</b> | <b><u>1261.44</u></b> |

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHB8044R
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher & Scene video

## **PREMIER AUTOMOTIVE SERVICES PTE LTD**

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8044R/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,



Claims Department – Gary Shi

Email: [gary.shi@premiertaxi.com](mailto:gary.shi@premiertaxi.com)

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd

## **AUTHORIZATION TO ACT**

I, **PREMIER TAXIS PTE LTD** (the third party claimant") of **23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443** (address), owner of **SHB 8044R** (vehicle no.) hereby authorize **PREMIER AUTOMOTIVE SERVICES PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no **SHB 8044R** that was damaged pursuant to the accident which occurred on **12/04/2018** (date) along **PATTERSON ROAD // WHEELLOCK PLACE** (location) involving vehicle no/s **SHD 4944J** ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 7 (day) of September (month) 2018 (year)



Signed by "the third party claimant"  
(with chop if applicable)



Signed by "the workshop"  
(with chop)

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18040389

Claimant Ref: SHB8044R/GS

We/I, PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 856.00 (repair cost), S\$ 285.44 (loss of use/rental), S\$        (search fee), vehicle no. SHB 8044R that was damaged pursuant to the accident which occurred on 12/04/2018 (date) at PATTERSON ROAD # WHEELLOCK PLACE (location) involving vehicle no. SHD 4944J (insured vehicle). This is pursuant to the inspection conducted on 16/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PREMIER TAXIS PTE LTD ("the third party claimant") of vehicle no. SHB 8044R to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHB 8044R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,141.44 to PREMIER AUTOMOTIVE SERVICES PTE LTD

Dated this 7 day of September 20 18

#### CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by "the workshop" (with chop)

Gary Shi

S881156SH

23 CHANGI SOUTH AVENUE 2 #01-03

SINGAPORE 486443

Singaporean

#### WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

PREMIER TAXIS PTE LTD  
 23 CHANGI SOUTH AVENUE 2 #03-02  
 SINGAPORE 486443

**TAX INVOICE**

 DATE 11-May-2018  
 PAGE 1 OF 1

| ITEM   | Description   | QTY | U.PRICE | AMOUNT    |
|--|---|-----|---------|-----------|
|  | FINAL REPAIR BILL FOR KIA OPTIMA<br>REGN NO: SHB 8044 R |     |         | \$ 800.00 |
| TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR |   |     |         | \$ 800.00 |
| GST @ 7%   |   |     |         | \$ 56.00  |
| GRAND TOTAL  |   |     |         | \$ 856.00 |


 for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



19 April 2018

To Whom It May Concern

Dear Sir/Madam

**CERTIFICATION LETTER**

This letter serves to inform that Lim Kwong of NRIC Number S0218297A is a registered driver of SHB8044R. Lim Kwong is paying daily rental rate of \$102.72 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

A handwritten signature in black ink, appearing to be "f. K. S." with a stylized flourish.

Chin Bee Lian (Ms)  
Assistant Vice President  
Taxis Administration

Prepared By: Hasniah

PREMIER TAXIS PTE LTD  
13 Changi South Avenue 2  
#03-02  
Singapore 486443  
Telephone: +65 6214 8880 Fax: +65 6214 0330  
[www.premiertaxi.com](http://www.premiertaxi.com)  
Co. Reg. No. 20030497511





REPLACEMENT VEH GIVEN YES / NO

VEH NO. \_\_\_\_\_

JOB NO. \_\_\_\_\_

## CHECK IN / OUT VOUCHER

|                                       |   |
|---------------------------------------|---|
| DRIVER'S NAME LIM KWONG               |   |
| NRIC S0218297A                        | HANDPHONE 90884171                      |
| TAXI REGN NO. SHB8044R                | MAKE / MODEL KO2                        |
| DATE IN 160418 TIME IN 0945           | DATE OUT 170418 TIME OUT 1415           |
| KILOMETRES IN FUEL IN E 1/4 1/2 3/4 F | KILOMETRES OUT FUEL OUT E 1/4 1/2 3/4 F |

TAXI METER DOWNLOADED

YES

NO

DATE / TIME TOWED IN TO WORKSHOP

DDMMYY HHMM

DATE / TIME CALL TO DRIVER FOR VEHICLE COLLECTION

DDMMYY HHMM

I ACKNOWLEDGE AND CONFIRM THAT I HAVE EXAMINED THE ABOVE SAID VEHICLE AND THAT THE SAME IS IN GOOD CONDITION AND TO MY SATISFACTION IN EVERY RESPECT TOGETHER WITH THE ACCESSORIES / ITEMS LIST ABOVE. THIS VOUCHER IS USED IN CONJUNCTION WITH THE TERM RENTAL AGREEMENT.

## CHECK IN

LIM KWONG x

DRIVER'S NAME

AC

x

DRIVER'S SIGNATURE / DATE / TIME

CHECKED IN BY  
(PREMIER'S AUTHORISED WORKSHOP)

## CHECK OUT

LIM KWONG x

DRIVER'S NAME


AC

x

DRIVER'S SIGNATURE / DATE / TIME

CHECKED OUT BY  
(PREMIER'S AUTHORISED WORKSHOP)

INDICATE AREA OF DAMAGE HERE:



BODY MARKINGS

- |                     |             |
|---------------------|-------------|
| 1 - Light Dent      | 5 - Damaged |
| 2 - Serious Dent    | 6 - Chip    |
| 3 - Light Scratch   | 7 - Crack   |
| 4 - Serious Scratch | 8 - Peeling |

|   |                  |
|---|------------------|
| SERVICE / REPAIRS DONE  | DRIVER'S REMARKS |
| <input type="checkbox"/> SERVICING <input type="checkbox"/> OTHERS:<br><input type="checkbox"/> T / BELT<br><input type="checkbox"/> AIRCON SYSTEM <input checked="" type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT:<br><input type="checkbox"/> TURBO 120418 1910<br><input type="checkbox"/> BRAKE SYSTEM TP/V<br><input type="checkbox"/> CLUTCH SYSTEM<br><input type="checkbox"/> BULB<br><input type="checkbox"/> UNDER CARRIAGE<br><input type="checkbox"/> CPF<br><input type="checkbox"/> BATTERY |                  |

## ...CLAIM SUBFOLDER...(Pending for Survey Report)





























Direct Settlement

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |            |   |
|--------------------------|---|---------------|--|--|--|------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                | Ins Auth'd | Status  |
| Main                     | 17 Apr 2018<br><a href="#">Edit Reg</a> |               | 16 Apr 2018<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$800.00</b><br><a href="#">Edit Estimates</a> | <b>S\$800.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main   | Reference  | Claim Details          | Documents  | Show All |         |             |              |            |       |
|--|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>  |  |                        |  |          |         |             |              |            |       |
| Insured:   | <b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R   |                        |  |          |         |             |              |            |       |
| Main Claimant:   | <b>PREMIER TAXIS PTE LTD</b> , Co. Reg. No.: 200304975H  |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:  | <b>SHB8044R</b>  | Date of Loss:          | 12/04/2018 19:00 - :59<br>[27 Months and 21 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:  | <b>TP / MCT18040389</b>  | Policy/Cover Note No.: | MCOM0015   |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):  | <b>SHD4944J</b>  | Policy No. (Claimant): | 5095103893   |          |         |             |              |            |       |
|  |  | Excess:                |  |          |         |             |              |            |       |
| Repairer:  | <b>Premier Automotive Services Pte Ltd (HQ)</b> 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880                         |                        |  |          |         |             |              |            |       |
| Handling Insurer:  | <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>NATALIE LEE</b> - 63476100 ext 243]             |                        |  |          |         |             |              |            |       |
| Claimant's Insurer:  | <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:  |                        |  |          |         |             |              |            |       |
| Adjuster:  | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 26/04/2018] |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>  |  |                        |  |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>III_SG (30/08/2018): Alert - Adj Mandate Approved (S\$1141.44) - SHB8044R - Claim Handler: NATALIE LEE</li> <li>III_SG (02/08/2018): Alert - Adj Mandate Approved (S\$0.00) - SHB8044R - Claim Handler: NATALIE LEE</li> <li>III_SG (23/04/2018): Alert - Adj Mandate Maintained - SHB8044R - Claim Handler: NATALIE LEE</li> </ul> |  |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>  |  |                        |  |          |         |             |              |            |       |
| Due Date   | Priority   | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.  |  |                        |  |          |         |             |              |            |       |

## Claim Documents

**\*SHB8044R (MCT18040389)**  
**[SHD4944J]**  
**TP**  
**PREMIER TAXIS PTE LTD**  
**Apr 12 2018 7:00PM**  
**[COMFORT TRANSPORTATION PTE LTD]**  
**Premier Automotive Services Pte Ltd**

| <a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> |                 |  | <b>View</b> <a href="#">View in Browser</a>  |                                     |
|---|-----------------|--|--|-------------------------------------|
| <b>Video</b>  |                 |  | 1 per page   | <input checked="" type="checkbox"/> |
| No  | Finalized On    | India International Insurance Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1   | 02/08/18 11:39  | Video - Accident (TP)                      |  Load AVI   |                                     |
| 2   | 02/08/18 12:35  | Video - Accident                           |  Load AVI   |                                     |
| <b>Photos/Images</b>  |                 |  | 3 per page   | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail  | Print                               |
| 1   | 18/04/18 08:04  | General View                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 2   | 18/04/18 08:04  | General View                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 3   | 18/04/18 08:04  | General View                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 4   | 18/04/18 08:04  | General View                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 5   | 18/04/18 08:04  | General View                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 6   | 18/04/18 08:04  | General View                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 7   | 18/04/18 08:04  | General View                               |  Load JPG  | <input checked="" type="checkbox"/> |
| 8   | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 9   | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 10  | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 11  | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 12  | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 13  | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 14  | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 15  | 18/04/18 08:04  | General View                               |  Load JPG | <input checked="" type="checkbox"/> |
| 16  | 09/05/18 08:02  | Reinspection Photo                         |  Load JPG | <input checked="" type="checkbox"/> |
| 17  | 09/05/18 08:02  | Reinspection Photo                         |  Load JPG | <input checked="" type="checkbox"/> |
| 18  | 09/05/18 08:02  | Reinspection Photo                         |  Load JPG | <input checked="" type="checkbox"/> |
| 19  | 09/05/18 08:02  | Reinspection Photo                         |  Load JPG | <input checked="" type="checkbox"/> |
| 20  | 09/05/18 08:02  | Reinspection Photo                         |  Load JPG | <input checked="" type="checkbox"/> |
| <b>Documentation</b>  |                 |  | 1 per page   | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail  | Print                               |
| 1   | 18/04/18 00:21  | TP ESTIMATE - MARKED                       |  Load PDF |                                     |
| 2   | 18/04/18 00:21  | TP GIA REPORT                              |  Load PDF |                                     |
| 3   | 07/08/18 15:06  | WORKSHOP INVOICE                           |  Load PDF |                                     |
| 4   | 07/08/18 15:06  | RENTAL RECEIPT                             |  Load PDF |                                     |
| 5   | 07/08/18 15:06  | LOD  |  Load PDF |                                     |
| 6   | 19/09/18 09:42  | DISCHARGE VOUCHER                          |  Load PDF |                                     |
| 7   | 19/09/18 09:42  | AUTHORISATION TO ACT FORM                  |  Load PDF |                                     |
| No  | Finalized On    | India International Insurance Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1   | 18/04/18 08:41  | Singapore Accident Statement               |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST   | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured.                                  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>              |       |      |       |
| <div></div>   |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer             |       |      |       |
| <small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18007097/K1EA3Q2

Date: 19/09/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
**Claimant Vehicle No :** SHB8044R **Insured Vehicle No :** SHD4944J  
 Date of Loss: 12/04/2018 Nature of Claim: TP Claim No: MCT18040389

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB8044R**  
 Make & Model: KIA OPTIMA, 1.7 D (A) Engine No: D4FDFH314485  
 Reg. Date: 22/12/2015 (Man. Year: 2015) Chassis No: KNAGM414MF5658068  
 Colour: Silver Odometer: 190602 km  
 Engine Capacity: 1685 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16  
 Front Left Side: Maxxis 7 mm Rear Left Side: Maxxis 7 mm  
 Front Right Side: Maxxis 7 mm Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's      | Adjuster's      | Difference      | Diff %       |
|---|-----------------|-----------------|-----------------|--------------|
| Parts   | 1,349.00        | 670.80          | 678.20          | 50.27        |
| Miscellaneous Items                             | 0.00            | 0.00            | 0.00            |              |
| Labour  | 1,430.00        | 380.00          | 1,050.00        | 73.43        |
| Paintwork Labour                                | 0.00            | 0.00            | 0.00            |              |
| Towing  | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>2,779.00</b> | <b>1,050.80</b> | <b>1,728.20</b> | <b>62.19</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                 | <b>800.00</b>   |                 |              |
| (S\$)   | 2,779.00        | 800.00          | 1,979.00        | 71.21        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 194.53          | 56.00           | 138.53          | 71.21        |
| <b>Nett Amount (S\$)</b>                        | <b>2,973.53</b> | <b>856.00</b>   | <b>2,117.53</b> | <b>71.21</b> |
| <b>+ Loss of Use (2.0 x S\$40.00/day) (S\$)</b> |                 | 80.00           |                 |              |
| <b>+ Car Rental (2.0 x S\$102.72/day) (S\$)</b> |                 | 205.44          |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>1,141.44</b> |                 |              |

### INSPECTION

Date of Assignment: 16/04/2018  
 Date Inspected: 16/04/2018 Inspected At: Premier Automotive Services Pte Ltd (HQ)  
 23 Changi South Ave 2, #01-02  
 Singapore 486443

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 07 Aug 2018)  |
| <b>Parts:</b> 143  | KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SHB8044R) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

## Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's   | Amount                 |
|-----|-----|----------|-----------------------------------|---------------|--|------------------------|
| 1   | 1   |          | *FRONT BUMPER                     | Deformed      | 531.00 FL  | *531.00 FL             |
| 2   | 1   |          | *FRONT BUMPER EMBLEM              | Necessary     | 44.00 FL   | *44.00 FL              |
| 3   | 1   |          | *FRONT BUMPER N/S SIDE RETAINER   | Serviceable   | 16.00 FL   | *- FL                  |
| 4   | 1   |          | *FRONT BUMPER N/S UPPER BRACKET   | Serviceable   | 16.00 FL   | *- FL                  |
| 5   | 1   |          | *FRONT BUMPER N/S SUPPORT BRACKET | Serviceable   | 16.00 FL   | *- FL                  |
| 6   | 1   |          | *FRONT BUMPER SPONGE              | Serviceable   | 110.00 FL  | *- FL                  |
| 7   | 1   |          | *FRONT BUMPER REINFORCEMENT       | Serviceable   | 328.00 FL  | *- FL                  |
| 8   | 1   |          | *FRONT BUMPER CENTRE GRILLE       | Serviceable   | 174.00 FL  | *- FL                  |
| 9   | 1   |          | *FRONT BUMPER N/S FOG LAMP COVER  | Cut           | 66.00 FL   | *66.00 FL              |
| 10  | 1   |          | *FRONT BUMPER N/S PROTECTOR       | Cut           | 51.00 FL   | *51.00 FL              |
| 11  | 1   |          | *FRONT BUMPER LOWER LIP           | Repair        | 38.00 FL   | *- FL                  |
| 12  | 1   |          | *SET FRONT BUMPER CLIPS           | Necessary     | 48.00 FS   | *48.00 FS              |
| 13  | 1   |          | *SUNDRY                           | Not Necessary | 50.00 FS   | *- FS                  |
|     |     |          |                                   |               | <b>Sub Total (\$\$)</b>                                    | <b>1,488.00 740.00</b> |
|     |     |          |                                   |               | <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | <b>139.00 69.20</b>    |
|     |     |          |                                   |               | <b>Total Parts (\$\$)</b>                                  | <b>1,349.00 670.80</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars  | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|--------|
| <u>Labour Items</u>     |  |          |            |        |
| 1                       | TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS                             | New      | 180.00     | 0.00   |
| 2                       | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN,REPAIR RESHAPE AND ADJUST OF THE SAME .ETC | New      | 650.00     | 200.00 |
| 3                       | TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,BONNET GRILLE   | New      | 400.00     | 180.00 |
| 4                       | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS  | New      | 200.00     | 0.00   |
| Gross Labour Cost (S\$) |  |          | 1,430.00   | 380.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;