

ASS. REC. BY:

REF:

CC/AC118007119/Alsbzn2

Special Instruction:

Surveyor

Ragil

## ASSIGNMENT (Office)

From (Person):

Julie

of

AGL

Date/Time:

17042018 333pm

Estimated Cost:

Bill to:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 31336

Insured:

SKT 4383H

at Workshop m/s

Wearnes

Tel:

9770 4368

of

249 Alexandra Rd

Policy No:

Claim No:

Sum Insured:

Excess:

D.O.A.

10042018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

25052018 @ 10 am

H.O.D. Endorsement:

Date/Time:

17042018 357pm

Person Contacted:

Mandy

Vehicle IN / OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SJA 31336 - X
	SKT 4383H - CS / AL118007119 / RW132

DLA: 270815

Signature *Rose*

REF: AGI

82275

ASSIGNMENT

From: \_\_\_\_\_ Date: 24/05/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJA 3133G  
at Workshop m/s: Wearnes Automotive  
of: 249 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Mandy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *Wp*

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJA 3133G Yr Regn: 2016 / 84P  
Type: ☒ M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: RACAL RACAL LMS RACAL C.C. 1999

Colour: R60 A/C: Insured / Std / NI / NA

Sp. Reading: 016057 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SALVA2A676H155885

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 10/04/18

Survey held at WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP \$2,964.29  
06/06/18 (\$7,874.80 - \$2,964.29) - Reduction = 62%

RECEIVED 06 JUN 2018

Date/Time: File Pass to?

06/06/18

1) TYP34

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) PIP \$2,964.29

Days Of Repair: 3

Resurvey No. of Trip: 0

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

250

## Shirley Hiew (LKK Auto)

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Friday, 8 June 2018 10:29 AM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** ASSIGNMENTS@LKKAUTO.COM; 'SUR'; 'Catherine Chong (LKK Auto)'  
**Subject:** RE: SJA3133G Claiming against SKT4383H

Hi Shirley

Claim No: C10001506/JM

Thank you,  
-Julie

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Friday, 8 June, 2018 10:01 AM  
**To:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Cc:** ASSIGNMENTS@LKKAUTO.COM; 'SUR' <sur@lkkauto.com>; 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>  
**Subject:** RE: SJA3133G Claiming against SKT4383H

Hi Julie,

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Tuesday, 17 April 2018 4:03 PM  
**To:** 'Julie Mangubat' <julie.m@budgetdirect.com.sg>  
**Cc:** ASSIGNMENTS@LKKAUTO.COM; 'SUR' <sur@lkkauto.com>  
**Subject:** RE: SJA3133G Claiming against SKT4383H

Dear Julie,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Catherine Chong (LKK Auto)**

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Tuesday, 17 April, 2018 3:23 PM  
**To:** assignments; SUR  
**Subject:** FW: SJA3133G Claiming against SKT4383H  
**Attachments:** 4211\_001.pdf

Hi Team

Please accept TPPD survey and survey on a without prejudice basis.

Thank you,  
-Julie

---

**From:** Mandy Neo <mandy.neo@wearnes.com>  
**Sent:** Tuesday, 17 April, 2018 2:47 PM  
**To:** Claims <claims@budgetdirect.com.sg>  
**Subject:** FW: SJA3133G Claiming against SKT4383H

Hi,

Attached for TP Claim,  
Kindly advise if direct settlement is possible

Best regards,

**Mandy Neo**  
Service Consultant  
Bodyshop & Paint



**Wearnes Automotive Pte. Ltd.**  
49 Alexandra Road 159935  
F (65) 6264 7137 O (65) 97704368  
[www.wearnes.com](http://www.wearnes.com) [mandy.neo@wearnes.com](mailto:mandy.neo@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

**From:** [it.services@wearnes.com](mailto:it.services@wearnes.com) [<mailto:it.services@wearnes.com>]  
**Sent:** Tuesday, 17 April, 2018 2:24 PM  
**To:** Mandy Neo  
**Subject:** Attached Image

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

## Shirley Hiew (LKK Auto)

**From:** Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Sent:** Wednesday, 6 June 2018 11:27 AM  
**To:** Mandy Neo  
**Cc:** SUR  
**Subject:** RE: SJA3133G Finalization

Hi Mandy,

Finalised amount at \$ 2,964.29 / 3 days confirmed

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Mandy Neo [<mailto:mandy.neo@wearnes.com>]  
**Sent:** Wednesday, 6 June, 2018 10:38 AM  
**To:** Admin A; Rasul (LKKAuto); Veron Chen (LKKAuto)  
**Subject:** FW: SJA3133G Finalization

Hi

Vehicle SJA3133G  
Attached copy for finalization

Best regards,

**Mandy Neo**

Service Consultant  
Bodyshop & Paint



**Wearnes Automotive Pte. Ltd.**

49 Alexandra Road 159935  
F (65) 6264 7137 O (65) 97704368  
[www.wearnes.com](http://www.wearnes.com) [mandy.neo@wearnes.com](mailto:mandy.neo@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

---

**From:** [it.services@wearnes.com](mailto:it.services@wearnes.com) [<mailto:it.services@wearnes.com>]  
**Sent:** Wednesday, 6 June, 2018 10:31 AM  
**To:** Mandy Neo  
**Subject:** Attached Image

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 11/04/2018 15:34  
 Date Of Accident 10/04/2018 14:00  
 Exact Location Of Accident IKEA TAMPINES CAR PARK  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SJA3133G  
**Insured/Policyholder**  
 Name Of Registered Owner KWOK KIT YEE  
 NRIC No S1818227J  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-96916999  
 Alternative Phone No OTHERS-96916999

### Vehicle Particulars

Manufacturer LAND ROVER  
 Model EVOQUE-2.0 (A)  
 Exact Purpose for which vehicle was being used at time of accident SOCIAL  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number  
 Cover Note Number 210048228-01

### Driver

Name of Driver KWOK KIT YEE  
 NRIC No S1818227J  
 Date Of Birth 25/08/1967  
 Occupation INDOOR  
 Date Of Driving Pass 08/05/1992  
 Driving Experience 25 YEARS AND 11 MONTHS  
 Gender FEMALE  
 Mobile Number (LOCAL) +65-96916999  
 Fax Number  
 Contact Number OTHERS-96916999  
 EMail Address NOEMAIL

Address	BLK 916 TAMPINES ST 91 #05-73
Postcode	520916
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ACCIDENT STATEMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	WAYNE
Phone Number	93888457
Email Address	

#### Details of Witness 2

Name	
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT4383H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



Venue: IKEA Tampines Car Park.

Time: Est 2-3pm

Date: 10 April 18 (Tues).

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Got a note from a witness Wayne shared that he witnessed my car got knocked by SKT4383H but left no putting a notification to me. Hence write down details send me pic and whatsapp ~~after~~ what happened after.

With the following, wrote a note to SKT4383H ~~put on the~~ and requested ~~on~~ car owner to call me.

Mr Woo (as identified) called and apologised for the accident later thru whatsapp he recommended me to a worse workshop instead going back to original distributor workshop for repair.

Mr Woo. (SKT4383H)  
Mobile: 98721906

Hence reported to Neames and report made by the insurance claim dept. for claims + further investigation.


Witness: Wayne  
Mobile: 93888457.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

11/4/18  
1:30pm.

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

11/4/18  
1:30pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

LKK Auto Consultant, hence notify  
the Repairer of the followings:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## SERVICE ESTIMATE

86869 - C00001 SL: SERVICE SALES - PC

Ms Kwok Kit Yee  
916 Tampines Street 91  
#05-73

Singapore 620916

Closed by .... : Mandy Neo  
Svc Consultant :  
Remarks ..... : Ms Kwok Kit Yee

GST Reg.No:M28920628X  
Inv.No. . : B&P 0 Page 1  
Inv.date. : 17/04/2018  
WIP No. . : 55174  
Veh.In/Out: 11/04/2018  
\*Tel.No. . : Mobile: 96916999  
Reg.No. . : SJA3133G  
Reg.date . : 13/09/2016  
Mileage ... : 0  
Chassis No: SALVA2AG7GH155885

all cars  
Touch  
up  
Vehno

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO PUTTY, SPRAY FRONT (Labour)	0	2400.00	0		<del>2,400.00</del> 1200	S
BUMPER							
800	TO PUTTY, SPRAY FRONT BUMPER	0	2200.00	0		<del>2,200.00</del> 1100	S
280	TO CHECK WIRING INCLUDE	0	486.00	0		<del>486.00</del>	S
RESETTING OF ALL ELECTRICAL MODULES							
	WHEEL MOULDING FRT L	1.0 EA	198.10			198.10	S
	BUMPER - FRONT	1.0 EA	2497.30			2,497.30	S
	BUMPER BRACKET FRT R	1.0 EA	46.70			46.70	S
	BUMPER BRACKET FRT L	1.0 EA	46.70			46.70	S

Resue  
Hp 90010068  
3 days  
24/05/18 @ 1630  
Resue after repair  
28/5/18

Labour Total 5,086.00  
Parts Total 2,788.80  
Package Total 0.00

Gross Total. 7,874.80  
Net..... 7,874.80  
GST @ 7.0% 551.24  
Total..... 8,426.05  
Paid..... 0.00  
Please Pay.. 8,426.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

### SERVICE ESTIMATE

0 - B00017  
BUDGET DIRECT INSURANCE  
190 CLEMENCEAU AVE  
#03-01 SPORE SHOPPING CENTRE  
SINGAPORE 239924

SL: BUDGET DIRECT INSURANCE

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1  
Inv.date. : 06/06/2018  
WIP No. : 62576  
Veh.In/Out: 24/05/2018 29/05/2018  
\*Tel.No. : 62212111  
Reg.No. : SJA3133G  
Reg.date : 13/09/2016  
Mileage : 0  
Chassis No: SALVA2AG7GH155885

Closed by .... : Mandy Neo  
Svc Consultant :  
Remarks ..... : Ms Kwok Kit Yee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPAIR FRONT BUMPER	0	1200.00	0		1,200.00	S /
800	TO PUTTY, SPRAY FRONT BUMPER	0	1100.00	0		1,100.00	S /
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00	S /
RESETTING OF ALL ELECTRICAL							
MOUDLES							
	WHEEL MOULDING FRT L J	1.0 EA	198.10	10		178.29	S

Gross Total. 2,964.29

Labour Total 2,786.00  
Parts Total 178.29  
Package Total 0.00

Net..... 2,964.29  
GST @ 7.0% 207.50  
Total..... 3,171.79  
Paid..... 0.00  
Please Pay.. 3,171.79

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI18007119/R1sbn2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 08-06-2018	
			Code : AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKT 4383H	Veh. Inspected	SJA 3133G	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001506/JM	Excess (\$)	0.00	
Assign From	JULIE	Assign Date	17/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RANGE ROVER LAND ROVER	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SALVA2AG7GH155885	Colour	RED	
Odometer	16057	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	6 mm	
L/H Front Tyre	235/60 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/04/2018	Inspection Date	24/05/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 3133G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	WHEEL MOULDING FRT L (SN)	SCRATCHED	198.10	178.29
1	BUMPER-FRONT (SN)	TO REPAIR SEE LABOUR	2,497.30	-
1	BUMPER BRACKET FRT R (SN)	NOT NECESSARY	46.70	-
1	BUMPER BRACKET FRT L (SN)	NOT NECESSARY	46.70	-
			2,788.80	178.29
	<b><u>LABOUR</u></b>			
	TO REPAIR FRONT BUMPER.		2,400.00	1,200.00
	TO PUTTY, SPRAY FRONT BUMPER.		2,200.00	1,100.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		486.00	486.00
			5,086.00	2,786.00
	<b>GRAND TOTAL</b>		<b>7,874.80</b>	<b>2,964.29</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,964.29</b>

Report Ref No. CS/AGI18007119/R1sbn2

MOHAMMED RASUL BIN MOHD YUNUS  
Automotive Assessor

ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.