

Our Ref : T 0418 / SHC8316B /WT(st)

Your Ref :

Date : 25-Apr-18

CDGE Taxi Claims Dept  
59 Loyang Drive 4th Flr  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

CHINA INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC8316B YOUR INSURED SJP7941K  
AND OTHER 2 VEHICLES ON 13.04.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHC8316B** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SJP7941K** we are submitting these claims for your consideration on behalf of the claimants.

#### TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 10,373.20
2	6 days Loss of Rental @ \$ 115.00 per day	\$ 690.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation Fees	\$ -
Sub Total :		\$ 11,070.69

#### HIRER'S CLAIM

7	6 days Loss of Income @ \$ 80.00 per days	\$ 480.00
Total Claims :		\$ 11,550.69

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 9 pcs.
- b) LTA search slip/s of : SJP7941K
- c) GIA / Police report/s of : SHC8316B
- d) Letter of authority from owner / hirer / operator
  - ( ) Traffic Compound ( ) Towing/Medical bill/receipts ( ) Certificate of Insurance
  - ( X ) Photograph/s of Accident Scen ( x ) Downtime/Mileage record ( x ) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully  
William Tan

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



**LETTER OF AUTHORISATION**

(NAF / PAF)

**ACCIDENT INVOLVING** i 40 SHC8316B , SJP7941K , SGQ5467G ,... ON 13-Apr-18 11:45  
**ALONG** CTE TWDS CITY B4 BALESTIER RD EXIT

I / We **TAN TONG HING** (Hirer) NRIC No.: **S0184948D**

and/or (Relief) NRIC No.:

Taxi Number **SHC8316B**  
hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **13-Apr-2018**

Name of Hirer **TAN TONG HING**  
Hirer NRIC **S0184948D**

Signature :



Address **498B TAMPINES STREET 45 #06-366**  
**521498**

Contact No. **93898829**



GST REG. NO. M2-8921817-3

## TAX INVOICE

COMPANY REG. NO.: 199506048W  
Page: 1

8010012

CHINA TAIPING INSURANCE CO(S) PTE L  
SPRINGLEAF TOWER

3 ANSON ROAD #16-00  
SINGAPORE SG 079909

CONTACT NO: 62222.366

VEHICLE NO  
SHC8316B

INV. NO/DATE  
91369251 24.04.2018

MAKE  
HYUNDAI

JOB NO.  
305141630

MODEL  
I-40

ODOMETER READING

DATE OF REG  
06.08.2015

DATE/TIME IN  
13.04.2018 13:20

CHASSIS CODE  
KMHLB41UMGU076842

Description : 3P 13.04.18

S/No Part No.

Qty Unit Price %Disc Net

### PART REQUISITION

0001	02-01-0103-0053	140VC MUFFLER ASSY-LH	1	954.00	20.00	763.20
0002	02-01-0103-0054	140VC MUFFLER ASSY-RH	1	954.00	20.00	763.20
0003	02-01-0103-0086	140VC PIPE-EXHAUST WR	1	1,150.30	20.00	920.24
0004	04-01-0103-2159	140VC MEMBER ASSY-RR FLOO	1	495.50	20.00	396.40
0005	04-01-0103-0577	140VC PANEL ASSY-TRUNK L	1	1,681.40	20.00	1,345.12
0006	04-01-0103-0800	140VC SYMBOL MARK-TRUNK L	1	27.20	20.00	21.76
0007	04-01-0103-0787	140VC EMBLEM-140	1	41.00	20.00	32.80
0008	04-01-0103-0786	140VC EMBLEM-CRDI	1	41.00	20.00	32.80
0009	28-01-0103-0005	(140/SONATA)REAR BOOT LOG	1	20.00	0.00	20.00
0010	28-01-0103-0006	(140/SONATA)REAR BOOT TR	1	10.00	0.00	10.00
0011	04-01-0103-0784	140VC MLDG-BACK PANEL	1	398.00	20.00	318.40

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91369251	10,373.20	

GST REG. NO. M2-8921817-3

## TAX INVOICE

COMPANY REG. NO.: 199506048W  
Page: 2

8010012

CHINA TAIPING INSURANCE CO(S) PTE L  
SPRINGLEAF TOWER

3 ANSON ROAD #16-00  
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO  
SHC8316B

INV. NO/DATE  
91369251 24.04.2018

MAKE  
HYUNDAI

JOB NO.  
305141630

MODEL  
I-40

ODOMETER READING

DATE OF REG  
06.08.2015

DATE/TIME IN  
13.04.2018 13:20

CHASSIS CODE  
KMHLB41UMGU076842

S/No	Part No.		Qty	Unit Price	%Disc	Net
0012	04-01-0103-0785	I40VC MLDG-CR PIECE	1	85.00	20.00	68.00
0013	04-01-0103-0780	I40V2 MT'G CLIP-RR COMBI	1	5.50	20.00	4.40
0014	04-01-0103-0579	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0015	04-01-0103-0738	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0016	04-01-0103-0739	I40VC ABSORBER-RR BUMPER	1	143.40	20.00	114.72
0017	04-01-0103-0740	I40VC BEAM-RR BUMPER#	1	504.35	20.00	403.48
0018	04-01-0103-0742	I40VC STAY-RR BUMPER LH	1	180.00	20.00	144.00
0019	04-01-0103-0743	I40VC STAY-RR BUMPER RH	1	180.00	20.00	144.00
0020	04-01-0103-0907	I40VC BRKT ASSY-RR BUMPER	1	49.00	20.00	39.20
0021	04-01-0103-0581	I40VC LAMP ASSY-RR COMB O	1	565.60	20.00	452.48
0022	04-01-0103-0585	I40VC LAMP ASSY-RR COMB O	1	565.60	20.00	452.48
0023	04-01-0103-0696	I40VC PANEL ASSY-BACK #	1	592.30	20.00	473.84
0024	04-01-0103-1053	I40VC TRIM-TRANSVERSE RR	1	57.70	20.00	46.16

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91369251	10,373.20	



GST REG. NO. M2-8921817-3

## TAX INVOICE

COMPANY REG. NO.: 199506048W  
Page: 3

8010012

CHINA TAIPING INSURANCE CO(S) PTE L  
SPRINGLEAF TOWER

3 ANSON ROAD #16-00  
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO  
SHC83168

INV. NO/DATE  
91369251 24.04.2018

MAKE  
HYUNDAI

JOB NO.  
305141630

MODEL  
I-40

ODMETER READING

DATE OF REG  
06.08.2015

DATE/TIME IN  
13.04.2018 13:20

CHASSIS CODE  
KMHLB41UMGU076842

S/No	Part No.		Qty	Unit Price	%Disc	Net
0025	04-01-0101-0111	HYUNDAI BUMPER COVER CLIP	10	2.20	20.00	17.60
0026	04-01-0103-1150	I40VC PROTECTOR MAT	1	50.00	0.00	50.00
0027	09-01-9999-0068	HYUNDAI REVERSE SENSOR AS	1	135.70	0.00	135.70
0028	FNPS	NO PLATE(S)	1	25.00	0.00	25.00
0029	04-01-0103-0710	I40VC EXTENSION ASSY-QTR	1	545.90	20.00	436.72
SUB-TOTAL			:			8,294.58

### JOB NATURE

0001	I	PANEL BEATING	600.00	600.00
0002	I	SPRAY PAINTING CHARGE	600.00	600.00
0003	I	WIRING CHARGE	20.00	20.00
0004	I	TUFF KOTE	20.00	20.00
0005	I	REMOVE/REFIX REVERSE SENSOR	20.00	20.00

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91369251	10,373.20	

GST REG. NO. M2-8921817-3

## TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO(S) PTE L  
SPRINGLEAF TOWER

3 ANSON ROAD #16-00  
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO  
SHC8316B

MAKE  
HYUNDAI

MODEL  
I-40

DATE OF REG  
06.08.2015

CHASSIS CODE  
KMHFB41UMGU076842

INV. NO/DATE  
91369251 24.04.2018

JOB NO.  
305141630

ODOMETER READING

DATE/TIME IN  
13.04.2018 13:20

S/No	Part No.	Qty	Unit Price	%Disc	Net
0006	L REMOVE/REFIX EXHAUST PIPE	90.00		90.00	
0007	L REMOVE/REFIX REAR UPHOLSTERY	50.00		50.00	
SUB-TOTAL:				:	1,400.00

Items total.	9,694.58
Add GST @ 7.000 %	678.62
Invoice amount.	10,373.20

Issued by : KATHERINETAN 24.04.2018 13:46:32  
Repair type : CLSO/57/57  
Payment Type/Term: /Credit 30 days

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91369251	10,373.20	

Our Ref: CT18040344

Date: 23 April 2018



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 13/04/2018 @ 11:45 hrs  
ALONG CTE TWDS CITY B4 BALESTIER RD EXIT  
INVOLVING SJP7941K, SGQ5467G, SLB7776X

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC8316B** (the "Taxi"). The Taxi was hired to **TAN TONG HING IC NO S0184948D** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$115.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.







**Enquire Vehicle Insurer**

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SJP7941K 13 Apr 2018 / 11:45:00 Successful C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#)[OK](#)

SHC8316B

