

AXA - FZ
LKK

COMFORTDELGRO ENGINEERING PTE LTD

Date: 16.04.2018

Time: 15:49:05

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305142149
REGN NO : SHA4973R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.07.2016
DATE/TIME IN : 16.04.2018 11:00
ACCIDENT DATE : 13.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1 L	603.60	20.00	482.88	X Repair
0002 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	X

SUB-TOTAL : 532.88

JOB NATURE

0000 L	PANEL BEATING- REAR	250.00	100
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	180
0002 17-01	CHECK ALL LIGHTING	50.00	X
0003 L	REMOVE/REFIX REVERSE SENSOR	120.00	X

SUB-TOTAL : 620.00

TOTAL : 1,152.88

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

AUTHORISED : YES / NO

LKK Auto Consultants hence notify DATE :
the Repairer of the following:
• To resurvey before/after painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey on a "Without Prejudice" basis
• No legal action is allowed
• Supplemental claims must be resurveyed and
is subject to approval from Insurance Company

Rm 8/5 repairer

Kelvin LKK

17/4/18 1045h.

2 Reps

PIP
After Repair photo