



ESTEE PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.eesteemperf.com.sg

Repair Estimates

SLN 4133 H

Parts	(a) Cost / List Price Items	\$	11,390.38
	Plus/Less 25%	\$	2,847.60
	Total of Cost / List	\$	8,542.79
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	8,742.79
Labour		\$	5,120.00
Total		\$	13,862.79

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____
Company : _____
Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : **SLN 4133 H**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU803556649**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	
2	Rear bumper	1	\$497.50		
3	Rear bumper clip	10	\$40.00		
4	Rear bumper side retainer LH	1	\$112.70		
5	Rear bumper side retainer RH	1	\$112.70		
6	Rear bumper reinforcement	1	\$398.90		
7	Rear bumper lower garnish centre	1	\$582.60		
8	Rear bumper lower garnish LH	1	\$149.70		
9	Rear bumper under cover	1	\$355.20		
10	Rear bumper under cover LH	1	\$187.60		
11	Rear bumper under cover clip	4	\$14.00		
12	Tail lamp LH - UPPER	1	\$498.75		
13	Tail lamp LH - LOWER	1	\$511.60		
14	Tail end panel	1	\$596.60		
15	Tail end panel garnish	1	\$151.60		
16	Tail end panel garnish clip	10	\$35.00		
17	Boot weatherstrip	1	\$353.10		
18	LH rear fender	1	\$883.60		
19	LH rear fender undershield	1	\$92.30		
20	LH rear fender undershield clip	10	\$30.00		
21	LH rear fender air duct	1	\$115.60		
22	LH rear inner trim	1	\$387.63		
23	LH rear lower arm	1	\$398.65		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 4133 H**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU803556649**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH rear knuckle arm	1	\$895.60		
25	LH rear knuckle bearing	1	\$421.90		
26	LH rear wheel hub	1			
27	LH rear wheel hub lock nut	1	\$17.30		
28	LH rear shock absorber	1	\$359.40		
29	LH rear shock absorber top mounting	1	\$165.70		
30	LH rear shock absorber stopper	1	\$85.70		
31	LH rear rim	1	\$1,555.10		
32	LH rear tyre	1	\$350.00		
33	LH rear hub cap	1	\$195.95		
34	LH side skirt	1	\$798.40		
35	LH side skirt clip	10	\$40.00		
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 4133 H** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL,LHR FENDER, LHR DOOR,LH SIDE SKIRT,TAILOOR,SPARE TYRE WELL PANEL)	\$2,000.00	
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL,LHR FENDER, LHR DOOR,LH SIDE SKIRT,TAILOOR,SPARE TYRE WELL PANEL)	\$1,800.00	
3	To check wiring	\$50.00	
4	To remove & refit reverse sensor to assist work load	\$120.00	
5	To tuff coat	\$250.00	
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	
7	To remove & refit undercarriage to assist work load.	\$250.00	
8	To do wheel alignment.	\$120.00	
9	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$120.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SLN 4133 H**

Submit By : Carmen Lim

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2018 12:59
Date Of Accident	15/04/2018 06:00
Exact Location Of Accident	JUNCTION OF DRAYCOTT RD AND STEVENS RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN4133H
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90777736
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	TEO CHOON CHOY
NRIC No	S7608379G
Date Of Birth	12/03/1976
Occupation	OUTDOOR
Date Of Driving Pass	30/07/2003
Driving Experience	14 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97717446
Fax Number	
Contact Number	
EMail Address	GUNNERHOUSE@GMAIL.COM

Address	APT BLK 14 LORONG 7 TOA PAYOH #15-219
Postcode	310014
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER AS ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	UNKNOWN
Phone Number	96161604
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR822H
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180415/2022

1 of 3

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20180415/2022

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/04/2018 10:09			Vide Report No.: E/20180415/0074		Station Diary No.: 32
Informant's Particulars					
Name of Informant: TEO CHOON CHOY			Address: APT BLK 14 LORONG 7 TOA PAYOH #15-219 SINGAPORE 310014		
ID Type / ID No.: NRIC NO / S7608379G			Contact No.: Home/Office: Mobile: 97717446		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 42	Date of Birth: 12/03/1976	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 15/04/2018 06:00	Type of Location:
Location: Junction of Road 1 and Road 2 DRAYCOTT DRIVE STEVENS ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLN4133H	Car				Slightly Damaged	1
SLR822H	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180415/2022

2 of 3

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20180415/2022

CONTINUATION OF REPORT

Driver			
Name	TEO CHOON CHOY	ID No.	S7608379G
Related Vehicle	SLN4133H (Car)	Contact No.	97717446
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 15/04/2018 at about 0602hrs, I was driving my grab car bearing vehicle plate registration number SLN4133H and was travelling along Draycott Drive.

As the traffic light was green on my side, I continue driving straight and suddenly felt an impact from the rear left side of my car while at the junction of Draycott road and Stevens Road. Another car had hit onto my car but did not stop and sped off leaving his plate number SLR822H behind after hitting my car.

My car has damages of dent and scratches to the left side rear and bumper. I am injured but had not gone to the doctor yet. I wish to inform that the traffic police also attended to my incident and I was asked to make a traffic accident report. Traffic accident report E/20180415/0074. I have a witness to my incident and his contact number is 96161604



**SINGAPORE
POLICE FORCE**



T/20180415/2022

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

3 of 3

Report No. T/20180415/2022

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 PHYLLIS HENG PEI LING

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT / SINGAPORE POLICE FORCE

SSI GOH GEOK LYE

Contact No.: 65476148

SW 168

Authentication Stamp


NP168

Signature Of Informant:

Date/Time:

15/04/2018 10:09

Classification Of Case:



HOTLINE: 9182 8211

ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@ymail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1181254Date: 15/4M/S: GS teemVehicle No: SLN4133H Model: TOYOTA PRIUS H13From: Draycott Dr Time Start: 7:25To: 385 Simming Dr Time End: 8:10

Remarks: _____

☐ Change Tyres / Jump Start☒ Accident☐ Use Car Carrier☐ Basement / Multi Carpark☐ Crane Up / Winch Out☐ Open Door☒ Using King Dolly☐ Dismantle Shaft / Brake☐ LoadedAMOUNT S\$ 110.60

GST S\$ _____

TOTAL S\$ _____

Received By

Important Note:

6655

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.