

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007176/K1vbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 25-04-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBG 9719R	Veh. Inspected	SHA 7278U	
Policy No.	5087841204-01	Coverage (\$)	0.00	
Claim No.	MT/0990856-002	Excess (\$)	0.00	
Assign From		Assign Date	17/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHET41VMBA813471	Colour	BLUE	
Odometer	280328	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm	
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm	
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm	
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	16/04/2018	Inspection Date	17/04/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			