

INS. CASE OWNER:

Sathen

CC 4/AIG1800

7181, Kpb

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

18/4/18

Date / Time:

18/4/18

Registered in Merimen:

18/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGX 8940A

Claim No.:

6012358986

Name of Insured:

Tan Siew Yin (Zheng Xinyin)

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$5

D.O.A.:

14/4/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Tan Siew Yin

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

906 4924

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLW 32700



INSRS:

WSP:

Tel:

Liability:

RMKS:

Supreme Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT

Date/ Time

18/4/18
INTSLW 32700 - X
SGX 8940A - Y
- no OI GIA, sent out 1st letter.

24/4/18

- Old Mr Tan called in. He had lodged the accident report on 24/4/18. Old received his 1st. Old wants to know final amount as it is minor damages.
- Email to AIG: Request for OI GIA.

30/4/18

- OI GIA ✓.
- Old called in. He wants to know how much of the claim. Inform him that we will let him know once it is ready.

21/5/18

3:15pm Called Old, Mr Tan. No response.
3:50pm Old Mr Tan called back. Advise him that we are still pending for part price.
Need to update him.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed)

BOLA S/N No.

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2500.00

Loss of Rental (LOR):

SS

600.00

(

6 days)

X 10

Loss of Use (LOU):

SS

-

(

5 x days)

Loss of Income (LOI):

SS

-

(

5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/Independent)

Legal Cost:

SS

-

Total:

SS

4002.00

Global Sum SS: 4000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4000.00

Name 1:

Supreme Auto Service Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$7200

COPY SENT

REF: ALH

ASSIGNMENT

From: Date: 18042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 3270D
at Workshop n/s Supreme Auto
of 176 Sin Ming Ave #02-01

Insured:

Policy No.

Claims No.


Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW 3270D Yr Regn: 02 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda 1, J422 C.C. 1497 1339

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 88515 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTHNGE 885095 203448

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 185 / 55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 14/4/18 D.O.I. 18/4/18

Survey held at: ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/4 File pass to Catherine, but not ready

45 at 3500 (Repaired step 6/6/24)

Order/Time, File Pass to?

☐

Prel. Report

11

☐

Final Report

Order/Time, File Return to?

21

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

1) S + R: \$

2) Photo

3) Other

4)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18007181/Kpb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 18-04-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGX 8940A	Veh. Inspected	SLN 3270D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/04/2018	Inspection Date	18/04/2018
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

2/12

TEL: 64528211 FAX: 64517420

Not Achieve
U/Lng 83500
Recovery after Post
9-5days

singapore 786548

9-5 days

9149.67

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 64528211 FAX: 64517420

ESTIMATE

TANG YANG KHANG

c/o 46 lentor plain

singapore 786548

Date : 16/4/2018

Not within
1/10/8?
Returning after Part
4-5 days

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE : HONDA JAZZ / SLW3270D	
1pc	front bonnet hinge <i>Rx</i>	@
1 pc	front bonnet <i>Br ✓</i>	
1 pc	front bonnet lock <i>Rx</i>	
1 pc	front bumper <i>Br Lm</i>	
2 pcs	front bumper side retainers <i>also in x</i>	@
1 pc	front bumper lower grille <i>?</i>	
1 pc	front bumper reinforcement <i>?</i>	
1 pc	front bumper tow cover <i>Sm x</i>	
1 pc	front bumper fog lamp cover <i>Sm x</i>	
1 pc	front bumper fog lamp <i>Sm x</i>	
15 pcs	front bumper clip <i>Sm</i>	@
2 pcs	front head lamp (HID) <i>?</i>	@
2 pcs	front head lamp lower bracket <i>?</i>	@
1 pc	front grille <i>?</i>	
1pc	front grille emblem <i>Sm</i>	
1 pc	front air-con condenser <i>?</i>	
1 pc	front air-con fan motor <i>?</i>	
1 pc	front radiator fan motor <i>Sm x</i>	
1 pc	front radiator assy <i>Sm x</i>	
2pc	radiator top bracket <i>?</i>	
1pc	radiator expansion tank <i>Sm x</i>	
1 pc	front support panel <i>?</i>	
1bot	radiator coolant <i>nn x</i>	s.nett
1pc	front number plate <i>}</i>	s.nett
1pc	front number plate casing <i>}</i>	s.nett
	sub-total	-
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	900.00 <i>500</i>
	To check wiring system.	50.00 <i>20</i>
	To apply putty & spray painting on affected areas.	850.00 <i>600</i>
	To replace air con component and top up gas	140.00 <i>?</i>
	Total	1,940.00

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 4 May 2018 8:44 AM
To: admin (admin@supreme.sg)
Cc: Kenneth Kong (LKKAuto)
Subject: *URGENT* <Request for Complete Repair Estimate> Your Ref: SLW 3270D *Our Ref: CC4/AIG18007181/Kpb3 [ACCIDENT INVOLVING SGX 8940A(AIG) & SLW 3270D ON 14/04/2018]
Attachments: TP_ESTIMATE.pdf

Your Ref: **SLW 3270D**
Our Ref: CC4/AIG18007181/Kpb3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SGX 8940A(AIG) & SLW 3270D ON 14/04/2018

We refer to the above matter.

Kindly let us have a complete set of repair estimate(with part price) for our surveyor's action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: admin@supreme.sg
Sent: Thursday, 13 September 2018 5:43 PM
To: Hsiao Tong (LKKAuto)
Subject: SLW 3270 D
Attachments: SLW3270D.pdf

Hi Hsiao Tong,

LOD attached for your settlement.

Best regards,
Yuki Ho
Supreme Auto Service Pte Ltd
No.176 Sin Ming Drive
#02-01 Singapore 575721
Tel: 64528211
Fax: 64517423

SUPREME AUTO SERVICE PTE LTD

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721

Email: admin@supreme.sg

•TEL: 6452 8211 •FAX: 6451 7420

Letter Of Demand **Direct Settlement-Third Party Claims**

Your ref:

Our ref: SLW3270D

AIG Asia Pacific Insurance Ltd

Attn: Officer In Charge

(Motor Claim Department)

06/09/2018

Dear Sir,

RE : ACCIDENT INVOLVING SLW3270D AND SGX8940A AT KEONG SAIK ROAD ON 14/04/2018.

We have been authorized by Tang Yang Khang, the registered owner of vehicle number SLW3270D (NRIC NO: S7905501H) which was involved in the above accident and at the material time to make a 3rd party claims against.

The accident was clearly caused by your insured's negligence. We, therefore seeking compensation from you for our client financial losses as itemized below: -

Repair cost	S\$	3,500.00
Loss Of Use (9 days x \$105.00 + GST 7%)	S\$	1011.15
Search Fee	S\$	2.00
Total	S\$	4,513.15

We have enclosed copies of relevant documents to support our claims.

Please settle this matter within 7 days.

Your prompt settlement of our claim would be much appreciated.
Do contact us at 64528211 for any clarification.

Thank you.

Yours faithfully,



Supreme Auto Service Pte Ltd

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 18 December 2018 3:14 PM
To: admin@supreme.sg
Subject: RE: SLW 3270 D

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$4,000.00(all-in).

Please confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: admin@supreme.sg <admin@supreme.sg>
Sent: Thursday, 13 September 2018 5:43 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: SLW 3270 D

Hi Hsiao Tong,

LOD attached for your settlement.

Best regards,

Yuki Ho

Supreme Auto Service Pte Ltd

No.176 Sin Ming Drive

#02-01 Singapore 575721

Tel: 64528211

Fax: 64517423



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNCV2018-00000049

Car plate number: 5LW3270D

Coverage start date: 26/03/2018

Coverage end date: 25/03/2019

Who is insured to drive: You and any Authorised Driver

Covered Geographical Area: Singapore, West Malaysia and Southern Thailand

About you (the Policyholder)

Name: Tang Yang Khang

NRIC/FIN: S7905501H

Address: 23 Punggol Field Walk 05-18 Waterwoods Singapore 828750

Email: yangkhang@hotmail.com

Mobile Number: 81881884

Date of Birth: 17/02/1979

Gender : Male

Marital status: Married

Certificate of Merit: Yes

Current no claims discount: 50%

Years of driving experience: Three or more

About your car and policy

Car make and model: HONDA JAZZ 1.5

Year of first registration : 2010

Chassis no.:

Engine no.:

Plan type: Comprehensive

Standard Excess: S\$1,500

NCD protector: Not Applicable

Your preferred workshop: Not Applicable

Overseas Booster: Not Applicable

Premium paid (Inclusive of GST): S\$1,266.79

Finance company: Creative auto



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18007181/Kpb3

09 MAY 2018

TAY SIEW YIN
BLK 58 STRATHMORE AVE
#07-109
SINGAPORE 142058

Dear Sir/Madam,

ACCIDENT INVOLVING SGX 8940A & SLW 3270D ON 14/04/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLW 3270D against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

To: Supreme Auto Service Pte Ltd
SINGAPORE

Letter of Authorisation

RE: ACCIDENT INVOLVING PLW 3270D & SGX 8940A
ALONG/AT George East Road
ON 14/04/2018.

1. I/We, Tang Yang Kheng (NRIC No. S7905501H),
owner/driver of motor vehicle no. PLW 3270D, & residing at
Supreme Auto Service Pte Ltd
respectively in consideration of your workshop repairing my/our vehicle, I/we hereby authorise you to claim on my/our behalf for the costs of repair and loss of use. I/We further confirm and authorise you to use my/our name/s to engage the said service of a solicitor to proceed with negotiation with the defaulting party's insurance company for payment of the same and in the event negotiation fails, to instruct the solicitor to issue Summons on my/our behalf and in my/our name/s to claim for the same. Irrespective whether the claim is successful or not, all legal costs incurred shall be borne by you, provided we rendered our assistance as per second paragraph stated herein below.
2. I/We understand that by signing this Letter of Authorisation, I/we has/have to render whatever reasonable assistance to you including signing all relevant Court's document and attendance in Court to give evidence to enable the claim to succeed. If I/we failed or neglected to do so despite request from you, you shall be entitled to claim from me/us the repair costs together with legal costs, other incidental costs and expenses pertaining the issuance of Summons in order to obtain payment from defaulting party.
3. You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit. Upon settlement of my/our claim, you are authorised to sign any Discharge Voucher or any document to confirm my acceptance of the settlement as full and final discharge of my/our claim, on my/our behalf. You also have my/our full authority to collect all compensation monies pertaining to the above-mentioned accident from insurance company or any other party, directly to your workshop M/s
Supreme Auto Service Pte Ltd
4. In the event the claim is settled or judgment is obtained against the defaulting party, payment after deducting all costs and disbursements incurred should be drawn in your name or my/our name/s (at your discretion) and will be forwarded to you.
5. This letter of Authorisation is irrevocable.

Signature: [Signature]

Name: Tang Yang Kheng

NRIC NO: S7905501H

Date this 16 day of April 2018.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SUPREME AUTO SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,000.00 (Global Sum) for vehicle no. SLW 3270D that was damaged pursuant to the accident which occurred on 14/04/2018 (date) along KEONG SAIK ROAD involving vehicle no/s SGX 8940A.

This is pursuant to the inspection conducted on 18/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TANG YANG KHANG ("the third party claimant") of vehicle no. SLW 3270D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLW 3270D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26 (day) of December (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721


TEL: 6452 8211 FAX: 6451 7420

CO. REG. NO. : 19-9404214-H

INVOICE : 17640

AIG ASIA PACIFIC INSURANCE LIMITED

DATE : 6/9/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: SLW 3270 D</u>	
	Lump sum repair	\$3,500.00
		
	Total	\$3,500.00



友立旅遊服務私人有限公司
UNIQUE TOURIST SERVICE (PTE) LTD

1, Rochor Road, #02-574,
Rochor Centre Singapore 180001
Tel: 6292 7656 Fax: (65) 6293 97
E-mail: unigtour@singnet.com.sg
STB LIC TA/00076

Co. Reg. No.: 197401067R
GST Reg. No.: M2-0019671-6

Mr Tang Yang Khang
23 Punggol Field Walk
#05-18
Singapore 828750

①

20, Sin Ming Lane,
#08-51, Midview City
Singapore 573958
Tel: 6292 7656

TAX INVOICE

NO. **WP2017364**

26.04.2018

Singapore, _____ 20

DATE	PARTICULARS	Q	\$	cts
------	-------------	---	----	-----

Rental of one unit Toyota Corolla Allis 1.6 Auto
Registration no. SJF 4219 K self driven
as from 16.04.2018 to 25.04.2018.

9 days at \$105.00 per day

\$ 945.00

Add GST at 7%

\$ 945.00

Amount Due

\$ 66.15

\$ 1011.15

(SIN DOLLARS: ONE THOUSAND ELEVEN AND FIFTEEN CENTS ONLY)

Standard Rated Supplies:\$ 945.00

Total Amount of GST:\$ 66.15


AUTHORISED SIGNATURE



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-057090

Date of Request: 16/04/2018

Your Ref No: Online Purchase

Supreme Auto Service Pte Ltd
176 Sin Ming Drive #02-01
Sin Ming Autocare
Singapore 575721

Dear Sir/Madam,

Enquiry Date 16/04/2018
Enquiry By Bee Gaik Har
TP Vehicle No. SGX8940A
Accident Date 14/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2018 Edit Reg		17 Apr 2018 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Tay Siew Yin (Zheng XiuYing) , ID: -								
Main Claimant:	TANG YANG KHANG , ID: S7905501H								
Vehicle Reg. No.:	SLW3270D	Date of Loss:	14/04/2018 19:00 - :59 [98 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claims Type:	TP / 6012353498SG	Policy/Cover Note No.:	1700020434 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGX8940A	Policy No. (Claimant):	PNCV2018-0000049						
		Excess:							
Repairer:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0715								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 27/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (19/04/2018): NO OI GIA REPORT AIG_SG (19/04/2018): NO TP GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW3270D (6012353498SG)
[SGX8940A]
TP
TANG YANG KHANG
Apr 14 2018 7:45PM
[Tay Siew Yin (Zheng XiuYing)]
Supreme Auto Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser		
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit			
Assessment Reports										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print			
1	30/04/18 11:49	Accident Statement <small>From: SC - Rep. No: SGX8940A, Claimant: TAY SIEW YIN</small>							Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
2	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
3	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
4	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
5	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
6	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
7	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
8	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
9	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
10	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
11	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
12	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
13	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
14	21/05/18 15:56	General View							Load JPG	<input checked="" type="checkbox"/>		
15	21/05/18 15:56	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
16	21/05/18 15:56	Chassis Number							Load JPG	<input checked="" type="checkbox"/>		
Documentation										1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	18/04/18 15:03	EMAIL FROM AIG DD 17042018							Load PDF			
2	18/04/18 15:03	NOTICE & GIA REPORT							Load PDF			
3	19/04/18 18:28	TP ESTIMATE- MARKED							Load PDF			
4	20/04/18 09:47	Non reporting letter							Load PDF			
5	18/01/19 16:21	WORKSHOP INVOICE							Load PDF			
6	18/01/19 16:21	AUTHORISATION TO ACT FORM							Load PDF			
7	18/01/19 16:21	Release Voucher							Load PDF			
8	18/01/19 16:21	RENTAL RECEIPT							Load PDF			
9	18/01/19 16:21	GIA SEARCH							Load PDF			
10	18/01/19 16:21	LETTER TO OI							Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LXX Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGX8940A (Insd veh)	Model:	HONDA JAZZ 1.3 (A)
	SLW3270D (TP veh)		
Date of Accident:	14/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$	9,144.64	
Final Repair Cost	:	\$	4,000.00	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		6 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$	4,000.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Supreme Auto Service Pte Ltd	:	\$ 4,000.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

18 Jan
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18007181/KPB3Q2

Date: 18/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700020434
Claimant Vehicle No : SLW3270D **Insured Vehicle No :** SGX8940A
 Date of Loss: 14/04/2018 Nature of Claim: TP Claim No: 6012353498SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW3270D**
 Make & Model: HONDA JAZZ, 1.3 (A) Engine No: HIDDEN
 Reg. Date: 01/02/2010 (Man. Year: 2010) Chassis No: JHMGE88509S203448
 Colour: Metallic Grey Odometer: 88515 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,204.64	3,295.32	3,909.32	54.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,220.00	720.00	37.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,144.64	4,515.32	4,629.32	50.62
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	9,144.64	3,500.00	5,644.64	61.73
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,102.00		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment: 17/04/2018
 Date Inspected: 18/04/2018 Inspected At: Supreme Auto Service Pte Ltd (HQ)
 176 Sin Ming Drive #02-01, Sin Ming
 Autocare
 Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BONNET HINGE	Repair	188.40 FL	*- FL
2	1		*FRONT BONNET	Broken	758.70 FL	*548.80 FL
3	1		*FRONT BONNET LOCK	Repair	96.50 FL	*- FL
4	1		*FRONT BUMPER	Buckled / Cracked	739.20 FL	*532.90 FL
5	1		*FRONT BUMPER SIDE RETAINERS	O/S Distorted	77.20 FL	*38.60 FL
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	386.90 FL	*215.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	427.60 FL	*231.20 FL
8	1		*FRONT BUMPER TOW COVER	Serviceable	28.10 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP COVER	Serviceable	197.80 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP	Serviceable	375.20 FL	*- FL
11	15		*FRONT BUMPER CLIP	Necessary	48.50 FL	*48.00 FL
12	2		*FRONT HEAD LAMP	Mtg Cracked	1,714.60 FL	*1,649.20 FL
13	2		*FRONT HEAD LAMP LOWER BRACKET	Repair	196.60 FL	*- FL
14	1		*FRONT GRILLE	Cracked	386.70 FL	*237.30 FL
15	1		*FRONT GRILLE EMBLEM	Scratched	76.30 FL	*76.30 FL
16	1		*FRONT AIR-CON CONDENSER	Serviceable	782.50 FL	*- FL
17	1		*FRONT AIR-CON FAN MOTOR	Serviceable	308.40 FL	*- FL
18	1		*FRONT RADIATOR FAN MOTOR	Serviceable	329.70 FL	*- FL
19	1		*FRONT RADIATOR ASSY	Serviceable	928.30 FL	*- FL
20	2		*RADIATOR TOP BRACKET	Serviceable	51.60 FL	*- FL
21	1		*RADIATOR EXPENSION TANK	Serviceable	198.20 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Buckled	596.30 FL	*485.60 FL
23	1		*RADIATOR COOLANT	Not Necessary	20.00 FS	*- FS
24	1		*FRONT NUMBER PLATE)	Dented	35.00 FS	*45.00 FS
25	1		*FRONT NUMBER PLATE CASING }	Dented	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,983.30	4,107.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,778.66	812.58
Total Parts (\$\$)	7,204.64	3,295.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	900.00	500.00
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	850.00	600.00
4	TO REPLACE AIR CON COMPONENT AND TOP UP GAS	New	140.00	100.00
Gross Labour Cost (S\$)			1,940.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >