

INS. CASE OWNER:

ASSIGNMENT

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

STAGE

DATE / PIC

26/4
17H

SLS 9995 C-X, SCU 44 C-X

Non-Reporting ltr (1st): 26/04/18

Non-Reporting ltr (2nd): 15/05/19

Non-Reporting ltr (Final): 17/05/2019

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

US

S\$ 6,850

(4 days)

Reduction:

53 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ass)

S\$ 7,329.50

O/D REVERSED 4M PROVED TP.

Loss of Rental (LOR):

S\$

(- days)

Loss of Use (LOU):

S\$

700 (\$ 100 x 7 days)

Loss of Income (LOI):

S\$

(\$ - x - days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$ 8,029.50

Global Sum S\$:

8,000

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

8,000

Name 1:

KUM CHEW MOTOR WORKSHOP

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
19/11/19Tr
\$320

REF: ALG

ASSIGNMENT

From:

Date: 18042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLS 9995C

at Workshop m/s

Kum Chew

of

160 Sin Ming Drive #05-08

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$65K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLS 9995C Yr Regn: FEB / 2010

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERC. E350

C.C. 3498

Colour:

BLACK

A/C. Insured / Std / NI / NA

Sp. Reading

96695

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2200572A 031010

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/35/R19

R: 275/30/R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

5/4/2018

D.O.I.

18/4/2018

Survey held at

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

(45:46,850 / Red \$7,775.90 (53%))

4 days + 1 Sunday + 2 pps = 7 days

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S + PS, \$

Photos

Others AR

TOTAL

\$2.84 x 2




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18007195/M1ua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 18-04-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCU 44C	Veh. Inspected	SLS 9995C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/04/2018	Inspection Date	18/04/2018
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

AIG ASIA PACIFIC INSURANCE PTE LTD
 78, SHENTON WAY #07-16
 SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64193000 62243698 Fax No. : 64153723/68357416

Estimate : ES004409

Date : 19/07/2018
 Vehicle Num. : SLS 9995 C
 Make/Model : MERCEDES BENZ E350-2009
 Chassis/Eng# : WDD2120572A031010/2729833124480
 Accident Date : 15/04/2018
 Claim No. :
 Reference : KC/TP9995/1804-05
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	FRT BONNET X NAI		2,355.00 X
2.	1 PC	FRT BUMPER		1,530.00
3.	2 4 PCS	FRT BUMPER PARKING SENSOR	275.00	1,100.00 550
4.	2 PCS	FRT BUMPER SIDE RETAINER	38.00	76.00
5.	12 PCS	FRT BUMPER CLIPS	12.00	144.00 30
6.	1 PC	FRT BUMPER REINFORCEMENT		535.00 X
7.	1 PC	FRT BUMPER SPONGE		185.00 X
8.	1 PC	FRT BUMPER LOWER GRILLE		160.00
9.	8 PCS	FRT BUMPER LOWER GRILLE CLIPS	12.00	96.00 20
10.	2 PCS	FRT BUMPER SIDE GRILLE	95.00	190.00
11.	6 PCS	FRT BUMPER SIDE GRILLE CLIPS	12.00	72.00
12.	1 PC	FRT BUMPER LOWER SPOILER		680.00
13.	1 PC	FRT BUMPER LOWER SPOILER CENTER (CHROME)		460.00
14.	2 PCS	FRT BUMPER LOWER SPOILER SIDE (CHROME)	230.00	460.00 230
15.	9 PCS	FRT BUMPER LOWER SPOILER CLIPS	12.00	108.00 20
16.	1 SET	FRT GRILLE (COMPLETE CHROME)		1,370.00 1215
17.	1 PC	FRT HEADLAMP - LH		3,340.00
18.	1 PC	FRT HEADLAMP PANEL - L/H		260.00 X
19.	1 PC	FRT NUMBER PLATE HOUSING		180.00 X
List TotalS\$:				13,301.00
10.00% Discount S\$:				1,330.10
				11,970.90
SPECIAL NETT ITEMS :				
1.	1 PC	FRT NUMBER PLATE X NAI		60.00 X
Special Nett Total S\$:				60.00

CONTINUE / ...

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

AIG ASIA PACIFIC INSURANCE PTE LTD
 78, SHENTON WAY #07-16
 SINGAPORE 079120

Attention : Motor Claim Department
 Contact : 64193000 62243698 Fax No. : 64153723/68357416

Estimate : ES004409

Date : 19/07/2018
 Vehicle Num. : SLS 9995 C
 Make/Model : MERCEDES BENZ E350-2009
 Chassis/Eng# : WDD2120572A031010/2729833124480
 Accident Date : 15/04/2018
 Claim No. :
 Reference : KC/TP9995/1804-05
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.

550.00 400✓

TO SPRAY & PAINT ON ACCIDENT PORTION.

950.00 300✓

TO CHECK WIRING FUNCTIONS.

180.00 X

TO ANTI-RUST AFFECTED AREAS.

200.00 30✓

TO RESET AND PROGRAMME HEADLAMP LIGHT.

380.00 80✓

TO RESET WARNING LIGHT.

85.00 X

TO RESET & PROGRAMME ON PARKING SENSOR.

250.00 80✓

Labour Total S\$:

2,595.00

SingDollars : Fourteen Thousand Six Hundred Twenty-Five & Cents Ninety Only

Total S\$: 14,625.90

KUM CHEW MOTOR WORKSHOP

LKK Auto Consultants hereby holds the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Catherine Chong (LKK Auto)

From: Supramaniam, Darshene <Darshene.Supramaniam@aig.com>
Sent: Tuesday, 17 April, 2018 4:45 PM
To: 'admin-a@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SCU44C AND SLS9995C ON 15 APRIL 2018
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SCU44C ... (39.9 KB); FaxFA08.tif

Hi,

Please refer to the enclosed request from **KUM CHEW MOTOR WORKSHOP.**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Ma Chin Fook** as Single Joint Expert as requested.

17042018 @ 513pm
mdm Lim veh in

Thank you.

Best Regards,

Darshene Supramaniam

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto

Shared Services - Malaysia | Global Business Services

Level 12, Menara Worldwide, 198 Jalan Bukit Bintang. 55100 Kuala Lumpur, Malaysia

Tel +603 2719 6000 ext 100-2208 | Fax +603 2719 6150

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SLS9995C (3172581046SG)**
[SCU44C]

TP

LEE CHER KIA

Apr 15 2018 12:00AM

[BB ENERGY ASIA PTE LTD]

Kum Chew Motor Workshop (160 Sin Ming)

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 19/04/2018 11:15 AM.

To LKK_HQ

CC NoorMariesa.AbuKassim@aig.com

Subject NO OI GIA REPORT

Hi

Kindly be informed that OI has not reported yet. OI details as below :

Name :BB ENERGY ASIA PTE LTD

Phone No. :98330758

Address :3 TEMASEK AVENUE CENTENNIAL TOWER #32-02 SINGAPORE 039190\

Thanks

Mariesa

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18007195/M1ua3

26th April 2018

BB ENERGY ASIA PTE LTD
3 TEMASEK AVENUE CENTENNIAL TOWER
#32-02
SINGAPORE 039190

Dear Sirs,

**ACCIDENT INVOLVING SCU 44C AND SLS 9995C ON 15.04.2018 ALONG / AT
TANGLIM MALL BASEMENT 2 CARPARK – LOT 62**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Thin Thin
Claims
Tel : 6841 2360
Fax: 6741 4108
Email : thinthin@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18007195/M1ea3

19 FEB 2019

By Registered Mail

BB ENERGY ASIA PTE LTD
3 TEMASEK AVENUE
#32-02 CENTENNIAL TOWER
SINGAPORE 039190

Dear Sir/Madam,

**ACCIDENT INVOLVING SCU 44C AND SLS 9995C ON 15/04/2018 ALONG TANGLIN MALL
BASEMENT 2 CARPARK – LOT 62 @ 17:00 HOURS**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **AIG Asia Pacific Insurance Pte Ltd** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of AIG reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from our office dated 26.04.18.

To enable us to look into the matter immediately, please let us hear from you within **fourteen (14)** days from date of this letter (by 05.03.19).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **AIG Asia Pacific Insurance Pte Ltd** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

ASHER SNG
Case Handler
DID: 6841 6051
Fax: 6741 4108
Email: ashersng@lkkauto.com

c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

To : Traffic Police – Deputy Head, Investigations Department
Fax : 65474885

ONLY FOR ACCIDENTS IN SINGAPORE

NON-INJURY MOTOR ACCIDENT REPORT SCHEME
FORM ON NON-REPORTING BY INSURED

Please be informed that we have yet to receive a motor accident report from our insured with regard to a non-injury motor accident as follows: -

Date of accident : 15/04/2018
Time of accident : 17:00
Place of accident : TANGLIN MALL BASEMENT 2 CARPARK – LOT 62
Third Party's name : LEE CHER KIA
Third Party's vehicle number : SLS 9995C
Our insured's name : BB ENERGY ASIA PTE LTD
Our insured's vehicle number : SCU 44C
Our insured's NRIC number : NIL
Our insured's address : 3 TEMASEK AVENUE CENTENNIAL TOWER #32-02 SINGAPORE 039190
Our Insured's telephone number : 98330758

A letter dated **(19/02/2019)** was sent to remind our insured to report the non-injury motor accident to us. No report has yet been made.

Please do not hesitate to contact the following for any clarification on the matter.
(Please cite our reference number: **(CC4/AIG18007195/M1ea3)**)

Name and address of insurance company : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#08-16
Singapore 079120

Name of contact person : Asher Sng
Contact Number : 6841 6051 Fax: 6741 4108
Date : 15/05/2019



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18007195/M1ea3

17 MAY 2019

By Registered Mail
(FINAL REMINDER)

BB ENERGY ASIA PTE LTD
3 TEMASEK AVENUE
#32-02 CENTENNIAL TOWER
SINGAPORE 039190

Dear Sir,

**ACCIDENT INVOLVING SCU 44C AND SLS 9995C ON 15/04/2018 ALONG TANGLIN MALL
BASEMENT 2 CARPARK – LOT 62 @ 17:00 HOURS**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 26/04/2018 & 19/02/2019.

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centers. For the listing of AIG reporting centers, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by 03 JUNE 2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Asher Sng
Case Handler
Tel : 6841 6051
Fax: 6741 4108
Email : AsherSng@lkkauto.com

This is a computer generated letter and no signature is required.

Cc AXA Insurance Pte Ltd
(Motor Claims Dept)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/05/2018 09:51
Date Of Accident	15/04/2018 16:00
Exact Location Of Accident	TANGLIN MALL BASEMENT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCU44C
Insured/Policyholder	
Name Of Registered Owner	BB ENERGY ASIA PTE LTD
Co Reg No	198900171E
Email Address	IMAD.NASR@BBENERGY.COM
Mobile Phone No	(LOCAL) +65-98330758
Alternative Phone No	OFFICE-98330758

Vehicle Particulars

Manufacturer	LAND ROVER
Model	DISCOVERY SPORT-2.0 SE SI4 (L550) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100492326-01
Cover Note Number	

Driver

Name of Driver	IMAD MAAROUF NASR
NRIC No	S2719631D
Date Of Birth	15/06/1951
Occupation	INDOOR
Date Of Driving Pass	02/05/2013
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98330758
Fax Number	
Contact Number	
Email Address	IMAD.NASR@BBENERGY.COM

Address	27 CLAYMORE ROAD #20-02
Postcode	229544
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - DIRECTOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS9995C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I AM A DIRECTOR OF BB ENERGY (ASIA) PTE LTD AND AUTHORIZED DRIVER OF THE COMPANY'S CAR.
ON 15/4/18 AROUND 4PM I PARKED THE CAR AT TANGLIN'S MALL IN B1 CARPARK IN THE LOT INDICATED ABOVE. UPON LEAVING AND DUE TO TIGHT SPOT, I HAD TO REVERSE SLOWLY BACKWARDS IN ORDER TO BE ABLE TO EXIT. WHILE REVERSING SLOWLY (DIRECTION OF THE ARROWS ABOVE) I WAS BIT CLOSE TO THE ROWS OF CARS PARKED ON THE LEFT HAND SIDE. I HEARD A TINY TWEAK SOUND AS IF MY TYRE STEPPED ON A METAL PLATE, I STOPPED AND ADVANCED A BIT TO ADJUST THE CAR'S POSITION IN ORDER TO REVERSE BACK AGAIN WITH A SAFETY DISTANCE. I REVERSED BACK AND THEN TURNED RIGHT TO EXIT THE CARPARK. THERE WAS NO ONE IN THE CAR WITH ME AND NO ONE IN THE CAR PARK. THE SOUND I HEARD WAS EXTREMELY FAINT AND THAT OF STEPPING ON A METAL PLATE RATHER THAN SCRATCHING A CAR FROM THE LEFT HAND SIDE. UNFORTUNATELY UNFORTUNATELY I RECEIVED A CALL FROM THE OFFICE ON THE FOLLOWING DAY WHILE I WAS IN JAKARTA ON A BUSINESS TRIP STATING THAT WAS A REPORT FILED FOR THE INCIDENCE. I TRIED TO CONTACT THE OWNER BY PHONE IN ORDER TO DISCUSS THE DECLARATION INCIDENCE OR WHAT IS REALLY THE DAMAGE, BUT NO SUCCESS I FILED A POLICE REPORT IMMEDIATELY UPON MY RETURN TO SINGAPORE.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



POLICY SCHEDULE

WEARNES AUTO PROTECTOR (LAND ROVER) PRIVATE VEHICLE

Policy No. : 2100492328-01

Period of Insurance : 29 Nov 2017 to 28 Nov 2018

Issued Date : 15 Nov 2017

ABOUT THE POLICYHOLDER

Name of Policyholder : BB ENERGY ASIA PTE LTD
 Address : 3 TEMASEK AVENUE
 #32-02 CENTENNIAL TOWER
 SINGAPORE 039190

Occupation/Nature of Business : Professional, Administrative & Support Services Activities (eg Audit/ Law firm)

ABOUT THE VEHICLE

Registration No. : SCU44C Engine Capacity/Tonnage : 1,999.00 CC
 Chassis No. : SALCA2AG1HH854545 Engine No. : 015074044122204PT
 Seating Capacity : 5 First Year of Registration : 2016 Body Type : SUV
 Make/Model : LANDROVER DISCOVERY SPORT S14 SE/HSE
 Hire Purchase Company/Employer's Loan : NA

ABOUT THE COVER

Sum Insured : Market Value
 Driver Restriction : NA

Off Peak Car : No
 Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDE") if You are or Your Authorized Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing the coverage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Strike, Riots and Civil Commotions, P1 to Authorized Driver / Unnamed Passenger - \$10000, Dealer - AIG Authorized Workshops, PA Insured - \$100000, Future and Accessories (CompuTag - \$2000, Sony Cam - \$1190, Personal Effects - \$1000, Key Replacement Cover - \$800, Loss of Use 250000, New For Old (25 months), In-Car Camera Excess Waiver, Glass Roof Moon Roof, Sun Rust Panoramic Glass Roof

EXCESS

Section 1
 Fire - \$0 Own Damage - \$000 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreens : \$100

PREMIUM

Premium : \$ 1,449.60
 GST (7%) : \$ 101.47

Total : \$ 1,551.07

Your Premium includes the following discount(s):

No Claim Discount - 50%

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCD518058075 Vehicle Registration No: SCU44C
Name (as shown in NRIC) : BB Energy Asia Pte Ltd NRIC/FIN/Passport No : 1989001716
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 15/4/2014 Time of Accident : 16:00
Place of Accident : Tanglin Mall Basement Carpark.
Insurance Company: AIK

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To amend vehicle No. SCU44k to SCU44C

Policyholder / Driver's Signature
Date:

CDG E, Klu

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18007195/M1ua3

26th April 2018

RECEIVED

30 APR 2018

BB ENERGY ASIA PTE LTD
3 TEMASEK AVENUE CENTENNIAL TOWER
#32-02
SINGAPORE 039190

Dear Sirs,

**ACCIDENT INVOLVING SCU 44C AND SLS 9995C ON 15.04.2018 ALONG / AT
TANGLIM MALL BASEMENT 2 CARPARK – LOT 62**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Thin Thin
Claims
Tel : 6841 2360
Fax: 6741 4108
Email : thinthin@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 4 November 2019 9:44 AM
To: kumchew1
Cc: Admin A
Subject: RE: ACCIDENT INVOLVING SLS 9995C AND SCU 44C ON 15/04/2018

Tracking:	Recipient	Delivery
	kumchew1	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 4/11/2019 9:44 AM
	shupeil@lkkauto.com	Delivered: 4/11/2019 9:44 AM
	olivialau@lkkauto.com	Delivered: 4/11/2019 9:44 AM

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter and your e-mail below.

For amicable settlement on a without prejudice basis, we propose settlement on a global sum for **\$8,000.00(all in)**.

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 28 May 2019 9:40 AM
To: [KUMCHEW1@SINGNET.COM.SG](mailto:kumchew1@singnet.com.sg)
Subject: ACCIDENT INVOLVING SLS 9995C AND SCU 44C ON 15/04/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2018 Edit Reg		17 Apr 2018 00:00 Edit Adj Rpt	\$6,850.00 Edit Estimates	\$6,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	BB ENERGY ASIA PTE LTD, Co. Reg. No.: 198900171E		
Main Claimant:	LEE CHER KIA, ID: S7127870J		
Vehicle Reg. No.:	SLS9995C	Date of Loss:	15/04/2018 16:00 - :59 [98 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3172581046SG	Policy/Cover Note No.:	2100492326 (Comprehensive)
Vehicle Reg. No. (Insured):	SCU44C	Policy No. (Claimant):	MT/00465409
		Excess:	
Repairer:	Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity, 575722 Sin Ming - Tel: 6456 3715		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 27/04/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (10/05/2019): Re: NO OI GIA REPORT
- AIG_SG (19/04/2018): NO OI GIA REPORT
- AIG_SG (19/04/2018): NO TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS9995C (3172581046SG)**
[SCU44C]
TP
LEE CHER KIA
Apr 15 2018 4:00PM
[BB ENERGY ASIA PTE LTD]
Kum Chew Motor Workshop (160 Sin Ming)

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/06/19 12:15	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
5	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
24	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
25	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
26	28/06/19 12:15	General View	Load JPG	<input checked="" type="checkbox"/>
27	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	28/06/19 12:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/06/19 12:15	Reinspection Photo		Load JPG
39	28/06/19 12:15	Reinspection Photo		Load JPG
40	28/06/19 12:15	Reinspection Photo		Load JPG
41	28/06/19 12:15	Reinspection Photo		Load JPG
42	28/06/19 12:15	Reinspection Photo		Load JPG
43	28/06/19 12:15	Reinspection Photo		Load JPG
44	28/06/19 12:15	Reinspection Photo		Load JPG
45	28/06/19 12:15	Reinspection Photo		Load JPG
46	28/06/19 12:15	Reinspection Photo		Load JPG
47	28/06/19 12:15	Reinspection Photo		Load JPG
48	28/06/19 12:15	Reinspection Photo		Load JPG
49	28/06/19 12:15	Reinspection Photo		Load JPG
50	28/06/19 12:15	Reinspection Photo		Load JPG
51	28/06/19 12:15	Reinspection Photo		Load JPG
52	28/06/19 12:15	Reinspection Photo		Load JPG
53	28/06/19 12:15	Reinspection Photo		Load JPG
54	28/06/19 12:15	Reinspection Photo		Load JPG
55	28/06/19 12:15	Reinspection Photo		Load JPG
56	28/06/19 12:15	Reinspection Photo		Load JPG
57	28/06/19 12:15	Reinspection Photo		Load JPG
58	28/06/19 12:15	Reinspection Photo		Load JPG
59	28/06/19 12:15	Reinspection Photo		Load JPG
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 16:06	NOTIFICATION FROM WORKSHOP		Load TIF
2	18/04/18 16:06	EMAIL PRS		Load PDF
3	18/04/18 16:06	ACKNOWLEDGEMENT EMAIL TO AIG DD 17.04.2018		Load PDF
4	20/04/18 11:47	TP GIA REPORT		Load PDF
5	26/04/18 09:03	Non reporting letter		Load PDF
6	19/02/19 14:22	1ST AR NON REPORTING LETTER		Load PDF
7	15/05/19 12:31	Final Reminder Letter		Load PDF
8	28/06/19 12:13	OI GIA		Load PDF
9	28/06/19 12:13	EMAIL TO INSURED		Load PDF
10	27/11/19 15:23	LOD		Load PDF
11	27/11/19 15:23	AUTHORISATION TO ACT		Load PDF
12	27/11/19 15:23	RELEASE VOUCHER		Load PDF
13	27/11/19 15:23	WORKSHOP INVOICE		Load PDF
14	27/11/19 15:23	REGISTERED MAIL FEE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCU44C (Insd veh)	Model:	MERCEDES-BENZ E350 3.5 (A)
	SLS9995C (TP veh)		
Date of Accident:	15/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	15,649.71
Final Repair Cost	:	\$	8,000.00
Loss of Use	:	\$	7.00 days at \$100.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	8,000.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Kum Chew Motor Workshop	:	\$ 8,000.00
2)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

27 Nov

2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18007195/M1KA3S2
Date: 27/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492326
Claimant Vehicle No : SLS9995C **Insured Vehicle No :** SCU44C
 Date of Loss: 15/04/2018 Nature of Claim: TP Claim No: 3172581046SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS9995C**
 Make & Model: MERCEDES-BENZ E350, 3.5 (A) Engine No: HIDDEN
 Reg. Date: 01/02/2010 (Man. Year: 2010) Chassis No: WDD2120572A031010
 Colour: Black Odometer: 96695 km
 Engine Capacity: 3498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 275/30 R19
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,030.90	7,715.70	4,315.20	35.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,595.00	890.00	1,705.00	65.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,625.90	8,605.70	6,020.20	41.16
Approved Total (Overridden) (S\$)		6,850.00		
(S\$)	14,625.90	6,850.00	7,775.90	53.17
+ GST 7.00/7.00% (S\$)	1,023.81	479.50	544.31	53.17
Nett Amount (S\$)	15,649.71	7,329.50	8,320.21	53.17
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		8,029.50		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 17/04/2018
 Date Inspected: 18/04/2018 Inspected At: Kum Chew Motor Workshop (160 Sin Ming) (HQ)
 160 Sin Ming Drive, #05-08 Sin Ming Autocity
 Singapore 575722
 Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Not Necessary	2,355.00 FL	*- FL
2	1		*FRT BUMPER	Broken	1,530.00 FL	*1,530.00 FL
3	4		*FRT BUMPER PARKING SENSOR	Shorted 2pcs Only	1,100.00 FL	*550.00 FL
4	2		*FRT BUMPER SIDE RETAINER	Broken	76.00 FL	*76.00 FL
5	12		*FRT BUMPER CLIPS	Necessary	144.00 FL	*30.00 FL
6	1		*FRT BUMPER REINFORCEMENT	Not Necessary	535.00 FL	*- FL
7	1		*FRT BUMPER SPONGE	Not Necessary	185.00 FL	*- FL
8	1		*FRT BUMPER LOWER GRILLE	Broken	160.00 FL	*160.00 FL
9	8		*FRT BUMPER LOWER GRILLE CLIPS	Necessary	96.00 FL	*20.00 FL
10	2		*FRT BUMPER SIDE GRILLE	Broken	190.00 FL	*190.00 FL
11	6		*FRT BUMPER SIDE GRILLE CLIPS	Necessary	72.00 FL	*72.00 FL
12	1		*FRT BUMPER LOWER SPOILER	Crushed	680.00 FL	*680.00 FL
13	1		*FRT BUMPER LOWER SPOILER CENTER (CHROME)	Crushed	460.00 FL	*460.00 FL
14	2		*FRT BUMPER LOWER SPOILER SIDE (CHROME)	Crushed 1pc Only	460.00 FL	*230.00 FL
15	1		*FRT BUMPER LOWER SPOILER CLIPS	Necessary	108.00 FL	*20.00 FL
			9pcs			
16	1		*SET FRT GRILLE (COMPLETE CHROME)	Broken	1,370.00 FL	*1,215.00 FL
17	1		*FRT HEADLAMP - LH	Broken	3,340.00 FL	*3,340.00 FL
18	1		*FRT HEADLAMP PANEL - L/H	Not Necessary	260.00 FL	*- FL
19	1		*FRT NUMBER PLATE HOUSING	Not Necessary	180.00 FL	*- FL
20	1		*FRT NUMBER PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,361.00	8,573.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,330.10	857.30
Total Parts (\$\$)	12,030.90	7,715.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.	New	550.00	400.00
2	TO SPRAY & PAINT ON ACCIDENT PORTION.	New	950.00	300.00
3	TO CHECK WIRING FUNCTIONS.	New	180.00	0.00
4	TO ANTI-RUST AFFECTED AREAS.	New	200.00	30.00
5	TO RESET AND PROGRAMME HEADLAMP LIGHT.	New	380.00	80.00
6	TO RESET WARNING LIGHT.	New	85.00	0.00
7	TO RESET & PROGRAMME ON PARKING SENSOR.	New	250.00	80.00
Gross Labour Cost (\$\$)			2,595.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >