

INS. CASE OWNER

Fran Khan

CC AXA 1800 720, K 1/1/11

LKK: IDAC

Surveyor:

KONNETH

DOI:

ASSIGNMENT 23/04/18

Date / Time:

18/14/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKD 694IT

Claim No.:

SRM00871/40279

Name of Insured:

STEPHANIE SMO ZI YUAN

Policy No.:

GA 23008711

Insured Tel No.:

HP: 92277769

Make / Model:

AUDI

Excess Sec II :SS

D.O.A: 17/4/18

Place of Accident:

WOLFRUMS AVE 1

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

6/7 31394



INSRS: WSP: Tel: Liability: RMKS:

city auto



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

| Date / Time | STAGE | DATE / PIC |
|-------------|-----------------------------------|-------------------------------------|
| 19/4/18 | Non-Reporting ltr (1st): | |
| | Non-Reporting ltr (2nd): | |
| | Non-Reporting ltr (Final): | |
| | Notification ltr (if non-pickup): | |
| | Call OI: | |
| | After call ltr to OI: | 21/05/18 |
| | Documentation Check List: | Handler Typist |
| | Notification ltr (if non-pickup) | <input type="checkbox"/> |
| | After call ltr to OI: | <input checked="" type="checkbox"/> |
| | Authorisation To Act: | <input checked="" type="checkbox"/> |
| | Release Voucher: | <input checked="" type="checkbox"/> |
| | Final Repair Bill: | <input checked="" type="checkbox"/> |
| | Car Rental Invoice: | <input checked="" type="checkbox"/> |
| | Towing Invoice: | <input type="checkbox"/> |
| | LTA / GIA: | <input checked="" type="checkbox"/> |
| | Medical Bill: | <input type="checkbox"/> |
| | PIR: | <input type="checkbox"/> |
| | Mandate/Reject Instruction: | <input checked="" type="checkbox"/> |
| | LOD: | <input checked="" type="checkbox"/> |
| | Payment Breakdown Form: | <input type="checkbox"/> |
| | Post-Repair Photos: | <input type="checkbox"/> |
| | Others: | <input type="checkbox"/> |

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 28/11/19 Confirm with: VIVONICA Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 0%

Repair Cost: (w/600) SS 1,016.50 (3 B VEH. C.O.; 01 2ND)

Loss of Rental (LOR): SS - (days)

Loss of Use (LOU): SS 300.00 (\$100 x 3 days)

Loss of Income (LOI): SS - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS 200

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost: SS -

Total: SS 1,318.50 Global Sum SS: -

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 1,318.50 Name 1: CITY AUTO PTE LTD

Payee 2: (Strike if N.A.) SS - Name 2: -

Payee 3: (Strike if N.A.) SS - Name 3: -

REF: ASM(AXA)

M

ASSIGNMENT

From: _____ Date: 23042018

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 3139U

at Workshop m/s: City Auto

of: Blk 160 Sim ming Dve # 05-01

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLJ 3139U Yr Regn: 07 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Scirocco 1984

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 111384 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZ88138AV446403

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD R/Rim or _____

(Policy Condition) 1pm

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 846k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.8.1% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Tyre Size: F: _____ R: 235/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front: _____ Rear: _____

R/Bal: 9 mm R/Bal: 9 mm

L/Bal: 9 mm L/Bal: 9 mm

D.O.A: 13/4/18 D.O.I: 23/4/18

Survey held at: _____ ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|------------------------|
| 24/4 | File pass to Customer |
| | L/ 2950.00 |
| | CRAB: \$1,569.00 (62%) |

Date/Time, File Pass to? : Prel. Report

1) - : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3) \$ + RS \$ _____

4) Photos _____

5) Others _____

TOTAL: _____

- Add Fee:
- : Site Insp (\$ _____)
 - : Interview (\$ _____)
 - : Tech Invs (\$ _____)
 - : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---------------------------|---|
| AXA INSURANCE PTE LTD | | Ref : CC4/ASM18007210/mb3 | |
| 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 | | Date : 18-04-2018 |  |
| | | Code : ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SKD 6941T | Veh. Inspected | SLJ 3139U |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 18/04/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 13/04/2018 | Inspection Date | |
| Survey held at | CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643. | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |



CITY AUTO PTE LTD

One Stop Automotive Solutions

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201804-000391(00)

Date : 17/04/2018

Vehicle No : SLJ3139U

Make/Model : VOLKSWAGEN SCIROCCO 2.0L AT
TSI 1379V3

Mileage (km) : 0

Chassis No : WVWZZZ13ZAV446403

Accident Date : 13/04/2018 00:00:00

Claim No : SKD6941T

Reference : SLJ3139U

Policy No : CN869285

AXA INSURANCE SINGAPORE PTE LTD

NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Contact : -

Fax No. :

*Not available
Resurvey by claim
2 days*

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|------|------------|----------|------------|------------|
|------|------------|----------|------------|------------|

LIST ITEMS :

| | | | | |
|------------------|----------------------|-----|--------|---------------|
| 1 | Rear bumper | 1.0 | 815.00 | 815.00 ✓ |
| 2 | Rear bumper sponge | 1.0 | 85.00 | 85.00 X |
| 3 | Rear bumper retainer | 2.0 | 55.00 | 110.00 X |
| List Total : | | | | 1,010.00 |
| 10% Discount S\$ | | | | 101.00 |
| | | | | <u>909.00</u> |

SPECIAL NET :

| | | | | |
|-----------------------|---------------------|-----|--------|---------------|
| 1 | Number plate | 1.0 | 25.00 | 25.00 X |
| 2 | Number plate casing | 1.0 | 35.00 | 35.00 X |
| 3 | Reverse sensor | 1.0 | 250.00 | 250.00 7X |
| SPECIAL NET Total S\$ | | | | <u>310.00</u> |

LABOUR :

| | | | | |
|--|-----|--------|------------|-----------------|
| *To water seal the leakage | 1.0 | 100.00 | 100.00 X | |
| - Spray painting on affected & replace parts | 1.0 | 650.00 | 650.00 220 | |
| - To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts | 1.0 | 550.00 | 550.00 200 | |
| | | | | <u>1,300.00</u> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

| | | |
|--|----------------|-----------------|
| E. & O.E. subject to final approval from Insurance Company | Total S\$ | 2,519.00 |
| Acknowledged by Repairer | GST 7% S\$ | 176.33 |
| Signature: | Amount Due S\$ | <u>2,695.33</u> |
| Date: | | |

Signature

for CITY AUTO PTE LTD

◀ Service Request Details

Claim
SBM00E8F

Reference
None ✎

Loss Date
April 13, 2018

Request Date
April 17, 2018

Due Date
April 24, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

*17042018 @ 241pm
Vanica veh not in*

Actions

Next Step
Agree to perform service

Vehicle Information

Incident Vehicle Registration #
SLJ3139U

Make
TPVD VOLKSWAGEN

...

Primary Contact/Insured

STEPHANIE SNG ZI YUAN
108 #10-166, WOODLANDS STREET 13, 730108, Singapore

CONTACTUS@INSMART.SG

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

◀ Re:MANDATE IA

Type

🔔 Question

Message

PLS PROCEED AS PROPOSED

Reply



CITY AUTO PTE LTD

One-Stop Automotive Solutions
BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Your ref: CC4/ASM18007210/Kmb3
Our ref: SLJ3139U

26/02/2019

WITHOUT PREJUDICE

Attr: Motor Claim Dept

AXA INSURANCE SINGAPORE PTE LTD
NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Dear Sir/Mdm,

Accident involving SLJ3139U and SKD6941T on 13/04/2018

We refer to the above said accident.

We enclosed here with relevant documents as stated below:-

- GIA report of SLJ3139U with police report
- Repair tax invoice
- Letter of authorization
- GIA search receipt


As instructed, we are claiming the following as stated below:-

| | | |
|---------------------------------|---|---------------------|
| Cost of Repair | : | S\$ 1,016.50 |
| Loss of use (3 Days x \$120.00) | : | S\$ 360.00 |
| LTA Search Fee | : | S\$ 2.00 |
| | | <u>S\$ 1,378.50</u> |

We do not have the survey report and photographs as our client's motor vehicle was surveyed by your appointed surveyor.

Please kindly let us know whether you are prepared to settle our client's claim & we look forward to hear from you soonest.

Thanks & regards



Vronica Law (Claim dept.)
Tel: 6453 1235
Fax: 64537944
Email: cityauto@singnet.com.sg



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AXA INSURANCE SINGAPORE PTE LTD

NO. 8
SHENTON WAY
AXA TOWER
SINGAPORE 068811

Attention: Motor Claim Department

Contact : 6338 7288

Fax No. : 6880 4838

TAX INVOICE

Tax Invoice : I2019-001285

Date : 26/02/2019

Vehicle No. : SLJ3139U

Make / Model : VOLKSWAGEN SCIROCCO 2.0L
AT TSI 1379V3

Mileage (km) : 111384

Chassis No. : WVVZZZ13ZAV446403

Accident Date : 13/04/2018

Claim No. : CC4/ASM18007210/Kmb3

Reference : JO201804-0456

Policy No. : CN869285

| S/No. | Particular | Amount |
|-------|------------------|------------|
| | * Lumpsum repair | S\$ 950.00 |

Total S\$: 950.00
GST @ 7% S\$: 66.50
Grand Total S\$: 1,016.50

CASH / NETS / CREDIT CARD PAYMENT ONLY

Customer's Signature/Co. Stamp


for CITY AUTO PTE LTD

Please note all works performed by City Auto Pte Ltd as performed in this invoice is subjected to the following Warranty conditions:

- 1) Any replacement of electrical components will carry 1 month warranty period from date of this invoice.
- 2) Any replacement of mechanical components will carry 3 months warranty period.

Please note that all warranty does not cover wear and tear conditions regardless of any components.

City Auto Pte Ltd reserves the right to determine any warranty conditions.

Thank You For Your Business !

K

LETTER OF DISCHARGE

We, CITY AUTO PTE LTD (workshop), hereby agreed and confirmed that we are authorized by the owner of motor vehicle SLJ3139U to accept the sum of \$ _____ (inclusive of into alia, damages, interests, loss of use, costs and disbursements) from M/s LKK Auto Consultants Pte Ltd, the authorized surveyors of M/s AXA Insurance Singapore Pte Ltd, the Third Party's insurers, on this matter.

This acceptance is in full and final settlement of any claim made against SKD6941T pursuant to the road accident which occurred along WOODLANDS AVE 3 on 13/04/2018.

We CITY AUTO PTE LTD (workshop) are further authorized by the said owner that this settlement is reached on a strictly without prejudice basis on the part of M/s AXA Insurance Singapore Pte Ltd. And or their insured or other person or persons arising out of this said accident.

In consideration of the said payment by the said M/s AXA Insurance Singapore Pte Ltd, we, the said authorized workshop, shall fully discharge them from any further claim whatsoever in respect of the said accident.

We also declare that we are authorized by the said owner to receive the said settlement sum and hereby undertake to indemnify M/s AXA Insurance Pte Ltd, against any claim made or which may be made in respect of this matter.

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575543
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

.....
For and on behalf of the owner of
()
(workshop stamp and authorized signature)

.....
For and on behalf of M/s AXA
Insurance Singapore Pte Ltd
(LKK stamp and authorized
signature)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007210/Khb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 03-12-2019

Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------|----------------|------------|
| Insured Veh. | SKD 6941T | Veh. Inspected | SLJ 3139U |
| Policy No. | GA230081/1 | Coverage (\$) | 0.00 |
| Claim No. | S8M00E8F | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 18/04/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------------|--------------|--------------------|
| Make & Model | VOLKSWAGEN SCIROCCO (A) | c.c | 1984 |
| Engine No. | HIDDEN | Year of Reg. | 2010 |
| Chassis No. | WWZZZ13ZAV446403 | Colour | METALLIC BLACK |
| Odometer | 111384 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-------------|-----------|---------|
| R/H Front Tyre | 235/40Z R18 | WEST LAKE | 9 mm |
| L/H Front Tyre | 235/40Z R18 | WEST LAKE | 9 mm |
| R/H Rear Tyre | 235/40Z R18 | WEST LAKE | 9 mm |
| L/H Rear Tyre | 235/40Z R18 | WEST LAKE | 9 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---------------------------|-----------------|------------|
| Accident Date | 13/04/2018 | Inspection Date | 23/04/2018 |
| Survey held at | 160 SIN MING DRIVE #05-01 | | |
| Repairer | CITY AUTO PTE LTD | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|-----------------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3139U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BUMPER (CONSISTENT) | DENTED / CUT | 815.00 | 815.00 |
| 1 | REAR BUMPER SPONGE (CONSISTENT) | SERVICEABLE | 85.00 | - |
| 2 | REAR BUMPER RETAINER @\$55.00 (CONSISTENT) | SERVICEABLE | 110.00 | - |
| | LESS 10% DISCOUNT | | -101.00 | -81.50 |
| | | | 909.00 | 733.50 |
| SPECIAL NETT ITEMS | | | | |
| 1 | NUMBER PLATE (SN) (CONSISTENT) | SERVICEABLE | 25.00 | - |
| 1 | NUMBER PLATE CASING (SN) (CONSISTENT) | SERVICEABLE | 35.00 | - |
| 1 | REVERSE SENSOR (SN) (CONSISTENT) | SERVICEABLE | 250.00 | - |
| | | | 310.00 | - |
| LABOUR | | | | |
| | TO WATER SEAL THE LEAKAGE. | NOT NECESSARY | 100.00 | - |
| | SPRAY PAINTING ON AFFECTED & REPLACE PARTS. | | 650.00 | 220.00 |
| | TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS. | | 550.00 | 200.00 |
| | | | 1,300.00 | 420.00 |
| GRAND TOTAL | | | 2,519.00 | 1,153.50 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 950.00 |

Report Ref No. CC4/ASM18007210/Khb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

| | |
|--------------|--|
| Claim | SBW0008F |
| Reference | CC4/ASM18007210/P003q2 |
| Loss Date | 13 April 2018 |
| Report Date | 17 Apr 2018 9:55:08 AM |
| Request Date | 24 November 2019 |
| Due Date | |
| Vendor Name | L&K AUTO CONSULTANTS PTE LTD (TP) |
| Type of Loss | Third Party Vehicle Damage |
| Services | Pending verification - Direct Settlement |

Actions

Next Step: Wait for: Approve Invoice

Add Invoice

| | |
|---------------------------------|-----------------|
| Vehicle Information | |
| Incident Vehicle Registration # | 5LJ3139U |
| Make | TPWD VOLKSWAGEN |
| Model | |
| Service Address | |

| | |
|---|--|
| ... | |
| Primary Contact/Insured | |
| STEPHANIE SNG ZI YUAN 108 #10-106, WOODLANDS STREET 13, 730108, Singapore | |
| CONTACTUS@INSMART.SG | |

| | |
|--|--|
| Claim Handler | |
| CHAN Kian Chuan 68805444 kianchuan.chun@axa.com.sg | |

Additional Instructions

[Messages](#)
[Invoices](#)
[History](#)
[Documents](#)
[Assessment](#)
[Metrics](#)
[Notes](#)

Document Type:

[+ Upload Documents](#)

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---------------------|---------|----------------------------|-----------------------------------|------------------|
| L&KInvoice1 (1).pdf | Invoice | Surveyor/ Assessor expense | L&K AUTO CONSULTANTS PTE LTD (TP) | 11 December 2019 |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|--|----------------------------|----------------------------------|--|------------------|
| LKKinspection (1).pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 December 2019 |
| LKKadjustment1a (2).pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 December 2019 |
| GIA SEARCH.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 December 2019 |
| PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf | Forms / Claim Documents | Satisfaction / Discharge Voucher | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 December 2019 |
| AUTHORIZATION TO ACT FORM.pdf | Forms / Claim Documents | POA / Authority Letter | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 December 2019 |
| MANDATE IA.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 November 2019 |
| LETTER TO OI.pdf | Letters and Correspondence | Policy Holders / Insured | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 November 2019 |
| TP LOO.PDF | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 November 2019 |
| LKK INSPECTION PHOTOS.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 November 2019 |
| Traffic Police Letter - Case under Investigation.pdf | Reports & Statement | Others | AJAX ADJUSTERS & SURVEYORS PTE LTD (MOTOR) | 19 October 2018 |
| TP ESTIMATE - MARKED.pdf | Reports & Statement | Estimate / Quotation | LKK AUTO CONSULTANTS PTE LTD (TP) | 24 April 2018 |
| Preliminary Advice VIA LKK.pdf | Reports & Statement | Estimate / Quotation | LKK AUTO CONSULTANTS PTE LTD (TP) | 24 April 2018 |
| SGA0321R GIA REPORT.PDF | Reports & Statement | GIA Report | SHAH Kuehal | 17 April 2018 |
| TP 05 VIA CITY AUTO.mig | Other | Other | SHAH Kuehal | 17 April 2018 |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|--|------------------------|------------|-------------|------------------|
| TP GIA Report (ELD113PU) - 1st vehicle (No injuries reported).PDF | Reports & Statement | GIA Report | SHAH Kuthal | 17 April 2018 |
| Insured GIA Report (KMD6941T) - 2nd vehicle.PDF | Reports & Statement | GIA Report | SHAH Kuthal | 17 April 2018 |