

ASS. REC. BY:

REF:

CS / TCS18007220 / ^D1416⁰²

Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

From (Person): Janice Goh of TCS Date/Time: 17042018 623pm

Estimated Cost: _____ Bill to: _____

OD / ^DTP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLV 3680J Insured: STL 7356Xat Workshop m/s Cycle & Carriage Tel: 83320062of 188 Pandan LoopPolicy No: _____ Claim No: DMPU18000113H

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

14.05.2018

H.O.D. Endorsement: _____

Date/Time: 18042018 1001am Person Contacted: Vincent Vehicle IN / ^DOUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 3680J - X
	STL 7356X - (C3 / TCS1701067) / Subsq ² DA: 300517
	Part by Part \$3980.41 (Red. 2800.04 : 41%)

REF: IS

ASSIGNMENT

From:

Date:

14052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLV 3680J

at Workshop m/s

of

Cycle & Carriage
188 Pandan Loop

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Vincent

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 3680J

Yr Regn:

FEB 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MARC 9320

C.C. 2996

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

6171

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2221622A 386672

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45/1719

R:

275/40/179

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

6/4/2018

D.O.I.

14/05/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 AUG 2018

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + P.T. \$

) Photos

) Other:

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Week-end (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

3970 41

250
10

260

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Tuesday, 17 April, 2018 6:23 PM
To: Vincent Seah Yong Kuan; 'assignments'
Cc: ECICS Claims
Subject: RE: SLV3680J // SJL7356X= DIRECT SETTLEMENT ; Our ref DMPU1800043H
Attachments: img-406172136-0001.pdf; SAS2386821.pdf

Without Prejudice

Dear Vincent

We would like to appoint LKK for the survey.
Our surveyor will contact you shortly.
Thank you.

Aside to LKK

Please assist to arrange TP PRI.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.****

-----Original Message-----

From: ECICS Claims
Sent: Tuesday, 17 April, 2018 6:19 PM
To: Vincent Seah Yong Kuan
Cc: ECICS Claims
Subject: RE: SLV3680J // SJL7356X= DIRECT SETTLEMENT ; Our ref DMPU1800043H

Without Prejudice

Dear Vincent

Liab is clear for direct settlement.
Thank you.

Regards,

Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

-----Original Message-----

From: Vincent Seah Yong Kuan [<mailto:vincent.seah@cyclecarriage.com.sg>]
Sent: Monday, 16 April, 2018 4:10 PM
To: ECICS Claims
Subject: RE: SLV3680J // SJL7356X= DIRECT SETTLEMENT

Hi

Can someone respond to email

Tks

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

-----Original Message-----

From: Vincent Seah Yong Kuan
Sent: Monday, 16 April 2018 4:05 PM
To: 'ECICS Claims' <claims@ecics.com.sg>
Subject: RE: SLV3680J // SJL7356X= DIRECT SETTLEMENT
Importance: High

HI

Kindly revert liability

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401

Fax.: 6872 1272

-----Original Message-----

From: Vincent Seah Yong Kuan
Sent: Wednesday, 11 April 2018 4:30 PM
To: 'ECICS Claims' <claims@ecics.com.sg>
Subject: FW: SLV3680J // SJL7356X= DIRECT SETTLEMENT
Importance: High

Hi

Kindly revert

Vincent Seah
Cycle & Carriage Ind. Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel : 83320062 (H/P) DID: 6771 4401
Fax.: 6872 1272

-----Original Message-----

From: Vincent Seah Yong Kuan
Sent: Friday, 6 April 2018 5:25 PM
To: ECICS Claims <claims@ecics.com.sg>
Subject: SLV3680J // SJL7356X= DIRECT SETTLEMENT

TO :ECICS ins.

Accident Claim Dept.

RE: Accident involving motor vehicle nos. SLV 3680J & SJL 7356 X along SLIP RD OF CLEMENTI RD TO AYE (TUAS) ,
Accident date: 06.04.18

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SLV 3680 J), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SJL 7356 X) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at vincent.seah@cyclecarriage.com.sg

Regards

Vincent Seah

Cycle & Carriage Industries Pte Limited
Body Care & Repair - Pandan Loop Service Center
188 Pandan Loop Singapore 128378
Tel: 8332 0062 (H/P)
Fax: 6872

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

[ECICS Facebook] [ECICS Twitter] [ECICS Limited]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2018 16:29
Date Of Accident	06/04/2018 08:10
Exact Location Of Accident	SLIP RD OF CLEMENTI RD TO AYE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV3680J
Insured/Policyholder	
Name Of Registered Owner	LEE GEOK PHOW
NRIC No	S1291333H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96743680
Alternative Phone No	OFFICE-96743680

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S320
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D29072229QMY
Cover Note Number	

Driver

Name of Driver	HO TEW NAM
NRIC No	S0105243H
Date Of Birth	18/07/1948
Occupation	INDOOR
Date Of Driving Pass	31/07/1985
Driving Experience	32 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98626126
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	10 DOVER RISE #07-07
Postcode	138680
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : LEE GEOK PHOW
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 6 APE 2018 AT 8.12 AM, I DROVE ALONG DOVER RD/CLEMENTI RD TWDS THE SLIP RD LEADING TO AYE (TUAS). WHILE I STOPPED MY CAR AT THE END OF THE SLIP RD, WAITING FOR A CAR FROM THE RIGHT TO PASS BY. I SUDDENLY HEARD A LOUD BANG AND REALISED THAT A CAR (SJL7356X) HAS HIT AT THE REAR BUMPER OF MY CAR. THE VISIBLE DAMAGE OF MY CAR WAS DENTS AND SCRATCHES ON THE REAR BUMPER. I WAS UNABLE TO ASCERTAIN WHEATHER THERE ARE OTHER HIDDEN DAMAGES AS A RESULT OF THE IMPACT. THERE IS NO PERSONAL INJURY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL7356X
Vehicle Make/Model/Colour	SUZUKI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AW BOON LENG
NRIC/Passport Number	S1632527I
Contact Number	97616462
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

06/04/18 14:00pm
Policyholder's Signature
Date & Time

06/04/18 04:00pm
Driver's Signature
(If driver is not the policyholder)
Date & Time

Vincent Seah
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Tel: 6771 4401 HP: 8332 0062 Fax: 6880 1272
Email: vincent.seah@cyclecarriage.com.sg
Reporting Centre Personnel's
Name:
NRIC/FIN No.:

SKETCH PLAN

SEE ATTACHED -

A: SLV 3680J

B: SJL 7356X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ON 6 APR 2018 AT ABOUT 8.12AM, I DROVE ALONG DOVED RD / CLEMENT RD TOWARDS THE SLIP RD LEADING TO AYE (THAS)
- Whilst I STOPPED MY CAR AT THE ~~REAR~~ END OF THE SLIP RD, WAITING FOR A CAR FROM THE RIGHT TO PASS BY, I SUDDENLY HEARD A LOUD BANG, AND REALIZED THAT A CAR WITH REG NO. SJL 7356X HAS HIT AT THE REAR BUMPER OF MY CAR SLV 3680J
- THE VISIBLE DAMAGES OF MY CAR WAS - DENTS AND SCRATCHES ON THE REAR BUMPER. I WAS UNABLE TO ASCERTAIN WHETHER THERE ARE OTHER HIDDEN DAMAGES AS A RESULT OF THE IMPACT. THERE IS NO PERSONAL INJURY IN THIS INSTANCE
- WISH TO FILE CLAIM AGAINST THE APPROPRIATE INSURANCE COMPANY FOR THE FOLLOWING

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

1. TOTAL REPAIR COST INCLUDING HIDDEN DAMAGES (IF ANY)

2. LOSS OF USE

3. EXCESS OF \$1000-

06/04/18 14:00pm

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name:

NRIC/FIN No.:

Vincent Seah
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Email: vincent.seah@cyclecarriage.com.sg
Tel: 4401 4401 HP: 8332 0952 Fax: 8822 1272

- THE VIDEO CLIP FROM DASH CAM IS AVAILABLE FOR VIEWING

- THATS ALL

167.11



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000

14 Jun 2016

280-000271

HO TEW NAM
BLK 10 DOVER RISE UNIT 07-07
SINGAPORE 138680

Our Ref : S0105243H



Dear Sir / Madam

ACKNOWLEDGEMENT OF RECEIPT OF MEDICAL EXAMINATION REPORT

We acknowledge receipt of your medical examination report on 14 Jun 2016.

- 2 As you have been certified medically fit to drive, you may continue to drive until your next medical examination.
- 3 If you are a foreigner, you may continue to drive until such date when your driving licence expires or until your next medical examination, whichever is earlier.
- 4 Traffic Police Department will send you another letter to go for your next medical examination when approaching your next age limit under the law.
- 5 Should you at any time be diagnosed to be unfit to drive by a medical practitioner, for your own safety and that of all road users, you are advised to surrender your licence to the Traffic Police.

Yours faithfully

HEAD OF TESTING AND LICENSING BRANCH
TRAFFIC POLICE

This is computer-generated and does not require a signature.



S000271



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

MOTOR MAX PLUS
Comprehensive

Certificate No. D 29072229 QMY

Excess : SGD1,000
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SLV3680J

2. Name of Policyholder
Lee Geok Phow

3. Effective Date of the Commencement of Insurance for the purposes of the Act
12/02/2018

4. Date of Expiry of Insurance
11/02/2019

5. Persons or Classes of Persons entitled to drive*

Lee Geok Phow
Ho Tew Nam

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.


This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.


Approved Insurers

for Chief Executive Officer



FOR C&C USE ONLY





VICTOR HO TENG NAM

[Signature]



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLV3680J

Mdm Lee Geok Phow

10 Dover Rise
#07-07
Singapore 138680

Mobile: 96743680

Vehicle & Document Information

WIP No **22635**
Reg No/Reg Date **SLV3680J / 12/02/2018**
Date In/Mileage **/ 0**
Chassis No **WDD2221622A380072**
Engine No **27682430771549**
Make/Model **MB/MB S 320 L SEDAN (V222) "FACELIFT"**
Colour/Trim **028 890 Cavansit B1/ 048 801 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	14/05/2018/ 09:53	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : D29072229QMY // 06.04.18 DRIVE IN/EXCESS : 06.04.18 // TP CAR NO.: SJL7356X =ECICS DATE IN/DATE SURVEY: 14.05.18// DIRECT SETTLEMENT: JANICE GOH-ECICS				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB DISASSEMBLE AND REPLACE REAR BUMPER				1200.00
A BPIRES RESPRAY ON REAR BUMPER				1200.00
M REAR BUMPER CENTRE MOULDING	1.00	110.24	00.00	110.24
M REAR LOWER BUMPER	1.00	537.09	00.00	537.09
M RIGHT ORNAMENTAL TRIM	1.00	109.57	00.00	109.57
M LEFT ORNAMENTAL TRIM	1.00	109.57	00.00	109.57
M REAR BUMPER	1.00	2040.41	00.00	2040.41
M REAR CROSS MEMBER	1.00	1093.57	00.00	1093.57

Not Authorized
PIP Repair
Before Paint Photo
LKK Ache (M)
14/5/2018 3w/ days

Confirmed & accepted by

7% GST on **Nett 6,780.45**
474.63

Authorized signatory and company stamp

Total Payable 7,255.08

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SLV3680J

Mdm Lee Geok Phow

10 Dover Rise
#07-07
Singapore 138680

WIP No

22635

Reg No/Reg Date

SLV3680J / 12/02/2018

Date In/Mileage

14/05/2018/ 6171

Chassis No

WDD2221622A380072

Engine No

27682430771549

Make/Model

MB/MB S 320 L SEDAN (V222) "FACELIFT"

Colour/Trim

028 890 Cavansit B1/ 048 801 Black

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	31/05/2018/ 14:12	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M. BPNSUN

POLICY NO/ACC DATE : 0290722290MY / 06/05/18
DRIVE IN/EXCESS : 06.04/18 // TP CAR NO. : SJ 7356X = EC108
DATE IN/DATE SURVEY: 14.05.18// MA-LKK 12:45PM
DIRECT SETTLEMENT: JANICE GOH-ECICS

A BPILAB

USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

DISASSEMBLE AND REPLACE REAR BUMPER

A BPIRES

RESPRAY ON REAR BUMPER

X REAR BUMPER

0.10 380.00

960.00

600.00

1.00 2040.41 00.00 2040.41

ESTIMATE

Finalization

3 days

Confirmed & accepted by

7% GST on **Nett** 3,980.41
278.63
Total Payable 4,259.04

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18007220/DTBN2

Date: 21/08/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLV3680J	Insured Vehicle No :	SJL7356X
Date of Loss:	06/04/2018	Nature of Claim:	TP
		Claim No:	DMPU1800043H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3680J	Engine No:	27682430771549
Make & Model:	MERCEDES-BENZ S320, 3.2 (A)	Chassis No:	WDD2221622A380072
Reg. Date:	12/02/2018 (Man. Year: 2017)	Odometer:	6171 km
Colour:	Black		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R19	Rear Tyre Size:	275/40R19
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,000.45	2,040.41	1,960.04	49.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,940.00	840.00	30.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,780.45	3,980.41	2,800.04	41.30
+ GST 7.00/7.00% (\$\$)	474.63	278.63	196.00	41.30
Nett Amount (\$\$)	7,255.08	4,259.04	2,996.04	41.30

INSPECTION

Date of Assignment:	17/04/2018	
Date Inspected:	14/05/2018	Inspected At:
		Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	3.0 days	

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2018)
Parts: 143	MERCEDES-BENZ S320 3.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV3680J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CENTRE MOULDING	Not Necessary	110.24 FS	*- FS
2	1		*REAR LOWER BUMPER	Not Necessary	537.09 FS	*- FS
3	1		*RIGHT ORNAMENTAL TRIM	Not Necessary	109.57 FS	*- FS
4	1		*LEFT ORNAMENTAL TRIM	Not Necessary	109.57 FS	*- FS
5	1		*REAR BUMPER	Distorted	2,040.41 FS	*2,040.41 FS
6	1		*REAR CROSS MEMBER	Not Necessary	1,093.57 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	4,000.45	2,040.41
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
2	DISASSEMBLE AND REPLACE REAR BUMPER	New	1,200.00	960.00
3	RESPRAY ON REAR BUMPER	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,780.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >