

22/03/2002

ASS. REC. BY:

REF:

CS/MSG18007226/11qbez

Special Instruction:

Surveyor

Merriman

Tanjung

ASSIGNMENT (Office)

From (Person):

Vimmala

of

MSLH

Date/Time:

18042018 11:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 5076B

Insured:

at Workshop m/s

Borneo Motor

Tel:

9847 6179

of

2 Pandan Crescent

Policy No:

MSD / VPCP / 18 - 000578 - 00

Claim No:

MSC / V / 18 - 000562

Sum Insured:

Excess:

\$ 300.00

Make of Veh:

D.O.A.

15042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18042018 1135am

Person Contacted:

Francis

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 5076B - X
19/4/18 @ 2:31pm	Report to Vimmala via Merriman.
19/4/18 @ 3:11pm	Huey NI informed C/A via Merriman.
20/4/18 @ 11:25am	Informed Francis C/A & Ex: \$300 by email.
13/6/18 @ 10:01am	Confirmed with Francis from fig \$4275, 3 days by email.
	(Add \$3158.44, 427.)

Tanpin

REF:

MSLG

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \$3300  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$74K  
 IDAC Accident Report: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 3 days Res: Yes or No  
 Lum Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT  
 Francis

Veh No: SKH 5076B Yr Regn: 2012 Dec.  
 Type: ☒ M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Camry G/S 1998  
 Colour: Bige A/C Insured / Std / NI / NA  
 Sp. Reading: 28957 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MRO53BK 50400 7739.  
 Gen. Cond: ☒ Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / ☒ Rim / STD A/Rim or  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 18/4/18 @ 1545  
 Survey held at Borneo Pandan  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Frt o/s  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

*[Signature]*  
 13/6/2018

RECEIVED 14 JUN 2018

Date/Time: File Pass to? ☐ : Preli. Report  
 11/6/18 Francis ☒ : Final Report  
 Date/Time: File Return to? \_\_\_\_\_

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech Insp (\$)  
☐ Weekend (\$)

Report Format: M-R-01  
 Lump Sum / I.B.I. (\$): 4275

Survey Fee	200
Transportation	
Phone	
Office	10
TOTAL	210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18007226/T1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 18-04-2018



Code : MSG

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKH 5076B
Policy No.	MSD/VPCP/18-000578-00	Coverage (\$)	0.00
Claim No.		Excess (\$)	3,300.00
Assign From	MERIMEN (VIMMALA)	Assign Date	18/04/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	15/04/2018	Inspection Date	18/04/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2018		18 Apr 2018 11:18 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:		TOYOTA MOTOR ASIA PACIFIC PTE LTD, Co. Reg. No.: 199002145R							
Vehicle Reg. No.:		SKH5076B	Date of Loss:	15/04/2018 17:00 - :59 [63 Months and 29 Days From LTA Reg Date (Man Yr)]					
Claim Type:		OD	Policy/Cover Note No.:	MSD/VPCP/18-000578-00 (Comprehensive) Coverage: 01/04/2018 - 31/03/2019					
			Excess:	S\$3,300.00					
Repairer:		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/04/2018]							
Driver/Custodian:		SIMANT ARUN (44 / Male), NRIC: G3371553L, Tel: +6591680541							
Adj Asg. Remarks:		Please survey and revert. OD excess \$300.00 + Young & Inexperience excess \$3,000=\$3,300. Repairer requested to arrange for survey on 18/04/2018 at 2 Pandan Crescent.							
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 13 June 2018 10:01 AM  
**To:** Francis Cher TCBC; SUR  
**Subject:** RE: SKH5076B FINAL BILL

Dear Francis,

Confirm final fig \$4,275.00 before excess \$300.00 & GST and 3 repair days.

Kindly send the relevant documents to MSIG insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Francis Cher TCBC [<mailto:francis.cher@borneomotors.com.sg>]

Sent: Saturday, 9 June 2018 10:05 AM

To: SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

Subject: SKH5076B FINAL BILL

Hi. Taufikh

Attached the above vehicle final bill for you to finalize.

Regards

Francis Cher

-----Original Message-----

From: [francis.cher@borneomotors.com.sg](mailto:francis.cher@borneomotors.com.sg) [<mailto:francis.cher@borneomotors.com.sg>]

Sent: Saturday, June 9, 2018 10:04 AM

To: Francis Cher TCBC

Subject: Scan Data from FX-0DBC96

Sent by: B050589 [[francis.cher@borneomotors.com.sg](mailto:francis.cher@borneomotors.com.sg)]

Number of Images: 1

Attachment File Type: PDF

Device Name: ApeosPort-V C2276

Device Location:

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 20 April 2018 11:25 AM  
**To:** Francis Cher TCBC  
**Cc:** SUR  
**Subject:** RE: SKH5076B OD CLAIM SURVEY

Dear Francis,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SKH 5076B (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Francis Cher TCBC [<mailto:francis.cher@borneomotors.com.sg>]  
**Sent:** Thursday, 19 April 2018 2:49 PM  
**To:** Vimmala D/O Raja Singam <[vimmala\\_rajasingam@sg.msig-asia.com](mailto:vimmala_rajasingam@sg.msig-asia.com)>  
**Cc:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** RE: SKH5076B OD CLAIM SURVEY

Hi. Ms. Mala

Noted With Thanks

Regards

Francis Cher

---

**From:** Vimmala D/O Raja Singam [[mailto:vimmala\\_rajasingam@sg.msig-asia.com](mailto:vimmala_rajasingam@sg.msig-asia.com)]  
**Sent:** Thursday, April 19, 2018 2:32 PM  
**To:** Francis Cher TCBC  
**Cc:** Shiau Chan (LKKAUTO)  
**Subject:** FW: SKH5076B OD CLAIM SURVEY

Hi Francis,

The OD excess is only \$300.00, since the driver has a valid foreign driving licence.

Please take notes.

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Apr 2018 17:04	CIm Veh Model Changed	(201714) TOYOTA CAMRY 2.0 (A).	[I] Vimmala D/O Raja Singam
2	17 Apr 2018 17:04	CIm Created	Reg No: SKH5076B. Policy No: MSD/VPCP/18-000578-00. Acct Date: 2018/04/15. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Born eo Motors (S) Pte Ltd (Pandan). Ins.Status => Incoming Claim. Created from SAS:M BM218050849	[I] Vimmala D/O Raja Singam
3	17 Apr 2018 17:20	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please survey and revert. OD excess \$300.00 + Young & Inexperience excess \$3,000=\$3,300. Repairer request to arrange for survey on 18/04/2018 at 2 Pandan Crescent.	[I] Vimmala D/O Raja Singam
4	17 Apr 2018 17:20	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/04/18	[I] Vimmala D/O Raja Singam
5	17 Apr 2018 17:20	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
6	18 Apr 2018 09:16	Assignment 1st Accessed		[A] Pauline Soh Li Ping
7	18 Apr 2018 11:17	Adj Assignment Cancelled	Workshop's email states survey today. IHS unable to survey today and tomorrow [ Today - Appt full and Claims Sharing, Tomorrow - ET(on leave) , AL(Paperwork)]	[I] Pauline Soh Li Ping
8	18 Apr 2018 11:17	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Pauline Soh Li Ping
9	18 Apr 2018 11:18	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please survey and revert. OD excess \$300.00 + Young & inexperience excess \$3,000=\$3,300. Repairer requested to arrange for survey on 18/04/2018 at 2 Pandan Crescent.	[I] Pauline Soh Li Ping
10	18 Apr 2018 11:18	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/04/19	[I] Pauline Soh Li Ping
11	18 Apr 2018 11:18	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Pauline Soh Li Ping
12	18 Apr 2018 11:33	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
13	18 Apr 2018 17:26	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] CATHERINE CHONG KAI LING
14	19 Apr 2018 14:24	Adj Rpt Initiated		[A] SHIAU CHAN
15	19 Apr 2018 14:27	CIm Registration Modified	Excess: 3300.00 -> 300.00.	[I] Vimmala D/O Raja Singam
16	19 Apr 2018 14:29	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/05/18	[A] SHIAU CHAN
17	19 Apr 2018 14:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/18	[A] SHIAU CHAN
18	19 Apr 2018 14:31	Adj Mandate Request	Cur.Req:5270.70:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NO T AUTHORISE REPAIR.	[A] SHIAU CHAN
19	19 Apr 2018 15:11	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/18. Mandate Remarks: check items of \$355.76 to be verified	[I] Eng Huey NI
20	19 Apr 2018 15:11	Adj Mandate Set	Approved:4914.94:check items of \$355.76 to be verified	[I] Eng Huey NI

Date From



Date To



Audit Type None

Go

### ACTIVITY

[18/04/2018 11:14] Pauline Soh Li Ping:  
Workshop's email states survey today. IHS unable to survey today and tomorrow [ Today - Appt full and Claims Sharing, Tomorrow - ET(on leave) , AL(Paperwork)]  
[18/04/2018 10:47] Pauline Soh Li Ping:  
No one pick call

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1781710	19/04/2018 14:24	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKH5076B		10.70

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 19 Apr 2018

**Preliminary Advice**

Vehicle No	: SKH5076B	Accident Date	: 15/04/2018
Make	: TOYOTA CAMRY	Policy No.	: MSD/VPCP/18-000578-00
Assignment Date	: 18/04/2018	Excess	: S\$3,300.00
Date of Inspection	: 18/04/2018	Est. Duration of Repair	: 3.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,433.44
Revised Amount	:S\$	4,914.94
Check Items (Estimated)	:S\$	355.76
Total	:S\$	5,270.70

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	59,573.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,427.00

**Remarks**

- ( X ) The vehicle is economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.



## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	2145R
<b>Vehicle Details</b>	
Vehicle No.:	SKH5076B
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO
Primary Colour:	Beige
Manufacturing Year:	2012
Engine No.:	1AZE258639
Chassis No.:	MR053BK5104007739
Maximum Power Output:	109.0 kW (146 bhp)
Open Market Value:	\$23,232.00
Original Registration Date:	17 Dec 2012
First Registration Date:	17 Dec 2012
Transfer Count:	0
Actual ARF Paid:	\$23,232.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Dec 2022
PARF Rebate Amount:	\$16,262.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	16 Dec 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$93,004.00
COE Rebate Amount:	\$43,311.00
<b>Total Rebate Amount:</b>	<b>\$59,573.00</b>

The information contained herein is correct as at 19 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/04/2018 13:23
Date Of Accident	15/04/2018 17:30
Exact Location Of Accident	IKEA TAMP NORTH CP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH5076B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TOYOTA MOTOR ASIA PACIFIC PTE LTD
Co Reg No	199002145R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91680541

### Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VPCP/18-000578-00
Cover Note Number	

### Driver

Name of Driver	SIMANT ARUN
Work Permit No	G3371553L
Date Of Birth	22/05/1973
Occupation	OUTDOOR
Date Of Driving Pass	12/10/2017
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91680541
Fax Number	
Contact Number	
Email Address	SIMANT.ARUN@TOYOTA-ASIA.COM

Address 20 ANSON RD TWENTY ANSON  
 Postcode 079912  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
 Weather Conditions RAINING  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TAMPINES N.P.C  
 Police Station Address ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER AS ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☐ DS

MCA: \_\_\_\_\_

## MOTOR ACCIDENT REPORT

Date Of Report: 17/4/2018 Time: 2205 Date Of Accident: 15/4/2018 Time: 1730  
Exact Location Of Accident: K&A TAMPINES NORTH CARPARK.  
Country/State of Loss: Singapore ☐ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐

## OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SKH5076B Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 199002145R  
Name Of Registered Owner: TOYOTA MOTOR ASIA PACIFIC PTE LTD  
Mobile Number: Alternative No: Email Address:

## Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: CAMRY 2.0  
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):  
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐  
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

## Insurance Company

Name of Insurance Company: MSIA  
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐  
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: MSD/VPCP/18-000578-00

## DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: SIMANT ARUN NRIC/ Passport / FIN No: G3371553L  
Date Of Birth: 22-05-73 Occupation: Indoor ☐ Outdoor ☒  
Date Of Driving Pass: 12-10-17 Gender: Male ☒ Female ☐  
Mobile Number: 9168-0541 Fax No: Alternative No:  
Address: TWENTY ANSON, 20 ANSON ROAD, SINGAPORE Postal Code: 079912  
Email Address: simant.arun@toyota-asia.com  
Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:  
Vehicle Registration Number of Driver's Own Vehicle (if applicable):  
Insurance Company of Driver's Own Vehicle (if applicable):

## GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: HIT & RUN Number of Passengers in the above vehicle (Including Driver):  
Weather Conditions: Clear ☐ Raining ☒ Others ☐ (If others, please state condition):  
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):  
Was any body injured in the Accident? No ☒ Yes ☐  
Was any foreign vehicle involved in this accident? No ☐ Yes ☒ Vehicle No: Vehicle type:  
Was any other material or property (e.g: other vehicle) damaged? No ☒ Yes ☐  
Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☐  
Was the accident reported to the police? No ☐ Yes ☒ (If yes, please state which Police Station):  
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☐ Yes ☐

## DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SKH5076B Vehicle Make/Model/Colour: TOYOTA/CAMRY/BEIGE  
Details Of Properties Damage in Accident: CAR BUMPER  
Name of Driver: SIMANT ARUN  
NRIC/Passport/FIN Number: G3371553L Contact Number:  
Address: Postal Code:  
Insurance Company Name:  
Nature Of Damage: No. Of Passenger (Including Driver):

## DETAILS OF ACCIDENT INDEPENDANT WITNESS

Name: NA  
Phone Number: NA  
Email Address: NA

## DETAILS OF INJURED PERSON 1 (Please fill Annex A if more person injured)

Name: NA Approximate Age:  
Address: Postal Code:  
Injuries Sustained: NA Injured person in which vehicle:  
Were seat belt worn? No ☐ Yes ☐ Were injured conveyed to hospital by ambulance? No ☐ Yes ☐

Describe Circumstances of the Accident

My car was parked at Parking Lot No. 88 of Level 1 at IKEA, Tampines. I had gone for shopping. Later on return, I found that my vehicle bumper has been damaged. I informed about the same to Ikea Officials and later to Singapore Police. More details about the same is in Police Complaint. The damaged has been done by other car and run from the incident place.

Declaration

We declare the foregoing particulars are true in every respect.

TOYOTA MOTOR ASIA PACIFIC PTE LTD

Policyholder's Signature / Date & Time

Simant Arun  
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


TOYOTA MOTOR ASIA PACIFIC PTE LTD

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan





**MSIG**

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)  
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
 Tel +65 6827 7888, Fax +65 6827 7800  
 msig.com.sg

**CERTIFICATE OF INSURANCE**

Motor Vehicles(Third Party Risks And Compensation) Act (Chapter 189)

Motor Vehicles (Third Party Risks And Compensation) Rules, 1960

Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

**MotorMax Plus**

21/03/2018

K1701-003

**CERTIFICATE No.**

MSD/VPCP/18-000578-00

1. Index Mark and Registration

Number of Vehicle

SKH5076B

2. Name of Policy holder

TOYOTA MOTOR ASIA PACIFIC PTE LTD

3. Effective date of the Commencement of

01/04/2018

Insurance for the purposes of the

Act

4. Date of Expiry of Insurance

31/03/2019

5. Persons of classes of Persons entitled to drive\*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order with <sup>their</sup> his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle. It has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And Provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its registration and licensing under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use\*

Use only for social, domestic &amp; pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward, tuition, driving test, racing, pace-making reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

AUTHORIZED SIGNATURE

**IMPORTANT NOTICE**

This Certificate is not transferable to a new owner of the vehicle.

If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that Effect must be made. Failure to comply with this obligation is an offence under the compulsory Insurance Legislation.

This Certificate must be returned if the insurance is suspended during its currency.

If you are involved in an accident, full details must be forwarded immediately to the Company.



**EMPLOYMENT PASS**  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

**Employer**  
TOYOTA MOTOR ASIA PACIFIC PTE LTD



**Name**  
ARUN SIMANT  
**Occupation**  
DEPUTY GENERAL MANAGER

**FIN**  
G3371553L

**Date of Application**  
12-04-2017  
**Date of Issue**  
03-07-2017  
**Date of Expiry**  
03-07-2019



L8090426

**VISIT PASS**  
Immigration Regulations

**Name**  
ARUN SIMANT



<b>Date of Birth</b>	<b>Sex</b>	<b>Nationality</b>
22-05-1973	M	INDIAN
<b>FIN</b>	<b>Date of Issue</b>	<b>Date of Expiry</b>
G3371553L	03-07-2017	03-07-2019

**MULTIPLE JOURNEY VISA ISSUED**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED  
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.





**REPUBLIC OF SINGAPORE** **DRIVING LICENCE**

Licence Number: **G3371553L**




Name: **ARUN SIMANT**

Birth Date: **22 May 1973**

Issue Date: **12 Oct 2017**

Valid Till: **11/10/2022**

002733432A

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

		EFFECTIVE DATE
Class 2B	Motorcycles $\leq 200$ cc	12 Oct 2017
Class 3	Motor cars with unladen weight $\leq 3000$ kg with $\leq 7$ passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500$ kg	12 Oct 2017

NP 428A





Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 15/04/2018 19:40	Vide Report No.: G/20180415/0208	Station Diary No.: 65
--	-------------------------------------	--------------------------

<b>Informant's Particulars</b>			
Name of Informant: ARUN SIMANT		Address: 177 TANJONG RHU ROAD #10-19 WATER PLACE SINGAPORE 436607	
ID Type / ID No.: FIN NO / G3371553L		Contact No.: Home/Office: Mobile: 91680541	
Nationality: INDIAN		Email:	
Sex: Male	Age: 44	Date of Birth: 22/05/1973	Type of Informant: Driver
Race: Indian		Language: English	Institution / School Name:
Occupation: Management executive		Driving Licence Information: Class: Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 15/04/2018 17:30	Type of Location: Car Park
Location: Along Road 1 TAMPINES NORTH DRIVE 2  IKEA, CARPARK B07, LEVEL 1, LOT NO.88				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: HIT&RUN			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKH5076B	Car	TOYOTA	CAMRY	Beige	Slightly Damaged	0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180415/2085

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

3 of 3

Report No. T/20180415/2085

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MUHAMMAD AL-HASSAN BIN ABDUL  
RAHMAN

Signature Of Informant:

*Simant Arun*

Signature Of Interpreter:

Not applicable

Date/Time:

15/04/2018 19:40

Officer In Charge Of Case:

TP / HRT /

SI TAN LEE HWANG DAWN

Contact No.: 65476215

Classification Of Case:



**SINGAPORE  
POLICE FORCE**

Authentication Stamp

NP168

SIGNATURE



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

## ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)  
Toyota Bodycage Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s Toyota Motor Asia Pacific Pt 20 Anson Road #13-01 Twenty Anson Singapore 079912 Work: 66313559
	Document No 0	
	Document Date 17/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	JEPEKT E1	ACV51R	17/12/2012	SKH5076B	0	30471	50D/SKH5076B/15041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053BK5104007739	1AZE258639	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MSD/VPCP/18-000578 ACC DATE:15.04.18 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				507. 100.00
2	B	BP-LAB REPLACE AND REFOCUS HEADLAMP.				169.50
3	B	BP-LAB REMOVE ALL NECESSARY DAMAGED PARTS TO REPACE, REPAIR, STRAIGHTEN FRT BUMPER, L/F FENDER AND AFFECTED PORTION OF CAR.				1017/ 2034.00
4	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				556/ 1668.00
5	1	S52119-06986 COVER, FR BUMPER	1.00	579.90	15.00	492.91
6	2	S52536-06160 RETAINER, FR BUMPER & RH	1.00	96.90	15.00	82.36
7	3	S81150-06A61 HEADLAMP ASSY, LH RH	1.00	3055.50	15.00	2597.17
8	4	T81220-0D042 RH X/FRT FOG LAMP ASSY,	1.00	300.90	15.00	255.76
9	5	S75443-06A50 PLATE, LUGGAGE	1.00	39.70	15.00	33.74

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 3,461.94 Labour 3,971.50 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	7,433.44
		GST 7.00%	520.34
		Less	0.00
		Amount Due	7,953.78

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE 17/04/2018

Acknowledged by Repairer 10:53

Signature

Date:

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SKH5076B

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Attn: Taufikh  
3 days. Final Bill  
**TAX INVOICE**

Page 2 of 2  
**Borneo Motors (Singapore) Pte Ltd**

Online Service Booking :  
[www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg)  
Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 38024346 Document Date 08/06/2018	M/s Toyota Motor Asia Pacific Pt 20 Anson Road #13-01 Twenty Anson Singapore 079912 Work: 66313559

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	JEPEKT E1	ACV51R	17/12/2012	SKH5076B	28957	30471	50D/SKH5076B/15041
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053BK5104007739	1AZE258639	60	Francis Cher T S	08/06/2018 16.38	08/06/2018 16.38		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MSD/VPCP/18-000578 ACC DATE:15.04.18 TOW/DRIVE IN: EXCESS:\$300 DATE-IN: DATE SURVEY:18.04.18 NO OF REPAIR DAYS: 3 DAYS BY:TAUFIKH (LKK) AUTHORISED ON:20.04.18	*			50.00
2	B	BP-LAB REPLACE AND REFOCUS HEADLAMP.	*			169.50
3	B	BP-LAB REMOVE ALL NECESSARY DAMAGED PARTS TO REPACE, REPAIR, STRAIGHTEN FRT BUMPER AND AFFECTED PORTION OF CAR.	*			1017.00
4	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			556.00
5	V	EXC Excess element of insurance repair to be 88 paidby the insured party				-300.00
6	1	S52119-06986 COVER, FR BUMPER	1.00	579.90	15.00	492.91
7	2	S52535-06170 RETAINER, FR BUMPER R	1.00	96.90	15.00	82.36
8	3	S81110-06A62 HEADLAMP ASSY, RH	1.00	2243.80	15.00	1907.23
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 2,482.50 Labour 1,792.50 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	3,975.00
			GST 7.00% 278.25 Less 0.00 Amount Due 4,253.25

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

366910

TO SECURITY GUARD

366910

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/06/2018  
TIME 19:14

VEHICLE NO SKH5076B

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Moto**

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2018		18 Apr 2018 11:18 <a href="#">Edit Adj Rpt</a>	<b>S\$4,275.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,275.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>












Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TOYOTA MOTOR ASIA PACIFIC PTE LTD, Co. Reg. No.: 199002145R								
Vehicle Reg. No.:	SKH5076B	Date of Loss:	15/04/2018 17:00 - :59 [63 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / MSC/V/18-000562	Policy/Cover Note No.:	MSD/VPCP/18-000578-00 (Comprehensive) Coverage: 01/04/2018 - 31/03/2019						
		Excess:	S\$300.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmla D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 18/05/2018]								
Driver/Custodian:	SIMANT ARUN (44 / Male), NRIC: G3371553L, Tel: +6591680541								
Adj Asg. Remarks:	Please survey and revert. OD excess \$300.00 + Young & inexperience excess \$3,000=\$3,300. Repairer requested to arrange for survey on 18/04/2018 at 2 Pandan Crescent.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (19/04/2018): Alert - Adj Mandate Approved (S\$4914.94) - SKH5076B - Claim Handler: Vimmla D/O...</li> <li>MSIG_SG (19/04/2018): SKH5076B (MSC/V/18-000562)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents
















\*SKH5076B (MSC/V/18-000562)  
OD  
Apr 15 2018 5:00PM  
[TOYOTA MOTOR ASIA PACIFIC PTE LTD]  
Borneo Motors (S) Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>
<b>Assessment Reports</b>		
		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)
1	17/04/18 13:27	<b>Accident Statement</b>
		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)
1	19/04/18 14:29	<b>Adjuster Immediate Advice</b>
		Load HTM
<b>Photos/Images</b>		
		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)
1	17/04/18 13:26	<b>Accident Photo</b> [Linked Accident Report Documents]
		Load JPG <input checked="" type="checkbox"/>
2	17/04/18 13:26	<b>Accident Photo</b> [Linked Accident Report Documents]
		Load JPG <input checked="" type="checkbox"/>
3	17/04/18 13:26	<b>Accident Photo</b> [Linked Accident Report Documents]
		Load JPG <input checked="" type="checkbox"/>
4	17/04/18 13:26	<b>Accident Photo</b> [Linked Accident Report Documents]
		Load JPG <input checked="" type="checkbox"/>
5	17/04/18 13:26	<b>Accident Photo</b> [Linked Accident Report Documents]
		Load JPG <input checked="" type="checkbox"/>
6	17/04/18 13:26	<b>Accident Photo</b> [Linked Accident Report Documents]
		Load JPG <input checked="" type="checkbox"/>
7	17/04/18 13:26	<b>Accident Photo</b> [Linked Accident Report Documents]
		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	19/04/18 14:30	<b>Odometer Reading</b>
		Load JPG <input checked="" type="checkbox"/>
2	19/04/18 14:30	<b>Chassis Number</b>
		Load JPG <input checked="" type="checkbox"/>
3	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
4	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
5	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
6	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
7	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
8	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
9	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
10	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
11	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
12	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
13	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
14	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
15	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
16	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
17	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
18	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
19	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
20	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
21	19/04/18 14:30	<b>General View</b>
		Load JPG <input checked="" type="checkbox"/>
<b>Documentation</b>		
		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)
		Load JPG <input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	17/04/18 17:22	Estimate from Borneo Motors	 Load PDF	
2	17/04/18 17:22	Email from repairer to arrange for survey on 18/04/2018	 Load PDF	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	17/04/18 13:27	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	17/04/18 13:27	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	17/04/18 13:27	CI [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	17/04/18 13:27	IC [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	17/04/18 13:27	IC [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	17/04/18 13:27	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	17/04/18 13:27	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 14:29	ESTIMATE	 Load PDF	
2	18/06/18 12:00	Workshop Invoice	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	17/04/18 13:27	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	17/04/18 13:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/04/18 13:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/04/18 13:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	17/04/18 13:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	17/04/18 13:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	17/04/18 13:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	17/04/18 13:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	17/04/18 13:27	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	17/04/18 13:27	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	17/04/18 13:27	CI	 Load JPG	<input checked="" type="checkbox"/>
4	17/04/18 13:27	IC	 Load JPG	<input checked="" type="checkbox"/>
5	17/04/18 13:27	IC	 Load JPG	<input checked="" type="checkbox"/>
6	17/04/18 13:27	Police Report	 Load JPG	<input checked="" type="checkbox"/>
7	17/04/18 13:27	Police Report	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			



**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG18007226/T1QBE2

Date: 18/06/2018

### REFERENCE

Insured/Claimant:	TOYOTA MOTOR ASIA PACIFIC PTE LTD	Policy No:	MSD/VPCP/18-000578-00	Claim No:	MSC/V/18-000562
Date of Loss:	15/04/2018	Nature of Claim:	OD		

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKH5076B</b>	Engine No:	1AZE258639
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK5104007739
Reg. Date:	17/12/2012 (Man. Year: 2012)	Odometer:	28957 km
Colour:	Beige		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,561.94	2,532.50	1,029.44	28.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,871.50	1,742.50	2,129.00	54.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,433.44</b>	<b>4,275.00</b>	<b>3,158.44</b>	<b>42.49</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>7,133.44</b>	<b>3,975.00</b>	<b>3,158.44</b>	<b>44.28</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>499.34</b>	<b>278.25</b>	<b>221.09</b>	<b>44.28</b>
<b>Nett Amount (S\$)</b>	<b>7,632.78</b>	<b>4,253.25</b>	<b>3,379.53</b>	<b>44.28</b>

### INSPECTION

Date of Assignment:	18/04/2018	
Date Inspected:	18/04/2018	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2018)
<b>Parts:</b> 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKH5076B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER, FR BUMPER	Deformed	492.91 FS	*492.91 FS
3	1		*RETAINER, FR BUMPER RH	Necessary	82.36 FS	*82.36 FS
4	1		*HEADLAMP ASSY, RH	Cut	2,597.17 FS	*1,907.23 FS
5	1		*RH FRT FOG LAMP ASSY	Not Necessary	255.76 FS	*- FS
6	1		*PLATE, LUGGAGE	Not Necessary	33.74 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>3,561.94</b>	<b>2,532.50</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE AND REFOCUS HEADLAMP	New	169.50	169.50
2	REMOVE ALL NECESSARY DAMAGED PARTS. TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, L/F FENDER AND AFFECTED PORTION OF CAR	New	2,034.00	1,017.00
3	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	1,668.00	556.00
Gross Labour Cost (S\$)			3,871.50	1,742.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >