



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18007241/Gvbe2

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 13-06-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	GBB 5745S	Veh. Inspected	SJT 4958L
Policy No.		Coverage (\$)	0.00
Claim No.	DMCV1700070H	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	10/04/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET AVEO	c.c	1399
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KL1SA4871AB018182	Colour	RED
Odometer	63237	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R14	TOYO	6 mm
L/H Front Tyre	175/65 R14	TOYO	6 mm
R/H Rear Tyre	175/65 R14	TOYO	6 mm
L/H Rear Tyre	175/65 R14	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/08/2017	Inspection Date	20/04/2018
Survey held at	UNI AUTOMOTIVE PL 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**