

ASS. REC. BY:

REF:

CS/GAU8007268/Tigb n2

Special Instruction:

Surveyor:

Toufiah

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAI

Date/Time:

19042018 938am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 3586P

Insured:

YM 7143K

at Workshop m/s

Borneo motor

Tel:

9221 3150

of

2 Pandan Crescent

Policy No:

Claim No:

CIMO MVC 000003172

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

20042018 @ 5pm

H.O.D. Endorsement:

Date/Time:

19042018 952am

Person Contacted:

Raymond

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 3586P - X

YM 7143K - NA / INC12002468 / ASZ

DOA: 310112

23/04/18

@ 15:31 p.m. revised to Rachel Tan via email.

27/5/18 @

1.53pm confirmed with Raymond final fig \$6921.46, 5 days.
(Ref \$ 3662.40, 35%)

Signature: Tayfun

REF: GRL

ASSIGNMENT

From: _____ Date: 20042018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKZ 3586P

at Workshop m/s: Borneo Motor

of: 2 Pandan Crescent

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Raymond

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Raymond

Veh No: SKZ3586P Yr Regn: 2016 Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota wish. C.C. 1798

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 61152 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDG20W30J00 3575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/4/18

Survey held at: Borneo Motor Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Raymond
22/5/2018

RECEIVED 23 MAY 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) 23/5/2018 ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: _____

Transportation _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

350

Report Format: TP

Lump Sum / I.B.I. (\$) 6779.46



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: -

Date: 23/04/2018

Our Ref: CS/GAI18007268/T1qb

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKZ 3586P.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/04/2018 at the premises of M/s Borneo Motors (Singapore) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 10,591.86</u>
Revised Estimate Amount	: <u>S\$ 6,929.46</u>
Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>


Description of Damage:

The vehicle sustained at the n/s portion.

Repair days: 5 Days

Comments/ Present Status:

Damage consistent



Yours faithfully

Taufikh
Motor Surveyor

Catherine Chong (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Thursday, 19 April, 2018 9:38 AM
To: Siti Nabilah PTCBC
Cc: LKK Assignments
Subject: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018
Attachments: SKZ3586P 16042018_SAS_Damaged Photos_Accident Scene Photos.pdf; SKZ3586P 16042018_Est Inv.pdf

Without prejudice

Dear Siti

Based on accident reports, liability is against YM7143K. We will arrange LKK to conduct survey.

Dear LKK

Please accept TP PRI. Attached TP GIA report, and estimates.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Siti Nabilah PTCBC <Siti.Nabilah@inchcape.com.sg>
Sent: Wednesday, April 18, 2018 5:28 PM
To: Ong, Joanna <Joanna.Ong@sg.gaig.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: Siti Nabilah PTCBC <Siti.Nabilah@inchcape.com.sg>
Subject: [External] Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos, Accident Scene Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured YM7143K thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Raymond Seah @ 9221 3150 / 6631 1865** located at **2 Pandan Crescent – Level 4** for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you very much in advance!

Best Regards,

Nabilah

TPR Team (Claims Accident Recovery Dpt)

DID 6631 1874 | FAX 6872 7260

Inchcape - Borneo Motors (S) Pte Ltd



THE ALL-NEW LEXUS LS
WITHOUT PRECEDENT



This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAuto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 23 May 2018 11:47 AM
To: Shiau Chan (LKKAuto)
Subject: RE: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

CLMOMVC000003172

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, May 23, 2018 11:42 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: [External] RE: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Dear Rachel,

Kindly provide us the claim number.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 23 April 2018 3:31 PM
To: Rachel.Tan@sg.gaig.com
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Dear Rachel,

Enclosed herewith preliminary advice of SKZ 3586P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Thursday, 19 April 2018 11:51 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; 'SUR' <sur@lkkauto.com>
Cc: 'LKK Assignments' <assignments@lkkauto.com>
Subject: RE: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 May 2018 1:58 PM
To: 'Raymond.Seah@borneomotors.com.sg'
Cc: SUR
Subject: RE: FINALISE FOR SKZ3586P

Dear Raymond,

Confirm final fig \$6,929.46 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 18 May 2018 12:19 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: FW: FINALISE FOR SKZ3586P

CS/GAI18007268/T1qb

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond Seah PTCBC [<mailto:Raymond.Seah@borneomotors.com.sg>]
Sent: Friday, 18 May 2018 11:56 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FINALISE FOR SKZ3586P

Dear Taufikh,

Attach are photos & estimate of SKZ3586P to finalize.

Thanks

Raymond Seah

9221 3150

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 23 April 2018 3:31 PM
To: 'Rachel.Tan@sg.gaig.com'
Cc: 'sur@lkkauto.com'; 'assignments@lkkauto.com'; 'admin-d@lkkauto.com'
Subject: FW: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018
Attachments: SKZ 3586P - Preli Advise.pdf

Dear Rachel,

Enclosed herewith preliminary advice of SKZ 3586P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Thursday, 19 April 2018 11:51 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; "SUR" <sur@lkkauto.com>
Cc: 'LKK Assignments' <assignments@lkkauto.com>
Subject: RE: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Dear Rachel,

Noted with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Thursday, 19 April, 2018 11:08 AM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; "SUR" <sur@lkkauto.com>
Cc: 'LKK Assignments' <assignments@lkkauto.com>
Subject: RE: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Dear all

Please ignore my email on April 19, 2018 10:58 AM and proceed with survey for TP vehicle : SKZ3586P

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Tan, Rachel
Sent: Thursday, April 19, 2018 10:58 AM
To: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; "SUR" <sur@lkkauto.com>
Cc: 'LKK Assignments' <assignments@lkkauto.com>
Subject: RE: [External] RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Hi
Please hold this survey.
NAC just provided DL. I need to confirm further.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Thursday, April 19, 2018 9:53 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>; "SUR" <sur@lkkauto.com>
Cc: 'LKK Assignments' <assignments@lkkauto.com>
Subject: [External] RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Dear Rachel,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Thursday, 19 April, 2018 9:38 AM
To: Siti Nabilah PTCBC <Siti.Nabilah@inchcape.com.sg>
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: RE: Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Without prejudice

Dear Siti
Based on accident reports, liability is against YM7143K. We will arrange LKK to conduct survey.

Dear LKK
Please accept TP PRI. Attached TP GIA report, and estimates.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Siti Nabilah PTCBC <Siti.Nabilah@inchcape.com.sg>

Sent: Wednesday, April 18, 2018 5:28 PM

To: Ong, Joanna <Joanna.Ong@sg.gaig.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

Cc: Siti Nabilah PTCBC <Siti.Nabilah@inchcape.com.sg>

Subject: [External] Direct Settlement(RS) - Accident Involving SKZ3586P and YM7143K DOA 16/04/2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos, Accident Scene Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured YM7143K thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Raymond Seah @ 9221 3150 / 6631 1865** located at **2 Pandan Crescent – Level 4** for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you very much in advance!

Best Regards,

Nabilah


TPR Team (Claims Accident Recovery Dpt)

DID 6631 1874 | FAX 6872 7260

Inchcape - Borneo Motors (S) Pte Ltd

Office Address: 2 Pandan Crescent, Inchcape Centre Level 4, Singapore 128462

www.borneomotors.com.sg | www.toyotasingapore.com.sg



THE ALL-NEW LEXUS LS
WITHOUT PRECEDENT

LEXUS



This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2018 08:58
Date Of Accident	16/04/2018 17:10
Exact Location Of Accident	INFRONT OF BLOCK R PANDAN LOOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ3586P
Insured/Policyholder	
Name Of Registered Owner	WONG YAN CHUNG
NRIC No	S8814286A
Email Address	CRISTAL1@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-81276176
Alternative Phone No	OFFICE-96172003
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80450584 AT2
Cover Note Number	
Driver	
Name of Driver	WONG TUCK SENG
NRIC No	S1154799J
Date Of Birth	03/06/1956
Occupation	INDOOR
Date Of Driving Pass	18/10/1978
Driving Experience	39 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96172003
Fax Number	(LOCAL) +65-68747011
Contact Number	OFFICE-68747022
EMail Address	CRISTAL1@SINGNET.COM.SG

Address	29 PAVILION ST
Postcode	548709
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM7143K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	GREAT AMERICAN INSURANCE COMPANY
Nature Of Damage	
No. Of Passenger (Including Driver)	

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DSMCA: Raymond

MOTOR ACCIDENT REPORT

Date Of Report: 17 APR 2018 Time: 11.00 Date Of Accident: 16 APR 2018 Time: 1710Exact Location Of Accident: In Front of BLOCK R PANDAN LOOPCountry/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SKZ 3586P Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 58814286-A
Name Of Registered Owner: WONG VAN CHUNG
Mobile Number: 81276176 Alternative No: 96172003 Email Address: cristal1@singnet.com.sg

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: WISH
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒ DS
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: MSIG
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: A8045 0584 AT2

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: WONG TUCK SENG NRIC/ Passport / FIN No: 51154794J
Date Of Birth: 03 JUNE 1956 Occupation: Indoor ☒ Outdoor ☐
Date Of Driving Pass: 30 SEPT 2003 18.10.1978 Gender: Male ☒ Female ☐
Mobile Number: 96172003 Fax No: 68747011 Alternative No: 68747022 (off)
Address: 29 PAVILION STREET Postal Code: 548709
Email Address: cristal1@singnet.com.sg
Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: FATHER
Vehicle Registration Number of Driver's Own Vehicle (if applicable): -
Insurance Company of Driver's Own Vehicle (if applicable): -

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: TP AT7 MIXED
Number of Passengers in the above vehicle (Including Driver): 1 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Gender: Male ☐ Female ☐
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
Was any body injured in the Accident? No ☒ Yes ☐
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
Number of vehicles involved in the accident: 2
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
Witness Name: Contact No.: Email:
Was there any other vehicle or property damaged? No ☒ Yes ☐
Was there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☒
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: YM 7143 K Vehicle Make/Model/Colour: MIT T250 LORRY
Details Of Properties Damage in Accident:
Vehicle Category:
Name of Driver:
NRIC/Passport/FIN Number: Contact Number:
Address: Postal Code:
Insurance Company Name:
Nature Of Damage: No. Of Passenger (Including Driver):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was driving out of the JTC Industrial estate. BLKR PANDAN LOOP is ~~in front~~ on my right hand side.

The road is a one way street.

As I approached the car park gantry, I felt my left hand side of the car shook after passing a Lorry (YM 7143K) driven by a person name

VEE RAIYAN MATHU KUMAR, drivers license no G 5492954X.

The time it happened was 5.10pm on 16th Apr 2018.

~~I got down the~~

I stopped the car immediately after sensing the impact and got out of the car to check what happened.


I discovered my left side rear car door dented badly and some scratches on the left car body.


The lorry driver had ~~is~~ swerved suddenly upon starting his lorry without looking out for oncoming vehicle. He collided into my left side of the car.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

 17th APR 2018
Driver's Signature (If driver is not the policyholder) / Date & Time
5.15pm


Witnessed by Reporting Centre Personnel

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1154799J





Name
WONG TUCK SENG
黄德成
Race
CHINESE
Date of Birth
03-06-1956
Sex
M
Country of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S1154799J
Name
WONG TUCK SENG
Birth Date 03 Jun 1956
Issue Date 30 Sep 2003

2775578



LIC No. S1154799J



Block Group Date of issue
B 11-01 1996
E 277121
MCM




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	18 Oct 1978

NP 428A

Licence No. S1154799J



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8814286A



Name

WONG YAN CHUNG
(HUANG YANCONG)

黄彦聰

Race

CHINESE

Date of birth

27-04-1988

Sex

M

S8814286A

Country of birth

SINGAPORE

29 PAVILION STREET
SINGAPORE 658709


Address



28-02-2008

Date of issue



S8814286A





**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

Toyota DriveElite 360
Comprehensive

Certificate No. A 80450584 AT2

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SK23586P

2. Name of Policyholder
Wong Yan Chung

3. Effective Date of the Commencement of Insurance for the purposes of the Act
20/01/2018

4. Date of Expiry of Insurance
19/01/2019

5. Persons or Classes of Persons entitled to drive*

Wong Yan Chung

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT BORNEO MOTORS (S) PTE LTD OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

AUTHORIZATION LETTER

Date : 16.4.2017

To : MSIG
Cc : Borneo Motors (S) Pte Ltd
Attn: To Whom It May Concern

Dear Sir / Madam,

RE : Authorization to Act on Behalf for Insurance Claims Documentation


I, (full name) WONG YAN CHUNG NRIC No. S8814286-A hereby
authorized my (relationship) FATHER (full name) WONG TUCK SEN,
NRIC No. S1154799-J to exercise and execute to sign all / any necessary transaction
documentation pertaining to my registration vehicle number SKZ 3586P as I am
currently having tight official business schedules / away from Singapore on duty overseas travel.

Please do not hesitate to contact me should you require any further clarification on the above.

Thank You

Yours truly,

Signature : _____
Name : WONG YAN CHUNG
Contact No: 81276176





Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

TP/DS

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM <i>Liability Check</i>	S1000020 / TPCLAIM	Mr Wong Yan Chung 29 Pavilion Street Singapore 658709 Mobile: 81276176
	Document No	
	Document Date	
	0	
	17/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	20/01/2016	SKZ3586P	0	30479	9DS/SKZ3586P-16041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W30J003575	22R1707679	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES-TP/DS CLAIM TP VEH:YM7143K ACC DATE:16/04/2018 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORIZED ON:				new ✓ 30.00
2	B	BP-ECU TO RESET ECU AND REPROGRAMME				✓ 508.50
3	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR LH DOOR				✓ 60.00
4	B	BP-LAB TO CHECK WIRING & LIGHTING. TO WATER TEST FOR LEAK.				✓ 115.26
5	B	BP-LAB TO TRANSFER REAR LH DOOR GLASS, BOARD, MECHANISM & OTHER ATTACHMENT TO NEW PANEL. 67%				✓ 339.00
6	B	BP-LAB TO REPLACE REAR LH DOOR AND OTHER AFFECTED AREAS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS				1356 3390.00
7	B	BP-RES TO SPRAY PAINT ON REAR LH SIDE ACCIDENT AFFECTED AREAS.				1668 2780.00
8	1	T67004-68050 L/REAR DOOR PANEL,	1.00	1482.50		bt ✓ 1482.50
9	2	T67872-68020 L/REAR DOOR W/STRIP,	1.00	175.00		W X 175.00 (17)
10	3	T68640-68011 CHECK ASSY, RR DOOR,	1.00	184.80		W X 184.80 (17)
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3622470

TO SECURITY GUARD

3622470

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2018
TIME 17:53

VEHICLE NO SKZ3586P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Wong Yan Chung 29 Pavilion Street Singapore 658709 Mobile: 81276176	
		Document No		
		Document Date		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	ZGE2OR	20/01/2016	SKZ3586P	0	30479 :9DS/SKZ3586P-16041:
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W30J003575		2ZR1707679	60	Raymond Seah L M	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
11	4	T75926-68010	L/R BLACK TAPE NO 3,	1.00	42.20		42.20
12	5	T68760-35042	HINGE ASSY, RR DOOR	1.00	83.30		83.30
13	6	T68780-52031	L/RR DOOR LOW HINGE,	1.00	73.30		73.30
14	7	TSUNCY-MOULD	SIDE MOULDING	1.00	211.50		211.50
15	8	T76902-68050	MUDGUARD SUB-ASSY	1.00	1109.50		1109.50
16	9	T75792-47010	CLIP, FR DOOR WINDOW	2.00	1.80		3.60
17	0	T75392-68030	RETAINER, OUTSIDE	2.00	1.70		3.40

Tanjiu 97495149
wp
20/4/18 @ 1640
5 days
Resuming before part
Sent @ 16400.com

LEK Auto Consultants hereby notify the Repairer of the following:

- To reserve color and spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a written report basis
- No illegal modification is allowed
- Supplementary item(s) must be requested and is subject to final approval

Acknowledged by Repairer
Signature:
Date:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	10,591.86
	Please acknowledge receipt of vehicle	Parts	3,369.10	GST 7.00% 741.43
		Labour	7,222.76	
		Materials	0.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			Less	0.00
			Amount Due	11,333.29

PLEASE TEAR ALONG PERFORATED LINE

3622471

3622471

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2018
TIME 17:53

VEHICLE NO SKZ3586P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No: MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462

Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail		Account No	Mr Wong Yan Chung 29 Pavilion Street Singapore 658709 Mobile: 81276176
Great American Insurance Company 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190		S1000027/ICGAIC	
		Document No 0	
		Document Date 16/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPKXP	S6	ZGE20R	20/01/2016	SKZ3586P	54614	30479 :9DS/SKZ3586P-16041
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W30J003575 2ZR1707679 60 Raymond Seah L M 14/05/2018 10.00 16/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES-TP/DS CLAIM TP VEH:YM7143K ACC DATE:16/04/201 8TP INS:GREAT AMERICAN NO OF REPAIR DAYS:05 DATE-IN:14/05/2018 DATE SURVEY:20/04/201 8BY:LKK-TAUFLIK AUTHORIZED ON:23/04/2018				30.00
2	B	BP-ECU TO RESET ECU AND REPROGRAMME				508.50
3	Z	BP-SLANT SUPPLY SEALANT (NETT)				60.00
4	B	FOR REAR LH DOOR TO CHECK WIRING & LIGHTING.	23			115.26
5	B	BP-LAB TO WATER TEST FOR LEAK.	23			339.00
6	B	BP-LAB TO TRANSFER REAR LH DOOR GLASS, BOARD, MECHANISM & OTHER ATTACHMENT TO NEW PANEL.	23			1356.00
7	B	BP-LAB TO REPLACE REAR LH DOOR AND OTHER AFFECTED AREAS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS	*			1668.00
8	1	BP-RES TO SPRAY PAINT ON REAR LH SIDE ACCIDENT AFFECTED AREAS.	1.00	1109.50		1109.50
9	2	T76902-68050 B0 MUDGUARD SUB-ASSY T67004-68050 PANEL ASSY RR DR LH	1.00	1482.50		1482.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

366838

PLEASE TEAR ALONG PERFORATED LINE

366838

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/05/2018
TIME 13:10

VEHICLE NO

SKZ3586P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
Great American Insurance Company 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190	S1000027 / ICGAIC	Mr Wong Yan Chung 29 Pavilion Street Singapore 658709 Mobile: 81276176
	Document No	
	Document Date	
	0	
	16/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S6	ZGE20R	20/01/2016	SKZ3586P	54614	30479 :9DS/SKZ3586P-16041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W30J003575 2ZR1707679 60 Raymond Seah L M 14/05/2018 10.00 16/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	3	T75926-68010 TAPE BLACK OUT	1.00	42.20		42.20
11	4	T75792-47010 CLIP, FR DOOR WINDOW	2.00	1.80		3.60
12	5	T75392-68030 RETAINER, OUTSIDE	2.00	1.70		3.40
13	6	TSUNCY-MOULD SIDE MOULDING	1.00	211.50		211.50
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	6,929.46
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	485.06
		Labour	2,852.70	
		Materials	4,076.76	
		Lubrication/Fluid	0.00	
		Others	0.00	
			Less	0.00
			Amount Due	7,414.52

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SKZ3586P

CUSTOMER

DATE 16/05/2018
TIME 13:10

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Vehicle Diagnostic Report

2ZRFAE

SKZ3586P

TOYOTA BODY CARE

Printed By: Default User(1)

17/05/2018 8:51:15 AM

Health Check Results All Systems(1 of 1)

Enhanced

Engine and ECT	Yes	P1604	X		X			36824200	
								A0C01000	
Main Body	No	B2324			X			660C1SCV**02	
Entry&Start	No	U0100			X			-	
	No	U0142			X				
	No	U0155			X				
ABS/SC/TRC								F152668071	
EMPS								JCF305F0	
Air Conditioner								838006827102	
Combination Meter								-	
D-Door Motor								-	
P-Door Motor								-	
RR-Door Motor								-	
RL-Door Motor								-	
Master Switch								-	
HL AutoLeveling								8917F68010	
SRS Airbag								-	
PM2 Gateway								-	
Starting Control								-	
Power Source Control								-	

Vehicle Diagnostic Report

2ZRFAE

SKZ3586P

TOYOTA BODY CARE

Printed By: Default User(1)

17/05/2018 8:52:15 AM

Health Check Results All Systems(1 of 1)

Enhanced

										36824200
										A0C01000
Engine and ECT										F152668071
										JCF305F0
ABS/VSC/TRC										-
EMPS										-
Air Conditioner										838006827102
Combination Meter										660C1SCV**02
Main Body										-
D-Door Motor										-
Entry&Start										-
P-Door Motor										-
RR-Door Motor										-
RL-Door Motor										-
Master Switch										-
HL AutoLeveling										8917F68010
SRS Airbag										-
PM2 Gateway										-
Starting Control										-
Power Source Control										-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18007268/T1qbn2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 28-05-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 7143K	Veh. Inspected	SKZ 3586P
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003172	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	19/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDGG20W30J003575	Colour	WHITE
Odometer	61152	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/04/2018	Inspection Date	20/04/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

Remarks

- 5a. A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Estimate Days of Repair

5b. ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
---	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3586P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	L/REAR DOOR PANEL (SN)	BENT	1,482.50	1,482.50
1	L/REAR DOOR W/STRIP (SN)	NOT NECESSARY	175.00	-
1	CHECK ASSY,RR DOOR (SN)	NOT NECESSARY	184.80	-
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	L/R BLACK TAPE NO 3 (SN)	NECESSARY	42.20	42.20
1	HINGE ASSY,RR DOOR (SN)	NOT NECESSARY	83.30	-
1	L/RR DOOR LOW HINGE (SN)	NOT NECESSARY	73.30	-
1	SIDE MOULDING (SN)	CUT	211.50	211.50
1	MUDGUARD SUB-ASSY (SN)	CUT	1,109.50	1,109.50
2	CLIP,FR DOOR WINDOW (SN)	NECESSARY	3.60	3.60
2	RETAINER,OUTSIDE (SN)	NECESSARY	3.40	3.40
			3,399.10	2,882.70
LABOUR				
	TO RESET ECU AND REPROGRAMME.		508.50	508.50
	SUPPLY SEALANT FOR REAR LH DOOR.		60.00	60.00
	TO CHECK WIRING & LIGHTING,TO WATER TEST FOR LEAK.		115.26	115.26
	TO TRANSFER REAR LH DOOR GLASS,BOARD,MECHANISM & OTHER ATTACHMENT TO NEW PANEL.		339.00	339.00
	TO REPLACE REAR LH DOOR AND OTHER AFFECTED AREAS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.		3,390.00	1,356.00
	TO SPRAY PAINT ON REAR LH SIDE ACCIDENT AFFECTED AREAS.		2,780.00	1,668.00
			7,192.76	4,046.76
			10,591.86	6,929.46
GRAND TOTAL				
RECOMMENDED COST OF REPAIRS				6,929.46

Report Ref No. CS/GAI18007268/T1qbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.