15/5/2010

INS. CASE OWNER: CC 3, LCR1800 7279, K1ja3

LKK:

IDAC:

ASSIGNMENT

Surveyor: Ank

DOI: 18/4/18

Date / Time : 18/4/18

Registered in Merimen: 19/4/18

Pre-assign / CCU / FTE SLF 6426S



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S$

D.O.A : 18/4/18

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If **NO**, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SHD 3025T → ____ → ____ → ____



INSRS:
WSP:
Tel : CD4B 10days.
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	
	SHD3025T - CC3/1651701260/412y397 : [illegible] 8/6/17
	SLF 6426S - X

STAGE	**DATE / PIC**
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	

Documentation Check List:	**Handler**	**Typist**
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☐	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$ (days)	Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	% (Agreed / Assessed)	BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S$		
Loss of Rental (LOR):	S$ (days)		
Loss of Use (LOU):	S$ ($ x days)		
Loss of Income (LOI):	S$ ($ x days)		
LOR only ☐	LOU only ☐ LOR + LOU ☐	LOR + LOI ☐ [Tick only one]	
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$		3) Survey fee:
Total:	**S$**	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 3025T Yr Regn: 3 Mc / 315

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai Z40 c.c 1685

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 373183 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB41AAG408978

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 265/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	18/4/18	D.O.I.	18/4/18

Survey held at CDGE (Loyang)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AZA PIP

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

Survey Fee:	
Transportation:	
___S+RS,___SI	
Photos	
Others	

OMFORTDELGRO ENGINEERING
member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
6 Defu Avenue 1 Singapore 539537

Date/Time: 18.04.2018 15:17 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: JC NO.305143412

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

REGN NO.: SHD3025T	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN 18.04.2018 12:30
YR OF MANU.: 03.12.2015	TARGET DATE
CHASSIS CODE: KMHLB41UMGU080978	COMPLETION DATE/TIME:

JOB DESCRIPTION

:cident Date: 18.04.2018
ATURE: 3P 18.04.18

'NO LABOR CODE DESCRIPTION

CKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

No.: SHD3025T JU AIG LKK

f Service Advisor

Signature/Date

turned to Service Reception upon collection

Exit Pass

Vehicle No.: SHD3025T

Name of Service Advisor

Date

To be kept by Security Guard