

05/11/13  
Sme Mr: Kevin

REF:

NS/INC18007334/Klvbnz

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate ☒ Cost

OD/TP /NS/TP RES / OD RES / EVA / INV / MV

To Insp ☒ Vehicle No: \_\_\_\_\_

at Work ☒ Shop No: \_\_\_\_\_

of \_\_\_\_\_

Insured: GBC 7133B

Policy No: 5067086038-03 140817-130818

Claims No: MT/0990969-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No:

SHC 2905 R

Yr Regt:

6 Oct 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C. 1798

Colour

Blue

A/C: ☒ Insured / Std / NI / NA

Sp. Reading

116971

T/Radio: ☒ Insured / Std / NI / NA

Eng/No:

C/No:

JTDKBJK400356936

Gen. Cond: Good / ☒ / Poor / Burnt

Steering: Inorder / ☒ / Jammed / Leaked / Burnt or

Brake: Inorder / ☒ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wetake

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

18/4/8

D.O.I.

19/4/8

Survey held at

(DGE (Loyang))

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	DA: 05112009	INC
	SHC 2905 R - CC3/A7609025258/Cwjh	DA: 03022018	PIP
25/4/8	GBC 7133 B - NA/INC18007334/Idi		
	Control PIP \$9266.12 / 4thp. (Red 3021.43, 25th)		

RECEIVED 26 APR 2010

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

26/4 - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Other (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other

160

35

195

TP

PIP \$9266.12




# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007334/K1vb			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 20-04-2018	
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBC 7253B	Veh. Inspected	SHC 2905R
Policy No.	5067086038-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	18/04/2018	Inspection Date	19/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0991115-002	Comfort Transportation	SHD 7101E	SIG 8197H	18/4/2018
2	MT/0989824-003	SMRT BUSES LTD	TIB 1129P	SLX 5295P	8/4/2018
3	MT/0990969-002	Comfort Transportation	SHC 2905R	GBC 7253B	18/4/2018

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5067086038-03	YONG FAH INTERNATIONAL PTE. LTD.	200306333C	GCV	Comprehensive	GBC7253B	GBC7253B	14/08/2017	13/08/2018

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/04/2018 08:46
Date Of Accident	18/04/2018 14:55
Exact Location Of Accident	AYE TWDS TUAS (BEFORE EXIT 9)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2905R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN CHIN KIANG
NRIC No	S1445088B
Date Of Birth	06/08/1960
Occupation	OUTDOOR
Date Of Driving Pass	05/06/1978
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 228 LORONG 8 TOA PAYOH  
#16-148  
Postcode 310228  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
Vehicle Registration Number of Driver's Own Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 3  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1 NAME: : -  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: -  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC7253B  
Vehicle Make/Model/Colour TOYOTA  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver PAUL LAM FUI PHONG  
NRIC/Passport Number S1247897F  
Contact Number 97573663  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage FRONT AND REAR

No. Of Passenger (Including Driver)

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKJ5688A
Vehicle Make/Model/Colour	VOLKSWAGEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

# **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SIAMIC SketchPlanForm\_V0





SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/4/2019 at about 1455 hrs, I vehicle A was driving along AVE toward Thas on the extremely right lane. As a vehicle in front of me applied brake and stop, I also do the same. A few second later I felt two impact on my back, when I got out of my taxi, I saw two vehicles pile up together. No one was injured at that times.

DECLARATION





I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIARMC SketchPlanForm\_V3



Date/Time: 19.04.2018 09:13

Page : 1

am: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order:

JC NO: 305143562

OMER  
IS COMFORT TRANSPORTATION PTE LTD  
OMER NO 7010045  
IESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)

REGN NO SHC2905R	MILEAGE
MAKE TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)18.04.2018 16:15	DATE/TIME IN
YR OF MANU 06.10.2017	TARGET DATE
CHASSIS CODE JTDKB3FU003569136	COMPLETION DATE/TIME:

DUNT CARD NO.

### JOB DESCRIPTION

Incident Date: 18.04.2018  
ATURE: 3P 18.04.18

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHC2905R

JU NTUC LKK

Vehicle No.:

SHC2905R

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE

VEHICLE NO : SHC 2905R

DATE : 18.04.2018

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER — Bent			\$ 922.50
REAR TRUNK LID LOCK — Bent			\$ 447.70
REAR TRUNK LID COVER TRIM BOARD Xsu			\$ 216.50
REAR TRUNK LID RUBBER Xsu			\$ 357.00
REAR TRUNK LID GLASS (BLACK COLOR) — shatter			\$ 721.30
BOARD ASSY, BACK DOOR TRIM Xsu			\$ 246.90
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE — ca			\$ 889.70
REAR TRUNK LID LOGO (PRIUS) — ne			\$ 60.80
REAR TRUNK LID LOGO (HYBRID) — ne			\$ 52.40
REAR TRUNK LID LOGO (TOYOTA STAR) — ne			\$ 45.90
REAR BUMPER — Bent			\$ 458.60
REAR BUMPER RE-INFORCEMENT — Bent			\$ 318.80
REAR BUMPER UNDER COVER — ca			\$ 552.60
REAR BUMPER SIDE RETAINER Xsu			\$ 112.70
REAR BUMPER SPONGE X 11			\$ 143.40
REAR BUMPER UNDER SIDE COVER (LH) Xsu			\$ 232.00
REAR BUMPER UNDER SIDE CENTRE COVER Xsu			\$ 552.60
REAR BUMPER CLIPS — ne			\$ 22.00
RETAINER, REAR BUMPER, SIDE, RH Xsu			\$ 94.80
SEAL, REAR BUMPER SIDE, RH Xsu			\$ 148.40
TAIL LAMP ASSY (UPPER) (RH) — ca			\$ 557.90
TAIL LAMP ASSY (LOWER) (RH) — ca			\$ 548.40
REAR END PANEL — Bent			\$ 602.10
REAR END PANEL GARNISH Xsu			\$ 121.60
REAR FENDER, RH X repair			\$ 817.50
REAR FENDER SHEILD (RH) X su			\$ 134.20
REAR WINDSCREEN GLASS — ne			\$ 1,555.80
REAR WINDSCREEN GLASS MOULDING — ne			\$ 280.60
SUB TOTAL			\$ 11,149.70
LESS 25%			\$ 2,787.43
DISCOUNTED TOTAL			\$ 8,362.28
REAR BUMPER REVERSE SENSOR — shatter	-10%		\$ 135.70
REAR WINDSCREEN SEALANT — ne	-10%		\$ 46.00
Rear Boot control sticker — ne	-10%		\$ 60.00
Rear Number plate — Bent		\$ 25	\$ 181.70
Rear Boot App sticker — ne	-10%	\$ 40	

NETT 126.13

NETT 41.40

54

36

Ka<sub>2</sub>CO<sub>3</sub> (K<sub>2</sub>CO<sub>3</sub>)  
✓ 19/4/18 10.45h  
4 days  
PIP  
Before Part p4.

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Page 2 of 2

VEHICLE NO. : SHC2905R  
JOB CARD NO. 305143562  
ACC.DATE 18/04/2018

TYPE OF CASE : NTUC

SURVEY BY : LKK-KALVIN

DATE : \_\_\_\_\_

[illegible]



## COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.04.2018

Time: 18:35:19

## REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS: COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305143562  
 REGN NO : SHC2905R  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 06.10.2017  
 DATE/TIME IN : 18.04.2018 16:15  
 ACCIDENT DATE : 18.04.2018

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0002	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0003	04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10
0004	28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1 N	30.00	10.00	27.00
0005	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1 N	30.00	10.00	27.00
0006	28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1 N	40.00	10.00	36.00
0007	04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50
0008	04-01-0302-2297-G	PRIG4 EMBLEM PANEL (PRIU	1	60.80	25.00	45.60
0009	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	45.90	25.00	34.42 /
0010	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.40	25.00	39.30
0011	04-01-0302-0795-G	PRIG4 LENS AND BODY REAR	1	548.40	25.00	411.30
0012	04-01-0302-0585-G	PRIG4 LENS & BODY RR COMB	1	557.90	25.00	418.42
0013	04-01-0302-2383-G	PRIG4 PANEL SUBASSY BODY	1	602.10	25.00	451.57

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 23.04.2018  
Time: 18:35:19  
Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305143562  
REGN NO : SHC2905R  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 06.10.2017  
DATE/TIME IN : 18.04.2018 16:15  
ACCIDENT DATE : 18.04.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 04-01-0302-2257-G PRIG4 GLASS BACK WINDOW F	1		721.30	25.00	540.97
0015 04-01-0302-2258-G PRIG4 GLASS BACK DOOR	1		1,555.80	25.00	1,166.85
0016 04-01-0302-2256-G PRIG4 PANEL SUB-ASSY BACK	1		922.50	25.00	691.87
0017 09-01-0302-2005-A PRIG4 REVERSE SENSOR ASSY	1	N	135.70	10.00	122.13
0018 05-01-0199-0032-A (ALL)WINDSCREEN AHESIVE-3	2	N	46.00	10.00	41.40
0019 04-01-0302-2346-G PRIG4 GARNISH SUB ASSY BA	1		889.70	25.00	667.27
0020 04-01-0302-2380-G PRIG4 LOCK ASSY BACK DOOR	1		447.79	25.00	335.84
0021 04-01-0302-0960-G PRIG4 MOULDING SUB-ASSY R	1		280.60	25.00	210.45
0022 04-01-0302-2403-G PRIG4 SPOILER SUBASSY	1		866.40	25.00	649.80
0023 04-01-0302-2286-G PRIG4 COVER REAR BUMPER-T	1		82.70	25.00	62.02
0024 04-01-0302-3941-G PRIG4 GARNISH SUB-ASSY LH	1		72.00	25.00	54.00
0025 04-01-0302-3839-G PRIG4 HINGE ASSY BACK DOO	2		94.10	25.00	70.57



## COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.04.2018

Time: 18:35:19

Page: 3

## REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS: COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305143562  
 REGN NO : SHC2905R  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(C  
 DATE OF REGN : 06.10.2017  
 DATE/TIME IN : 18.04.2018 16:15  
 ACCIDENT DATE : 18.04.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0026 09-01-0302-2135-G PRIG4 LAMP SET STOP CENTE	1		136.00	25.00	102.00
0027 FNPS NO PLATE(S) 1 N			25.00	2.50-	25.00
0028 04-01-0302-0796-G PRIG4 LENS AND BODY REAR	1		548.40	25.00	411.30
SUB-TOTAL :					7,656.08

## JOB NATURE

0000 L	PANEL BEATING- REAR	600.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	800.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0004 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	50.00
0005 L	LUBRICATE LOCK HINGES & HOOR LATCH	100.00

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 23.04.2018  
Time: 18:35:19  
Page: 4

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305143562  
REGN NO : SHC2905R  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 06.10.2017  
DATE/TIME IN : 18.04.2018 16:15  
ACCIDENT DATE : 18.04.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0006 L	LUBRICATE LOCK HINGES & HOOH LATCH			20.00		
						SUB-TOTAL : 1,610.00
						TOTAL : 9,266.08

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

Our Job Ref No : 305143562  
Date : 24/04/2018

## FINALIZATION FORM

To : LKK  
Attn : KALVIN  
Vehicle Reg No. : SHC2905R

Fax :

Date of Accident : 18/04/2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- GBC7253P  
###
- The finalized amount shall be:
 


(a) Spare Parts after List discount		\$7,656.12
(b) Labour Charges	###	\$1,610.00
<b>Total for Part-By-Part Repair Cost</b>		<b>\$9,266.12</b>
(c) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: 20%		
<b>Final Lumpsum Repair cost</b>		


3. Estimated normal period for repairs: 4 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : KALVIN  
Date : 25/4/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



Thatcham escribe

## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007334/K1vbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Date: 04-05-2018



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 7253B	Veh. Inspected	SHC 2905R
Policy No.	5067086038-03	Coverage (\$)	0.00
Claim No.	MT/0990969-002	Excess (\$)	0.00
Assign From		Assign Date	19/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003569136	Colour	BLUE
Odometer	116971	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	18/04/2018	Inspection Date	19/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2905R**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR TRUNK LID COVER	BENT	922.50	922.50
1	REAR TRUNK LID LOCK	JAMMED	447.79	447.79
1	REAR TRUNK LID COVER TRIM BOARD	SERVICEABLE	216.50	-
1	REAR TRUNK LID RUBBER	SERVICEABLE	357.00	-
1	REAR TRUNK LID GLASS (BLACK COLOR)	SHATTERED	721.30	721.30
1	BOARD ASSY, BACK DOOR TRIM	SERVICEABLE	246.90	-
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	CRACKED	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	45.90	45.90
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	CRACKED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER SPONGE	NOT NECESSARY	143.40	-
1	REAR BUMPER UNDER SIDE COVER (LH)	SERVICEABLE	232.00	-
1	REAR BUMPER UNDER SIDE CENTRE COVER	SERVICEABLE	552.60	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	RETAINER, REAR BUMPER, SIDE, RH	SERVICEABLE	94.80	-
1	SEAL, REAR BUMPER SIDE, RH	SERVICEABLE	148.40	-
1	TAIL LAMP ASSY (UPPER)(RH)	CRACKED	557.90	557.90
1	TAIL LAMP ASSY (LOWER)(RH)	CRACKED	548.40	548.40
1	REAR END PANEL	DENTED	602.10	602.10
1	REAR END PANEL GARNISH	SERVICEABLE	121.60	-
1	REAR FENDER, RH	TO REPAIR	817.50	-
1	REAR FENDER SHIELD (RH)	SERVICEABLE	134.20	-
1	REAR WINDSCREEN GLASS	NECESSARY	1,555.80	1,555.80
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	280.60	280.60
1	SPOILER SUBASSY	CRACKED	866.40	866.40
1	REAR BUMPER TOWING COVER	CUT	82.70	82.70

Report Ref No. NS/INC18007334/K1vbn2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GARNISH SUB-ASSY LH	MISSING	72.00	72.00
1	BOOTLID HINGE	BENT	94.10	94.10
1	THIRD BRAKE LAMP	CRACKED	136.00	136.00
1	TAILLAMP LH LOWER	CRACKED	548.40	548.40
	LESS 25% DISCOUNT		-3,253.60	-2,459.20
			9,760.79	7,377.59
	<b>NETT ITEMS</b>			
1	REAR BUMPER REVERSE SENSOR (N)	SHORTED	135.70	135.70
1	REAR WINDSCREEN SEALANT (N)	NECESSARY	46.00	46.00
1	REAR BOOT COMFORT STICKER (N)	NECESSARY	60.00	60.00
1	REAR BOOT APP STICKER (N)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-	-28.17
			281.70	253.53
	<b>SPECIAL NETT ITEMS</b>			
1	REAR NUMBER PLATE (SN)	DENTED	25.00	25.00
			25.00	25.00
	<b>LABOUR</b>			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,440.00	790.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,050.00	820.00
			2,490.00	1,610.00
	<b>GRAND TOTAL</b>		<b>12,557.49</b>	<b>9,266.12</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>9,266.12</b>

Report Ref No. NS/INC18007334/K1vbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.