

22/03/2007

A.S. R.C. BY:

REG:

CS/TML18007356/Nrbez

Special Instruction:

Surveyor

Naz

ASSIGNMENT (Office)

mekmen

From (Person):

Tona Gun

of

TML

Date/Time:

20042018 1039am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7134B

Insured:

ABC 2609S

at Workshop m/s

Comfort Delgro

Tel:

of

B1 Laundry Drive

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19042018

CA / REV / REP. / REV 24 HRS (w/p)

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 7134B - CS / ALH 1800433 / Kinas
	ABC 2609S - X


RA: 010318

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record): \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 71343 Page: 24 MAR 2016  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI 140  
 Colour: BLUE 10 Insured / Std / NI / NA  
 Sp. Reading: 251,841 10 Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C-No: KMHLB41UMGUOS6622

Gen. Cond: Good (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / (STD) / Rim or

Tyre Size: F: 205 60 R16 (275)

R: 205 60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 3 Tyres WESTLAKE RIGHT REAR HAN KOO

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>19/4/18</u>	D.O.I. <u>20/4/18</u>

Survey held at: CDGE LOYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

T/MAEWE P/P

25/4/18 FINALIZED PART / PART \$1,142.88 / 2 DAYS  
Red: 81289.50, 55%

RECEIVED 04 MAY 2018

Date/Time File Pass to: ☐ : Preli. Report

by 1st ☒ : Final Report

Date/Time File Return to:

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

Transporter

\_\_\_\_\_ \$ - RS \_\_\_\_\_

Phone

\_\_\_\_\_

Add Fee: ☐ : Site Insp \$

☐ : Interview \$

☐ : Tech. Insp \$

☐ : Mobile \$

Report Format: 7P

Lump Sum / L.B. / S: 1142.88

250

10

260

## ...CLAIM SUBFOLDER...(New Assignment)

Pre-Repair Survey

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Apr 2018 18:30 Sendback Est	19 Apr 2018 18:34 S\$2,432.38	20 Apr 2018 10:39 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA7134B	Date of Loss:	19/04/2018 10:00 - :59 [24 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	GBC2609S	Policy No. (Claimant):	MCOM0015
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/05/2018]		
Adj Asg. Remarks:	OU INSURED HAVE NOT REPORT THE ACCIDENT. PLS. CHECK CONSISTENCY OF THE DAMAGE.		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

member of COMFORTDELGRO

Date/Time: 19.04.2018 15:01 Page : 1

m: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 3818929 JC NO305143719

MER  COMFORT TRANSPORTATION PTE LTD 7010045 MER NO SS 383 SIN MING DRIVE Singapore SINGAPORE 575717 R) 65508755 (O) P)  JNT CARD NO.	REGN NO SHA7134B	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 19.04.2018 11:35
	YR OF MANU 24.03.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU086622	COMPLETION DATE/TIME:

JOB DESCRIPTION

cident Date: 19.04.2018  
TURE: 3P 19.04.18/B

NO LABOR CODE DESCRIPTION

LED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

edgement Slip  lo.: SHA7134B FZ TOKIO	Exit Pass
	Vehicle No.: SHA7134B
Service Advisor	Signature/Date
turned to Service Reception upon collection	To be kept by Security Guard

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/04/2018 13:52
Date Of Accident	19/04/2018 10:00
Exact Location Of Accident	CLEMENTI AVE 2 TWDS WEST COAST ST 2 SLIP RD AYE C
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7134B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	140
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN BOON THIAM
NRIC No	S1721154D
Date Of Birth	18/08/1965
Occupation	OUTDOOR
Date Of Driving Pass	16/05/1985
Driving Experience	32 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 795 YISHUN RING ROAD #12-3402
Postcode	760795
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2609S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO REG. NO. 199303821R

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON. 19 April 2018 @ 1000hr. I VEH

A was driving along Clementi Ave 2  
towards Ship Rd of Ave to cte.

I veh A slow down and stop at Ship  
Rd gave way sign. Suddenly veh B from  
Rear hit veh A Rear. at the point  
of accident I veh A ferry a male  
passenger he near cte.

## DECLARATION




I/We declare the foregoing particulars are true in every respect.






COMFORT TRANSPORTATION PTE LTD  
CO REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**T/MARINE**  
**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)  
 59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

Fauzy

F<sub>2</sub>

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**COMFORT TRANSPORTATION PTE LTD**

Singapore

**Claimant Insurer:** India International Insurance Pte Ltd

PARTICULARS OF CLAIM			
----------------------	--	--	--

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/04/2018
Vehicle Reg. No.:	SHA7134B	Driveable?	NO
Party At Fault:	UNKNOWN		
Driver (TP):	TAN BOON THIAM		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	24/03/2016
Vehicle Colour:	BLUE	Gen Condition:	FAIR
Engine No:	D4FDFU605345	Chassis No:	KMHLB41UMGU086622
Odometer:	200000 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLS REFER TO ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,672.38
Miscellaneous Items	10.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>2,432.38</b>
<b>+ GST 7.00% (\$\$)</b>	<b>170.27</b>
<b>Nett Amount (\$\$)</b>	<b>2,602.65</b>

This claim is handled by: FAUZY BIN MOKHTAR

Generated using Merimen e-Claims Internet Estimation & Adjusting System

T/Marine LKK P/P

Fauzy

F2

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2018)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA7134B/19/04/2018 18:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

PorVae

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*603.60 FL ✓ crack
2	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*504.35 FL ✓ Svc
3	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	*180.00 FL ✓ Svc
4	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	*180.00 FL ✓ Svc
5	10		*REAR BUMPER REINFORCEMENT CLIPS	20.00	0.00	*22.00 FL ✓ Svc
6	1		*REAR BUMPER SPONGE	20.00	0.00	*143.40 FL ✓ Svc
7	1		*REAR BUMPER UNDER COVER	20.00	0.00	*225.00 FL ✓ dent
8	1		*REVERSE SENSOR	0	0.00	*135.70 FS X S/N 109516
9	1		*REAR BUMPER ADVERTISEMENT LOGO	0	0.00	*50.00 FS ✓ ncl

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,044.05
- List Item Discount on L Items (\$)	ncl 371.67
Total Parts (\$)	1,672.38

ComfortDelGro Engineering Pte Ltd/SHA7134B/19/04/2018 18:34. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

1858 35

2 day P/P  
T=(21/4) NA2

**T/MARKING**

## Estimates on Miscellaneous Items

Fauzy

Amount

Miscellaneous Items

No	Qty	Particulars	Amount
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Labour Items

1	PANEL BEAT	New	<del>200.00</del> 200
2	SPRAY PAINTING CHARGE	New	<del>300.00</del> 200
3	WIRING CHARGE	New	<del>30.00</del> X 11
4	REMOVE/REFIX REVERSE SENSOR	New	✓ 20 120.00 <del>200</del>

Gross Labour Cost (\$\$)	750.00
--------------------------	--------

ComfortDelGro Engineering Pte Ltd/SHA7134B/19/04/2018 18:34. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

NA2

LKK 20/4/17 1200

LTS PIP

2 days.

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305143719  
Date : 23.04.2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK  
Attn : NAZ

Fax :

Vehicle Reg No. : SHA7134B Date of Accident : 19.04.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- GBC2609S
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$662.88
  - (b) Labour Charges \$480.00
  - Total for Part-By-Part Repair Cost** \$1,142.88
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$0.00  
**Final Lumpsum Repair cost** \$0.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : NAZ

Date : 25/4/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.04.2018

## REPAIR ESTIMATE

Time: 18:55:16

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305143719  
REGN NO : SHA7134B  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 24.03.2016  
DATE/TIME IN : 19.04.2018 11:35  
ACCIDENT DATE : 19.04.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0103-0579-G I40VC COVER ASSY-RR BUMPE 1 603.60 20.00 482.88

0002 04-01-0103-0738-G I40VC COVER-RR BUMPER LWR 1 225.00 20.00 180.00

SUB-TOTAL : 662.88

## JOB NATURE

0000 20-05 RENEW ADVERTISMENT REAR BUMPER 50.00

0001 L PANEL BEATING 200.00

0002 L SPRAY PAINTING CHARGE 200.00

0003 L REMOVE/REFIX REVERSE SENSOR 20.00

0004 L MERIMEN FEE 10.00

SUB-TOTAL : 480.00

TOTAL : 1,142.88

AUTHORISED : YES / NO

MVA NAME &amp; SIGNATURE

SURVEYOR NAME &amp; SIGNATURE

DATE :

DATE :



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Pre-Repair Survey









CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Apr 2018 <a href="#">Sendback Est</a>	19 Apr 2018 18:34 <b>\$2,432.38</b>	20 Apr 2018 10:39 <a href="#">Edit Adj Rpt</a>	<b>\$1,142.88</b> <a href="#">Edit Estimates</a>	<b>\$1,142.88</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>JQ-LOM</b> , Co. Reg. No.: 53245811K								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SHA7134B</b>	Date of Loss:	19/04/2018 10:00 - :59 [24 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / M1802081</b>	Policy/Cover Note No.:	MU011043 (Third Party Only) Coverage: 25/10/2017 - 24/10/2018						
Vehicle Reg. No. (Insured):	<b>GBC2609S</b>	Policy No. (Claimant):	MCOM0015						
		Excess:	\$0.00						
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Fiona Gan Bee Song</b> - 65926378]								
Claimant's Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 02/05/2018]								
Adj Asg. Remarks:	OU INSURED HAVE NOT REPORT THE ACCIDENT. PLS. CHECK CONSISTENCY OF THE DAMAGE.								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




















## Claim Documents

SHA7134B (M1802081)  
[GBC2609S]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Apr 19 2018 10:00AM  
[JQ-LOM]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Assessment Reports								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)							Thumbnail	Print	
1	19/04/18 14:00	Accident Statement						1	Load HTM		
2	19/04/18 18:34	Repairer Estimates						1	Load HTM		
Photos/Images								3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)							Thumbnail	Print	
1	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
2	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
3	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
4	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
5	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
6	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
7	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
8	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
9	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
10	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
11	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
12	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
13	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
14	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
15	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
16	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
17	19/04/18 13:57	Accident Photo [Linked Accident Report Documents]						1	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
2	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
3	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
4	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
5	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
6	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
7	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
8	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	
9	25/04/18 10:46	General View						1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
10	25/04/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/04/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/04/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
13	25/04/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
14	25/04/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
15	25/04/18 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	08/05/18 16:18	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/04/18 13:59	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/04/18 14:00	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	19/04/18 13:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/04/18 13:59	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

	^ v
--	--------

**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI18007356/NRBE2**Date:** 09/05/2018**REFERENCE****Handling Insurer:** Tokio Marine Insurance Singapore Ltd**Policy No:** MU011043**Claimant Vehicle No :** SHA7134B**Insured Vehicle No :** GBC2609S**Date of Loss:** 19/04/2018**Nature of Claim:** TP**Claim No:** M1802081**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SHA7134B**Make & Model:** HYUNDAI I40, 1.7 D CRDi (A)**Engine No:** D4FDFU605345**Reg. Date:** 24/03/2016 (Man. Year: 2015)**Chassis No:** KMHLB41UMGU086622**Colour:** Blue**Odometer:** 251841 km**Engine Capacity:** 1685 cc**Market Value/New Car Price:** N/A**Sum Insured (S\$):** Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Fair **Steering (Serviceable):****Yes** **Footbrake (Serviceable):****Yes****Handbrake (Serviceable):** Yes **Engine Modification:****No** **Pre-accident Condition:****Average****CONDITION OF TYRES****Front Tyre Size:** 205/60 R16**Rear Tyre Size:** 205/60 R16**Front Left Side:** West Lake 5 mm**Rear Left Side:** West Lake 5 mm**Front Right Side:** West Lake 5 mm**Rear Right Side:** Hankook 5 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,672.38	712.88	959.50	57.37
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	750.00	420.00	330.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,432.38</b>	<b>1,142.88</b>	<b>1,289.50</b>	<b>53.01</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>170.27</b>	<b>80.00</b>	<b>90.27</b>	<b>53.02</b>
<b>Nett Amount (S\$)</b>	<b>2,602.65</b>	<b>1,222.88</b>	<b>1,379.77</b>	<b>53.01</b>

**INSPECTION****Date of Assignment:** 20/04/2018 **Present Location:**ComfortDelGro Engineering Pte Ltd  
(Loyang)**Date Inspected:** 20/04/2018 **Inspected At:**59 Loyang Drive  
Singapore 508969**Estimated Period of Repair:** 2.0 days**Adjuster:** Muhammad Nazrii Bin Abdullah**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 09 May 2018)  
**Parts:** 143      **HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SHA7134B)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	603.60 FL	*603.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	504.35 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Serviceable	180.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Serviceable	180.00 FL	*- FL
5	10		*REAR BUMPER REINFORCEMENT CLIPS	Serviceable	22.00 FL	*- FL
6	1		*REAR BUMPER SPONGE	Serviceable	143.40 FL	*- FL
7	1		*REAR BUMPER UNDER COVER	Dented	225.00 FL	*225.00 FL
8	1		*REVERSE SENSOR	Serviceable	135.70 FS	*- FS
9	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
					<b>Sub Total (S\$)</b>	<b>2,044.05      878.60</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>371.67      165.72</b>
					<b>Total Parts (S\$)</b>	<b>1,672.38      712.88</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$)			10.00	10.00

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEAT	New	300.00	200.00
2	SPRAY PAINTING CHARGE	New	300.00	200.00
3	WIRING CHARGE	New	30.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	20.00
Gross Labour Cost (\$)			750.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >