

ASS. REC. BY:

REF: CS/MSI-18007367 / T/vb

Special Instruction:

Survivor  
Merimen

Tawfik

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSLH

Date/Time:

19/04/2018 220pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 8269B

Insured:

SKL 104R

at Workshop in/s

Burneo Motor

Tel:

9742 7757

of

2 Pandan Crescent

Policy No:

27578133SMP

Claim No:

555595

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wapi

20/04/2018 @ 230pm

H.O.D. Endorsement:

Date/Time:

20/04/2018 337pm

Person Contacted:

Joe

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SLW 8269B - X

SKL 104R - X

23/4/18

Send preli revised by merimen

13/6/18

Final fig \$ 5460.55 confirmed by email (Ref 11, 243.23, 67%)

Tanpin

REF: MSL4

# ASSIGNMENT

From: Date: 20042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 8269B

at Workshop m/s

Borneo Motor  
2 Pandan Crestant

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Joe - 9712 7957

(Policy Condition)

2:30pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPI

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 8269B

Yr Regn:

2018 / March

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

C.C.

1798

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

1998

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

STD 6620W40J00 8994

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/4/18 @ 1440

Survey held at

Borneo Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 13/6 - typist

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Report Format:

merimen

Lump Sum / I.B.I: (\$

5460.55

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2018		19 Apr 2018 14:20 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

Insured:	LEOW WEI CHIEH (LIU WEIJIE), ID: 57617818F, Tel: +6592988358 [Created by insurer]		
Main Claimant:	WANG KAI, ID: 58362428		
Vehicle Reg. No.:	SLW8269B	Date of Loss:	13/04/2018 17:00 - :59 [1 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555595	Policy/Cover Note No.:	275781335MP (Comprehensive) Coverage: 13/09/2017 - 12/09/2018
Vehicle Reg. No. (Insured):	SKL104R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Borneo Motors (Singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/04/2018]		
Driver/Custodian (Insured):	LEOW WEI CHIEH (LIU WEIJIE) (), NRIC: S7617818F, Tel: +6592988358		
Adj Asg. Remarks:	ON WP. Survey appt on 20/04/18, 2pm, Owner waiting. Please contact us ASAP if you are not able to attend this assignment, thank you.		

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

## ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jasmine Lok Kheng Kwei	Date: 23 Apr 2018
<b><u>Preliminary Advice</u></b>	

Insured Vehicle No	: SKL104R		
TP Vehicle No	: SLW8269B	Accident Date	: 13/04/2018
Make	: TOYOTA WISH	Assignment Date	: 19/04/2018
Date of Inspection	: 20/04/2018	Est. Duration of Repair	: 6.00
Inspection At	: BORNEO MOTORS (SINGAPORE) PTE LTD - (PANDAN) (HQ) TOYOTA BODYCARE CENTRE, NO. 2 PANDAN CRESENT SINGAPORE 128462		

## **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,703.78
Revised Amount	:S\$	5,555.46
Check Items (Estimated)	:S\$	364.30
Total	:S\$	5,919.76
Lump Sum Repair	:S\$	

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

## **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.



# CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2081415 Account No. : 14885  
Coverage : Comprehensive (SmartDrive Toyota Prestige)  
Sum Insured : Market Value At The Time Of Loss  
Name of Policy Holder : WANG KAI  
Vehicle Registration No. : SLW8269B  
Period of Insurance : From 06/03/2018 To 05/03/2020 (Both Dates Inclusive)

## PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

- (a) The Policyholder  
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner  
(b) Any other person who is driving on the Policyholder's order or with his permission  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

## LIMITATIONS AS TO USE\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business  
The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 1,200.00

An Additional Excess is applicable as follows:

S\$2,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.

(Please refer to your policy on the terms & conditions)\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOAGPH on 08/03/2018

## IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).  
The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8362428J



Name

WANG KAI

王 凱

Race

CHINESE

Date of birth

06-10-1983

Sex

M

S8362428J

Country of birth

CHINA

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S8362428J

Name

WANG KAI

Birth Date 06 Oct 1983

Issue Date 16 Sep 2017



9111805

NRIC No. S8362428J



Nationality

CHINESE

Date of issue

18-10-2012

32 WOODLANDS CRESCENT #08-04  
SINGAPORE 738087

S8362428J

01/08/2013 (R)

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight  $\leq$  2500kg 16 Sep 2017

NP 425A



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-056388

Date of Request: 14/04/2018

Your Ref No: Online Purchase

Borneo Motors (S) Pte Ltd  
33 Leng Kee Road  
Singapore 159096

Dear Sir/Madam,

Enquiry Date 14/04/2018

Enquiry By Angela Tan Hong Choo

TP Vehicle No. SKL104R

Accident Date 13/04/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKL104R	MSIG Insurance (Singapore) Pte. Ltd.	13/09/2017-12/09/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/04/2018 12:34
Date Of Accident	13/04/2018 17:45
Exact Location Of Accident	AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW8269B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WANG KAI
NRIC No	S8362428J
Email Address	KEVIN.WANG19831006@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81892831
Alternative Phone No	OFFICE-81892831

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2081415
Cover Note Number	

### Driver

Name of Driver	WANG KAI
NRIC No	S8362428J
Date Of Birth	06/10/1983
Occupation	INDOOR
Date Of Driving Pass	16/09/2017
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81892831
Fax Number	
Contact Number	OFFICE-81892831
Email Address	KEVIN.WANG19831006@GMAIL.COM



Address	32 WOODLANDS CRESCENT #08-04
Postcode	738087
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL104R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	92988358
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: JOE TAN

## MOTOR ACCIDENT REPORT

Date Of Report: 14/04/2018 Time: 1010 AM Date Of Accident: 13/04/2018 Time: 17:48 PM  
Exact Location Of Accident: AYE  
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

## OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLW 8269B Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S8362428J  
Name Of Registered Owner: WANG KAI  
Mobile Number: 81892837 Alternative No: Email Address: KEVIN.WANG19831006@gmail.com

## Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: WISH  
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):  
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒  
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

## Insurance Company

Name of Insurance Company: AXA  
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐  
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: VPA/P208/415

## DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: WANG KAI NRIC/ Passport / FIN No: S8362428J  
Date Of Birth: 06/10/1983 Occupation: Indoor ☒ Outdoor ☐  
Date Of Driving Pass: 16/09/2017 Gender: Male ☒ Female ☐  
Mobile Number: 81892837 Fax No: Alternative No:  
Address: 32 Woodlands Crescent #08-04 Postal Code: 738087  
Email Address: KEVIN.WANG19831006@gmail.com  
Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: Owner  
Vehicle Registration Number of Driver's Own Vehicle (if applicable):  
Insurance Company of Driver's Own Vehicle (if applicable):

## GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: REAR COLLISION  
Number of Passengers in the above vehicle (Including Driver): 1 / If more than 2 Pax Please fill ANNEX B

## PASSENGER 1

Name: Gender: Male ☐ Female ☐  
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):  
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):  
Was any body injured in the Accident? No ☒ Yes ☐  
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐  
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:  
Number of vehicles involved in the accident: 2  
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below  
Witness Name: | Contact No.: | Email:  
Was there any other vehicle or property damaged? No ☒ Yes ☐  
Was there any video captured by Car Camera? No ☐ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☐  
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):  
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

## DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SKL 104R Vehicle Make/Model/Colour:  
Details Of Properties Damage in Accident:  
Vehicle Category:  
Name of Driver:  
NRIC/Passport/FIN Number: Contact Number: 9298 8358 Postal Code:  
Insurance Company Name:  
Nature Of Damage: No. Of Passenger (Including Driver):

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &  
Time

14/04/2018

10:10 AM

Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan

A - SLW8269B  
B - SKL104R


**Describe Circumstances of the Accident**

I was driving along AYE, at inner line. And the traffic was heavy. All the car is stopping. Suddenly I feel a bump behind my car. I came down and see a BMW (SKL 104R) hit my car behind.

**Declaration**

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

 14/04/2018  
10:10 AM

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel





Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg)  
**Toyota Bodycare Centre**  
**No. 2 Pandan Crescent**  
**Singapore 128462**  
**Tel no.: 6631 1188**

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9


**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
<b>THIRD PARTY CLAIM</b>	<b>S1000020 /TPCLAIM</b>	<b>Mr Wang Kai</b> <b>32 Woodlands Crescent</b> <b>#08-04</b> <b>Singapore 738087</b> <b>Mobile: 81892837</b>
	Document No	
	Document Date	
	0	
	16/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	06/03/2018	SLW8269B	0	30436	84/TP/SLW8269B
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J008994	2ZROA58117	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES:TP CLAIM <i>Nk</i> POLICY NO.:VPA/P2081415 TOW/DRIVE IN: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 50 100.00
2	B	BP-LAB TO CHECK WIRING AND LIGHT FUNCTIONING AND CARRY OUT WATER LEAK TEST.				✓ ✓ 115.26
3	B	BP-ECU TO RESET ECU AND REPROGRAMME				✓ ✓ 508.50
4	B	BP-LAB TO DRILL HOLE AND RE-INSTALL REAR SENSOR				✓ ✓ 169.50
5	B	BP-LAB TO REMOVE AND TRANSFER REAR TAILGATE COMPONENT AND MECHANISM TO NEW TAILGATE.				X 339.00
6	2	BP-SLANT SUPPLY SEALANT (NETT)				X 60.00
7	B	BP-LAB TO REMOVE AND RE-INSTALL REAR WINDSCREEN TO ENABLE REPAIR.				X 678.00
8	S	BP-SUBLET TO INSTALL REAR WINDSCREEN SOLAR FILM <i>[34]</i>				X 350.00
9	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGED PARTS, REPLACE, REPAIR AND STRAIGHTEN REAR END PANEL, REAR BUMPER, AND AFFECTED REAR PORTION OF CAR.				✓ 2034 4068.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3622361

TO SECURITY GUARD

3622361

PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/04/2018  
 TIME 10:11

VEHICLE NO SLW8269B

CUSTOMER

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)  
 Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no.: 6631 1189

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
<b>THIRD PARTY CLAIM</b>	<b>S1000020 / TPCLAIM</b>	<b>Mr Wang Kai</b> <b>32 Woodlands Crescent</b> <b>#08-04</b> <b>Singapore 738087</b> <b>Mobile: 81892837</b>
	Document No	
	Document Date	
	0	
	16/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE2OR	06/03/2018	SLW8269B	0	30436 84/TP/SLW8269B
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J008994	2ZR0A58117	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-RES TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR. <i>SS6 photo - end panel</i>				✓ 1668 - 3336.00
11	1	T52159-68907 REAR BUMPER COVER, <i>488-66</i>	1.00	574.90		da ✓ 574.90 ✓
12	2	SP2061-12010 16 O70 SENSOR	1.00	151.60		nn X 151.60 X
13	3	S52161-OK040 PIECE, RR BUMPER <i>39.72</i>	12.00	3.90		acc ✓ 46.80 ✓
14	4	T52576-68020 L/R SIDE BPR RETAINER, <i>37.74</i>	1.00	44.40		nee ✓ 44.40 ✓
15	5	T52575-68020 R/R SIDE BPR RETAINER, <i>37.74</i>	1.00	44.40		nee ✓ 44.40 ✓
16	6	T52156-68030 L/RR BUMPER SUPPORT, <i>79.51</i>	1.00	93.90		nee ✓ 93.90 ✓
17	7	T52155-68030 R/RR BUMPER SUPPORT,	1.00	93.90		nee ✓ 93.90 X
18	8	T58307-68031 REAR LOWER FLR PANEL,	1.00	520.00		R X 520.00
19	9	T52181-68010 REAR BUMPER ARM,	1.00	52.10		cur? 52.10 X
20	0	T89997-30070 ELECTRICAL ANTENNA, <i>136.51</i>	1.00	160.60		Ro 160.60 ✓
21	1	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		X 1428.40
22	2	T68105-68071 REAR BACK DOOR GLASS,	1.00	1009.20		X 1009.20
23	3	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		X 90.08
24	4	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		X 173.44
25	5	T04562-12010 W/SCREEN GLS DAM KIT,	1.00	101.00		X 101.00
26	6	T76821-68070 PROTECTOR, BACK DOOR	1.00	9.10		X 9.10
27	7	T76811-68130 GARNISH, BACK DOOR,	1.00	281.00		X 281.00
28	8	T90975-02086 TOYOTA SYMBOL EMBLEM, <i>61.37</i>	1.00	72.20		nee ✓ 72.20 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3622362

TO SECURITY GUARD

3622362

PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/04/2018  
 TIME 10:11

VEHICLE NO SLW8269B

CUSTOMER

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**





Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)  
**Toyota Bodycare Centre**  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no.: 6631 1188

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
<b>THIRD PARTY CLAIM</b>	<b>S1000020 / TPCLAIM</b>	<b>Mr Wang Kai</b>
	Document No	<b>32 Woodlands Crescent</b>
	<b>0</b>	<b>#08-04</b>
	Document Date	<b>Singapore 738087</b>
	<b>16/04/2018</b>	<b>Mobile: 81892837</b>

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	06/03/2018	SLW8269B	0	30436	84/TP/SLW8269B
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J008994	2ZROA58117	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	9	T75444-68010 LUGGAGE "VALVE MATIC "	1.00	39.70		39.70
30	0	T81580-68020 LAMP ASSY, RR, RH	1.00	316.40		X 316.40
31	1	T81590-68020 LAMP ASSY, RR, LH	1.00	316.40		X 316.40
32	2	T69350-28151 LOCK ASSY, BACK DOOR	1.00	399.60		X 399.60
33	3	T76817-50010 CLIP, BACK DOOR	1.00	1.90		X 1.90
34	4	T67881-68030 RR BACK DOOR W/STRIP,	1.00	325.80		X 325.80
35	5	T67935-68020 BO PLATE BACK DOOR	1.00	288.70		X 288.70
36	6	T81551-68062 LENS & BODY, RR	1.00	344.00		X 344.00

Tanfik 97495749  
 20/4/18 @ 245pm  
 WP.  
 Resurvey before paint  
[sur@lkkauto.com](mailto:sur@lkkauto.com)  
 6 days.

*[Signature]*  
 30/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Date:	Total
<i>[Signature]</i>	Please acknowledge receipt of vehicle	Parts	6,979.52	16,703.78
		Labour	9,374.26	GST 7.00%
		Materials	350.00	1,169.26
		Lubrication/Fluid	0.00	Less
		Others	0.00	0.00
			Amount Due	17,873.04

PLEASE TEAR ALONG PERFORATED LINE

3622363

3622363

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/04/2018  
 TIME 10:11

VEHICLE NO SLW8269B

CUSTOMER

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 13 June 2018 10:18 AM  
**To:** 'Joe Tan SMTC'; SUR  
**Subject:** RE: SLW8269B FOR FINALIZATION TP CLAIM PART1

Dear Joe,

WITHOUT PREJUDICE

Confirmed **\$5,460.55** before GST and 06 working days.

**Final invoice and all supporting documents sent over to MSIG.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joe Tan SMTC [mailto:Joe.Tan@borneomotors.com.sg]  
**Sent:** Wednesday, 13 June 2018 8:17 AM  
**To:** SUR <sur@lkkauto.com>  
**Subject:** SLW8269B FOR FINALIZATION TP CLAIM PART1

Hi,

The above attached document and before paint photo for finalization  
vehicle no. SLW8269B.

The repair amount is \$5,460.35 before GST and 06 working days.

Thank you.

Best Regards ,

Joe Tan.



---

**From:** Joe.Tan@borneomotors.com.sg <Joe.Tan@borneomotors.com.sg>  
**Sent:** 13 June 2018 08:09  
**To:** Joe Tan SMTC  
**Subject:** Scan Data from FX-0DBC96

Sent by: B050577 [Joe.Tan@borneomotors.com.sg]  
Number of Images: 4  
Attachment File Type: PDF

Device Name: ApeosPort-V C2276  
Device Location:

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Page 3 of 3  
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462

Tel no.: 6631 1188  
Customer Detail

Account Detail	Account No	Mr Wang Kai 32 Woodlands Crescent #08-04 Singapore 738087 Mobile: 81892837
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	
	Document No	
	0	
	Document Date	
	15/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	06/03/2018	SLW8269B	1117	30436	84/TP/SLW8269B
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W40J008994 2ZROA58117 60 Joe Tan Joo Seng 10/05/2018 8.00 15/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES: TP CLAIM(DIRCT SETTLEMENT) TOW/DRIVE IN:DRIVE DATE-IN:10/05/2018 DATE SURVEY:20/04/2018 NO OF REPAIR DAYS:06 DAYS BY:LKK-TAUFLIK27/04/2018 AUTHORIZED ON:				50.00
2	B	BP-LAB TO CHECK WIRING AND LIGHT FUNCTIONING AND CARRY OUT WATER LEAK TEST.	*			115.26
3	B	BP-ECU TO RESET ECU AND REPROGRAMME	18			508.50
4	B	BP-LAB TO DRILL HOLE AND RE-INSTALL REAR SENSOR	*			169.50
5	B	BP-LAB TO REMOVE ALL NECESSARY DAMAGED PARTS, REPLACE, REPAIR AND STRAIGHTEN REAR END PANEL, REAR BUMPER, AND AFFECTED REAR PORTION OF CAR.	*			2034.00
6	B	BP-RES TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.	*			1668.00
7	1	T52159-68907 COVER RR BUMPER	1.00	574.90	15.00	488.66
8	2	S52161-OK040 PIECE, RR BUMPER	12.00	3.90	15.00	39.72
9	3	T52576-68020 RETAINER RR BUMPER	1.00	44.40	15.00	37.74
10	4	T52575-68020 RETAINER RR BUMPER	1.00	44.40	15.00	37.74

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3668254

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/05/2018  
TIME 11:08

3668254

VEHICLE NO

SLW8269B

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

CUSTOMER



Co Reg No: 196700086Z  
GST Reg No: MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

## ESTIMATE

Account Detail	Account No	Mr Wang Kai 32 Woodlands Crescent #08-04 Singapore 738087 Mobile: 81892837
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	
	Document No	
	0	
	Document Date	
	15/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	2GE20R	06/03/2018	SIWB269B	1117	30436 84/TP/SIWB269B
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W40J008994 2ZROA58117 60 Joe Tan Joo Seng 10/05/2018 8.00 15/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	5	T52156-68030 SUPPORT RR BUMPER LH	1.00	93.90	15.00	79.81
12	6	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	15.00	61.37
13	7	T75444-68010 PLATE, LUGGAGE COMPT	1.00	39.70	15.00	33.74
14	8	T89997-30070 ANTENNA, ELECTRICAL (QUESTION MARK ITEM)	1.00	160.60	15.00	136.51

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	5,460.55
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	382.24
		Labour 915.29	Less	0.00
		Materials 4,545.26		
		Lubrication/Fluid 0.00		
		Others 0.00		
		0.00	Amount Due	5,842.79

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SIWB269B

CUSTOMER

DATE 15/05/2018  
TIME 11:08

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

# Vehicle Diagnostic Report

2ZRFAE

SLW8269B

TOYOTA BODY CARE

Printed By: Default User(1)

11/05/2018 4:21:27 PM

## Health Check Results All Systems(1 of 1)

Enhanced

						Pass/Fail	Pass/Fail	Pass/Fail
D-Door Motor	No	B2312			X			-
Entry&Start	No	U0100			X			-
	No	U0142			X			-
	No	U0155			X			-
Engine and ECT								36824200
								A0C01000
ABS/VSC/TRC								F152668071
EMPS								JCF305F0
Air Conditioner								-
Combination Meter								838006827102
Main Body								660C1SCV**02
P-Door Motor								-
RR-Door Motor								-
RL-Door Motor								-
Master Switch								-
HL AutoLeveling								-
SRS Airbag								8917F68010
PM2 Gateway								-
Starting Control								-
Power Source Control								-

# Vehicle Diagnostic Report

2ZRFAE

SLW8269B

TOYOTA BODY CARE

Printed By: Default User(1)

11/05/2018 4:23:02 PM

## Health Check Results All Systems(1 of 1)

Enhanced

Health Check Results							DATE	Calculated
System	Pass/Fail	Pass/Fail	Pass/Fail	Pass/Fail	Pass/Fail	Pass/Fail		
Engine and ECT								36824200
								A0C01000
ABS/VSC/TRC								F152668071
EMPS								JCF305F0
Air Conditioner								-
Combination Meter								838006827102
Main Body								660C1SCV**02
D-Door Motor								-
Entry&Start								-
P-Door Motor								-
RR-Door Motor								-
RL-Door Motor								-
Master Switch								-
HL AutoLeveling								-
SRS Airbag								8917F68010
PM2 Gateway								-
Starting Control								-
Power Source Control								-

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Apr 2018		19 Apr 2018 14:20 <a href="#">Edit Adj Rpt</a>	<b>S\$5,460.55</b> <a href="#">Edit Estimates</a>	<b>S\$5,460.55</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>




  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>LEOW WEI CHIEH (LIU WEIJIE)</b> , ID: S7617818F, Tel: +6592988358								
Main Claimant:	<b>WANG KAI</b> , ID: S8362428J								
Vehicle Reg. No.:	<b>SLW8269B</b>	Date of Loss:	13/04/2018 17:00 - :59 [1 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 555595</b>	Policy/Cover Note No.:	27578133SMP (Comprehensive) Coverage: 13/09/2017 - 12/09/2018						
Vehicle Reg. No. (Insured):	<b>SKL104R</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>Borneo Motors (singapore) Pte Ltd - (pandan) (HQ)</b> Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 19/05/2018]								
Driver/Custodian (Insured):	LEOW WEI CHIEH (LIU WEIJIE) (), NRIC: S7617818F, Tel: +6592988358								
Adj Asg. Remarks:	ON WP. Survey appt on 20/04/18, 2pm, Owner waiting. Please contact us ASAP if you are not able to attend this assignment, thank you.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLW8269B (555595)**  
**[SKL104R]**  
**TP**  
**WANG KAI**  
**Apr 13 2018 5:00PM**  
**[LEOW WEI CHIEH (LIU WEIJIE)]**  
**Borneo Motors (singapore) Pte Ltd - (pandan)**

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>			
Video									1 per page		<div></div>	<div></div>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print		
1	26/04/18 12:12	Video - Accident						<div></div>	Load MOV			
Assessment Reports									1 per page		<div></div>	<div></div>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	23/04/18 12:09	Adjuster Immediate Advice						<div></div>	Load HTM			
Photos/Images									3 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
2	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
3	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
4	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
5	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
6	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
7	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
8	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
9	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
10	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
11	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
12	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
13	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
14	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
15	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
16	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
17	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
18	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
19	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
20	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
21	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
22	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
23	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
24	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
25	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
26	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
27	23/04/18 12:10	General View						<div></div>	Load JPG	<div></div>		
28	13/06/18 10:13	Reinspection Photo						<div></div>	Load JPG	<div></div>		
29	13/06/18 10:13	Reinspection Photo						<div></div>	Load JPG	<div></div>		
30	13/06/18 10:13	Reinspection Photo						<div></div>	Load JPG	<div></div>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/18 16:33	E-FILE REPORT (SKL104R)	 Load PDF	
2	16/04/18 16:33	E-FILE REPORT (SLW8269B)	 Load PDF	
3	16/04/18 16:40	TP EST BILL	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	^ v
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007367/T1VBQ2

Date: 13/06/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27578133SMP

Claimant Vehicle No : SLW8269B

Insured Vehicle No : SKL104R

Date of Loss: 13/04/2018

Nature of Claim: TP

Claim No: 555595

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW8269B

Make &amp; Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR0A58117

Reg. Date: 06/03/2018 (Man. Year: 2017)

Chassis No: JTDGG20W40J008994

Colour: White

Odometer: 1998 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,079.52	965.29	6,114.23	86.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,624.26	4,495.26	5,129.00	53.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,703.78</b>	<b>5,460.55</b>	<b>11,243.23</b>	<b>67.31</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,169.26</b>	<b>382.24</b>	<b>787.02</b>	<b>67.31</b>
<b>Nett Amount (S\$)</b>	<b>17,873.04</b>	<b>5,842.79</b>	<b>12,030.25</b>	<b>67.31</b>

### INSPECTION

Date of Assignment: 19/04/2018

Date Inspected: 20/04/2018 Inspected At:

Borneo Motors (singapore) Pte Ltd -  
(pandan) (HQ)

Toyota Bodycare Centre, No. 2 Pandan

Crescent

Singapore 128462

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLW8269B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*REAR BUMPER COVER,	Deformed	574.90 FS	*488.66 FS
3	1		*070 SENSOR	Not Necessary	151.60 FS	*- FS
4	12		*PIECE,RR BUMPER	Necessary	46.80 FS	*39.72 FS
5	1		*L/R SIDE BPR RETAINER ,	Necessary	44.40 FS	*37.74 FS
6	1		*R/R SIDE BPR RETAINER ,	Necessary	44.40 FS	*37.74 FS
7	1		*L/RR BUMPER SUPPORT ,	Necessary	93.90 FS	*79.81 FS
8	1		*R/RR BUMPER SUPPORT ,	Not Necessary	93.90 FS	*- FS
9	1		*REAR LOWER FLR PANEL ,	Repair	520.00 FS	*- FS
10	1		*REAR BUMPER ARM ,	Not Necessary	52.10 FS	*- FS
11	1		*ELECTRICAL ANTENNA ,	Cracked	160.60 FS	*136.51 FS
12	1		*PANEL ASSY ,BACK DOOR	Repair	1,428.40 FS	*- FS
13	1		*REAR BACK DOOR GLASS ,	Not Necessary	1,009.20 FS	*- FS
14	1		*SUPER FAST URETHANE BLACK	Not Necessary	90.08 FS	*- FS
15	1		*SINGLE STEP PRIMER	Not Necessary	173.44 FS	*- FS
16	1		*W/SCREEN GLS DAM KIT ,	Not Necessary	101.00 FS	*- FS
17	1		*PROTECTOR ,BACK DOOR	Not Necessary	9.10 FS	*- FS
18	1		*GARNISH ,BACK DOOR ,	Not Necessary	281.00 FS	*- FS
19	1		*TOYOTA SYMBOL EMBLEM	Necessary	72.20 FS	*61.37 FS
20	1		*LUGGAGE VALVE MATIC	Necessary	39.70 FS	*33.74 FS
21	1		*LAMP ASSY ,RR, RH	Not Necessary	316.40 FS	*- FS
22	1		*LAMP ASSY ,RR, LH	Not Necessary	316.40 FS	*- FS
23	1		*LOCK ASSY ,BACK DOOR	Not Necessary	399.60 FS	*- FS
24	1		*CLIP,BACK DOOR	Not Necessary	1.90 FS	*- FS
25	1		*RR BACK DOOR W/STRIP ,	Not Necessary	325.80 FS	*- FS
26	1		*PLATE BACK DOOR	Not Necessary	288.70 FS	*- FS
27	1		*LENS & BODY ,RR	Not Necessary	344.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>7,079.52</b>	<b>965.29</b>
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND LIGHT FUNCTIONING AND CARRY OUT WATER LEAK TEST	New	115.26	115.26
2	TO RESET ECU AND REPROGRAMME	New	508.50	508.50
3	TO DRILL HOLE AND RE-INSTALL REAR SENSOR	New	169.50	169.50
4	TO REMOVE AND TRANSFER REAR TAILGATE COMPONENT AND MECHANISM TO NEW TAILGATE	New	339.00	0.00
5	SUPPLY SEALANT	New	60.00	0.00
6	TO REMOVE AND RE-INSTALL REAR WINDSCREEN TO ENABLE REPAIR	New	678.00	0.00
7	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	350.00	0.00
8	TO REMOVE ALL NECESSARY DAMAGED PARTS ,REPLACE ,REPAIR AND STRAIGHTEN REAR END PANEL, REAR BUMPER ,AND AFFECTED REAR PORTION OF CAR	New	4,068.00	2,034.00
9	TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR	New	3,336.00	1,668.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,624.26</b>	<b>4,495.26</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >