

ASS. REC. BY:

REF: CS/AWA18007376/AHbez

Special Instruction:

Surveyor

Kasul

ASSIGNMENT (Office)

From (Person): Stella Goh of AWA Date/Time: 20042018 4:18pm

Estimated Cost: Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 731M Insured: GBE 4724T

at Workshop m/s Lee Kuan Hwa Tel: 6269 9192

of 24 Sungai Kachet St 4

Policy No: AVCPSB0090881700 Claim No: NSV 1800245/KW

Sum Insured: Excess:

Make of Veh: D.O.A. 12042018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 23-042018 @ 1130am

H.O.D. Endorsement:

Date/Time: 20042018 4:41pm Person Contacted: Shue Ting Vehicle-IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	XE 731M - X
	GBE 4724T - NA - /INC1800735 /13
	lump sum \$2800, 3days (Red: 1823, 39%)

DA: 0902018

Surveyor: *[Signature]*

REF: AWA

4246c

### ASSIGNMENT

From: Date: 23042018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 731M

at Workshop m/s: Lee Kuan Hwa

of 24 Surgei Kadut St 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11.30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'Wp'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: XE 731M

Yr Regn: 2015 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer or

Make: Volvo FMX370

c.c 10837

Colour: MULTI

A/C: Insured / Std / NI / NA

Sp.Reading: 137807

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 4V2X1E1G2E5704626

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 315/80R22-5

R: - 2/0

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8/8 mm

L/Bal. 8 mm

L/Bal. 8/8 mm

D.O.A. 12/04/18

D.O.I. 23/04/18

Survey held at LEE KUAN HWA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 12 NOV 2018

Date/Time, File Pass to?

1) Bill Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$ 2800/-)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$ )

☐ Interview (\$ )

☐ Tech. Invs (\$ )

☐ Weekend (\$ )

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

150

150

**Catherine Chong (LKK Auto)**

---

**From:** Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey  
<Motorsurvey@awac.com>  
**Sent:** Friday, 20 April, 2018 4:18 PM  
**To:** 'assignments'  
**Cc:** 'SUR'; 'Lee Kuan Hwa'  
**Subject:** TP Survey assignment for XE 731M - DOA: 12/04/2018 Our ref: NSV1800245/KW

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Mohamad Taufikh** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	XE 731 M
Insured Vehicle	:	GBE 4724 T
Policy Number	:	AVCP SB0090881700
Name of Workshop	:	Lee Kuan Hwa Motor Service
Contact Number	:	6269 9192
Person to Contact	:	Chin Shue Ting
Estimated Cost of repairs	:	\$ NA

Regards,  
Claims Division

Copy to Lee Kuan Hwa Motor Service via Email

Note -

- ( X )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards  
Motor Claims  
Claims Group

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	17/04/2018 11:16
Date Of Accident	12/04/2018 15:00
Exact Location Of Accident	JALAN KEMBANGAN
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	XE731M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIAN WANG TRADING PTE LTD
Co Reg No	199204246C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63687277
<b>Vehicle Particulars</b>	
Manufacturer	VOLVO
Model	FMX37064R-10.8 D SLEEPER CAB (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

**Insurance Company**

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P1944852
Cover Note Number	

**Driver**

Name of Driver	NG CHEE SUN
NRIC No	S2746980I
Date Of Birth	31/08/1960
Occupation	OUTDOOR
Date Of Driving Pass	02/03/1982
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84218109
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NO
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE4724T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LI HONGWEI
NRIC/Passport Number	G8613886M
Contact Number	87392069
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the date 12/04/18 at about 1500 hours, I was driving my vehicle A XE731 M along Jalan Kambagan. The vehicle B GBE472AT from right lane suddenly cut into my lane and hit onto my vehicle A XE731 M right side. I am claiming against the vehicle B GBE472AT insurance policy.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Transaction ref 20150612104839225664

The owner and vehicle particulars for Vehicle No. XE731M as at 12 Jun 2015 are as follows:

1. Name	: LIAN WANG TRADING PTE LTD
2. Identification No. Type	: Company
3. Identification No.	: 199204246C
4. Place Of Passport Issue	: -
5. Vehicle No.	: XE731M
6. Previous Vehicle No.	: -
7. Effective Date of Ownership	: 10 Jun 2015
8. Original Registration Date	: 10 Jun 2015
9. First Registration Date	: 10 Jun 2015
10. Vehicle Type	: B30 - Goods (Open) Lorry (Wooden Body)
11. Vehicle Scheme	: Normal
12. Attachment 1	: With Crane
13. Attachment 2	: -
14. Attachment 3	: -
15. Vehicle Make	: VOLVO
16. Vehicle Model	: FMX370 84R RSS DC
17. Year of Manufacture	: 2014
18. Primary Colour	: White
19. Secondary Colour	: -
20. Passenger Capacity	: 1
21. Chassis/Trailer Chassis No.	: YV2X1E1G2EB704626
22. Propellant	: Diesel
23. Engine No./Motor No.	: D11335414
24. Engine Capacity(cc)/Power Rating(kW)	: 10,837.0
25. Unladen Weight(kg)	: 20020
26. Maximum Laden Weight(kg)	: 34000
27. Open Market Value	: \$103,332.00
28. PARF Eligibility	: No
29. PARF Eligibility Expiry Date	: -
30. Minimum PARF Benefit	: -
31. No. of Transfers	: 0
32. IU Label No.	: 2010493712
33. COE No.	: 2015070105000017K
34. COE Expiry Date	: 09 Jun 2025
35. COE Category	: C - Goods Vehicle & Bus
36. Quota Premium/Prevailing Quota Premium	: \$50,900.00
37. Actual Quota Premium/PQP Paid	: \$50,900.00
38. Actual ARF Paid	: \$5,177.00
39. CO2 Emission(g/km)	: -
40. Actual CEVS Rebate Utilised	: -
41. CEVS Surcharge Paid	: -
42. Actual Green Vehicle Rebate Utilised	: -
43. Vehicle Lifespan Expiry Date	: 09 Jun 2035
44. Road Tax Amount	: \$0.00
45. Road Tax Start Date	: 10 Jun 2015
46. Road Tax End Date	: 09 Dec 2015
47. Remarks	: To renew the COE, the Prevailing Quota Premium payable is that of Category C.

LEEKUANHWA 62692239  
Apr-19-2018 12:12 PM

Job	Date	Time	Type	Identification	Duration	Pages	Result
2163	04/19/2018	12:11:23 PM	Send	64230864	0:51	0	Comm Error

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 2A, Sungei Kadu Street 4 Singapore 720050  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712

M/s: ALLIED WORLD ASSURANCE CO LTD  
60 Anson Road #09-01  
Maple Tree Anson  
Singapore 079914

Date: 19.04.2018

Motor Claim Dept

Vehicle number: XE 731 M  
Make/Model: VOLVO FMX370  
Date of accident: 12.04.2018  
Claim Type: TP Claim

Accident involving XE 731 M & GHE 4724 T along Jalan Kembaruan on 12.04.2018.

Ret Estimate

1.	1 pc	Rear mudguard RH (S/Net)	\$	600.00
2.	1 pc	Rear tyre rim hub RH	\$	189.00
3.	1 pc	Cover, oil/leg control valve	\$	216.00
4.	4 pcs	Lever hand	\$	152.00
5.	1 pc	Button Emergency stop	\$	93.00
6.	1 pc	Oil tank cover	\$	767.00
7.	1 pc	Locking mechanism	\$	15.00
8.	1 pc	HXE3200 cover	\$	677.00

\$	2,709.00	To Wiring Service
\$	180.00	To Repair & Replace Labour Charges
\$	1,000.00	To Putty and Spray Painting
\$	500.00	
\$	4,389.00	Total

Yours Faithfully,

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 0269 9192 FAX: 0269 2239 H/P: 9631 1712

# LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 24, Sungei Kadut Street 4 Singapore 729050  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712  
Business Reg. No: 36463500B

1130hrs

M/s: **ALLIED WORLD ASSURANCE CO LTD**

60 Anson Road #09-01

MapleTree Anson

Singapore 079914

Date : 19.04.2018

Motor Claim Dept

Vehicle number : **XE 731 M**  
Make/Model : **VOLVO FMX370**  
Date of accident : **12.04.2018**  
Claim Type : **TP Claim**

**Accident involving XE 731 M & GBE 4724 T along Jalan Kembangan on 12.04.2018 .**

## Re: Estimate

- |    |       |                           |
|----|-------|---------------------------|
| 1. | 1 pc  | Rear mudguard RH (S/Nett) |
| 2. | 1 pc  | Rear tyre rim hub RH      |
| 3. | 1 pc  | Cover,o/leg control valve |
| 4. | 4 pcs | Lever hand                |
| 5. | 1 pc  | Button Emergency stop     |
| 6. | 1 pc  | Oil tank cover            |
| 7. | 1 pc  | Locking mechanism         |
| 8. | 1 pc  | HXE3200 cover             |

R48ul

Ap 90010068

3 days

43

23/04/18 @ 1135

Resurvey after repair

\$	600.00	PA - S/K
\$	189.00	BT -
\$	216.00	CRA - 2109
\$	152.00	CRA - 102
\$	93.00	CRA - 1898
\$	767.00	BT -
\$	15.00	CRA -
\$	677.00	BT - S/K-300
<hr/>		
\$	2,709.00	

To Wiring Service  
To Repair & Replace Labour Charges  
To Putty and Spray Painting

\$	180.00	50
\$	1,000.00	500
\$	500.00	300
<hr/>		
\$	4,389.00	

**Total**

**\$ 4,389.00**

Yours Faithfully,

李光華 摩 嘜 燒 焊

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1

4623

3 days 43 - 2,180

P - 1898.10  
S/K - 600.00  
L - 850.00  
Supp - 150.00  
T - 3498.10  
202  
2,198.18

## LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 24, Sungei Kadut Street 4 Singapore 729050  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712  
Business Reg. No: 36463500B

M/s: **ALLIED WORLD ASSURANCE CO LTD**  
60 Anson Road #09-01  
MapleTree Anson  
Singapore 079914

Date : 04.05.2018

Motor Claim Dept

Vehicle number : **XE 731 M**  
Make/Model : **VOLVO FMX370**  
Date of accident : **12.04.2018**  
Claim Type : **TP Claim**

Accident involving XE 731 M & GBE 4724 T along Jalan Kembangan on 12.04.2018 .

Re: Supplementary Estimate

1.	1 pc	Hydraulic pump bracket lamp <i>at</i>	\$	<del>234.00</del> 150
Total			\$	234.00

Yours Faithfully,

李光華 摩嘜燒焊

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18007376/R1tbe2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 13-11-2018



Code : AWA

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 4724T	Veh. Inspected	XE 731M
Policy No.	AVCPSPB0090881700	Coverage (\$)	0.00
Claim No.	NSV1800245/KW	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	20/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	VOLVO FMX370	c.c	10837
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	YV2X1E1G2EB704626	Colour	MULTI COLOUR
Odometer	137807	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

Accident Date	12/04/2018	Inspection Date	23/04/2018
Survey held at	LEE KUAN HWA MOTOR SERVICE 24 SUNGEI KADUT ST. 4 SINGAPORE 729050		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 731M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TYRE RIM HUB RH	BENT	189.00	189.00
1	COVER, O/LEG CONTROL VALVE	CRACKED	216.00	216.00
4	LEVER HAND	CRACKED	152.00	152.00
1	BUTTON EMERGENCY STOP	CRACKED	93.00	93.00
1	OIL TANK COVER	BENT	767.00	767.00
1	LOCKING MECHANISM	CRACKED	15.00	15.00
1	HXE3200 COVER	BENT	677.00	677.00
	LESS 10% DISCOUNT		-	-210.90
			2,109.00	1,898.10
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR MUDGUARD RH (SN)	BENT	600.00	600.00
1	HYDRAULIC PUMP BRACKET LAMP (SN) (ADDITIONAL)	CUT	234.00	150.00
			834.00	750.00
<b><u>LABOUR</u></b>				
	TO WIRING SERVICE.		180.00	50.00
	TO REPAIR & REPLACE LABOUR CHARGES.		1,000.00	500.00
	TO PUTTY AND SPRAY PAINTING.		500.00	300.00
			1,680.00	850.00
<b>GRAND TOTAL</b>			<b>4,623.00</b>	<b>3,498.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,800.00</b>

Report Ref No. CS/AWA18007376/R1tbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.