

SS. REC. BY:

REF: CS3/ATL18007412/Gzubs

Special Instruction:

Survivor  
Maximum

GR

ASSIGNMENT (Office)

From (Person):

Chin Hee Ying

of

ALU

Date/Time:

23042018 12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 6802Z

Insured:

SLD 8861R

at Workshop m/s

Aforce Autotechnik

Tel:

6209 8108

of

10 Kaki Bukit Rd 2 #0134

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

17042018

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

23042018 1207pm

Person Contacted:

Elle.

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKP 6802Z - X
	SLD 8861R - X
24/4/18	dismantled

PR5  
Xhal

REF: A16

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s Exforce  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SKP 6802Z /r Regn: 30 Sep 2014  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Volkswagen Jetta cc 1390  
Colour: Black A/C: Insured / Std / NI / NA  
Sp. Reading: 117639 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WUW 888168-EM059100  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD / A/Rim or \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
	<u>0</u>

Bal. or Market Value: \$60K  
IDAC Accident Rport. \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Tyre Size: F: 205/55R16  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 23-04-18  
Survey held at: w/s 3:30pm  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>27/4/18</u>	<u>Submit DAR Report</u>

RECEIVED 5 APR 2018

Date/Time, File Pass to?  : Preli. Report  
1)  : Final Report

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	
Transportation	
_____ \$ + RS _____ \$	
Photos	
Others	
TOTAL	

Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_  
Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

**Catherine Chong (LKK Auto)**

**From:** Chin, Lee-Ying <Lee-Ying.Chin@aig.com>  
**Sent:** Monday, 23 April, 2018 12:00 PM  
**To:** 'assignments'  
**Subject:** FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLD8861R AND SKP6802Z ON 17 APRIL 2018

Fax3D57 (2) (2) - Windows Photo Viewer

File Print E-mail Burn Open

Catherine Chong  
From: Lee-Ying Chin  
Sent: Monday, 23 April 2018 12:00 PM  
To: 'assignments'  
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLD8861R AND SKP6802Z ON 17 APRIL 2018

The Motor Claims Department  
AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
Singapore 079120

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION  
ACCIDENT INVOLVING SKP6802Z & SLD8861R ON 17/04/2018 @1  
ALONG BEHIND 78 SHENTON WAY**

We refer to your fax of even date.

Please be informed that we are not agreeable to your proposed motor surveyor Alan Cheong K.H. of M/s. C L Appraiser Pte Ltd to conduct a Pre-Repair Inspection.

Please be informed that the said vehicle can be inspected at:

Name of workshop	:	M/s. Gforce Autotechnik Pte Ltd
Address	:	10 Kaki Bukit Road 2 #01-34 First East Centre, Singapore 417848
Contact person	:	Elle
Telephone number	:	63630123 / 91391448

Please be informed that if we do not hear from you within 2 working days, we will assume, as per the Protocol, that you have no objections to our above named surveyor being deemed to have agreed as a "single joint expert".

If you object to our motor surveyor, we will accordingly inform the claim Surveyor to conduct the pre-repair survey.

Yours faithfully,

  
C. Yogarajah LLC  
enc  
c.c. client  
Ong Li Ching Charlene

<b>For Surveyor</b> Please initial here Thank you.
<b>Name:</b>
<b>Signature:</b>

---

**From:** Chin, Lee-Ying

**Sent:** Monday, April 23, 2018 11:59 AM

**To:** 'assignments'

**Subject:** AIGENCRYPT - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLD8861R AND SKP680ZZ ON 17 APRIL 2018

Re-send

---

**From:** Chin, Lee-Ying

**Sent:** Monday, April 23, 2018 11:48 AM

**To:** 'assignments'; 'Admin A'

**Cc:** Fong, Andy-SY

**Subject:** AIGENCRYPT - FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLD8861R AND SKP680ZZ ON 17 APRIL 2018

Hi LKK,

Vehicle is in, please assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/04/2018 15:54
Date Of Accident	17/04/2018 11:35
Exact Location Of Accident	BEHIND 7B SHENTON WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP6802Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG LI CHING CHARLENE
NRIC No	S79108508
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93446206
Alternative Phone No	OFFICE-98446206

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA 1.4 TSI A/T ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099192529 CLASSIC
Cover Note Number	

### Driver

Name of Driver	ANDY SOH KOK HWEE (SU GUOHUI)
NRIC No	S7902476C
Date Of Birth	12/01/1978
Occupation	INDOOR
Date Of Driving Pass	17/03/1997
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96317344
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	27 ELIAS ROAD #04-14 RIS GRANDEUR
Postcode	519932
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD8861R
Vehicle Make/Model/Colour	MERCEDES BENZ C180
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the vehicle they covered the claim process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The **issue and acceptance** of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and the copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my work(s) and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal and/or personal information set out in this Form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for use or more of the above Purposes; and
- (c) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms, which may be located outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed
  - (i) to all Insurers and/or any other third parties may be used in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**UAC KAKI BUKIT (VAC)**  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: vac@singnet.com.sg

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Extension's Signature  
 Name:  
 NRIC/IN NO:

19 APR 2018

SKETCH PLAN



A: SKP6802Z  
 B: SLD8861R

Behind 78 Shenton Way

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17 April 2018 about 11:34am, I was waiting for my  
 passage behind 78 Shenton Way. Suddenly, I felt a hit  
 on my back of my car. I came out and saw the  
 vehicle CLD8861R hit my bumper and my bumper was damaged.

DECLARATION

(We declare the foregoing particulars true in every respect)

Policyholder's Signature  
 Date & Time

  
 Driver's Signature  
 I/Driver is/are the responsible party  
 Date & Time: 19 APR 2018

IDAC KAKI BUKIT (VAC)  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: vac@idac.com.sg

Reporting Case Handler's Signature  
 Name  
 Tel: 67416697

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0850B
Vehicle Details	
Vehicle No.:	SKP6802Z
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI A/T ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CAXE85017
Chassis No.:	WVWZZZ16ZEM059100
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,154.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$9,154.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$6,865.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,000.00
COE Rebate Amount:	\$39,852.00
<b>Total Rebate Amount:</b>	<b>\$46,717.00</b>

The information contained herein is correct as at 25 Apr 2018

OK



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2018 <a href="#">Edit Reg</a>		23 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>ASIA PACIFIC POWER PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>ONG LI CHING CHARLENE</b> , ID: S7910850B								
Vehicle Reg. No.:	<b>SKP6802Z</b>	Date of Loss:	17/04/2018 11:00 - :59 [42 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 6184156710SG</b>	Policy/Cover Note No.:	2100469098 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLD8861R</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Gforce Autotechnik Pte Ltd (HQ)</b> 10 Kaki Bukit Road 2, #01-34 First East Centre, 417866 Kaki Bukit - Tel: 6363 0123 / 9139 1448								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 07/05/2018]								
Claimant's Solicitor:	<b>C YOGARAJAH LLC</b> - Tel: 62925838								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
• AIG_SG (26/04/2018): <b>TP GIA REPORT</b>									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKP6802Z (6184156710SG)**  
**[SLD8861R]**  
**TP**  
**ONG LI CHING CHARLENE**  
**Apr 17 2018 11:00AM**  
**[ASIA PACIFIC POWER PTE LTD]**  
**Gforce Autotechnik Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			View	View in Browser ▼
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	25/04/18 15:20	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
25	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
26	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
27	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
28	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
29	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
30	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
31	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
32	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
33	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
34	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>
35	25/04/18 15:21	<b>Dismantled Parts</b>	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
36	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
37	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
38	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
39	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
40	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
41	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
42	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
43	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
44	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
45	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
46	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
47	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
48	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
49	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
50	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓
51	25/04/18 15:21	<b>Dismantled Parts</b>	1	Load JPG ✓

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18007412/GZ4BS2

Date: 07/05/2018

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100469098
Claimant Vehicle No :	SKP6802Z	Insured Vehicle No :	SLD8861R
Date of Loss:	17/04/2018	Nature of Claim:	TP
		Claim No:	6184156710SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SKP6802Z</b>	Engine No:	CAXE85017
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Chassis No:	WVWZZZ16ZEM059100
Reg. Date:	30/09/2014 (Man. Year: 2014)	Odometer:	117639 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	23/04/2018		
Date Inspected:	23/04/2018	Inspected At:	Gforce Autotechnik Pte Ltd (HQ) 10 Kaki Bukit Road 2, #01-34 First East Centre Singapore 417866
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Damaged	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER BRACKET INNER	Broken	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	Scratched	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F
7	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
10	1		*BOOTLID	Repair	0.00 F	*- F
11	1		*BOOTLID EMBLEM	Repair	0.00 F	*- F
12	1		*BOOTLID LAMP RH	Scratched	0.00 F	*- F
13	1		*BOOTLID LOCK	Dented	0.00 F	*- F
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >