

AS. REC. BY:

REF: CS3/ATG13007413/G244b52

Special Instruction:

Surveyor: Ma'mun

ASSIGNMENT (Office)

From (Person): Safina

of ALG

Date/Time: 23042018 11:45am

Estimated Cost: _____ Bill to: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFG 7000X

Insured: SKP 9697R

at Workshop m/s Safe Auto

Tel: 9199 3103

of Blk 1 Kaki Bukit Ave 6 #01-52

Policy No: 2100390066

Claim No: 195751717066

Sum Insured: _____

Excess: _____

Make of Veh: _____
(Client's Record)

D.O.A. 18042018

CA / REV / REP. / REV 24 HRS 'w.p.'

H.O.D. Endorsement: _____

Date/Time: 23042018 12:04pm

Person Contacted: _____

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SFG 7000X - N/A / ENCO 9012720 / 121 SKP 9697R - X .
24/4/18	Dismantled

DA: 0710609

PRS
XMR

REF: AIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Safe Auto
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$7K.
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFG 7000X Yr Regn: 31 Jun 2013
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Volvo S60 T4 cc 1596
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 91958 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YV1FS48HBD2233341
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD / Rim or _____
 Tyre Size: F: 215/50ZR17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 23-04-18
 Survey held at w/s \$pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/4/18	Submit DAR Report
RECEIVED 30 APR 2018	

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$ _____))
 Interview (\$ _____))
 Tech. Invs (\$ _____))
 Weekend (\$ _____))

Survey Fee: _____
 Transportation: _____
) S - RS)
) Photos)
) Others)
)
) TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Apr 2018		23 Apr 2018 11:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	Htun Stanley Steven, ID: A488716364, Tel: +6598933385								
Main Claimant:	HO SEE KHEONG, ID: 56901176D								
Vehicle Reg. No.:	SFG7000X	Date of Loss:	18/04/2018 00:00 - :59 [56 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1957517170SG	Policy/Cover Note No.:	2100390066 (Comprehensive) Coverage: 28/10/2017 - 27/10/2018						
Vehicle Reg. No. (Insured):	SKP9697R	Policy No. (Claimant):	Excess:						
Repairer:	Safe Auto (KAKI BUKIT) 1 KAKI BUKIT AVENUE 6, AUTOBAY, # 01-52, 417883 Kaki Bukit - Tel: 91993103								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/05/2018]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS									
				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/04/2018 10:24
Date Of Accident	18/04/2018 23:05
Exact Location Of Accident	SLIP ROAD AT BRADDELL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFG7000X
Insured/Policyholder	
Name Of Registered Owner	HO SEE KHEONG
NRIC No	S6901176D
Email Address	HOEUGENE99@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92217682
Alternative Phone No	OTHERS-92217682

Vehicle Particulars

Manufacturer	VOLVO
Model	S60
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3051591702
Cover Note Number	

Driver

Name of Driver	HO SEE KHEONG
NRIC No	S6901176D
Date Of Birth	07/01/1969
Occupation	INDOOR
Date Of Driving Pass	02/04/1990
Driving Experience	28 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92217682
Fax Number	
Contact Number	OTHERS-92217682
Email Address	HOEUGENE99@GMAIL.COM

Address	BLK 412 PANDAN GARDENS #15-106
Postcode	600412
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HO EUGENE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP9697R
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 19 APR 2013
10:24 AM

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/FIN No.: S6840583A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/4/18 at 2309H, I stopped my car SFG7000X in front of the traffic light towards Braddell Road (to Bantley Road direction). Suddenly, the car (SKP9697R) hit very hard to the rear of my vehicle. The driver, Liu Bowen, S8875388G, Hp. 97707690, came forward to apologize to me. Liu Bowen asked me to settle with his insurance. There were scratches and slight dent at my rear car bumper

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

19/4/18

CONFIDENTIAL INFORMATION

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

Poh Kwee Choo

NRIC/FIN No.:

S6840583A

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1176D
Vehicle Details	
Vehicle No.:	SFG7000X
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	VOLVO
Vehicle Model:	S60 T4
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	B4164T1139738
Chassis No.:	YV1FS48HBD2233341
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$32,446.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$32,425.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2023
PARF Rebate Amount:	\$24,318.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,802.00
COE Rebate Amount:	\$38,943.00
Total Rebate Amount:	\$63,261.00

The information contained herein is correct as at 25 Apr 2018

OK

▶ volvo s60 Used Vehicle List (10 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Volvo S60 T4	\$81,800	\$11,820 /yr	12-Nov-2013	1,596 cc	99,749 km	Motor-East Pte Ltd	Availat
High COE At \$72609, No Gimmicks! Down Payment \$8180 With Monthly \$1403, Full Wearnes Service Record, 1 Owner, GPS, City Safety Drive System, Keyless Entry/Start, Rear Knockdown Seat, Dark Grey In Colo... Office No. - 67772200 Henry Ong - 98516566 John Toh - 92717577 Cynthia Tian - 91193219 Vincent Lim - 86872202							
Volvo S60 T4	\$79,800	\$11,740 /yr	24-Sep-2013	1,596 cc	75,000 km	Faster Auto Trading	Availat
Facelifted Model,1 Owner,Low Mileage Done,Full Serviced Histories With Agent,Depisit \$10,000,Interest At 2.98%,Monthly\$1,232,Ex-Bankruptcy And Bad Credit Welcome. Office No. - 64761970 Thomas - 96645002							
Volvo S60 T4	\$82,999	\$12,340 /yr	23-Sep-2013	1,596 cc	36,000 km	Premium Automobiles	Availat
Mileage Only 34,000Km Done! 1 Owner, Agent Serviced, Flexible Financial Package Can Be Arranged And Trade In, Please SMS Or Call For Viewing And Details. Office No. - 68366223 Joime Lee - 81110548 Ricky Tan - 98449488							
Volvo S60 T4	\$79,800	\$11,810 /yr	13-Sep-2013	1,596 cc	97,353 km	Motor-East Pte Ltd	Availat
High COE Value At \$76223, No Gimmicks! Down Payment \$7980 With Monthly \$1402, Full Wearnes Service Record, 1 Owner, GPS, City Safety Drive Syst Keyless Entry/Start, Reverse Camera, Rear Knockdown S... Office No. - 67772200 Vincent Lim - 86872202 Alvin Neo - 81886100 Henry Ong - 98516566 John Toh - 92717577							
Volvo S60 T4	\$78,500	\$11,660 /yr	28-Aug-2013	1,596 cc	75,000 km	Marquee Kars	Availat
Wearnes Automotive Maintained,Facelift Model, Digital Instrument Panel, Well Maintained, Sincere Pricing, Dropby To View Now. Office No. - 64754484 Johnson Lim - 97994327 Patrick - 98593180							
Volvo S60 Diesel D2 (Diesel - Euro 5 Engine and Above)	\$68,800	\$11,140 /yr	26-Jun-2013	1,560 cc	77,000 km	Highline Automotive	Availat
Drive E Model With Higher 154 BHP. 1 Owner! Genuine Low Mileage! Fully Agent Maintained. Superb Fuel Consumption. Stylish S60 Where Performance, Comfort And Safety Gel Together Perfectly! Equipped Wit... Office No. - 67778887 Harris Tan - 96881515 Brayann Chong - 97109695 JC Chua - 93666111							
Volvo S60 T4	\$75,800	\$11,690 /yr	30-May-2013	1,596 cc	109,000 km	Hua Yang Credit Pte Ltd	Availat
Up To 100% Loan With Our In House Financing Today!(optional) Hua Yang Group Since 1984' All Our Cars Went Through Technical/Optical Check (STA) Your Added Assurance, Trade In/Over Trade Welcome, R... Office No. - 64677118 George Yep - 88088825 Patrick - 96357438							
Volvo S60 T4	\$71,800	\$10,970 /yr	30-May-2013	1,596 cc	122,000 km	Hua Yang Credit Pte Ltd	Availat
Accelerate Your Passion! High Loan Up To 90% Available. Minimum Cash Upfront Drive Away. More Flexible Loan Packages Available To Choose From. Lc Mileage. High Trade-in Value For Your Car! No Hidden ... Office No. - 64633732 Christy - 87500597 Gen - 81001413							
Volvo S60 T4	\$73,500	\$11,320 /yr	28-May-2013	1,596 cc	140,500 km	Edmund Motor Pte Ltd	Availat
Accelerate Your Passion! Interest Rates 2.18% High Loan Up To 90% Available. Minimum Cash Upfront Drive Away. More Flexible Loan Packages Availab To Choose From. Low Mileage. High Trade-in Value For... Office No. - 67893339							

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Apr 2018		23 Apr 2018 11:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Htun Stanley Steven , ID: A488716364, Tel: +6598933385								
Main Claimant:	HO SEE KHEONG , ID: S6901176D								
Vehicle Reg. No.:	SFG7000X	Date of Loss: 18/04/2018 00:00 - :59 [56 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 1957517170SG	Policy/Cover Note No.: 2100390066 (Comprehensive) Coverage: 28/10/2017 - 27/10/2018							
Vehicle Reg. No. (Insured):	SKP9697R	Policy No. (Claimant): Excess:							
Repairer:	Safe Auto (KAKI BUKIT) 1 KAKI BUKIT AVENUE 6, AUTOBAY, # 01-52, 417883 Kaki Bukit - Tel: 91993103								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/05/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFG7000X (1957517170SG)
[SKP9697R]**

TP

HO SEE KHEONG

Apr 18 2018 12:00AM

[Htun Stanley Steven]

Safe Auto

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input checked="" type="checkbox"/>
1	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
2	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
3	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
4	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
5	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
6	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
7	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
8	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
9	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
10	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
11	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
12	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
13	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
14	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
15	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
16	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
17	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
18	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
19	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
20	25/04/18 15:25	General View	<input checked="" type="checkbox"/> Load JPG
21	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
22	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
23	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
24	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
25	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
26	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
27	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
28	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
29	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
30	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
31	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
32	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
33	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG
34	25/04/18 15:26	Dismantled Parts	<input checked="" type="checkbox"/> Load JPG

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18007413/GZ4BS2

Date: 07/05/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100390066
Claimant Vehicle No :	SFG7000X	Insured Vehicle No :	SKP9697R
Date of Loss:	18/04/2018	Nature of Claim:	TP
		Claim No:	1957517170SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFG7000X	Engine No:	B4164T1139738
Make & Model:	VOLVO S60, 1.6 T4 (A)	Chassis No:	YV1FS48HBD2233341
Reg. Date:	31/07/2013 (Man. Year: 2013)	Odometer:	91958 km
Colour:	Silver		
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50ZR17	Rear Tyre Size:	215/50ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/04/2018		
Date Inspected:	23/04/2018	Inspected At:	Safe Auto (KAKI BUKIT) 1 KAKI BUKIT AVENUE 6, AUTOBAY , # 01-52 Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER BEAM	Repair	0.00 F	*- F
4	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
5	1		*REAR END PANEL WEATHERSTRIP	Deformed	0.00 F	*- F
6	1		*BOOTLID LOCK	Damaged	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >