

12/03/2012

ASS. REC. BY:

REF: CS/CTU8007421/Tlvb 32 Special Instruction:

Survivor:

Maimed:

From (Person):

Taufik

Chung Boon Sen

ASSIGNMENT (Office)

of CTL

Date/Time: 20/04/2018 5:58 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 8365P

Insured:

XD 1584U

at Workshop m/s

Zenith Engineering

Tel:

9107 9212.

of

No. 34 Joo Koon Circle

Policy No:

DMCV3N1753131700

Claim No:

SNM18002016C02

Sum Insured:

Excess:

D.O.A.

18/04/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Up'

Date/Time: 20/04/2018 5pm

Person Contacted:

Mr Ong / Marcus H.O.D. Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	XD 8365P - X
	XD 1584U - NJN / INC10021662 / y1
25/9/18	Taufik explaint to Simon
27/9/18	LS \$ 10,400 confirmed by email (Reel 1200, 10/9)

9670
6443

DCA: 2710-10

Signature
merimen

Taufik

REF: CTL

ASSIGNMENT

From: Date: 23042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: XD 8365P
at Workshop m/s Zenith Engineering
of No. 34 Joo Koon Circle

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: #230pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS Wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

XD 8365P Yr Regn: 2013, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLVO FEE300 C.C 7146

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

226562

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

YU2VH70D6E13670616

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

295/55R22.5

R:

2 1 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenza

Front

R/Bal.

8

mm

Rear

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

D.O.I.

23/4/18

Survey held at

Zenith Eng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufik

pls see my remarks

RECEIVED 27 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

27/9- typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Days Of Repair: 15

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

: S + RS, SI

: Photos

: Others

TOTAL

Report Format: merimen

Lump Sum / I.B.I: (\$ 10,400/-)

2201

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Apr 2018		20 Apr 2018 14:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		LEE HARDWARE & BUILDING MATERIALS P/L, Co. Reg. No.: 201526812G							
Main Claimant:		SEMBWASTE PTE LTD, Co. Reg. No.: 199507280G							
Vehicle Reg. No.:		XD8365P	Date of Loss:	18/04/2018 11:00 - :59					
Claim Type:		TP / SNM18D02016C02	Policy/Cover Note No.:	DMCVSN1753131700 (Comprehensive)					
Vehicle Reg. No. (Insured):		XD1584U	Policy No. (Claimant):	5088412823-01					
		Excess:	S\$0.00						
Repairer:		Zenith Engineering Pte Ltd (HQ) NO 34 JOO KOON CIRCLE, 629060 Jurong West - Tel:							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/05/2018]							
Driver/Custodian (Insured):		YONG KAM YUNG (39 / Male), NRIC: S7888217D, Tel: +6594475585							
Adj Asg. Remarks:		QUOTATION PRICE \$12,412.00 , CASE WITH SJE.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Admin-D (LKKAUTO)
Sent: Monday, 9 July 2018 4:13 PM
To: 'Claims Dept of CTI'; assignments; SUR
Cc: 'Chong Boon Sen'; 'Alfred Toh'; 'Chee So Chow'
Subject: RE: TP SURVEY REPORT - XD8365P (SNM18D02016C02/4 - XD1584U)

Dear Alfred,

Thank you for your email.

Dear Veron,

FYNA. Our Ref: CS/CTI18007421/T1vb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept of CTI [mailto:claimsdept@sg.cntaiping.com]

Sent: Monday, 9 July, 2018 4:02 PM

To: 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: TP SURVEY REPORT - XD8365P (SNM18D02016C02/4 - XD1584U)

Dear Ms Catherine Chong

We refer to the above matter.

Please assist to notify attending surveyor to **upload the survey report and bill for services rendered in Merimen** to enable us to negotiate claim with the third party.

Best Regards

Alfred Toh

Senior Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: +65 6389 6183

FAX: +65 6224 7478/6224 7175

Email: claimsdept@sg.cntaiping.com

alfred.toh@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/04/2018 00:29
Date Of Accident	18/04/2018 11:30
Exact Location Of Accident	TPE TWDS SLE BEF JLN KAYU EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD8365P
Insured/Policyholder	
Name Of Registered Owner	SEMBWASTE PTE LTD
Co Reg No	199507280G
Email Address	MOHAMAD.RANI@SEMBCORP.COM
Mobile Phone No	(LOCAL) +65-83465098
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	VOLVO
Model	YV2VH70D6EB670616
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5088412823-01
Cover Note Number	

Driver

Name of Driver	LEOW KEAN CHUN
NRIC No	S2576292D
Date Of Birth	24/08/1956
Occupation	OUTDOOR
Date Of Driving Pass	26/02/1982
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83465098
Fax Number	
Contact Number	
Email Address	MOHAMAD.RANI@SEMBCORP.COM

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



A - X0836SP

B - X015844

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight on lane 3 on TPE towards BLE before Jalan Kaya exit when the bus ahead of me came to a stop. It then backed to a stop and suddenly X015844 collided to the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 18/04/18 1730hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time: 18/04/18 1730hrs

Reporting Centre Personnel's Signature


Name: Mohd Yusoff

NRIC/FIN No: 587039920

Accident Photo



Accident Photo



Accident Photo



XD8365P - Damages



Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.:	199507280G
Owner ID Type:	Company
Owner Name:	SEMBWASTE PTE. LTD.
Registered Address:	30 HILL STREET #05-04 SINGAPORE 179360
Mailing Address:	-
Birth Date:	-

Vehicle Particulars

Vehicle No.:	XD8365P
Previous Vehicle No.:	-
Effective Date of Ownership:	18 Dec 2013
Original Regn Date:	18 Dec 2013
Registration Date:	18 Dec 2013
Year of Manufacture:	2013
Vehicle Type:	Goods (Open) Garbage/Sanitary Wagon
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	VOLVO
Vehicle Model:	FEE300 64R DC AUTO
Primary Colour:	White
Secondary Colour:	-
Passenger Capacity:	2
Chassis No.:	YV2VH70D6EB670616
Engine No.:	11494895
Engine Capacity / Power Rating:	7146 cc / -
Maximum Power Output:	-
Propellant:	Diesel
Max Unladen Weight:	14660 kg
Maximum Laden Weight:	28000 kg
Open Market Value:	\$123,637.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	0
IU Label No.:	2010460828
COE No.:	2013121805000585H
COE Expiry Date:	17 Dec 2023
COE Category:	C - Goods Vehicle & Bus
COE Registration Category:	C - Goods Vehicle & Bus
Quota Premium (QP) / Prevailing Quota Premium:	- / \$67,470.00
PQP Paid:	\$24,487.00
QP (Regn Cat):	--
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$0.00
Additional Registration Fee Rate:	5.00 %
Actual ARF Paid:	\$6,182.00
Vehicle Lifespan Expiry Date:	17 Dec 2033
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	The vehicle is registered under Early Turnover Scheme.

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5088412823-01

Cover : Preferred Workshop Plan

- | | |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle | : XD8365P |
| Chassis Number | : YV2VH70D6EB670616 |
| 2. Name of Policyholder | : SEMBWASTE PTE LTD |
| 3. Effective Date of Insurance | : 05 May 2017 |
| 4. Expiry Date of Insurance | : 04 May 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business. | |

This Policy does not cover:

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$5,000
EXCESS (SECTION 2)	: S\$2,500
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : JARDINE LLOYD THOMPSON PTE LTD (00000690216)
Date of Issue : 04 May 2017 15:00 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive



ZENITH ENGINEERING PTE LTD

34 Joo Koon Circle, Singapore 629060
Tel: (65) 6861 1100 Fax: (65) 6862 1948
Email: info@ze.com.sg Website: www.ze.com.sg
CO No: 197904024Z GST Reg No: M2-0037093-7

QUOTATION
NO: QU18-L0374-R00

Customer : SembWaste Pte Ltd
4543 Jalan Bukit Merah
Singapore 159470

Attn : Mr Mohamad Azman
Tel : 62723821 Fax : 62271443

Date : 19/04/18
Validity : 19/05/18
Account No : SE04
Currency : Singapore Dollar
Page : Page 1 of 1

No.	Description	Qty	UOM	Unit Price S\$	Amount S\$
Re: Replacement of new binlifter Assy for RCV XD8365P caused by accident					
1	Supply labour and material for the repair of RCV XD8365P as follows removing of damaged binlifter Assy, forming & welding, fabrication of sub assembly, retrofitting new bin lifter onto the RCV and testing and painting of Binlifter assembly of affected area of repair.	1	EA	11,600.00	11,600.00

TERMS & CONDITIONS

Payment : Thirty Days Only

Validity : 30 days from the date of this quotation

PK/ak

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Net Amount	:	11,600.00
Add 7% GST	:	812.00
Total Amount	:	12,412.00

Ong Poh Kiat
Head of Service Department
68611100



Confirmed & Accepted By:
SembWaste Pte Ltd
Name:
Title:
Date:
Company Stamp:

Veron Chen (LKKAUTO)

From: Siew York <siewyork@ze.com.sg>
Sent: Thursday, 27 September 2018 11:27 AM
To: 'Yong Hooi Ying'
Cc: Ong Poh Kiat; 'Marcus Chen'; Veron Chen (LKKAUTO); 'Rachel Kwan'; 'May Lee'
Subject: FW: XD 8365P-DOA: 18/4/2018

Dear Hooi Ying ,

Please assist us on this email below.

SO No:SO18-L0269
Job No :SR00563

Best regards

Siew York

 **Zentith Engineering Pte Ltd**

34 Joo Koon Circle, Jurong Town
Singapore 629060
T: +65 68611100 | F: +65 68621948
E: info@ze.com.sg | W: www.ze.com.sg

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 27 September, 2018 11:23 AM
To: Siew York <siewyork@ze.com.sg>
Cc: SUR <sur@lkkauto.com>; 'Marcus Chen' <marcuschen@ze.com.sg>; pohkiat@ze.com.sg
Subject: RE: XD 8365P-DOA: 18/4/2018

Dear Siew York,

Noted with thanks.

Kindly send Final invoice and all supporting documents to CHINA TAIPING INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Siew York <siewyork@ze.com.sg>
Sent: Thursday, 27 September 2018 11:09 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Marcus Chen' <marcuschen@ze.com.sg>; pohkiat@ze.com.sg
Subject: RE: XD 8365P-DOA: 18/4/2018

Dear Veron ,

Yes confirm , this is the correct amount.

Best regards

Siew York

 **Engineering Pte Ltd**

34 Joo Koon Circle, Jurong Town

Singapore 629060

T: +65 68611100 | F: +65 68621948

E: info@ze.com.sg | W: www.ze.com.sg

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Thursday, 27 September, 2018 11:08 AM

To: info@ze.com.sg; pohkiat@ze.com.sg

Cc: SUR <sur@lkkauto.com>; siewyork@ze.com.sg

Subject: RE: XD 8365P-DOA: 18/4/2018

Dear Mr Ong,

Re-forward.

WITHOUT PREJUDICE

Offer Lump Sum \$10,400 @ 15 working days

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 25 September 2018 11:59 AM

To: 'info@ze.com.sg' <info@ze.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: XD 8365P-DOA: 18/4/2018

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$10,400 @ 15 working days

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 27 September 2018 11:23 AM
To: 'Siew York'
Cc: SUR; 'Marcus Chen'; pohkiat@ze.com.sg
Subject: RE: XD 8365P-DOA: 18/4/2018

Dear Siew York,

Noted with thanks.

Kindly send Final invoice and all supporting documents to CHINA TAIPING INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Siew York <siewyork@ze.com.sg>
Sent: Thursday, 27 September 2018 11:09 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Marcus Chen' <marcuschen@ze.com.sg>; pohkiat@ze.com.sg
Subject: RE: XD 8365P-DOA: 18/4/2018

Dear Veron ,

Yes confirm , this is the correct amount.

Best regards

Siew York



Engineering Pte Ltd

34 Joo Koon Circle, Jurong Town
Singapore 629060

T: +65 68611100 | F: +65 68621948

E: info@ze.com.sg | W: www.ze.com.sg

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 27 September, 2018 11:08 AM
To: info@ze.com.sg; pohkiat@ze.com.sg
Cc: SUR <sur@lkkauto.com>; siewyork@ze.com.sg
Subject: RE: XD 8365P-DOA: 18/4/2018

Dear Mr Ong,

Re-forward.

WITHOUT PREJUDICE

Offer Lump Sum \$10,400 @ 15 working days

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 25 September 2018 11:59 AM

To: 'info@ze.com.sg' <info@ze.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: XD 8365P-DOA: 18/4/2018

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$10,400 @ 15 working days

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Apr 2018		20 Apr 2018 14:58 Edit Adj Rpt	S\$10,400.00 Edit Estimates	S\$10,400.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE HARDWARE & BUILDING MATERIALS P/L, Co. Reg. No.: 201526812G		
Main Claimant:	SEMBWASTE PTE LTD, Co. Reg. No.: 199507280G		
Vehicle Reg. No.:	XD8365P	Date of Loss:	18/04/2018 11:00 - :59 [52 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02016C02	Policy/Cover Note No.:	DMCVSN1753131700 (Comprehensive)
Vehicle Reg. No. (Insured):	XD1584U	Policy No. (Claimant):	5088412823-01
		Excess:	S\$0.00
Repairer:	Zenith Engineering Pte Ltd (HQ) NO 34 JOO KOON CIRCLE, 629060 Jurong West - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/05/2018]		
Driver/Custodian (Insured):	YONG KAM YUNG (39 / Male), NRIC: S7888217D, Tel: +6594475585		
Adj Asg. Remarks:	QUOTATION PRICE \$12,412.00 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPIING (09/07/2018): Alert - Adj Mandate Approved (S\$0.00) - XD8365P - Claim Handler: Chong Boon Sen

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***XD8365P (SNM18D02016C02)**
[XD1584U]

TP

SEMBWASTE PTE LTD

Apr 18 2018 11:00AM

[LEE HARDWARE & BUILDING MATERIALS P/L]

Zenith Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:38	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:36	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	19/04/18 00:36	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	19/04/18 00:36	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	19/04/18 00:36	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	19/04/18 00:36	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	19/04/18 00:36	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	19/04/18 00:36	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/18 11:46	General View	Load PDF	
2	25/09/18 11:46	Reinspection Photo (1)	Load PDF	
3	25/09/18 11:46	Reinspection Photo (2)	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/04/18 14:49	PRS	Load PDF	
2	20/04/18 14:50	OI GIA REPORT	Load PDF	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:36	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	19/04/18 00:36	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:38	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:36	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	19/04/18 00:36	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	19/04/18 00:36	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	✓
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
4	19/04/18 00:36	Accident Photo	 Load JPG	✓
5	19/04/18 00:36	Accident Photo	 Load JPG	✓
6	19/04/18 00:36	Accident Photo	 Load JPG	✓
7	19/04/18 00:36	Accident Photo	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:36	Sketch Plan	 Load JPG	✓
2	19/04/18 00:36	Sketch Plan #2	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007421/T1VBS2

Date: 03/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1753131700

Claimant Vehicle No: XD8365P Insured Vehicle No: XD1584U

Date of Loss: 18/04/2018 Nature of Claim: TP Claim No: SNM18D02016C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD8365P

Make & Model: VOLVO UD TRUCKS, 7.0 D with Hood (Normal) (M) Engine No: 11494895

Reg. Date: 18/12/2013 (Man. Year: 2013) Chassis No: YV2VH70D6EB670616

Colour: White Odometer: 226562 km

Engine Capacity: 7146 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5(D)

Front Left Side: Firenza 8 mm Rear Left Side: Firenza 8/8 mm

Front Right Side: Firenza 8 mm Rear Right Side: Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,600.00	10,400.00	1,200.00	10.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,600.00	10,400.00	1,200.00	10.34
+ GST 7.00/7.00% (S\$)	812.00	728.00	84.00	10.34
Nett Amount (S\$)	12,412.00	11,128.00	1,284.00	10.34

INSPECTION

Date of Assignment: 20/04/2018

Date Inspected: 23/04/2018 Inspected At: Zenith Engineering Pte Ltd (HQ)
NO 34 JOO KOON CIRCLE
Singapore 629060

Estimated Period of Repair: 15.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 Oct 2018)

Parts: N/A VOLVO UD TRUCKS 7.0 D with Hood (Normal) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD8365P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY LABOUR AND MATERIAL FOR THE REPAIR.	New	11,600.00	10,400.00
Gross Labour Cost (\$\$)			11,600.00	10,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >