

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2018 15:35
Date Of Accident	20/04/2018 08:05
Exact Location Of Accident	B4 JUNC OF SEMBAWANG RD & YISHUN AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX8422T
Insured/Policyholder	
Name Of Registered Owner	MDM TAN CHIN NA REGINA
NRIC No	S8028308C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96808422
Alternative Phone No	OTHERS-96808422

Vehicle Particulars

Manufacturer	VOLVO
Model	XC60
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1527511702
Cover Note Number	

Driver

Name of Driver	ZHANG MUTONG,EDMUND
NRIC No	S8301173D
Date Of Birth	10/01/1983
Occupation	OUTDOOR
Date Of Driving Pass	12/05/2004
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83331173
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 686 HOUGANG ST 61 #07-172
Postcode	530686
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC119G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Individual Statement



On 20/04/2018 at about 0805 hrs before Junction of Sembawang Road and Yishun Ave 5. I was travelling on the 2nd lane from the Right along Sembawang Road towards Gambas Ave and when coming towards the above mentioned Junction, I checked that my left lane was cleared as such I switched my lane. While I was ^{on the 3rd lane}, a Vehicle (B) on the extreme left lane made a reckless switching of lane and encroached into my lane without cautious and hence collided onto my left front portion of my Vehicle (A) causing damages to my Vehicle.

(A) SJX 8422 T
(B) SHC 119 G

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Identification Card



SJX8422T
DRIVER



Driving License



SIX 8477
DRIVE-12

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Genus	<i>Herposiphonia</i> Griseb.	2000, 2002
Class	Males: 60–100 mm; 100–150 mm; 150–200 mm; 200–250 mm; 250–300 mm; 300–350 mm; 350–400 mm; 400–450 mm; 450–500 mm; 500–550 mm; 550–600 mm; 600–650 mm; 650–700 mm; 700–750 mm; 750–800 mm; 800–850 mm; 850–900 mm; 900–950 mm; 950–1000 mm; 1000–1050 mm; 1050–1100 mm; 1100–1150 mm; 1150–1200 mm; 1200–1250 mm; 1250–1300 mm; 1300–1350 mm; 1350–1400 mm; 1400–1450 mm; 1450–1500 mm; 1500–1550 mm; 1550–1600 mm; 1600–1650 mm; 1650–1700 mm; 1700–1750 mm; 1750–1800 mm; 1800–1850 mm; 1850–1900 mm; 1900–1950 mm; 1950–2000 mm; 2000–2050 mm; 2050–2100 mm; 2100–2150 mm; 2150–2200 mm; 2200–2250 mm; 2250–2300 mm; 2300–2350 mm; 2350–2400 mm; 2400–2450 mm; 2450–2500 mm; 2500–2550 mm; 2550–2600 mm; 2600–2650 mm; 2650–2700 mm; 2700–2750 mm; 2750–2800 mm; 2800–2850 mm; 2850–2900 mm; 2900–2950 mm; 2950–3000 mm; 3000–3050 mm; 3050–3100 mm; 3100–3150 mm; 3150–3200 mm; 3200–3250 mm; 3250–3300 mm; 3300–3350 mm; 3350–3400 mm; 3400–3450 mm; 3450–3500 mm; 3500–3550 mm; 3550–3600 mm; 3600–3650 mm; 3650–3700 mm; 3700–3750 mm; 3750–3800 mm; 3800–3850 mm; 3850–3900 mm; 3900–3950 mm; 3950–4000 mm; 4000–4050 mm; 4050–4100 mm; 4100–4150 mm; 4150–4200 mm; 4200–4250 mm; 4250–4300 mm; 4300–4350 mm; 4350–4400 mm; 4400–4450 mm; 4450–4500 mm; 4500–4550 mm; 4550–4600 mm; 4600–4650 mm; 4650–4700 mm; 4700–4750 mm; 4750–4800 mm; 4800–4850 mm; 4850–4900 mm; 4900–4950 mm; 4950–5000 mm; 5000–5050 mm; 5050–5100 mm; 5100–5150 mm; 5150–5200 mm; 5200–5250 mm; 5250–5300 mm; 5300–5350 mm; 5350–5400 mm; 5400–5450 mm; 5450–5500 mm; 5500–5550 mm; 5550–5600 mm; 5600–5650 mm; 5650–5700 mm; 5700–5750 mm; 5750–5800 mm; 5800–5850 mm; 5850–5900 mm; 5900–5950 mm; 5950–6000 mm; 6000–6050 mm; 6050–6100 mm; 6100–6150 mm; 6150–6200 mm; 6200–6250 mm; 6250–6300 mm; 6300–6350 mm; 6350–6400 mm; 6400–6450 mm; 6450–6500 mm; 6500–6550 mm; 6550–6600 mm; 6600–6650 mm; 6650–6700 mm; 6700–6750 mm; 6750–6800 mm; 6800–6850 mm; 6850–6900 mm; 6900–6950 mm; 6950–7000 mm; 7000–7050 mm; 7050–7100 mm; 7100–7150 mm; 7150–7200 mm; 7200–7250 mm; 7250–7300 mm; 7300–7350 mm; 7350–7400 mm; 7400–7450 mm; 7450–7500 mm; 7500–7550 mm; 7550–7600 mm; 7600–7650 mm; 7650–7700 mm; 7700–7750 mm; 7750–7800 mm; 7800–7850 mm; 7850–7900 mm; 7900–7950 mm; 7950–8000 mm; 8000–8050 mm; 8050–8100 mm; 8100–8150 mm; 8150–8200 mm; 8200–8250 mm; 8250–8300 mm; 8300–8350 mm; 8350–8400 mm; 8400–8450 mm; 8450–8500 mm; 8500–8550 mm; 8550–8600 mm; 8600–8650 mm; 8650–8700 mm; 8700–8750 mm; 8750–8800 mm; 8800–8850 mm; 8850–8900 mm; 8900–8950 mm; 8950–9000 mm; 9000–9050 mm; 9050–9100 mm; 9100–9150 mm; 9150–9200 mm; 9200–9250 mm; 9250–9300 mm; 9300–9350 mm; 9350–9400 mm; 9400–9450 mm; 9450–9500 mm; 9500–9550 mm; 9550–9600 mm; 9600–9650 mm; 9650–9700 mm; 9700–9750 mm; 9750–9800 mm; 9800–9850 mm; 9850–9900 mm; 9900–9950 mm; 9950–10000 mm; 10000–10050 mm; 10050–10100 mm; 10100–10150 mm; 10150–10200 mm; 10200–10250 mm; 10250–10300 mm; 10300–10350 mm; 10350–10400 mm; 10400–10450 mm; 10450–10500 mm; 10500–10550 mm; 10550–10600 mm; 10600–10650 mm; 10650–10700 mm; 10700–10750 mm; 10750–10800 mm; 10800–10850 mm; 10850–10900 mm; 10900–10950 mm; 10950–11000 mm; 11000–11050 mm; 11050–11100 mm; 11100–11150 mm; 11150–11200 mm; 11200–11250 mm; 11250–11300 mm; 11300–11350 mm; 11350–11400 mm; 11400–11450 mm; 11450–11500 mm; 11500–11550 mm; 11550–11600 mm; 11600–11650 mm; 11650–11700 mm; 11700–11750 mm; 11750–11800 mm; 11800–11850 mm; 11850–11900 mm; 11900–11950 mm; 11950–12000 mm; 12000–12050 mm; 12050–12100 mm; 12100–12150 mm; 12150–12200 mm; 12200–12250 mm; 12250–12300 mm; 12300–12350 mm; 12350–12400 mm; 12400–12450 mm; 12450–12500 mm; 12500–12550 mm; 12550–12600 mm; 12600–12650 mm; 12650–12700 mm; 12700–12750 mm; 12750–12800 mm; 12800–12850 mm; 12850–12900 mm; 12900–12950 mm; 12950–13000 mm; 13000–13050 mm; 13050–13100 mm; 13100–13150 mm; 13150–13200 mm; 13200–13250 mm; 13250–13300 mm; 13300–13350 mm; 13350–13400 mm; 13400–13450 mm; 13450–13500 mm; 13500–13550 mm; 13550–13600 mm; 13600–13650 mm; 13650–13700 mm; 13700–13750 mm; 13750–13800 mm; 13800–13850 mm; 13850–13900 mm; 13900–13950 mm; 13950–14000 mm; 14000–14050 mm; 14050–14100 mm; 14100–14150 mm; 14150–14200 mm; 14200–14250 mm; 14250–14300 mm; 14300–14350 mm; 14350–14400 mm; 14400–14450 mm; 14450–14500 mm; 14500–14550 mm; 14550–14600 mm; 14600–14650 mm; 14650–14700 mm; 14700–14750 mm; 14750–14800 mm; 14800–14850 mm; 14850–14900 mm; 14900–14950 mm; 14950–15000 mm; 15000–15050 mm; 15050–15100 mm; 15100–15150 mm; 15150–15200 mm; 15200–15250 mm; 15250–15300 mm; 15300–15350 mm; 15350–15400 mm; 15400–15450 mm; 15450–15500 mm; 15500–15550 mm; 15550–15600 mm; 15600–15650 mm; 15650–15700 mm; 15700–15750 mm; 15750–15800 mm; 15800–15850 mm; 15850–15900 mm; 15900–15950 mm; 15950–160	

