

S. REC. BY:

REF:

CS/msh18007447/R193b

Special Instruction:

Surveyor

Muhimen

Rgsw

## ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

msh

Date/Time:

23/04/2018 2:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 6883R

Insured:

SJP 7026C

at Workshop m/s

Borneo Motor

Tel:

9847 6171

of

2 Pandan Crescent

Policy No:

A2871 26509MA

Claim No:

553957

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/03/2018

CA / REV / REP. / REV 24 HRS wpr

25/04/2018 @ 9am - 12pm

H.O.D. Endorsement:

Date/Time:

23/04/2018

11:40pm

Person Contacted:

Thomas

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJR 6883R - x

SJP 7026C - x

30/04/18

@ 13:47 p.m. revised to Catherine Thia Shi Y. via memo.

Signature  
[Signature]

REF: MSLH

30308

# ASSIGNMENT

From: Date: 25042018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJR 6883R

at Workshop n/s Borneo motor

of 2 Pandan Crescent

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh: Thomas

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJR 6883R Yr Regn: 2009 / July

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA VIOS 1.5 A C.C: 1497

Colour: GREEN A/C: Insured / Std / NI / NA

Sp.Reading: 226044 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053HY9305120229

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 28/03/18 D.O.I. 28/04/18

Survey held at Borneo motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Pgmt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$2,717.01 / 3 days

C \$1,624.29 Red - 3% ?

RECEIVED 27 JUN 2018

Date/Time, File Pass to?

24/06/18

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RE \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 2,717.01 P/P )

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018		23 Apr 2018 14:56 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:		SURESH S/O ARUMUGASAMY, ID: S87050128							
Main Claimant:		GOH HWEE CHIT, ID: S17030308							
Vehicle Reg. No.:		SJR6883R	Date of Loss:	28/03/2018 20:00 - :59 [104 Months and 21 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 553957	Policy/Cover Note No.:	A28712650SMA (TP, Fire & Theft) Coverage: 01/04/2017 - 31/03/2018					
Vehicle Reg. No. (Insured):		SJP7026C	Policy No. (Claimant):						
		Excess:							
Repairer:		Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/04/2018]							
Driver/Custodian (Insured):		MANJARI D/O PANEERCHELVAN (), NRIC: S9026373J, Tel: +6591137024							
Adj Asg. Remarks:		ON WP. Survey on 25/04/18, Owner leave car from 9 to 12pm. Please contact us ASAP if you are not able to attend this assignment							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 10 May 2018 11:32 AM  
**To:** Thomas.Pang@borneomotors.com.sg  
**Cc:** Rasul@lkkauto.com; 'SUR'  
**Subject:** FW: FINALIZE REPORT FOR SJR6883R  
**Attachments:** IMG-20180425-WA0005.jpg; IMG-20180425-WA0003.jpg; IMG-20180425-WA0004.jpg; 28042018110312-0001.pdf

Dear Thomas,

Confirm figure at \$2,717.01, 3days

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Thomas Pang PTCBC [mailto:Thomas.Pang@borneomotors.com.sg]  
**Sent:** Saturday, 28 April 2018 11:10 AM  
**To:** Rasul (LKKAuto) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINALIZE REPORT FOR SJR6883R

Dear Rasul,

Attach finalize report for your perusal.

Thank you

Regards

Thomas

Borneo Motors

DID:6631 1860 FAX:6773 3094

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 30 Apr 2018

## Preliminary Advice

Insured Vehicle No	: SJP7026C	Accident Date	: 28/03/2018
TP Vehicle No	: SJR6883R	Assignment Date	: 23/04/2018
Make	: TOYOTA VIOS EA	Est. Duration of Repair	: 3 days
Date of Inspection	: 25/04/2018		
Inspection At	: Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent Singapore 128462		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,341.30
Revised Amount	:S\$	2,814.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,814.90

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/03/2018 13:40
Date Of Accident	28/03/2018 21:00
Exact Location Of Accident	WOODLANDS CRESCENT CP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR6883R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOH HWEE CHIT
NRIC No	S1703030B
Email Address	DAVGOH@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-91388336
Alternative Phone No	OFFICE-96165776

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100149205
Cover Note Number	

### Driver

Name of Driver	GOH HWEE CHIT
NRIC No	S1703030B
Date Of Birth	11/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	21/11/1986
Driving Experience	31 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91388336
Fax Number	
Contact Number	OFFICE-96165776
Email Address	DAVGOH@SINGNET.COM.SG

Address	434 CHOA CHU KANG AVE 4 #10-549
Postcode	680434
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER AS ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP7026C
Vehicle Make/Model/Colour	GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
09:30 AM  
29.03.2018  
Policyholder's Signature / Date & Time

  
09:30 AM  
29.03.2018  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

### Sketch Plan






Describe Circumstances of the Accident


- PARKED VEHICLE (8JR6883R)
- COLLECTION CAR TIME. THIRD PARTY VEHICLE OWNER APPROACHED AND CLAIMED THAT HIS VEHICLE KNOCKED ON MY CAR (BACK BUMPER) WHILE HIS CAR IS MOVING OUT FROM PARKING.
- OWNER OF THE CAR, PASS ME ALL HIS PARTICULARS (INSURANCE / IC)

Declaration

We declare the foregoing particulars are true in every respect.

 (11:10)  
29.03.2018  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyotasingsapore.com.sgToyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 129462  
Tel no.: 6631 1100Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg &amp; earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Goh Hwee Chit 434 Choa Chu Kang Avenue 4 #10-549 Singapore 680434 Mobile: 91388336
	Document No	
	Document Date	
	0	
	29/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
09	BEPRKT	NCP93R	07/07/2009	SJR6883R	0	30197	SJR6883R
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053HY9305120229	1NZX932689	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: <i>TP INS: 1/10</i> TP VEH: SJP7026C DATE OF ACC: 28.03.2018				<i>30 50</i> 108.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (NETT)				154.00
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NETT)				154.00
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				616.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				<i>616</i> 1232.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS				<i>506</i> 1512.00
7	L	BP-LPO SUPPLY REVERSE SENSOR (NETT)				<i>907.91</i> 200.00
8	1	S52159-0D983 REAR BUMPER COVER,	1.00	479.90		<i>su x 2</i> 479.90
9	2	S52576-0D070 L/RR BUMPER RETAINER,	1.00	99.20		<i>su x 2</i> 99.20
10	3	S52156-0D030 L/R SIDE BPR SUPPORT,	1.00	33.70		<i>su x</i> 33.70
11	4	S52575-0D070 R/RR BUMPER RETAINER,	1.00	99.20		<i>su x</i> 99.20
12	5	S52155-0D030 R/R SIDE BPR SUPPORT,	1.00	33.70		<i>su x</i> 33.70
13	6	S52161-0K040 PIECE, RR BUMPER	10.00	3.90		<i>33.70 net</i> 39.00
14	7	S81910-0D010 R/R BUMPER REFLECTOR,	1.00	88.60		<i>su x 2</i> 88.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of	Customer's Signature	Change Summary	Total
<b>Borneo Motors</b> agents hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Please acknowledge receipt of vehicle	Parts 873.30	4,341.30
		Labour 3,268.00	GST 7.00% 303.89
		Materials 200.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 4,645.19

Acknowledged by Repairer	Signature	Date	DATE	TIME
TO SECURITY GUARD			29/03/2018	11:03
PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.				

VEHICLE NO SJR6883R

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

## ESTIMATE

Page 3 of 3  
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no. 1 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Goh Hwee Chit 434 Choa Chu Kang Avenue 4 #10-549 Singapore 680434 Mobile: 91388336
	Document No	
	Document Date	
	0	
	27/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
09	BEPRKT	NCP93R	07/07/2009	SJR6883R	220084	30197	72/DS/SJR6883R
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053HY9305120229 1N2X932689 60 Thomas Pang W T 25/04/2018 8.00 27/04/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: MSIG INSURANCE TP VEH: SJP7026C DATE OF ACC: 28.03.2018 BY:LKK- RASUL @ 25.04.2018 03 WORKING DAYS				30.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N 02 ETT)				154.00
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET 02 T)				154.00
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				616.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS 02 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				616.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS 25				506.00
7	L	BP-LPO SUPPLY REVERSE SENSOR (NETT)				200.00
8	1	S52159-0D983 COVER, RR BUMPER	1.00	479.90	15.00	407.91
9	2	S52161-0K040 PIECE, RR BUMPER	10.00	3.90	15.00	33.10
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 441.01 Labour 2,076.00 Materials 200.00 Lubrication/Fluid 0.00 Others 0.00	2,717.01
			GST 7.00% 190.19 Less 0.00 Amount Due 2,907.20

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 27/04/2018  
TIME 10:47

VEHICLE NO SJR6883R

SIGNATURE



Borneo Motors

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018		23 Apr 2018 14:56 <a href="#">Edit Adj Rpt</a>	<b>S\$2,717.01</b> <a href="#">Edit Estimates</a>	<b>S\$2,717.01</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	SURESH S/O ARUMUGASAMY, ID: S8705012B								
Main Claimant:	GOH HWEE CHIT, ID: S17030308								
Vehicle Reg. No.:	SJR6883R	Date of Loss:	28/03/2018 20:00 - :59 [104 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 553957	Policy/Cover Note No.:	A28712650SMA (TP, Fire & Theft) Coverage: 01/04/2017 - 31/03/2018						
Vehicle Reg. No. (Insured):	SJP7026C	Policy No. (Claimant):							
		Excess:							
Repairer:	Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/05/2018]								
Driver/Custodian (Insured):	MANJARI D/O PANEERCHELVAN (), NRIC: S9026373J, Tel: +6591137024								
Adj Asg. Remarks:	ON WP. Survey on 25/04/18, Owner leave car from 9 to 12pm. Please contact us ASAP if you are not able to attend this assignment								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJR6883R (553957)  
 [SJP7026C]  
 TP  
 GOH HWEE CHIT  
 Mar 28 2018 8:00PM  
 [SURESH S/O ARUMUGASAMY]  
 Borneo Motors (singapore) Pte Ltd - (pandan)

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Assessment Reports</b>						1 per page <input type="button" value="Print"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail		Print	
1	02/04/18 10:34	<b>Accident Statement</b> From: SC - Reg. No: SJP7026C, Claimant: SURESH S/O ARUMUGASAMY				Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail		Print	
1	30/04/18 13:47	<b>Adjuster Immediate Advice</b>				Load HTM	
<b>Photos/Images</b>						3 per page <input type="button" value="Print"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail		Print	
1	27/06/18 13:32	Odometer Reading				Load JPG <input type="button" value="Print"/>	
2	27/06/18 13:32	Chassis Number				Load JPG <input type="button" value="Print"/>	
3	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
4	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
5	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
6	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
7	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
8	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
9	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
10	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
11	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
12	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
13	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
14	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
15	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
16	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
17	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
18	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
19	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
20	27/06/18 13:32	General View				Load JPG <input type="button" value="Print"/>	
21	27/06/18 13:33	Reinspection Photo				Load JPG <input type="button" value="Print"/>	
22	27/06/18 13:33	Reinspection Photo				Load JPG <input type="button" value="Print"/>	
23	27/06/18 13:33	Reinspection Photo				Load JPG <input type="button" value="Print"/>	
<b>Documentation</b>						1 per page <input type="button" value="Print"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail		Print	
1	02/04/18 10:34	<b>TP ACCIDENT REPORT - SJR6883R</b> From: SC - Reg. No: SJP7026C, Claimant: SURESH S/O ARUMUGASAMY				Load PDF	
2	02/04/18 10:38	<b>TP PRI Request</b>				Load PDF	
3	02/04/18 10:39	<b>TP SJR6883R Estimates</b>				Load PDF	
4	02/04/18 10:39	<b>SJR6883R Damaged Photos</b>				Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007447/T1SBQ2

Date: 29/06/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A28712650SMA

Claimant

Vehicle No : SJR6883R

Insured Vehicle No : SJP7026C

Date of Loss: 28/03/2018

Nature of Claim: TP

Claim No: 553957

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR6883R

Make &amp; Model: TOYOTA VIOS EA, 1.5 (A)

Engine No: 1NZX932689

Reg. Date: 07/07/2009 (Man. Year: 2009)

Chassis No: MR053HY9305120229

Colour: Grey

Odometer: 226044 km

Engine Capacity: 1497 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,173.30	671.01	502.29	42.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,168.00	2,046.00	1,122.00	35.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,341.30</b>	<b>2,717.01</b>	<b>1,624.29</b>	<b>37.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>303.89</b>	<b>190.19</b>	<b>113.70</b>	<b>37.41</b>
<b>Nett Amount (S\$)</b>	<b>4,645.19</b>	<b>2,907.20</b>	<b>1,737.99</b>	<b>37.41</b>

### INSPECTION

Date of Assignment: 23/04/2018

Date Inspected: 25/04/2018 Inspected At:

Borneo Motors (singapore) Pte Ltd - (pandan) (HQ)

Toyota Bodycare Centre, No. 2

Pandan Crescent

Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2018)
<b>Parts:</b> 143	TOYOTA VIOS EA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJR6883R)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	100.00 FS	*30.00 FS
2	1		*REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
3	1		*REAR BUMPER COVER,	Deformed	479.90 FS	*407.91 FS
4	1		*L/RR BUMPER RETAINER ,	Serviceable	99.20 FS	*- FS
5	1		*L/R SIDE BPR SUPPORT ,	Serviceable	33.70 FS	*- FS
6	1		*R/RR BUMPER RETAINER ,	Serviceable	99.20 FS	*- FS
7	1		*R/R SIDE BPR SUPPORT	Serviceable	33.70 FS	*- FS
8	10		*PIECE ,RR BUMPER	Necessary	39.00 FS	*33.10 FS
9	1		*R/R BUMPER REFLECTOR ,	Serviceable	88.60 FS	*- FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>1,173.30</b>	<b>671.01</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	154.00	154.00
2	CHECK WIRING AND CONDUCT WATER TEST	New	154.00	154.00
3	TO RESET ECU AND REPROGRAMME	New	616.00	616.00
4	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN /REALIGN ACC AFFECTED AREAS	New	1,232.00	616.00
5	RESPRAY ACC AFFECTED AREAS	New	1,012.00	506.00
Gross Labour Cost (S\$)			<b>3,168.00</b>	<b>2,046.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >