

ASS. REC. BY:

REF: CS/CT118007448/Arb n2

Special Instruction:

Surveyor

Addlan

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time: 23042018 3:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 1757E

Insured:

GZ 9504J

at Workshop m/s

Borneo motor

Tel:

9847 6209

of

17 Ubi Rd 4

Policy No:

DMCVSN3000081800

Claim No:

SNM18D01996C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17042018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

05062018 @ morning

H.O.D. Endorsement:

Date/Time:

23042018 405pm

Person Contacted:

Sam

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 1757E - X

GZ 9504J - X

Confirm \$ 3575.46 @ 5 days

Red: \$8136.05, 69%

Est. Repairs:

05 8/8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

D.O.A.

D.O.I.

05/06/18

Survey held at

Borneo (ubi)

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP China

RECEIVED 20 AUG 2018

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

5

1) Input



Final Report

Resurvey No. of Trip:

✓

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:



Site Insp (\$

) S + RS. St



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format:

TP

Lump Sum / I.B.I. (\$

3575.46

TOTAL

220