

7/2/2018

ASS. REC. BY:

REF: CS / CT118007448 / Arb n2

Special Instruction:

Supervisor:

Adrian

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time: 23042018 3:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 1757E

Insured:

GZ 9504J

at Workshop m/s

Borneo Motor

Tel:

9847 6209.

of

17 Ubi Rd 4

Policy No:

DMCVSN3000081800

Claim No:

SNM18D01996C02.

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wsp'

05062018 @ morning

Date/Time:

23042018 405pm

Person Contacted:

Sam

H.O.D. endorsement:

Vehicle IN) OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLW 1757E - X
	GZ 9504J - X
	Confirm \$ 3575.46 @ 5 days
	Red: \$ 8136.05, 69%.

REF: 077

ASSIGNMENT

From: Date: 05062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SLW 1757E
at Workshop m/s: Borneo motor
of: 17 Ubi Rd 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Thomas
Moring

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05884

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLW1757E Yr Regn: 2018 Jan.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish.

cc 1758.

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

3124

T/Radio: Insured / Std / NI / NA

Eng/No:

JTDG620W00J008751

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

05/06/18.

Survey held at

Borneo (Ubi)

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP Chire

RECEIVED 28 AUG 2018

Date/Time. File Pass to?



Preli. Report



Final Report

1) Input

Date/Time. File Return to?

2)

Report Format:

TP

Lump Sum / I.B.F. (\$)

3575.46

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

) \$ + P.O. \$

) Photos

) Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		23 Apr 2018 15:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<div>CLAIM SUBFOLDER DETAILS</div> <div> <div>Insured:</div> <div>EZON RENOVATION PTE LTD, Co. Reg. No.: 201526772H</div> </div> <div> <div>Main Claimant:</div> <div>KWEK TUAN ZE, ID: S84072101</div> </div> <div> <div>Vehicle Reg. No.:</div> <div>SLW1757E</div> </div> <div> <div>Claim Type:</div> <div>TP / SNM18D01996C02</div> </div> <div> <div>Vehicle Reg. No. (Insured):</div> <div>GZ9504J</div> </div> <div> <div>Repairer:</div> <div>Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4, 408611 Ubi - Tel: 6631 1868</div> </div> <div> <div>Handling Insurer:</div> <div>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]</div> </div> <div> <div>Claimant's Insurer:</div> <div>AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288</div> </div> <div> <div>Adjuster:</div> <div>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/05/2018]</div> </div> <div> <div>Driver/Custodian (Insured):</div> <div>YEAP KOOT WANG (30 / Male), NRIC: G7868441R, Tel: +6591695618</div> </div> <div> <div>Adj Asg. Remarks:</div> <div>EST \$12,531.32, CASE WITH SJE.</div> </div> <div> <div>View All</div> <div>Compose Case Mail</div> </div>																								
<div>ASSOCIATED MAIL RECEIVED</div> <div>There are no mail for this case.</div>																								
<div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/04/2018 16:49
 Date Of Accident 17/04/2018 18:00
 Exact Location Of Accident BLK 307C ANCHORVALE RD LOADING/UNLOADING BAY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW1757E
Insured/Policyholder
 Name Of Registered Owner KWEK TUAN ZE
 NRIC No S8407210I
 Email Address KTUANZE@GMAIL.COM
 Mobile Phone No (LOCAL) +65-91713885
 Alternative Phone No OFFICE-91713885
Vehicle Particulars
 Manufacturer TOYOTA
 Model WISH-1.8 (A)
 Exact Purpose for which vehicle was being used at time of accident NORMAL USAGE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number GA315040
 Cover Note Number
Driver
 Name of Driver CHEW YIN SY
 NRIC No S8819155B
 Date Of Birth 07/06/1988
 Occupation INDOOR
 Date Of Driving Pass 14/03/2012
 Driving Experience 6 YEARS AND 1 MONTH
 Gender FEMALE
 Mobile Number (LOCAL) +65-91392286
 Fax Number
 Contact Number
 Email Address ROBINCLARA8488@GMAIL.COM

Address BLK 471B FERNVALE ST #16-111
 Postcode 792471
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : KWEK YING EN FAITH
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH SAM AT UBI
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ9504J
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver YEAP KOOI WANG
 NRIC/Passport Number G7868441R
 Contact Number 91695618
 Address
 Postcode
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan





Describe Circumstances of the Accident


- ① My Baby girl is seated in the baby car seat (rear-facing) behind the driver seat. I was fetching my girl to my parent's house. While waiting for my parent to come downstairs (loading/unloading area) to fetch my girl, I decided to park at the loading/unloading bay ~~as~~ so as to not obstruct the road as there is only 1 lane for each direction of travel.
- ② I was in the midst of parking into the lot (as in diagram), stationary at that particular moment to check for blindspot and to make sure that I can park into the lot. Just at this moment, the lorry suddenly reversed to leave its lot and immediately I sounded the horn continuously. But the lorry did not stop instantly and continue to reverse. The lorry only came to a stop when the driver realised that a collision has taken place.
- ③ The left side of the car (near the front passenger area) was dented inside due to the collision.

Declaration

We declare the foregoing particulars are true in every respect.

 18/04/18 2.40pm
Policyholder's Signature / Date & Time

 18/4/18 2.40pm
Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Kwek Tuan Ze (Guo TuanZe) 471B Fernvale Street #16-111 Singapore 792471 Mobile: 91713885	
		Document No		
		Document Date		
		0		
		19/04/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	2GE20R	31/01/2018	SLW1757E	881	16356 7DS/SLW1757E/170411
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W00J008751		2ZR0A52409	60	Sam San Joi	18/04/2018 14.45	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GZ9504J ACC DATE:17/04/2018 DRIVE IN:18/04/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00 <i>rec</i>
2	S	BP-SUBLET CHECK LIGHTING & WIRING SYSTEM				115.26
3	S	BP-SUBLET REPLACE & INSTALL FUSE BOX ASSY TO ASSIS T REPAIR				339.00
4	S	BP-SUBLET REMOVE & INSTALL SIDE SKIRT TO ASSIST RE PAIR				84.75
5	B	BP-MECH RESET ECU AND REPROGRAMME				402.00
6	S	BP-SUBLET REPLACE FRT LH FENDER, FRT LH APRON PANEL , ETC STRAIGHTEN & ALIGN LH FRT ACCIDENT AFFECTED AR EAS				4068.00 <i>678</i>
7	S	BP-SUBLET RESPRAY JOB ON LH FRT ACCIDENT AFFECTED AREAS				3336.00 <i>112</i>
8	1	T53812-68060 FENDER SUB-ASSY, LH <i>Detec</i>	1.00	955.90		955.90
9	2	T53876-68020 L/FRT FENDER LINER, <i>Detec</i>	1.00	167.10		167.10
10	3	T53828-68020 PROTECTOR, FR FENDER <i>Detec</i>	1.00	86.20		86.20
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For all on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3639849

TO SECURITY GUARD

3639849

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/04/2018
TIME 10:26

VEHICLE NO SLW1757E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!


Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Kwek Tuan Ze (Guo TuanZe) 471B Fernvale Street #16-111 Singapore 792471 Mobile: 91713885	
		Document No		
		Document Date		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	2GE20R	31/01/2018	SLW1757E	881	16356 :7DS/SLW1757E/17041:
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W00J008751		22R0A52409	60	Sam San Joi	18/04/2018 14.45	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	4	SEAL, FR FENDER TO <i>new</i>	1.00	33.00		+ 33.00
12	5	CLIPS <i>new</i>	10.00	2.90		+ 29.00
13	6	APRON SUB-ASSY, FR <i>new</i>	1.00	501.70		+ 501.70
14	7	UNIT, HEADLAMP LH <i>new</i>	1.00	1222.20		+ 1222.20
15	8	COVER, RELAY BLOCK, <i>new</i>	1.00	78.60		+ 78.60
16	9	ENGINE BLOCK ROOM, <i>new</i>	1.00	175.40		+ 175.40
17	0	COVER, RELAY BLOCK, <i>new</i>	1.00	87.40		+ 87.40

Adrian
P/P 05/06/18
OSR

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 3,336.50	11,711.51
		Labour 432.00	GST 7.00%
		Materials 7,943.01	819.81
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 12,531.32

PLEASE TEAR ALONG PERFORATED LINE

3639850

3639850

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES

DATE 19/04/2018
TIME 10:26

VEHICLE NO SLW1757E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Reg No : 196700086Z
T Reg No: MR-8500000-9

Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mr Kwek Tuan Ze (Guo TuanZe) 471B Fernvale Street #16-111 Singapore 792471 Mobile: 91713885
	Document No 39006793	
	Document Date 20/06/2018	

Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
HPXNP S6	ZGE20R	31/01/2018	SLW1757E	2195	16356	7DS/SLW1757E/17041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
TGG20W00J008751	22R0A52409	60	Sam San Joi		18/04/2018 14.42	07/06/2018 8.34

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
2	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GZ9504J ACC DATE:17/04/2018 DRIVE IN:18/04/2018 DATE-IN:04/06/2018 DATE SURVEY:05/06/2018 NO OF REPAIR DAYS:5 DAYS BY:ADRIAN (LKK)				30.00
2 S	BP-SUBLET CHECK LIGHTING & WIRING SYSTEM A45				115.26
3 B	BP-MECH RESET ECU AND REPROGRAMME 18				402.00
4 S	BP-SUBLET REPLACE FRT LH FENDER A45				678.00
	STRAIGHTEN & ALIGN LH FRT ACCIDENT AFFECTED AREAS				
5 S	BP-SUBLET RESPRAY JOB ON LH FRT ACCIDENT AFFECTED AREAS A45				1112.00
6 1	T53812-68060 L/FRONT FENDER SUB-ASSY,	1.00	955.90		955.90
7 2	T53876-68020 L/FRONT FENDER LINER	1.00	167.10		167.10
8 3	T53828-68020 L/FRONT FENDER PROTECTOR,	1.00	86.20		86.20
9 4	T90467-07201 CLIP	10.00	2.90		29.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 1,238.20	3,575.46
		Labour 432.00	GST 7.00%
		Materials 1,905.26	250.28
		Lubrication/Fluid 0.00	Less
		Others 0.00	0.00
		Amount Due	3,825.74

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 120402 **3691691**

SECURITY GUARD

3691691

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/06/2018
TIME 16:49

VEHICLE NO SLW1757E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007448/ARBN2

Date: 28/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3000081800	
Claimant Vehicle No :	SLW1757E	Insured Vehicle No :	GZ9504J	
Date of Loss:	17/04/2018	Nature of Claim:	TP	Claim No: SNM18D01996C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW1757E	Engine No:	2ZR0A52409
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W00J008751
Reg. Date:	31/01/2018 (Man. Year: 2017)	Odometer:	3124 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,366.50	1,268.20	2,098.30	62.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,345.01	2,307.26	6,037.75	72.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,711.51	3,575.46	8,136.05	69.47
+ GST 7.00/7.00% (S\$)	819.81	250.28	569.53	69.47
Nett Amount (S\$)	12,531.32	3,825.74	8,705.58	69.47

INSPECTION

Date of Assignment:	23/04/2018	Inspected At:	Borneo Motors (S) Pte Ltd (Ubi)
Date Inspected:	05/06/2018		17 Ubi Road 4
			Singapore 408611
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW1757E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY,LH	Dented	955.90 FS	*955.90 FS
2	1		*L/FRT FENDER LINER	Deformed	167.10 FS	*167.10 FS
3	1		*PROTECTOR,FR FENDER	Necessary	86.20 FS	*86.20 FS
4	1		*SEAL,FR FENDER TO	Not Necessary	33.00 FS	*- FS
5	10		*CLIPS	Necessary	29.00 FS	*29.00 FS
6	1		*APRON SUB-ASSY,FR	Repair	501.70 FS	*- FS
7	1		*UNIT,HEADLAMP LH	Not Necessary	1,222.20 FS	*- FS
8	1		*COVER,RELAY BLOCK	Not Necessary	78.60 FS	*- FS
9	1		*ENGINE BLOCK ROOM	Not Necessary	175.40 FS	*- FS
10	1		*COVER,RELAY BLOCK	Not Necessary	87.40 FS	*- FS
11	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,366.50	1,268.20
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK LIGHTING & WIRING SYSTEM	New	115.26	115.26
2	REPLACE & INSTALL FUSE BOX ASSY TO ASSIST REPAIR	New	339.00	-
3	REMOVE & INSTALL SIDE SKIRT TO ASSIST REPAIR	New	84.75	-
4	RESET ECU AND REPROGRAMME	New	402.00	402.00
5	REPLACE FRT LH FENDER,FRT LH APRON PANEL,ETC STRAIGHTEN & ALIGN LH FRT ACCIDENT AFFECTED AREAS	New	4,068.00	678.00
6	RESPRAY JOB ON LH FRT ACCIDENT AFFECTED AREAS	New	3,336.00	1,112.00
Gross Labour Cost (S\$)			8,345.01	2,307.26

Report was unsubmitted during this print-out.

< END OF ESTIMATES >