



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2016 MITSUBISHI CANTER FEB71ER4SDEC
(CBU) (YP6077J)

Date of Loss 16 April 2018

Time of Loss 4.00

Loss Description YP6077J (INSD) C/W GBG1947B

Comment

Workshop Details

Total Rebate Amount 43840

Nett Loss Amount \$46,160.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 402

Maximum value is 365



SERVICE REQUESTS

MESSAGES

CLAIMS

● Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# YP6077J

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

06/04/2017



Mileage

77448

Age of Vehicle

1

Driver Details

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2016

2016

Make

MITSUBISHI

MITSUBISHI

Model

CANTER
FEB71ER4SDEC
(CBU)

CANTER FEB71ER4S

CATEGORY

FNOL
INFORMATIONPOST SURVEY
INFORMATION

Driver Name

ABDUL
ZAINUDIN BIN

Date of Birth

dd/mm/yyyy



Age

0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	FEB71EA20393	FEB71EA20393
Engine No	4P10C49317	4P10C49317
Engine Capacity		2998
Sum Insured	0	0
Market Value	0	90000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Unknown	
Marital status	Unknown	
Identification #	S1622853B	



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

24/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

800

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/75R17.5

Rear Tyre Size

215/75R17.5(D)

Front left side

WESTLAKE6mm

Rear left side

WESTLAKE6/6mm

Front right side

WESTLAKE6mm

Rear right side

WESTLAKE6/6mm



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			BUMPER ASSY, FRONT			Bent	697.32				697.32	Reviewing	
		2	1			COVER, FR BMPR CORNER, RH			Serviceable	0	0	0	0	0	Deny	
		3	1			COVER, FR BMPR CORNER, LH			Serviceable	0	0	0	0	0	Deny	
		4	1			STAY, FR BUMPER, LH			Bent	140.21				140.21	Reviewing	
		5	1			STAY, FR BUMPER, RH			Bent	140.21				140.21	Reviewing	
		6	1			GRILLE, RADIATOR			Cracked	789.86				789.86	Reviewing	
		7	1			BRKT, FR GRILLE			Bent	18.72				18.72	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		8	1			PANEL, FRONT			Bent	801.85				801.85	Reviewing	
		9	1			HEADLAMP L			Cracked	346.09				346.09	Reviewing	
		10	1			HEADLAMP R			Cracked	346.09				346.09	Reviewing	
		11	1			SIGNAL LAMP ASSY - LH			Serviceable	0	0	0	0	0	Deny	
		12	1			SIGNAL LAMP ASSY - RH			Cracked	183.86				183.86	Reviewing	
		13	1			GARNISH, HEADLAMP RH			Cracked	158.97				158.97	Reviewing	
		14	1			HORN / R70 12V HIGH TONE73			Bent	69.58				69.58	Reviewing	
		15	1			COVER, HORN			Bent	23.6				23.6	Reviewing	
		16	1			C/MBR ASSY, FR. FLOOR			Bent	340.18				340.18	Reviewing	
		17	1			BRKT, CAB HINGE			Bent	659.54				659.54	Reviewing	
		18	1			BRKT, CAB HINGE			Bent	588.27				588.27	Reviewing	
		19	1			BUSH			Deformed	13.15				13.15	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		20	1			RUBBER ASSY, FR.CAB MTG			Deformed	158.92				158.92	Reviewing	
		21	1			BAR, TORSION			Bent	428.78				428.78	Reviewing	
		22	1			HEATER UNIT			Serviceable	0	0	0	0	0	Deny	
		23	1			BOX, AIR INTAKE			Serviceable	0	0	0	0	0	Deny	
		24	1			HOSE, HEATER WATER			Bent	16.56				16.56	Reviewing	
		25	1			HOSE, HEATER WATER			Bent	14.99				14.99	Reviewing	
		26	1			PIPE ASSY, HEATER WATER			Bent	52.68				52.68	Reviewing	
		27	1			HOSE, SUCTION			Bent	326.77				326.77	Reviewing	
		28	1			CLAMP, PIPE			Cracked	7.94				7.94	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	2400	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		2		TO CHECK AND RECTIFY WIRING FAULTS, TO CARRY OUT DIAGNOSTICS CHECK	150	0	0	Reviewing		
		3		TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC	1225	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 8 DAYS	Reviewing			
		2	FRONT LICENSE PLATE	Reviewing	20	BENT	
		3	SUNDRIES	Reviewing	30	NECESSARY	



⊖ Please enter the required fields in General & Workshop Details



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Claim Amount	\$9,349.14	Claim Amount	\$9,349.14
--------------	------------	--------------	------------

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$6,324.14

\$6,324.14

Labour

\$3,775.00

\$3,775.00

Miscellaneous

\$50.00

\$50.00

Excess

-\$800.00

-\$800.00

[Submit for Review](#)