

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Registration No Chassis No Model Owner's Name Ins Policy No.

BOSUN

BMA01D

BMC01D

SUNDRIES

REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. 1

REMOVE & INSTALL RADIATOR WITH FITTINGS.

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

1

: LONPAC INSURANCE BHD	Document No.	: SQT18001620	Page	
100 BEACH ROAD	Date	: 19. Apr 2018		
#19-00 SHAW TOWERS	Customer No.	: WZL009		
SINGAPORE 189702	Svc Advisor	: NG SIN HAI		
: SKT8674S	Engine No	: L15Z71000196		
: MRHRU1830FP000169	Date Time	: 19. Apr 2018 2:20:05 PM		
: HRV LX CVT YM 2015	Surveyor Name	:		
: CHONG PEI LAN	Survey Date	:		
ř.	Authorisation Date	2		

Date of Accident	: 18/4/2018							
							0% GST	Amount
Item	Description		Qty	Unit Price	Disc %	Amount	Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:CHONG PEI LAN							
	OWNER INSURER:AVIVA LTD							
	ACC DATE:18/04/2018							
	SURVEYED BY:							
	DATE:							
	REF NO:							
	TP INSURER:LONPAC INSURANCE BHD							
	TP VEH:SDQ2868M							
71101-T7J-H00ZZ	FACEFR.BUMPER		1	466.20	25	349.65	24.48	374.13
71101-175-110022 71102-T7W-A00	FACEFR.BUMPER LOWER		1	133.90	25	100.42	7.03	107.45
71102-17 W-A 00 71103-T7J-H00	GRILLEFR.BUMPER LOWER		1	71.50	25 25	53.62	3.75	57.37
71103-173-H00 71110-T7A-000	SPOILERFR.BUMPER AIR		1	50.00	25 25	37.50	2.63	40.13
71110-17A-000 71121-T8N-P50	BASEFR.GRILLE		1	190.00	25 25	142.50	9.98	152.48
71121-18N-P50 71122-T8N-T50	MOLDINGFR.GRILLE							
			1	130.80	25	98.10	6.87	104.97
71123-T8N-T00	BARR.FR.GRILLE MOLDING		1	57.20	25	42.90	3.00	45.90
71128-T8N-T00	BARL.FR.GRILLE MOLDING		1	57.20	25	42.90	3.00	45.90
75700-TA0-A00	EMBLEMFR.		1	25.90	25	19.42	1.36	20.78
71151-T7J-H00	BEAMR.FR.GRILLE SIDE UPPER		1	4.50	25	3.37	0.24	3.61
71130-T8N-T00ZZ	BEAM COMPFR.BUMPER		1	249.60	25	187.20	13.10	200.30
71140-T7A-000	BEAMR.FR.BUMPER UPPER		1	23.90	25	17.92	1.25	19.17
71193-T7A-000	SPACERR.FR.BUMPER SIDE		1	10.40	25	7.80	0.55	8.35
71198-T7A-000	SPACERL.FR.BUMPER SIDE		1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER		18	2.00	25	27.00	1.89	28.89
33100-T7S-T51	HEADLIGHT ASSY,R.		1	348.20	25	261.15	18.28	279.43
					Sum Item	1399.25	97.96	<u>1,497.21</u>

100.00

380.00

330.00

1

100.00

380.00

330.00

7.00

26.60

23.10

107.00

406.60

353.10



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT18001620

2 Page

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

100 BEACH ROAD

#19-00 SHAW TOWERS 189702

: LONPAC INSURANCE BHD

Customer No.

: 19. Apr 2018 : WZL009

SINGAPORE

Svc Advisor

Date

: NG SIN HAI : L15Z71000196

Registration No Chassis No

Customer

: SKT8674S

Engine No Date | Time

: 19. Apr 2018 2:20:05 PM

Model

: MRHRU1830FP000169 : HRV LX CVT YM 2015

Surveyor Name

Owner's Name

: CHONG PEILAN

Survey Date

Authorisation Date

Ins Policy No. **Date of Accident**

:

: 18/4/2018

0% GST Amount **Amount** incld GST Item Description Qtv Unit Price Disc % <u>Amount</u> BML01I INSPECT FR LIGHTING MECHANISMS & FOCUS 192.60 1 180.00 180.00 12.60 **BKBH01M CUT OFF & RENEW BULKHEAD. STRAIGHTEN** 1500.00 1500.00 105.00 1605.00 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 4 BP05R 1000.00 1000.00 1070.00 70.00 (5P) Sum Labor 3490.00 244.30 3,734.30 Survey By Date & Time **Total Amount** 4,889.25 342.26 5,231.51 Excess Total (Inclusive of GST) 5,231.51 Status Signature





SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	18/04/2018 18:42
Date Of Accident	18/04/2018 12:15
Exact Location Of Accident	REN CI HOSPITAL & MEDICARE CENTRE 71 IRRAWADY RD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKT8674S
Insured/Policyholder	
Name Of Registered Owner	CHONG PEI LAN
NRIC No	S7301508A
Email Address	CPEILAN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92235825
Alternative Phone No	OFFICE-92235825
Vehicle Particulars	
Manufacturer	HONDA
Model	HRV 1.5 LX CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10664052
Cover Note Number	
Oriver Control of the	
Name of Driver	CHONG PELLAN

Name of Driver

CHONG PEI LAN

NRIC No

S7301508A

Date Of Birth

14/01/1973

Occupation

INDOOR

Date Of Driving Pass

11/03/1995

Driving Experience 23 YEARS AND 1 MONTH

Gender FEMALE

Mobile Number (LOCAL) +65-92235825

Fax Number

Contact Number OFFICE-92235825

EMail Address CPEILAN@HOTMAIL.COM

Address

NA

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2 NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

n

Details of Police Action

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

Police Station Name

BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 1 DUKE ROAD, POSTCODE: 268914, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-4629999 - FAX NO: 64628933

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO: (T/20180418/2081) ON 18/04/2018 AT 2:00PM, I WAS INFORMED BY MY SECURITY OFFICER THAT ANOTHER VEHICLE (SDQ2868M) HAD COLLIDED IN TO MY VEHICLE (SKT8674S). SOMEONE HAD INFORMED MY SECURITY OFFICER OF THAT MATTER AND MY SECURITY OFFICER PROCEEDED TO INVESTIGATE THE MATTER BY VIEWING THE CCTV. SHE THEN OBSERVED THAT ANOTHER VEHICLE (SDQ2868M) MOVING TO HAVE COLLIDED IN TO MY VEHICLE (SKT8674S) AS IT TRYING TO MANEUVER OUT OF THE LOT. WHILE DOING SO, IT APPEARED TO HAVE COLLIDED IN TO MY VEHICLE'S FRONT RIGHT SIDE. WHEN THE CONTACT WAS MADE MY VEHICLE WAS OBSERVED TO SHAKE. THE OTHER VEHICLE (SDQ2868M) IMMEDIATELY STOPPED WHEN THE CONTACT WAS MADE AND IT REVERSED AND TOOK A WIDER ANGLE TO MANEUVER OUT OF THE LOT. THE VEHICLE (SDQ2868M) DID NOT STOP TO LEAVE A NOTE NOR DID THE DRIVER APPROACH ANY OF MY SECURITY OFFICERS AND IT DROVE OUT OF THE CAR PARK AND LEFT THE VICINITY.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDQ2868M

Vehicle Make/Model/Colour

VOLVO/ XC90 2.5 /BROWN

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN DRIVER

NRIC/Passport Number

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

POLICE REPORT



Police Station Of Origin: Bukit Timah N P.C 1 Duke's Road SINGAPORE 268914 Tel No. 1800-4629999



5 of 3

Report No. T/20160418/2081

Date/Time Report Made: 18/04/2018 15:25			Vide Report No:	Station Diary No. 46	
Informa	nt's Partic	ulara			
	Informant		65 GREENWOOD AVENUE	SINGAPORE 289271	
ID Type / ID No.: NRIC NO / S7301508A		ABO	Contact No.: Home/Office: Mobile 92235625		
Nationali			Emeil.		
Sex Female	Age:	Date of Birth: 14/01/1973	Type of Informant: Vehicle Owner		
Race: Chinese			Language English	Institution / School Name:	
Occupation SENIOR MANAGEMENT			Driving Licence Information: Class 3	Date of Expiry	

Type of Accident.	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 18/04/2018 12:15	Type of Location: Car Park
Location Along Road 1 IRRAWADDY	ROAD at 71 Irrawaddy Roa	d lot number 22		
Weather.		Road Surface:		Road Speed Limit
		Traffic Control		Traffic Volume:
Traffic Flow:				Tanic volune.

Details of V	ehicle Invo	lved				
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SDQ2868M	Car	VOLVO		Brown		0
SKT8674S	Car	HONDA		White	Slightly	0
				NO PROPRIE	Damaged	

Details of V	ehicle insurance		The second second	77 3 3
	Insurance Company	Insurance No	Effective	Expiry Date
SKT8674S	AVIVA LTD	10684052	25/06/2016	THE RESERVE AND ADDRESS OF THE PARTY OF THE
	Sentantic Commence Control			

POLICE REPORT



Police Station Of Ongin. Bukit Timah N.P.C 1 Duke's Road SINGAPORE 268914 16/ No. 1800-4629999


2 of 3

Report No. 7/20160418/2081

CONTINUATION OF REPORT

Brief Details.
On 18/04/2018 at 02 00PM. I was informed by my security officer that another vehicle (SDQ2868M) had collided into my vehicle (SKT8674S). Someone had informed my security officer of that matter and my security officer proceeded to investigate the matter by viewing the CCTV. She then observed that another vehicle (SDQ2868M) moving very close to my vehicle (SKT8574S) as it trying to manauver out of the lot. While doing so, it appeared to have collided into my vehicle (SDQ2868M) immediately stopped when the contact was made and it reversed and took a wider angle to maneuver out of the lot. The vehicle (SDQ2868M) did not stop to leave a note nor did the driver approach any of my security officers and it drove out of the carpark and left the vicinity. drove out of the carpark and left the vicinity.

POLICE REPORT



Signature Of Officer Recording The Report.

Sr Staff Sgt TAN ZHENG YE, JOHANNES

Signature Of Interpreter:

Officer In Charge Of Case:


SI KALESWARI PALANI Contact No. 65476902

Authentication Stamp

Not applicable

TP/HRT/

NP16H



Classification Of Case: