

08/11/13

Binec: Kelvin

REF: NS/INC18007474/KHbn2

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate No: \_\_\_\_\_

OD / TP / INS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: \_\_\_\_\_

at Work Shop No: \_\_\_\_\_

of \_\_\_\_\_

Insured: GY 734B

Policy No: 5047861371-07 13-12-17 - 16-12-18

Claims No: MT/0991206-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHD 3440C Yr Regn: 30 May 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C: 1798

Colour: Blue A/C: Ins / Std / NI / NA

Sp. Reading: 162678 T/Radio: Ins / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3F4X0355761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 20/4/10 D.O.I. 23/4/10

Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 3440C - NS/EQT/70114597 / Kly (B2) DA: 200717 INC
	GY 734B - NA/INC/8007382/24 DA: 200418 PIP
26/4/18	Confirmed PIP \$500 / 20%. (Red: 1130.88 : 69%)
	RECEIVED 27 APR 2018

Date/Time, File Pass to?  : Prel. Report

1) JFH Typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech \_\_\_\_\_

: \_\_\_\_\_

Survey Fee:	160
Transportation:	35
S + RS, SI	
Photos	
Other	
	195

4s: 5007



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007474/K1tb			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 23-04-2018	
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GY 734B	Veh. Inspected	SHD 3440C
Policy No.	5047861571-07	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	20/04/2018	Inspection Date	23/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)

[My Desktop](#)  
[Notice of Loss](#)

**Policy Query**

Policy No.  Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5047861571-07	XING GANG RENOVATION & CONSTRUCTION	53177056K	GCV	Third Party, Fire & Theft	GY734B	GY734B	17/12/2017	16/12/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0991171-002	Comfort Transportation	SHC 1863J	SLK 8879D	20/4/2018
2	MT/0991056-002	Comfort Transportation	SH 6314M	SHC 6794S	19/4/2018
3	MT/0991265-002	Comfort Transportation	SHA 7627X	SLS 1369M	21/4/2018
4	MT/0991375-002	Comfort Transportation	SHC 2164L	SJE 68K	21/4/2018
5	MT/0991583-002	Comfort Transportation	SHA 5984C	SFZ 1009L	21/4/2018
6	MT/0991278-002	Comfort Transportation	SH 6746A	SKW 2592T	21/4/2018
7	MT/0991262-002	Comfort Transportation	SHC 3572K	GBG 8101D	20/4/2018
8	MT/0991924-001	Comfort Transportation	SHD 4138U	SGY 5128T	19/4/2018
9	MT/0991927-001	Comfort Transportation	SHA 3460K	FQ 2735P	22/4/2018
10	MT/0991206-002	Comfort Transportation	SHD 3440C	GY 734B	20/4/2018

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/04/2018 15:24
Date Of Accident	20/04/2018 13:20
Exact Location Of Accident	SHENTON WAY TWDS KEPPEL ROAD.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3440C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN CHEE LYE
NRIC No	S6815055H
Date Of Birth	07/04/1968
Occupation	OUTDOOR
Date Of Driving Pass	13/11/1999
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	SIMONTAN02@YAHOO.COM.SG

Address 306 #15-83 CANBERRA ROAD  
 Postcode 750306  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

SEE ATTACH.

**Attachment(s)**


Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GY734B  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage LEFT FRT  
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/4/2018 at about 1320 hrs, I vehicle A was driving along Shenton way toward Keppel road. While I was on the second a-d going straight following a bus behind, suddenly vehicle B came from my right and sway into my lane brushes against my taxi right rear portion. No one was injured at that time.

*[Signature]*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD.  
CO. REG. NO. 199303821R

20/4/18  
Jackson Heng  
CSO *[Signature]*

Policyholder's Signature

Driver's Signature

Reporting Centre Personnel's Signature

Sketch Plan Pg. 2


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**




I understand, acknowledge, agree and consent that:






- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
 CC REG NO 199303021R  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

20/4/18  
  
 Jackson Heng  
 CSO  
 Reporting Centre Personnel's Signature  
 Name: TAN CHEE LYE  
 NRIC/PIN No.: S68150551A







COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

VEHICLE NO : SHD 3440C

MAKE :

MODEL : TOYOTA PRIUS

NTUC / LKK  
 RIGHT REAR

DATE : 23.04.2018

FZ

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <i>X 1pc</i>			\$ 458.60
REAR BUMPER SIDE RETAINER <i>X 1pc</i>			\$ 112.70
RETAINER, REAR BUMPER, SIDE, RH <i>1pc</i>			\$ 94.80
SEAL, REAR BUMPER SIDE, RH <i>X 1pc</i>			\$ 148.40
<i>Pen RH fender X repair</i>			
SUB TOTAL			\$ 814.50
LESS 25%			\$ 203.63
DISCOUNTED TOTAL			\$ 610.88
REAR BUMPER RUBBER MAT <i>X 1pc</i>			\$ 50.00
<b>LABOUR CHARGE</b>			
Panel Beating			\$ <del>250.00</del> <sup>100</sup>
Spray Painting Charge			\$ <del>500.00</del> <sup>400</sup>
Wiring Charge			\$ <del>50.00</del> <sup>X 10</sup>
Tuff Kote			\$ <del>50.00</del> <sup>500</sup>
Remove/Refix Reverse Sensor			\$ <del>120.00</del> <sup>X 10</sup>
TOTAL LABOUR			\$ 970.00
ESTIMATE TOTAL			\$ 1,630.88
<b>NETT</b>			

*Ka Hic Cky*  
*23/4/8 1416h*  
*2 Rys*  
*P/P*  
*After Repair p/lt*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 24.04.2018

REPAIR ESTIMATE

Time: 18:56:44

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305144707  
REGN NO : SHD3440C  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 30.05.2017  
DATE/TIME IN : 23.04.2018 10:20  
ACCIDENT DATE : 20.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 L	PANEL BEATING	100.00
0001 L	SPRAY PAINTING CHARGE	400.00

SUB-TOTAL : 500.00

TOTAL : 500.00

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

Our Job Ref No : 305144707

Date : 25.04.2018

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD3440C

Date of Accident : 20.04.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GY 734B
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	<u>\$0.00</u>
(b) Labour Charges	<u>\$500.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<u>\$0.00</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>\$0.00</u>
<b>Final Lumpsum Repair cost</b>	<u>\$0.00</u>

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : FAUZY BIN MOKHTAR

Name : Calvin

Tel : 62148319

Date : 26/4/18

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham ecribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007474/K1tbn2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 07-05-2018	
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GY 734B	Veh. Inspected	SHD 3440C
Policy No.	5047861571-07	Coverage (\$)	0.00
Claim No.	MT/0991206-002	Excess (\$)	0.00
Assign From		Assign Date	23/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FUX03557611	Colour	BLUE
Odometer	162638	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	BRIDGESTONE	7 mm
L/H Front Tyre	195/65 R15	BRIDGESTONE	7 mm
R/H Rear Tyre	195/65 R15	BRIDGESTONE	7 mm
L/H Rear Tyre	195/65 R15	BRIDGESTONE	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	20/04/2018	Inspection Date	23/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3440C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	TO REPAIR	458.60	-
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	RETAINER,REAR BUMPER,SIDE,RH	SERVICEABLE	94.80	-
1	SEAL,REAR BUMPER SIDE,RH	SERVICEABLE	148.40	-
1	REAR RH FENDER (NPA)	TO REPAIR	-	-
	LESS 25% DISCOUNT		-203.62	-
			610.88	-
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
			50.00	-
<b>LABOUR</b>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		420.00	100.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		550.00	400.00
			970.00	500.00
<b>GRAND TOTAL</b>			<b>1,630.88</b>	<b>500.00</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>500.00</b>

Report Ref No. NS/INC18007474/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.