GINYEUUT: CS/TP 1800	17506/RIHOEV 9417K
annun	GNMENT
From: Date:	Veh No: SBS 340(H Yr Regn: Jol4/Jung
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP //WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: S&S 340(H	Make: Volvo 39769.464 c.c 9364
at Workshop m/s Tombe Kgm 1T	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 22 8384 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/NO: 4V3S4P921EA167454
Claims No.	Gen. Cond: Good / (air) Poor / Burnt
Sum Insured: Excess:	Steering: Igorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
shwitch	Tyre Size: F: 275 76R22.5
(Policy Condition) 68171747 482243	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA /MIC/ OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 8 mm R/Bal. 8/8 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 8 mm L/Bal. 8/8 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 17/04/08 D.O.I. 20/04/18
Lum Sum: % 3 Val.: Yes or No	Survey held at Truen TRANSIT
CA / REV / REP. / 24 HRS	Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	(Red: 145.10:2%) 245 /2018
	Days Of Repair: 6 Resurvey No. of Trip: Survey Fee: 750
2) Add Fee	Transportation: 50
	: Interview (\$) Photos 54
Report Format:	: Tech. Invs (\$) Others
Lump (\$653170)	: Weekend (\$
	TOTAL 384

Rasul (LKKAuto)

From: Sharifah Nusaybah Binte Syed Jamil Binshahab <sharifah@towertransit.sg>

Sent: Thursday, 26 April, 2018 5:16 PM

To: Rasul (LKKAuto); Admin-D (LKKAuto); SUR

Cc: Subramanian Kasi; Wu Tzu Ying; Denise Tay (LKKAuto)

Subject: RE: Pre-Repair Inspection - Accident Involving SBS3401H & JLA8567 on 17/04/18

Hi Rasul,

Confirmed COR @ \$6,531.70 / 6 days repair.

Thank you.

Sharifah Nusaybah (Ms) Senior Executive, Claims

·

Mobile +65 9848 2243 Office +65 6817 1747

Email sharifah@towertransit.sg



Tower Transit Singapore Pte Ltd 21 Bulim Drive, Bulim Bus Depot, Singapore 648170 Registration number 201419417K www.towertransit.sg



Disclaimer: This email and any attached files may be coincidental, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email by error, please delete it and notify the sender immediately. The views expressed in this email are not necessarily the views of Tower Transit.

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]

Sent: Thursday, 26 April, 2018 5:08 PM

To: Sharifah Nusaybah Binte Syed Jamil Binshahab <sharifah@towertransit.sg>; Admin-D (LKKAuto) <admin-

d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Subramanian Kasi <Subramanian.kasi@towertransit.sg>; Wu Tzu Ying <Wu.Zy@towertransit.sg>; Denise Tay

(LKKAuto) <denisetay@lkkauto.com>

Subject: RE: Pre-Repair Inspection - Accident Involving SBS3401H & JLA8567 on 17/04/18

Hi Sharifah,

As spoken, finalise amount is at \$ 6,531.70 / 6 days part by part Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

From: Sharifah Nusaybah Binte Syed Jamil Binshahab [mailto:sharifah@towertransit.sq]

Sent: Thursday, 26 April, 2018 4:51 PM

To: Admin-D (LKKAuto); Rasul (LKKAuto); SUR

Cc: Subramanian Kasi; Wu Tzu Ying

Subject: RE: Pre-Repair Inspection - Accident Involving SBS3401H & JLA8567 on 17/04/18

WIHTOUT PREJUDICE

Hi Rasul,

Apologies, please see the attached repair estimate instead.

COR:

Parts: \$1,331.70 (before 7% gst) Labour: \$6,240.00 (before 7% gst)

Repair Days: 06 Days

Please finalise on the cost.

Thank you.

Sharifah Nusaybah (Ms) Senior Executive, Claims

Mobile +65 9848 2243 Office +65 6817 1747

Email sharifah@towertransit.sg



Tower Transit Singapore Pte Ltd 21 Bulim Drive, Bulim Bus Depot, Singapore 648170 Registration number 201419417K www.towertransit.sg



Disclaimer: This email and any attached files may be coincidental, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email by error, please delete it and notify the sender immediately. The views expressed in From: Sharifah Nusaybah Binte Syed Jamil Binshahab

Sent: Thursday, 26 April, 2018 1:52 PM

To: 'Catherine Chong (LKK Auto)'
| 'Catherine Chong (LKK Auto)'
| Catherine Ch

'sur@lkkauto.com' <sur@lkkauto.com>

Cc: Subramanian Kasi < Subramanian.kasi@towertransit.sg >; Wu Tzu Ying < Wu.Zy@towertransit.sg >

Subject: RE: Pre-Repair Inspection - Accident Involving SBS3401H & JLA8567 on 17/04/18

WITHOUT PREJUDICE

Hi Rasul,

Please see attached repair estimate & after-repair photos as requested.

COR:

Parts: \$1,683.76 (before 7% gst) Labour: \$6,000.00 (before 7% gst)

Repair Days: 06 Days

Please finalise on the cost.

Thank you.

Sharifah Nusaybah (Ms) Senior Executive, Claims

Mobile +65 9848 2243 Office +65 6817 1747

Email sharifah@towertransit.sg



Tower Transit Singapore Pte Ltd 21 Bulim Drive, Bulim Bus Depot, Singapore 648170 Registration number 201419417K www.towertransit.sg



Disclaimer: This email and any attached files may be coincidental, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email by error, please delete it and notify the sender immediately. The views expressed in this email are not necessarily the views of Tower Transit.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 19 April, 2018 5:04 PM

To: Alvin Tan <alvin.tan@towertransit.sg>; assignments@lkkauto.com

Cc: Robert Subanney < robert.subanney@towertransit.sg >; Sharifah Nusaybah Binte Syed Jamil Binshahab

- <<u>sharifah@towertransit.sg</u>>

Subject: RE: Survey

Dear Alvin,

Thank you for your email.

We will arrange survey on 20.04.2018.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alvin Tan [mailto:alvin.tan@towertransit.sg]

Sent: Thursday, 19 April, 2018 4:13 PM

To: assignments@lkkauto.com

Cc: Robert Subanney < robert.subanney@towertransit.sg >; Sharifah Nusaybah Binte Syed Jamil Binshahab

<sharifah@towertransit.sg>

Subject: Survey

Hi

As spoken, we will need your service to do a independent survey on our bus as involving an accident with a Malaysia car. Kindly advice.


Thanks & Regards Alvin Tan

Mobile +65 8498 1515 Office +65 6817 1735

Email alvin.tan@towertransit.sg



Tower Transit Singapore Pte Ltd 21 Bulim Drive, Bulim Bus Depot, Singapore 648170 Registration number 201419417K www.towertransit.sg



Disclaimer: This email and any attached files may be coincidental, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email by error, please delete it and notify the sender immediately. The views expressed in this email are not necessarily the views of Tower Transit.

DISCLAIMER: This email and any attached files may be confidential, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email in error please delete it and notify the sender immediately. If you do not wish to receive general email communications, or you wish to change/update your email details, please email grey@towertransit.co.uk to tell us. The views expressed in this email are not necessarily the views of Tower Transit
DISCLAIMER: This email and any attached files may be confidential, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email in error please delete it and notify the sender immediately. If you do not wish to receive general email communications, or you wish to change/update your email details, please email grey@towertransit.co.uk to tell us. The views expressed in this email are not necessarily the views of Tower Transit
DISCLAIMER: This email and any attached files may be confidential, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email in error please delete it and notify the sender immediately. If you do not wish to receive general email communications, or you wish to change/update your email details, please email grey@towertransit.co.uk to tell us. The views expressed in this email are not necessarily the views of Tower Transit

collision report card/aide memoire

details given to third party? Y/(N)



bus captain details bus reg: Sb\$ 3401 H employee no: 10310 insurance ref: depot ref: third party details driver's name: nric: occupation: address: tel: 01>>>570458 (m) vehicle reg: JLA \$67 colour: BLAck make: MSIA. insurance details: location: JTH -> Jln Ahmad time: 8.52pm passengers: 7 collision circumstances please give your account of what happened damage to other vehicle/ property (full description): injuries: NIL

photographs obtained? (Y) N

• • •				
		,		
ketch of incident scene				
		į		
		7		
		1		
		j		
lamage to bus				
please mark with an X the point(s) of impac		cle one of the		
following words to indicate the extent of th	e dåmage.	***		
nearside offside				
front rear rear	front front	rear		
▋ ┦ ╎┝┈╙╌┸╌┦				
light / moderate / severe light / moderate /	severe light / m	oderate / severe		
		·) .	
oolice details		<u> </u>	j	
did the police attend? (Y) N PC ho.,	/ station: 🖒 - 🔀	18-0417-A	1)	
	ادمما	-,,,,,	'1	
vitness details	JEARY			
8 3 4 E 8 C 1 2 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
name:	tel:	(m)		
address:		1		
passenger/ pedestrian/ motorcyclist/ other:	*	_ (please circle)		
2224	#-1	/		
name: address:	tel:	(m)		
		Inlance simple)		
passenger/ pedestrian/ motorcyclist/ other:		_ (please circle)		

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the Géneral Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Policyholder's Signature Date & Time:



BC Statement Form

Name: PANG MAN LIN Emp No: 10310	Date of statement: 17/4/18 Time of statement: 11.60 pm
Statement taken by - Name : SHANCT	Position:
Incident details - Nature of incident :	
Date of incident	Time of incident :
Statement of details of Incident.	
`	••
-	
	·
I confirm that the above statement provided by me conthe best of my ability. Name:	tains the details of the incident as stated to Signed:
	1

PICPUMIC DI SAI				>	
SREICH PLAN		1/2 X	hand	1 brahim	$\Delta^{(-1)}$
D		OIN A	TIMU	(Bio(rt)	i May 1
		- · · ·			
AYE	138				
4	X 20 X				
	TO				
	2				
4	3 1				er e
			. ' :		
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT			1-1	
· · · · · · · · · · · · · · · · · · ·			·	- k - 161 /_ /_ /	
	the same of the sa	132 5		- 1/ ///	
	<u> </u>			Colombia de la participa de la	4
		- 1 m - 1	/_	,	
	· · · · · · · · · · · · · · · · · · ·	<u> </u>			
1 WAS Drive	e my bus se	5 3/11 H a	nina Stra	aiaht abna	the
junction of Jun		Road towa			oad.
		to the right		bus in a	nother
	oing straight w	en the ma	lays: or	or Tungal	eft
when I harned	at the car which				
1	ertake the bus		•		in
time despite -	the slow speed	d and hence	e, collic	ted with t	ne
Car.				· · · · · · · · · · · · · · · · · · ·	
DECLARATION					
I/We declare the foregoing parti	culars are true in every respect		9.		(
	74/2 X	4/14/18		1 Xin	

Oriver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Policyhoider's Signature

used early light in La

Date & Time:



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$2725414D



PANG MAN LIN



CHINESE Date of birth 21-07-1966 Country of birth





This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrandered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Туре

Description

Issue Date

06

OMNI BUS VL

13/04/2016





MIC No. S2725414D



MALAYSIAN Date of leases 01-07-2004

APT 8LK 358 BUKIT BATOK STREET 31 #11-381 SINGAPORE 650358 NRIC No: \$27254140 Date: 09/04/2013

Date: 09/04/2013

8623921

30 M 1313 17 Sep 2013

\$2725414B

S / No. 9000188080

NP 428A



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	TATE OF	ini-ini	тетл	III = 1.7 1 •	111
		12.3	1 O I A		

Date Of Report

23/04/2018 11:15

Date Of Accident

17/04/2018 20:50

Exact Location Of Accident

JURONG TOWN HALL ROAD

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SBS3401H

Insured/Policyholder

Name Of Registered Owner

TOWER TRANSIT SINGAPORE PTE LTD

Co Reg No

201419417K

Email Address

SHARIFAH@TOWERTRANSIT.SG

Mobile Phone No

Alternative Phone No

OFFICE-68171747

Vehicle Particulars

Manufacturer **VOLVO**

Model

B9TL-9.4 D (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

BUS

Insurance Company

Name of Insurance Company

MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

YES

Policy Number

D-17089154MFBP

Cover Note Number

Driver - 4014

Name of Driver PANG MAN LIN

NRIC No Date Of Birth S2725414D

21/07/1966 Occupation **OUTDOOR** Date Of Driving Pass 17/09/2013

Driving Experience

4 YEARS AND 7 MONTHS

Gender

FEMALE

Mobile Number

Fax Number

Contact Number

EMail Address

NOEMAIL.

Address

21 BULIM DRIVE

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JLA8567 (PRIVATE CAR)

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

q

Details of Police Action to Acust

YES

Was the accident reported to the police? If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE HEADQUARTERS

Police Station Address

ROAD: 10 UBI AVENUE 3 SINGAPORE, POSTCODE: 408865,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED STATEMENT.

Attachment(s)

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Are accident photos available for attachment? Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>tructiful</u> and <u>accurate as possible</u>. Any within misrepresentation or withholding of material facts may allow insurance companies to <u>reputilate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any failer reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the Géneral Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my daims (including the mailing of correspondence, statements, invokes, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims_(collectively the "Purposes")
- (b) ell insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sized outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or creat orders

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:


MRIC/FIN No.:

Reporting Control Persons

Page 3 of 5

٠.	Sketch Pla	n #2	
BRETTOH PLAN		Uln 4thmad	Ibrahim;
AVE	4 12 42 A		
DESCRIBE CHCUMSTANCE DE	THE ACCUPANT		
1 WAS Drive	my bus SBS 3		aight about the
while the car Juliane I was quit into the occurring	of Society was to the same wants	the malays: a	e bus in another
to try and over- time despite the	L-L- 4	he bus could	not Stop in
DECLARATION			
VWs disclare the foregoing particular	验公	7/4/18	Aa-
Folicyholder's Signature Cete & Yime:	Oriver's Signature (If driver is not the policyholder) Deta & Times	Reporting Carf Name: NRIC/PIN No.:	SIANO.

they are the state of the



ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	2050HRS	BUS REGISTRATION NUMBER	SBS3401H
ACCIDENT DATE	17-Apr-18	BUS TYPE (SD/DD)	DD
BUS CAPTAIN NAME	PANG MAN LIN	BUS ROUTE NUMBER	
EMPLOYEE NUMBER		BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

	Part No.	Part or Item Description	Quantity	Total Cost
	77200199	LAMP IND. FRONT LED		1 3/6/ \$219.83
	77200602	HEADLAMP DIPPED BEAM		1 \$80/ \$163.70
	77201117	O/S CORNER BUMPER		1 CAA / \$327.14
	77201118	O/S LIGHT BEZEL		1 (04 / \$132.29
-	77201121	N/S CORNER BUMPER		1 CA / \$358.7
	77201116	O/S DEFLECTOR		1 44 / \$120.82
	77040867	TOWER TRANSIT CUT OUT LOGO STICKERS		1 nec / \$9.20
				1331.70
			7% GST	\$93.22
			FINAL TOTAL COST	\$1,424.92

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

	LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
	TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)		5200 \$6,240.00
			· ·
			Sico
		7% GST	\$436.8
		FINAL TOTAL COST	\$6,676.80

242120

PAGE 1

ESTIMATED ACCIDENT REPAIR COST



SECTION 5: REPAIRS TO BUS ADVERTISMENT	VINYLS/PANELS (ADVERTISEMENT COST)
--	------------------------------------

TOTAL ADVERTISEMENT REPAIR COST

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

LOSS OF USE COST			\$2,400.00
BUS TYPE (SD / DD)	DD	Number of Days Under Repa	ir 6
		Date Out From Repairs	26/4/2018
		Date In For Repairs	20/4/2018

SUMMARY					
SECTION NO.	COST				
1	\$1,424.92				
2	\$6,676.80				
3	•				
4	-				
5	\$2,400.00				
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$10,501.72				

1331.70 5200.00 6531.70

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u>
 is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90000068

6 days

7/P

20/04/18@1715

Resurry 64 paint



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internat	ionale Des Ex	perts En Automo	bile - A - A - A - A - A - A - A - A - A -				
TOWER TRANSIT SIN	GAPORE PTE. LTD.	Ref : C	S/TP18007506/	/R1tbe2				
21 BULIM DRIVE SINGAPORE 648170 ON BEHALF OF TOWER TRANSIT SINGAPORE PTE LTD		Date: 3	30-05-2018					
		Code: T	P479					
1.	Policy Particulars :- THIRD PARTY-CLAIM							
Insured Veh.	Insured Veh.		pected	SBS 3401H 0.00				
Policy No. Claim No.		Coverag	e (\$)					
		Excess (\$)		0.00				
Assign From		Assign [Date	20/04/2018				
2.	Vehicle Part	iculars & C	ondition 👑	(中国) (中国) (中国) (中国) (中国) (中国) (中国) (中国)				
Make & Model	VOLVO B9TL 9.4L AUTO	c.c		9364				
Engine No.	HIDDEN	Year of Reg.		2014				
Chassis No.	YV3S4P921EA167464	Colour		GREEN				
Odometer	Odometer 228384 Brakes IN ORDER			IN ORDER				
Brakes			tion	NIL				
General	FAIR		<u>.</u>					
3.	Condi	tions of Ty	rés					
	Size	Make		Balance				
R/H Front Tyre	275/70 R22.5	MICHELIN	N	8 mm 8 mm				
L/H Front Tyre	275/70 R22.5	MICHELIN	J					
R/H Rear Tyre	275/70 R22.5 (D)	MICHELIN MICHELIN		8/8 mm 8/8 mm				
L/H Rear Tyre	275/70 R22.5 (D)							
4. 35	Descript	ion of Dam	ages 🐪 😕					
THE VEHICLE SU	STAINED DAMAGES AT THE F	RONT PORT	ION.					
DAMAGES SEE D	ETAILS.							
5.	Gener	al Informat	ion.					
Accident Date	17/04/2018	Inspection		20/04/2018				
Survey held at	TOWER TRANSIT SINGAPOR	E PTE. LTD.						
	21 BULIM DRIVE SINGAPORE 648170							
5a.		Remarks	Pallings of the Control of the Contr					
A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS, I	ITHOUT PRE WE HAVE NO	JUDICE" BASIS OT AUTHORISE	S. D REPAIRS.				
5b.	Estimate	e Day s of R	epair 💮 🦠					
ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6	Working Days					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 3401H

RECOMMENDED COST OF REPAIRS

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	
	REPLACEMENT OF PARTS			
1	LAMP IND. FRONT LED	BROKEN	219.81	219.81
1	HEADLAMP DIPPED BEAM	BROKEN	163.76	163.76
1	O/S CORNER BUMPER	CRACKED	327.14	327.14
1	O/S LIGHT BEZEL	CRACKED	132.25	132.25
1	N/S CORNER BUMPER	CRACKED	358.72	358.72
1	O/S DEFLECTOR	CRACKED	120.82	120.82
1	TOWER TRANSIT CUT OUT LOGO STICKERS	NECESSARY	9.20	9.20
			1,331.70	1,331.70
	LABOUR			
	TO REPLACE / REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)		6,240.00	5,200.00
			6,240.00	5,200.00
	GRAND TOTAL		7,571.70	6,531.70

Report Ref No. CS/TP18007506/R1tbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.