

ASS. REC. BY:

REF: CS3 / msl18007520 / Sz4b54

Special Instruction:

Survivor  
Melimen

Sebastian

ASSIGNMENT (Office)

From (Person):

Hionel Tan

of

MSTH

Date/Time:

24/04/2018 8:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 4426K

Insured:

FBF 251L

at Workshop m/s

Seng Hwee Motor

Tel:

9786 5675

of

Blk 1078 Yishun Ind Park A #01-350

Policy No:

8290 75336 TPY

Claim No:

556352

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'lap'

H.O.D. Endorsement:

Date/Time:

24/04/2018 9:31am

Person Contacted:

Mr. Kueh

Vehicle IN OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLX 4426K - X
	FBF 251L - X

SYDNEY

REF:


# ASSIGNMENT

Yr Regn: 28/3/2018

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLX 9426K  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai / Elantra C.C. 1591  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 823 T/Radio: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C/No: KM140842 Cam JU 626858  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or  
 Brake:  Inorder / Jammed / Leaked / Burnt or  
 Modi:  Nil / S/Rim / STD A/Rim or  
 Tyro Size: F: 225/45 R17  
 R: 11

(Policy Condition)  
 Remark: The vch had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Pirelli

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	22/4/18	D.O.I.	24/4/18

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Survey held at Seng Hwee  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
N/S Rear  
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
 \* Repair Estimate : \$ 2500 - 3000  
 \* 2 days

23/4/18 Submit PRS Submit

RECEIVED 30 APR 2018

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Date/Time, File Return to?

Report Format :  
 Lump Sum / L.B.: \$

Days Of Repair:  
 Resurvey No. of Trip:

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Survey Fee:  
 Transportation:  
 \$ - RS. \$  
 : Photos  
 : Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		24 Apr 2018 08:51 Assign				<b>New Assignment</b> Cancel Case

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HASHIM BIN MOHAMED, ID: S1348570D, Tel: +6598297345, Email: CLAIMS@GOLDAUTOWORDS.COM.SG								
Main Claimant:	BANTIAN ENGINEERING & TRADING SERVICES, Co. Reg. No.: 39265600X								
Vehicle Reg. No.:	SLX4426K	Date of Loss: 22/04/2018 11:00 - :59 [25 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 556352	Policy/Cover Note No.: B29075336TPY (Third Party Only) Coverage: 14/03/2018 - 13/03/2019							
Vehicle Reg. No. (Insured):	FBF251L	Policy No. (Claimant): Excess:							
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/04/2018]								
Driver/Custodian (Insured):	HASHIM BIN MOHAMED (58 / Male), NRIC: S1348570D, Tel: +6598297345								
Adj Asg. Remarks:	Please contact MR KUEH @ 9786 5675 / 6755 5205 to arrange for survey.								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your ref : FBF 251L  
 Our client's vehicle / ref: SLX 4426K ; SW/sy/ms  
 Date : 23 April 2018

MSIG Insurance (Singapore) Pte Ltd

By Email Only

Dear Sirs,

**DATE OF ACCIDENT: 22 APRIL 2018**  
**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	William Ng	Allied Auto Appraisal
2.	Foo Philip	Precision Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : Seng Hwee Motor  
 Address : Block 1018 Yishun Industrial Park A  
 #01-350  
 Singapore 768760  
 Contact : Mr Kueh (6755 5205 / 9786 5675)

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,

*Gay*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/04/2018 15:04
Date Of Accident	22/04/2018 11:45
Exact Location Of Accident	AFTER WOODLANDS CHECKPOINT TWDS JOHORE BAHRU
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX4426K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BANTIAN ENGINEERING & TRADING SERVICES
Co Reg No	39265600X
Email Address	JIMMY.CHIA.BANTIAN@LIVE.COM
Mobile Phone No	(LOCAL) +65-96625132
Alternative Phone No	OFFICE-96625132

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN885171
Cover Note Number	28/03/2018 - 27/03/2019

### Driver

Name of Driver	CHIA TEAN YONG
NRIC No	S1415122B
Date Of Birth	29/04/1960
Occupation	INDOOR
Date Of Driving Pass	21/08/1982
Driving Experience	35 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96625132
Fax Number	
Contact Number	
Email Address	JIMMY.CHIA.BANTIAN@LIVE.COM

Address BLK 239 BUKIT BATOCK EAST AVE 5  
#09-161

Postcode 2365

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 5

Passenger 1 NAME: : CHIA WAN TIAN  
GENDER: : MALE

Passenger 2 NAME: : CHIA SER LI  
GENDER: : FEMALE

Passenger 3 NAME: : CHIA AEE LING  
GENDER: : FEMALE

Passenger 4 NAME: : CHIA WEN TING  
GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BUKIT BATOM NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 21 BUKIT BATOM EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED STATEMENT AND POLICE - NOTICE OF REPORTING

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WITH OWNER - STILL TRYING TO RETRIEVE


Was there any audio recorded? NO

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBF251L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	98297345
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


on 22.04.2018 at 1145 hrs, I was driving my car A (SLX4426K) along the driveway on the furthestmost left lane after woodlands checkpoint towards Johor checkpoint when a motorcycle B (FBF251L) tried to overtake my car on the left and grazed against the left rear side of my car. AS a result, the left rear wheel rim, left rear tyre and left rear bumper were damaged,

claim TP of my workshop - Sengy Kure motor  
email report to them too

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 23-04-2018  
 Sole proprietor

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 23-4-2018

**AH LIM MOTOR COMPANY**  
 No. 10 Ang Mo Kio Industrial Park 2A  
 Singapore 5680A1  
 Tel: 6383 1244 Fax: 6383 8174  
 Name:  
 NRIC/FIN No.:



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2018		24 Apr 2018 08:51 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HASHIM BIN MOHAMED, ID: S1348570D, Tel: +6598297345, Email: CLAIMS@GOLDAUTOWORDS.COM.SG								
Main Claimant:	BANTIAN ENGINEERING & TRADING SERVICES, Co. Reg. No.: 39265600X								
Vehicle Reg. No.:	SLX4426K	Date of Loss: 22/04/2018 11:00 - :59 [25 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 556352	Policy/Cover Note No.: B29075336TPY (Third Party Only) Coverage: 14/03/2018 - 13/03/2019							
Vehicle Reg. No. (Insured):	FBF251L	Policy No. (Claimant): Excess:							
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 25/04/2018]								
Driver/Custodian (Insured):	HASHIM BIN MOHAMED (58 / Male), NRIC: S1348570D, Tel: +6598297345								
Adj Asg. Remarks:	Please contact MR KUEH @ 9786 5675 / 6755 5205 to arrange for survey.								
<b>ASSOCIATED MAIL RECEIVED</b>									
		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
• MSIG_SG (26/04/2018): REQ FINAL REPORT - SLX4426K									
<b>ALL ASSOCIATED TASKS</b>									
		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLX4426K (556352)**  
**[FBF251L]**

TP

**BANTIAN ENGINEERING & TRADING SERVICES**

**Apr 22 2018 11:00AM**

**[HASHIM BIN MOHAMED]**

**Seng Hwee Motor**

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/04/18 08:23	<b>Accident Statement</b> From:SC - Reg. No: FBF251L, Claimant: HASHIM BIN MOHAMED	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	25/04/18 11:40	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/04/18 08:23	<b>TPD SLX4426K GIA REPORT</b> From:SC - Reg. No: FBF251L, Claimant: HASHIM BIN MOHAMED	Load PDF	
2	24/04/18 08:27	<b>Pre-Repair Survey</b>	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG18007520/SZ4BS2  
**Date:** 03/05/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29075336TPY
<b>Claimant Vehicle No :</b>	SLX4426K	<b>Insured Vehicle No :</b>	FBF251L
Date of Loss:	22/04/2018	Nature of Claim:	TP
		Claim No:	556352

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLX4426K</b>	Engine No:	G4FGJU133372
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU626858
Reg. Date:	28/03/2018 (Man. Year: 2018)	Odometer:	823 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	255/45R17	Rear Tyre Size:	255/45R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	24/04/2018		
Date Inspected:	24/04/2018	Inspected At:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350 Singapore 768760
Estimated Period of Repair:	0.0 days		

**Adjuster:** Sebastian Yeang Wai Keen

**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2018)
<b>Parts:</b> 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLX4426K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >