

ASS. REC. BY:

REF: CS/MSH18007930/R1vbn2 Special Instruction:

Surveyor: Rasul ASSIGNMENT (Office)From (Person): Limel Tan of MSLH Date/Time: 24042018 1129am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFV 85T Insured: SJV 87819at Workshop m/s Volkswagen Tel: 6305 7176of 247 Alexandra RdPolicy No: 8024 2384 SMP Claim No: 556400

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 22042018
(Client's Record)CA / REV / REP. / REV 24 HRS WSP 25-04-2018 @ 1230 pm I.O.D. Endorsement: _____Date/Time: 24042018 233pm Person Contacted: Charmaine Vehicle-IN/OUT: OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SFV 85T - X
	SJV 87819 - X
26/4/18	Send preli revised by merimen
16/5/18	Final fig \$ 8572.22 (Red 4572.26, 33%) confirmed by email

15/5

Wagon
Sut Sum
Maimen

REF: msh

75364

ASSIGNMENT

From: Date: 25042018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFV 85T

at Workshop m/s Volkswagen
of JHA Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

12.30pm

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFV 85T Yr Regn: 2014 / Jun

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen SHARAN 2.0 C.C. 1984

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 52007 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVW2227NZE60288897

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 225/50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/04/18 D.O.I. 25/04/18

Survey held at Volkswagen main

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: 1

2) 16/5 - typist

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation

S + RS. SI

Photos

Others

Report Format: maimen

Lump Sum / I.B.I. (\$) 8572.22

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

TOTAL

300

10

310

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		24 Apr 2018 11:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM PEK HONG, ID: S0165226E, Tel: +6597572391								
Main Claimant:	KOH KHENG SIONG, ID: S0157536H								
Vehicle Reg. No.:	SFV85T	Date of Loss:	22/04/2018 12:00 - :59 [46 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556400	Policy/Cover Note No.:	80242384SMP (Comprehensive) Coverage: 12/02/2018 - 11/02/2019						
Vehicle Reg. No. (Insured):	SJV8781S	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/04/2018]								
Driver/Custodian (Insured):	LIM SHU-EN ARIEL (27 / Male), NRIC: S9024655J, Tel: +6597572391								
Adj Asg. Remarks:	Please contact Ms Charmaine Kong @ 6305 7176 to arrange for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Lionel Tan Tian Pei	Date: 26 Apr 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SJV8781S		
TP Vehicle No	: SFV85T	Accident Date	: 22/04/2018
Make	: VOLKSWAGEN SHARAN	Assignment Date	: 24/04/2018
Date of Inspection	: 25/04/2018	Est. Duration of Repair	: 5.00
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE (HQ) 247 ALEXANDRA ROAD SINGAPORE 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,819.60
Revised Amount	:S\$	8,522.46
Check Items (Estimated)	:S\$	51.94
Total	:S\$	8,574.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 16 May 2018 2:30 PM
To: 'Cheong, Pearlyn (VWG Singapore)'; Rasul (LKKAUTO); SUR; Admin A; Admin-D (LKKAUTO)
Cc: Kong, Charmaine (VWG Singapore); Wong, Mei (VWG Singapore); Foo, John (VWG Singapore)
Subject: RE: SFV85T - FINALISE

Dear Pearlyn,

WITHOUT PREJUDICE

Confirmed COR \$8,572.22 before GST

Total 5 working days

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]
Sent: Wednesday, 16 May 2018 1:52 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Mei (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>
Subject: RE: SFV85T - FINALISE

fyi


Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
Main line: +65 6305 7299

Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>



From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 16 May, 2018 12:13 PM
To: Cheong, Pearlyn (VWG Singapore); Rasul (LKKAuto); SUR; Admin A; Admin-D (LKKAuto)
Cc: Kong, Charmaine (VWG Singapore); Wong, Mei (VWG Singapore); Foo, John (VWG Singapore)
Subject: RE: SFV85T - FINALISE

Dear Pearlyn,

Please provides us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Monday, 14 May 2018 7:50 AM
To: 'Cheong, Pearlyn (VWG Singapore)' <Pearlyn.cheong@vw.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Mei (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>
Subject: RE: SFV85T - FINALISE

Dear Pearlyn,

Please provides us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]

Sent: Saturday, 12 May 2018 11:11 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>

Subject: SFV85T - FINALISE

Dear Rasul,

Please confirmed

COR \$8572.22 before GST

Total 5 working days

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
Main line: +65 6305 7299
Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>

New Arteon.

This is high performance art.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2018 09:27
Date Of Accident	22/04/2018 12:40
Exact Location Of Accident	ALG LEEDON PARK TOWARDS JALAN SAMPURNA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFV85T
Insured/Policyholder	
Name Of Registered Owner	KOH KHENG SIONG
NRIC No	S0157536H
Email Address	KOCHKHENGSIONG@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97800033
Alternative Phone No	OFFICE-97800033

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SHARAN NF 2.0 TSI (DSG6)+EQP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28750224 AVW
Cover Note Number	

Driver

Name of Driver	HARTMAN KEVIN ROBERT
Passport No/FIN	G1323270P
Date Of Birth	19/01/1979
Occupation	INDOOR
Date Of Driving Pass	08/05/2014
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91256214 (MRS KOH)
Fax Number	(LOCAL) +65-91256214
Contact Number	
Email Address	SIAN_KOH@YAHOO.COM.SG

Address	9 JALAN HARUM
Postcode	268482
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SON-IN-LAW
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : JAIME KOH GENDER: : FEMALE
Passenger 2	NAME: : AIDAN HARTMAN GENDER: : MALE
Passenger 3	NAME: : GALEN HARTMAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MORE DETAILS PLEASE REFER TO SKETCH PLAN & VIDEO FOOTAGE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SIZE FILE EXCEEDED, UNABLE UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV8781S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM SHU-EN, ARIEL
NRIC/Passport Number	S9024655J

Contact Number

97572391

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attachment

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Phing

Policyholder's Signature _____
Date & Time: _____

Keri Her

Driver's Signature
(If driver is not the policyholder)
Date & Time:

h

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

On the afternoon of 22/04/2018, I was driving along Leedon Park towards Jalan Sampurna. As I approached the left-hand bend, I slowed down my vehicle. As I began to negotiate the left-hand bend, I saw a white vehicle approaching from the opposite direction via the road safety convex mirror. The driver of the oncoming car was driving outside of its lane. I then took evasive action by slowing down to a complete stop. Despite my efforts, the oncoming car impacted the front right of my vehicle. Photos were taken at the incident area and after both parties moved to the side of the road to exchange particulars; the driver acknowledged she was at fault.

Ariel Lim: 9757-2391

Vehicle: SJV 87815


Day: 22-04-2018

Time: 12:40pm

Driver

- Kania Han
23-04-2018

Owner


Koh Kheng Siang



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

VW DRIVEEASY
Comprehensive

Certificate No. A 28750224 AVW

Excess : SGD1,500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SFV85T

2. Name of Policyholder
Koh Kheng Siong

3. Effective Date of the Commencement of Insurance for the purposes of the Act
13/06/2017

4. Date of Expiry of Insurance
12/06/2018

5. Persons or Classes of Persons entitled to drive*

Koh Kheng Siong

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

STV 857

A 28750874 Am

Area: 41.5

NCO: 50% + 5%

Yes protected.



REPUBLIC OF SINGAPORE
FIN G1323270P



Name
HARTMAN KEVIN ROBERT

Date of Birth 10-01-1979 Sex M
Nationality AMERICAN



Mrs. Koh

91256214

9 Jln Harum

sian_koh@yahoo.com.sg

Accident Sketch Plan Pg. 1

FA2019871

VISIT PASS
Immigration Regulations



FIN G1323270P

PLUS


Date of Issue 10-10-2017 Date of Expiry 10-10-2020



YOU ARE TO Surrender THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Class 3. Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 06 May 2014

NP 428A



Date : 23/04/18

Dear Sir or Madam :

To whom it may concern,

RE: Authorization to act on behalf

Vehicle No.: S 7V 857

I, Poh Khay Sing, bearing NRIC Number S01 573867,


would like to authorize Hartman Lenn Robey, bearing NRIC

Number 6 1323270P, to act on my behalf to exercise my

Insurance Policy to give authorization on the repair, submit and signing of
all claims related documents including signing of Insurance discharge
voucher for the above said vehicle.

Thank You.

Yours Sincerely,


.....X
Signature

PDI TUAS

PDI TUAS

KOH KHENG SIONG
9 JALAN HARUM
Singapore, 268482
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV025505
Quote No. SER/QUO/1800701
QuoteDate 23/04/18
Salesperson Jeremy Lee
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Sharan NF 2.0 TSI (DSG6)+EQP	51,946	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SFV85T	WVWZZZ7NZEVO28897	13/06/14	Jeremy Lee
Engine Code	Labor Type	Engine No.	Model Code
	10	CCZ 422942	7N14H3

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT	✓ 1680	3,360.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT	✓ 1600	3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un	✓	480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un	✓	280.00
	Sum Labor				7,320.00
P 7N0807184A	BUMPER BRACKET RHS	1	Pieces	ne / ?	24.88 ✓
P 7N0807217J GRU	FRONT BUMPER	1	Pieces	defond, ser / ?	1,479.91 ✓
P 7N0807724	BUMPER RETAINER RHS	1	Pieces	ser / ?	27.06 X
P 7N0821022B	FENDER RHS	1	Pieces	R	965.20
	Use Predecessor 7N0821022A				
P 7N2941754B	HEADLAMP RHS	1	Pieces	ser /	3,002.55 ✓
	Use Predecessor 7N2941754A				
	Sum Item				5,499.60
				12, 844.48	
	Sum Labor				7,320.00
	Sum Item				5,499.60
	Total SGD				12,819.60
	7% GST			12,819.60	897.37
	Total SGD Incl. GST				13,716.97

Payments to: - BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO.: 18IP1105

CUSTOMER NO.: CV025505

CUSTOMER NAME: KOH KHENG SIONG

TELEPHONE NO.:

ADDRESS: 9 JALAN HARUM

Singapore

VEH No.: SFV85T

Order Date: 25/04/18

Reg Date: 13/06/14

KM: 51,946

VIN NO.: WVVZZZ7NZEV028897

ENGINE NO:

SA: Cheong Pearlyn

MODEL: Sharan NF 2.0 TSI (DSG6)+EQP MODEL NO.: 7N14H3

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
2	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280		280
3	B&P ALEX LABOUR LABOUR	2	UNIT	840		1,680
4	B&P ALEX PAINT SPRAY PAINT	2	UNIT	800		1,600
Item						
5	7N0807217J GRU FRONT BUMPER	1	PCS	1,479.91		1,479.91
6	7N2941754B HEADLAMP RHS	1	PCS	3,002.55		3,002.55
7	7N0807183A BUMPER SIDE BRACKET LH	1	PCS	24.88		24.88
8	7N0807184A BUMPER SIDE BRACKET RH	1	PCS	24.88		24.88

Remarks : MSIG DIRECT SETTLEMENT

DOA 22/04/2018

SURVEYOR LKK RASUL

TP VEHICLE SJV8781S

TOTAL	8,572.22
GST AMOUNT	600.06
TOTAL AMOUNT	9,172.28

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007530/R1VBN2

Date: 17/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80242384SMP
Claimant Vehicle No :	SFV85T	Insured Vehicle No :	SJV8781S
Date of Loss:	22/04/2018	Nature of Claim:	TP
		Claim No:	556400

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV85T	Engine No:	CCZ422942
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI AT 7N14H3 (A)	Chassis No:	WVWZZZ7NZE028897
Reg. Date:	13/06/2014 (Man. Year: 2014)	Odometer:	52007 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,524.48	4,532.22	992.26	17.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	4,040.00	3,280.00	44.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,844.48	8,572.22	4,272.26	33.26
+ GST 7.00/7.00% (S\$)	899.11	600.06	299.05	33.26
Nett Amount (S\$)	13,743.59	9,172.28	4,571.31	33.26

INSPECTION

Date of Assignment:	24/04/2018	
Date Inspected:	25/04/2018	Inspected At:
		Volkswagen Centre Singapore (HQ)
		247 Alexandra Road
		Singapore 159934

Estimated Period of Repair: 5.0 days**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2018)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFV85T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER BRACKET RHS	Necessary	24.88 FS	*24.88 FS
2	1		*FRONT BUMPER	Deformed/Scratched	1,479.91 FS	*1,479.91 FS
3	1		*BUMPER RETAINER RHS	Serviceable	27.06 FS	*- FS
4	1		*FENDER RHS	Repair	965.20 FS	*- FS
5	1		*HEADLAMP RHS	Scratched	3,002.55 FS	*3,002.55 FS
6	1		*BUMPER SIDE BRACKET LH	Necessary	24.88 FS	*24.88 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **5,524.48** **4,532.22**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	3,360.00	1,680.00
2	SPRAY PAINT	New	3,200.00	1,600.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
4	CHECK WIRE HARNESS,ECU,S	New	280.00	280.00
Gross Labour Cost (\$\$)			7,320.00	4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >