



SMRT Automotive Service Pte Ltd  
 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592  
 Estimator Telephone Number : 68662623  
 Accident Reporting Number : 68662672

## SMRT Accident Vehicle Repair Estimates

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SMB177J  
 Ref. No : BUS/03/18/1016  
 Reg. Date : 12/03/2018  
 Vehicle Type : BUS -12M  
 Make : MBOC500 (MERCEDES)  
 Model : MB CITARO O530  
 Name of Driver : Samsudin Bin Parik  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 10/03/2018 10:48:00 AM  
 Accident Reported Date / Time : 12/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : AIG  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC, if any :  
 SMB177J - RIGHT REAR PORTION  
 SLS5993J (TP) - INSURED WITH AIG  
 Prepared Date : 12/03/2018 06:10:49 PM



Chassis No :  
Work Shop :

Mileage : 0  
Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	795.00	0.00
Total Spray Painting Charges	616.00	0.00
Total Material Charges	0.00	0.00
Other Charges	0.00	0.00
<b>TOTAL</b>	<b>1,411.00</b>	<b>0.00</b>
Lum Sum Total	1,400.00	0.00
No. of Repair Days	2.00	0.00
Prepared / Adjusted By		<i>1 day - Surveor</i>
Arc / Surveyor Sing Off Date	20/04/2018 09:36:38 AM	01/01/1900 12:00:00 AM

*[Signature]*  
*[Signature]*  
*20/04/18 Ellis*

Prepared / Adjusted Date :  
Remarks :  
Prepared Date : 20/04/2018 09:36:38 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :  
Quotation Date :  
Invoice Amount :  
Invoice No :  
Invoice Date :  
Prepared Date :

LKX Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	795.00	0.00
<b>Total Labour</b>	<b>795.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>616.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
-------------	---------	----------	-----------	-----	-----------------	--------------	------------------	-----------------	-------------------	-----------------

**TOTAL MATERIALS**

TOTAL MATERIALS(Discounted)

0.00 0.00

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------

**TOTAL SUPPLEMENTARY MATERIALS**