

REC. BY:

REF: 033 / CT118007530 / 72463

Special Instruction:

SURVEYOR

Mafma

GIR

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 26/4/2018 4:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 4208E

Insured:

SJJ 9838U

at Workshop m/s

mcs Auto

Tel:

6296 9939

of

1100 Serangoon Rd

Policy No:

DMPCSN3084161700

Claim No:

SNM18D01997C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17042018

CA / REV / REP. / REV 24 HRS Wpt

H.O.D. Endorsement:

Date/Time:

26/4/2018 9:40am

Person Contacted:

Stephanie

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	FBL 4208E - CS/MSA18007276 / Avb	DM: 170418
	SJJ 9838U - CS/AXA13012584 / Hlg3	DM: 390613
30/4/18	Dismantled	
10/5/18	After Repair	

REF:

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBL H208E

Yr Regn: 2016 Oct 11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha YBR125

C.C. 124

Colour:

White

A/C: Insured / Std / NI / NA

Sp Reading

35071

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LBPRE101000058489

Gen. Cond: Good / Fair / Poor / BurntSteering: Inoper / Jammed / Leaked / Burnt orBrake: Inoper / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 2.75 - 18

R: 3.00 - 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17042018

D.O.A.

24042018 @ 6:17pm

Survey held at

MCS Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$4,000 - \$4,800

Range + No. of days

30/7/18

Submit PIR report

27/7/2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + PS: \$

) Photos

) Others

Report Format: PRE

Lump Sum / I.B.I. (\$

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		23 Apr 2018 16:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	TUNG KWAN LOOI, ID: S8086957F		[Created by insurer]
Main Claimant:	HAFETZ HAKIM BIN HALIL, ID: 4 05925621		
Vehicle Reg. No.:	FBL4208E	Date of Loss:	17/04/2018 13:00 - :59
Claim Type:	TP / SNM18D01997C02	Policy/Cover Note No.:	DMPCSN3084161700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJJ9838U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/05/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
No results.									

MS118051881 / STA INSPECTION PTE LTD - Sin Ming
ENTRY DATE & TIME: 19/04/2018 15:02
SUBMITTED BY: Wang Lip Yong

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 19/04/2018 15:08

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/04/2018 15:02
Date Of Accident 17/04/2018 13:50
Exact Location Of Accident CTE TOWARDS AYE NEAR BRADDELL EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBL4208E
~~Insured Policyholder~~
Name Of Registered Owner WILSON PARKING (SINGAPORE) PTE LTD
Co Reg No NA
Email Address FREDDIE.CHEW@WILSONPARKING.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-84303285

Vehicle Particulars

Manufacturer YAMAHA
Model YBR125-123CC (M)
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number B 27638761 VMF
Cover Note Number

Driver

Name of Driver HAFETZ HAKIM BIN HALIL
NRIC No G2930721R
Date Of Birth 07/05/1993
Occupation INDOOR
Date Of Driving Pass 02/08/2017
Driving Experience 0 YEAR AND 8 MONTH
Gender MALE
Mobile Number (LOCAL) +65-84303285
Fax Number
Contact Number
Email Address NOEMAIL

Address 300 BEACH ROAD
SINGAPORE

Postcode 199555

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLJ9838U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TUNG KUAN LOOI

NRIC/Passport Number

Contact Number 85530118

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGW2255Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CAJ JIAYI

NRIC/Passport Number

Contact Number

97769922

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FBN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along CTE towards AVE, near Braddell, vehicles in front of me slowed down, so I slowed my vehicle too. Suddenly vehicle B came from behind and hit my vehicle, caused that my vehicle pushed forward and hit vehicle C.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRCC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		23 Apr 2018 16:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TUNG KWAN LOOI , ID: S8086957F		
Main Claimant:	HAFETZ HAKIM BIN HALIL , ID: 4 05925621		
Vehicle Reg. No.:	FBL4208E	Date of Loss:	17/04/2018 13:00 - :59 [18 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01997C02	Policy/Cover Note No.:	DMPCSN3084161700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJJ9838U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/05/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBL4208E (SNM18D01997C02)**
[SJJ9838U]

TP

HAFETZ HAKIM BIN HALIL

Apr 17 2018 1:00PM

[TUNG KWAN LOOI]

Mcs Auto

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	18/04/18 17:20	Accident Statement	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	18/04/18 15:47	Scene Photo [Linked Accident Report Documents]	1 Load JPG	✓
2	18/04/18 15:48	MOTORBIKE'S DRIVING LICENCE & WORK PERMIT [Linked Accident Report Documents]	1 Load JPG	✓
3	18/04/18 15:50	Scene Photo [Linked Accident Report Documents]	1 Load JPG	✓
4	18/04/18 15:50	SGZ2255Z - DRIVER'S NRIC & DRIVING LICENCE [Linked Accident Report Documents]	1 Load JPG	✓
5	18/04/18 15:57	SCENE PHOTO [Linked Accident Report Documents]	1 Load JPG	✓
6	18/04/18 15:58	Scene Photo [Linked Accident Report Documents]	1 Load JPG	✓
7	18/04/18 17:20	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
8	18/04/18 17:20	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
9	18/04/18 17:20	Accident Photo [Linked Accident Report Documents]	1 Load JPG	✓
10	18/04/18 17:20	CHASSIS NUMBER [Linked Accident Report Documents]	1 Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/18 15:53	General View	1 Load PDF	
2	25/07/18 15:54	Photographs of Damaged Parts	1 Load PDF	
3	25/07/18 15:54	Photo After Spray	1 Load PDF	
Documentation			1 per page ▼	✓
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	18/04/18 15:14	Sketch Plan [Linked Accident Report Documents]	1 Load TIF	
2	18/04/18 15:15	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	1 Load TIF	
3	18/04/18 15:15	DRIVER'S NRIC & DRIVING LICENCE [Linked Accident Report Documents]	1 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/04/18 16:08	PRS	1 Load PDF	
2	23/04/18 16:09	OI GIA REPORT	1 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	✓
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	18/04/18 17:20	Accident Statement	1 Load HTM	

Assessment Reports					☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
Photos/Images				3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/04/18 15:47	Scene Photo		Load JPG	☒
2	18/04/18 15:48	MOTORBIKE'S DRIVING LICENCE & WORK PERMIT		Load JPG	☒
3	18/04/18 15:50	Scene Photo		Load JPG	☒
4	18/04/18 15:50	SGZ2255Z - DRIVER'S NRIC & DRIVING LICENCE		Load JPG	☒
5	18/04/18 15:57	SCENE PHOTO		Load JPG	☒
6	18/04/18 15:58	Scene Photo		Load JPG	☒
7	18/04/18 17:20	Accident Photo		Load JPG	☒
8	18/04/18 17:20	Accident Photo		Load JPG	☒
9	18/04/18 17:20	Accident Photo		Load JPG	☒
10	18/04/18 17:20	CHASSIS NUMBER		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/04/18 15:14	Sketch Plan		Load TIF	
2	18/04/18 15:15	CERTIFICATE OF INSURANCE		Load TIF	
3	18/04/18 15:15	DRIVER'S NRIC & DRIVING LICENCE		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118007538/GZ4BS2

Date: 31/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3084161700
Claimant Vehicle No :	FBL4208E	Insured Vehicle No :	SJJ9838U
Date of Loss:	17/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01997C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL4208E	Engine No:	HIDDEN
Make & Model:	YAMAHA YBR125, 123cc (M)	Chassis No:	LBP101000058489
Reg. Date:	11/10/2016 (Man. Year: 2016)	Odometer:	35071 km
Colour:	White		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	3.00-18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/04/2018		
Date Inspected:	24/04/2018	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$4,800.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 31 Jul 2018)

Parts: N/A YAMAHA YBR125 123cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBL4208E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >