

22000000

ASS. REC. BY:

REF:

CS/CT18007543 / Uv6

Special Instructions:

Surveyor

Mwals

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTL

Date/Time:

24/04/2018 11:43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJE 1398B

Insured:

SJJ 1763D

at Workshop m/s

Tevergum Auto

Tel:

9382 9991

of

Blk 3022A Ubi Rd 1 #01-51

Policy No:

DMPCSNM1432091713

Claim No:

SNM13D01731C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01.04.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

25-04-2018 @ after 12pm

H.O.D. Endorsement:

Date/Time:

24/04/2018 1202pm

Person Contacted:

Annabel

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJE 1398B - CS3/ALG11014590/Kylin

DOA: 24/05/2011

SJJ 1763D - CS3/AXA11014346/Tigle2

DOA: 19/07/2011

REF: CTL

Signature

merimen

## ASSIGNMENT

From: Date: 25042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJE 1398B

at Workshop m/s: Evergem Auto

of: Blk 3022A Ubi Rd 1 # 01-51

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

QW / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: 1.5 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / DS

15:25h

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJE 1398B Yr Regn: 16/4/08

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Toyota ACHS

CC: 15-98

Colour: silver

A/C: Insured / Std / NI / NA

Sp. Reading: 17/150

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0532EE106105428

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rip / STD A/Rim or

Tyre Size: F: 195/65/15

R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm

R/Bal: 7 mm

L/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 1/4/18

D.O.A: 25/4/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision

27/4/18 Confirmed final of \$720.00 with Amabel (Red 2103.90, 75%)  
 LIA of merimen. (10% seen)  
 30/4/18  
 7/1? as only 1.5% . No 7-As all over,

RECEIVED 30 APR 2018

Date/Time: File Pass to?

☐

Prel. Report

To

☐

Final Report

Date/Time: File Return to?

30/4- typist

Report Format: merimen

Lump Sum / I.B.I: \$ 720

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

\$ + R\$ \$

Photos

Others

TOTAL

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 24 Apr 2018 |               | 24 Apr 2018<br>11:43<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

|      |           |               |           |          |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |  |                        |                        |
|-----------------------------|--|------------------------|------------------------|
| Insured:                    | STEPHEN CHUNG CHEN SHIONG  |                        |                        |
| Main Claimant:              | GOH KOK FUI, ID: S1425525G   |                        |                        |
| Vehicle Reg. No.:           | SJE1398B   | Date of Loss:          | 01/04/2018 22:00 - :59 |
| Claim Type:                 | TP / SNM18D01731C02  | Policy/Cover Note No.: | DMPCSNM1432091703      |
| Vehicle Reg. No. (Insured): | SJJ1763D   | Policy No. (Claimant): | 2100506558             |
|                             |  | Excess:                | S\$0.00                |
| Repairer:                   | Evergum Auto Services (HQ) BLK 3022A Ubi Road 1, #01-51, 408716 Ubi - Tel: 93829991                          |                        |                        |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]   |                        |                        |
| Claimant's Insurer:         | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000  |                        |                        |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/05/2018]                            |                        |                        |
| Adj Asg. Remarks:           | DEAR MARCUS, PLEASE CONDUCT THIRD PARTY SURVEY, CHECK CONSISTENCY OF THE DAMAGES AND DO A DIRECT SETTLEMENT. |                        |                        |

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                          |
|-------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>    |                          |
| Owner ID Type:                      | Singapore NRIC           |
| Owner ID:                           | 5525G                    |
| <b>Vehicle Details</b>              |                          |
| Vehicle No.:                        | SJE1398B                 |
| Vehicle to be Exported:             | No                       |
| Intended De-registration Date:      | 26 Apr 2018              |
| Vehicle Make:                       | TOYOTA                   |
| Vehicle Model:                      | COROLLA ALTIS 1.6 AUTO   |
| Primary Colour:                     | Silver                   |
| Manufacturing Year:                 | 2008                     |
| Engine No.:                         | 3ZZ4755017               |
| Chassis No.:                        | MR053ZEE106105428        |
| Maximum Power Output:               | 80.0 kW (107 bhp)        |
| Open Market Value:                  | \$16,994.00              |
| Original Registration Date:         | 16 Apr 2008              |
| First Registration Date:            | 16 Apr 2008              |
| Transfer Count:                     | 0                        |
| Actual ARF Paid:                    | \$16,994.00              |
| <b>Intended PARF Rebate Details</b> |                          |
| PARF Eligibility:                   | Forfeited                |
| PARF Eligibility Expiry Date:       | -                        |
| PARF Rebate Amount:                 | \$0.00                   |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date:                    | 15 Apr 2028              |
| COE Category:                       | A - Car (1600cc & below) |
| COE Period(Years):                  | 10                       |
| PQP Paid:                           | \$38,655.00              |
| COE Rebate Amount:                  | \$38,545.00              |
| <b>Total Rebate Amount:</b>         | <b>\$38,545.00</b>       |

The information contained herein is correct as at 26 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                              |
|----------------------------|------------------------------|
| Date Of Report             | 02/04/2018 14:11             |
| Date Of Accident           | 01/04/2018 22:30             |
| Exact Location Of Accident | MALAYSIA CUSTOM TOWARDS TUAS |
| Country/State of Loss      | SINGAPORE                    |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJE1398B             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | GOH KOK FUI          |
| NRIC No                     | S1425525G            |
| Email Address               | GOHKFJ@HOTMAIL.COM   |
| Mobile Phone No             | (LOCAL) +65-97714307 |
| Alternative Phone No        | OTHERS-97714307      |

### Vehicle Particulars

|  |                       |
|--|-----------------------|
| Manufacturer   | TOYOTA                |
| Model  | COROLLA ALTIS-1.6 (A) |
| Exact Purpose for which vehicle was being used at time of accident           |                       |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                    |
| If No, Please state action to be taken                                       | REPORTING ONLY        |
| Vehicle Category   | PRIVATE CAR           |

### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                        |
| Fleet Policy              | NO                                   |
| Policy Number             | 2100506558                           |
| Cover Note Number         |                                      |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | GOH KOK FUI           |
| NRIC No              | S1425525G             |
| Date Of Birth        | 28/09/1960            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 21/01/1982            |
| Driving Experience   | 36 YEARS AND 2 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-97714307  |
| Fax Number           |                       |
| Contact Number       | OTHERS-97714307       |
| Email Address        | GOHKFJ@HOTMAIL.COM    |

|   |  |
|---|--|
| Address   | BLK 491E TAMPINES STREET 45 #10-200<br>SINGAPORE |
| Postcode  | 524491   |
| Was driver an employee of the Insured's Company     | NO   |
| If No, Relationship of the Driver with the Insured  | OWNER  |
| Vehicle Registration Number of Driver's Own Vehicle | -  |
|   | -  |
|   | -  |
| Insurance Company of Driver's Own Vehicle           | -  |
|   | -  |
|   | -  |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |  |
|---|--|
| Was any foreign vehicle involved in this accident?  | NO   |
| Number of vehicles involved in the accident   | 2  |
| Was any body injured in the Accident?   | NO   |
| Was any injured conveyed to hospital by ambulance?  | NO   |
| Was any other material or property damaged?   | YES  |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO   |
| Number of Passengers (Including Driver)   | 3  |
| Passenger 1   | NAME: : CHONG POH LIN<br>GENDER: : FEMALE      |
| Passenger 2   | NAME: : GOH SI NING RACHEL<br>GENDER: : FEMALE |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |             |
|-----------------------------|-------------|
| Vehicle Registration Number | SJJ1763D    |
| Vehicle Make/Model/Colour   |             |
| Details Of Properties       |             |
| Vehicle Category            | PRIVATE CAR |
| Name of Driver              |             |
| NRIC/Passport Number        |             |
| Contact Number              |             |
| Address                     |             |
| Postcode                    |             |

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature

Date & Time:

02 April 2018  
2:25pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/TIN No.:

PERMEN



## Sketch Plan #2

### SKETCH PLAN

Towards Malaysia custom (in the direction of TUNAS CID)

Vehicle No  
A - SJE1398B  
B - SJJ1763D

Legend  
 Vehicle  
 Bike

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01 April 2018, As I'm driving towards Malaysia custom (in the direction of TUNAS CID), as I'm joining the traffic, just queuing left behind the vehicle queue, bumper to bumper.

suddenly I noticed a HONDA Civic 'Black colour' SJJ1763D tried to switch lane as a result the car hit my rear right side bumper.

My wife and daughter they are all okay, no injury.

The owner of SJJ1763D refused to exchange IC and driving licence particulars.

Time of Accident : 10:30 pm, 01 April 2018  
 weather condition : Dry, clear vision

Cheng Poh Lim  
 Goh Si Ning Rachel.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.  
 Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time: 02 April 2018  
 3:25pm

Driver's Signature

(If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature

Name:  
 NRIC/TIN No.:



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



# Evergum Auto Services

Blk 3022A Ubi Road 1, #01-51, Singapore 408716

Mobile: 93829991 Fax: 68415718

18 April 2018

The Motor Claim Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
DID: 6389 6177  
Fax: 6224 7478 / 6224 7175

Not Affirmed  
Lkh  
Tel: 67418438  
Take photo after repair  
2 day  
25/4/18

## REPAIR ESTIMATE FOR SJE1398B

### SPARE PARTS

|                              |   |    |          |   |
|------------------------------|---|----|----------|---|
| Rear bumper                  | 1 | R  | 516.40   | X |
| Rear bumper side retainer    | 2 | 11 | 130.60   | X |
| Rear bumper corner retainer  | 2 | 11 | 112.40   | X |
| Rear bumper clip             | 8 | 11 | 44.00    | X |
| Rear bumper inner foam c/bar | 1 | 11 | 231.00   | X |
| Rear end panel               | 1 | 11 | 530.80   | X |
| Subtotal of the above        |   |    | 1,565.20 |   |

Discount 25% 391.30

Subtotal 1: 1,173.90

Subtotal 2: 280.00

Part cost 1,453.90

### LABOUR

|   |        |     |
|---|--------|-----|
| To remove and replace damaged parts, to knock and straighten damaged areas and to cut and weld support panel. | 600.00 | 200 |
| To putty and spray paint necessary parts.   | 600.00 | 280 |
| To check wiring and install reverse sensors.  | 100.00 | 40  |
| To apply anti-rust undercoat.   | 90.00  | X   |

Labour cost 1,390.00

Total repair cost 2,843.90

Yours faithfully

EVERGUM AUTO SERVICES

Siew Mei

LINK Auto Consultants hence notify the Repairs of the following:

- To resurvey before after spray painting
- To replace damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

P/P \$ 720/2



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |            |   |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                | Ins Auth'd | Status  |
| Main                     | 24 Apr 2018 |               | 24 Apr 2018<br>11:43<br><a href="#">Edit Adj Rpt</a> | <b>S\$720.00</b><br><a href="#">Edit Estimates</a> | <b>S\$720.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main   | Reference  | Claim Details          | Documents  | Show All |         |             |              |            |       |
|--|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>   |  |                        |  |          |         |             |              |            |       |
| Insured:   | <b>STEPHEN CHUNG CHEN SHIONG</b> , ID: -   |                        |  |          |         |             |              |            |       |
| Main Claimant:   | <b>GOH KOK FUI</b> , ID: S1425525G   |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:  | <b>SJE1398B</b>  | Date of Loss:          | 01/04/2018 22:00 - :59<br><b>[119 Months and 16 Days From LTA Reg Date (Man Yr)]</b> |          |         |             |              |            |       |
| Claim Type:  | <b>TP / SNM18D01731C02</b>   | Policy/Cover Note No.: | DMPCSNM1432091703  |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):  | <b>SJJ1763D</b>  | Policy No. (Claimant): | 2100506558   |          |         |             |              |            |       |
|  |  | Excess:                | S\$0.00  |          |         |             |              |            |       |
| Repairer:  | <b>Evergum Auto Services (HQ)</b> BLK 3022A Ubi Road 1, #01-51, 408716 Ubi - Tel: 93829991   |                        |  |          |         |             |              |            |       |
| Handling Insurer:  | <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Jowyn Tay</b> - 6389 6174]             |                        |  |          |         |             |              |            |       |
| Claimant's Insurer:  | <b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000   |                        |  |          |         |             |              |            |       |
| Adjuster:  | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 04/05/2018]</b> |                        |  |          |         |             |              |            |       |
| Adj Asg. Remarks:  | DEAR MARCUS, PLEASE CONDUCT THIRD PARTY SURVEY, CHECK CONSISTENCY OF THE DAMAGES AND DO A DIRECT SETTLEMENT.                         |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>   |  |                        |  |          |         |             |              |            |       |
| There are no mail for this case.   |  |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span> |  |                        |  |          |         |             |              |            |       |
| Due Date   | Priority   | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.  |  |                        |  |          |         |             |              |            |       |

## Claim Documents

\*SJE1398B (SNM18D01731C02)  
[SJJ1763D]  
TP  
GOH KOK FUI  
Apr 1 2018 10:00PM  
[STEPHEN CHUNG CHEN SHIONG]  
Evergum Auto Services

| Upload Documents   Upload Photos   Compose New Letter |                 |  | View <span>View in Browser</span> |                                     |
|---|-----------------|--|-----------------------------------|-------------------------------------|
| <b>Photos/Images</b>                                  |                 |  | 3 per page                        | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                        | Thumbnail                         | Print                               |
| 1   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 2   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 3   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 4   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 5   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 6   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 7   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 8   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 9   | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 10  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 11  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 12  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 13  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 14  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 15  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 16  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 17  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 18  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 19  | 26/04/18 08:21  | General View   | Load JPG                          | <input checked="" type="checkbox"/> |
| 20  | 27/04/18 19:03  | Reinspection Photo                                       | Load JPG                          | <input checked="" type="checkbox"/> |
| 21  | 27/04/18 19:03  | Reinspection Photo                                       | Load JPG                          | <input checked="" type="checkbox"/> |
| 22  | 27/04/18 19:03  | Reinspection Photo                                       | Load JPG                          | <input checked="" type="checkbox"/> |
| 23  | 27/04/18 19:03  | Reinspection Photo                                       | Load JPG                          | <input checked="" type="checkbox"/> |
| 24  | 27/04/18 19:03  | Reinspection Photo                                       | Load JPG                          | <input checked="" type="checkbox"/> |
| 25  | 27/04/18 19:03  | Reinspection Photo                                       | Load JPG                          | <input checked="" type="checkbox"/> |
| <b>Documentation</b>                                  |                 |  | 1 per page                        | <input checked="" type="checkbox"/> |
| No  | Finalized On    | China Taiping Insurance (Singapore) Pte. Ltd. (HQ)       | Thumbnail                         | Print                               |
| 1   | 24/04/18 11:45  | INSURED SAS REPORT SJJ1763D                              | Load PDF                          |                                     |
| 2   | 24/04/18 11:47  | THIRD PARTY SAS REPORT SJE1398B                          | Load PDF                          |                                     |
| 3   | 24/04/18 11:47  | THIRD PARTY SJE1398B -FROM EVERGUM AUTO -TP ESTIMATE     | Load PDF                          |                                     |
| 4   | 24/04/18 11:47  | THIRD PARTY SJE1398B -PRS EMAIL BTW CIC AND EVERGUM AUTO | Load PDF                          |                                     |

## Linked Accident Report Documents

|                           |              |                                     | View <span>View in Browser</span> |                                     |
|---------------------------|--------------|-------------------------------------|-----------------------------------|-------------------------------------|
| <b>Assessment Reports</b> |              |                                     | 1 per page                        | <input checked="" type="checkbox"/> |
| No                        | Finalized On | Progressive Automotive Pte Ltd (HQ) | Thumbnail                         | Print                               |

| Assessment Reports |                |                                     | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------|--|-------------------------------------|
| No                 | Finalized On   | Progressive Automotive Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 02/04/18 14:33 | Accident Statement                  |  Load HTM |                                     |
| Photos/Images      |                |                                     | 3 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Progressive Automotive Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 02/04/18 14:32 | Accident Photo                      |  Load JPG | <input checked="" type="checkbox"/> |
| 2                  | 02/04/18 14:32 | Accident Photo                      |  Load JPG | <input checked="" type="checkbox"/> |
| 3                  | 02/04/18 14:32 | Accident Photo                      |  Load JPG | <input checked="" type="checkbox"/> |
| 4                  | 02/04/18 14:32 | Accident Photo                      |  Load JPG | <input checked="" type="checkbox"/> |
| 5                  | 02/04/18 14:32 | Accident Photo                      |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |                                     | 1 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Progressive Automotive Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 02/04/18 14:27 | Sketch Plan                         |  Load JPG | <input checked="" type="checkbox"/> |
| 2                  | 02/04/18 14:27 | Sketch Plan #2                      |  Load JPG | <input checked="" type="checkbox"/> |
| 3                  | 02/04/18 14:28 | DRIVER NRIC & LICENSE               |  Load TIF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST   | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured.  |       |      |       |
| <p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>               |       |      |       |
| <p><b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18007543/UVBQ2

Date: 04/05/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNM1432091703

Claimant Vehicle  
No: SJE1398BInsured Vehicle  
No: SJJ1763D

Date of Loss: 01/04/2018

Nature of Claim: TP

Claim  
No: SNM18D01731C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJE1398B

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4755017

Reg. Date: 16/04/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106105428

Colour: Silver

Odometer: 171150 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15    | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Michelin 7 mm | Rear Left Side:  | Michelin 7 mm |
| Front Right Side: | Michelin 7 mm | Rear Right Side: | Michelin 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's      | Adjuster's    | Difference      | Diff %       |
|--------------------------|-----------------|---------------|-----------------|--------------|
| Parts                    | 1,453.90        | 200.00        | 1,253.90        | 86.24        |
| Miscellaneous Items      | 0.00            | 0.00          | 0.00            |              |
| Labour                   | 1,390.00        | 520.00        | 870.00          | 62.59        |
| Paintwork Labour         | 0.00            | 0.00          | 0.00            |              |
| Towing                   | 0.00            | 0.00          | 0.00            |              |
| <b>Nett Amount (S\$)</b> | <b>2,843.90</b> | <b>720.00</b> | <b>2,123.90</b> | <b>74.68</b> |

## INSPECTION

Date of Assignment: 24/04/2018

|                            |               |  |
|----------------------------|---------------|--|
| Date Inspected: 25/04/2018 | Inspected At: | Evergum Auto Services (HQ)<br>BLK 3022A Ubi Road 1, #01-51<br>Singapore 408716 |
|----------------------------|---------------|--|

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 04 May 2018)  |
| <b>Parts:</b> 143          | TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SJE1398B)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's  | Amount                 |
|-----|-----|----------|-------------------------------|---------------|---|------------------------|
| 1   | 1   |          | *REAR BUMPER                  | Repair        | 516.40 FL   | *- FL                  |
| 2   | 2   |          | *REAR BUMPER SIDE RETAINER    | Not Necessary | 130.60 FL   | *- FL                  |
| 3   | 2   |          | *REAR BUMPER CORNER RETAINER  | Not Necessary | 112.40 FL   | *- FL                  |
| 4   | 8   |          | *REAR BUMPER CLIP             | Not Necessary | 44.00 FL  | *- FL                  |
| 5   | 1   |          | *REAR BUMPER INNER FOAM C/BAR | Not Necessary | 231.00 FL   | *- FL                  |
| 6   | 1   |          | *REAR END PANEL               | Not Necessary | 530.80 FL   | *- FL                  |
| 7   | 1   |          | *SET REVERSE SENSOR           | Shorted       | 280.00 FS   | *200.00 FS             |
|     |     |          |                               |               | <b>Sub Total (S\$)</b>                                    | <b>1,845.20 200.00</b> |
|     |     |          |                               |               | <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | <b>391.30 0.00</b>     |
|     |     |          |                               |               | <b>Total Parts (S\$)</b>                                  | <b>1,453.90 200.00</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars  | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|--------|
| <u>Labour Items</u>     |  |          |            |        |
| 1                       | TO REMOVE AND REPLACE DAMAGED PARTS ,TO KNOCK AND STRAIGHTEN DAMAGED AREAS AND TO CUT AND WELD SUPPORT PANEL | New      | 600.00     | 200.00 |
| 2                       | TO PUTTY AND SPRAY PAINT NECESSARY PARTS   | New      | 600.00     | 280.00 |
| 3                       | TO CHECK WIRING AND INSTALL REVERSE SENSORS  | New      | 100.00     | 40.00  |
| 4                       | TO APPLY ANTI-RUST UNDERCOAT   | New      | 90.00      | 0.00   |
| Gross Labour Cost (S\$) |  |          | 1,390.00   | 520.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >