15/5/2010		CC 3/LPC1800 75	154 / Kleasn	LKK: IDAC:
INS. CASE OWNE	1 22	ASSIGNMEN		Let a
, Surveyor:	ANC	DOI: 234	Date / Time :	23/4/18
of our received			Registered in N	Merimen:
Pre-assign / CCU	/FTE	WI by T		
Insured Vehicle	SW	46467	Claim No. : 17/18	118 NOUZ 0 DUSTO
	[ \mvsvv	Van Oct. 1/27		DID IVPOST NICEZG Q - DDI
Name of Insured	C Destroy	GIZARTADA	Policy No. :	(-1 61
Insured Tel No.	TA	HP: 95 MS 997	Make / Model : 19	cents forta
Excess Sec II :SS	3	D.O.A: 19 4118	Place of Accident :	(or ker
Is driver the own	er? (YES / NO )	Nature of Accident :		
If NO, Driver N	ame / Age :		DI GIA REPORT: YES / NO	; TP GIA REPORT: YES / NO
Driver Te	100000000000000000000000000000000000000	and the same of th	nsured Liability: %	
(1+B & C+SH	6	1995		
3110 0301				
INSRS:	INSR	i:	INSRS:	NSRS:
WSP: Prunni	WSP:		WSP: Tel:	WSP:
Liability:	Liabil	ity:	Liability:	Liability :
RMKS:	RMK!		RMKS:	RMKS:
Date/ Time				
-M	Western all	an - c. undulmining	Malaga STAGE	DATE / PIC
Acher	2/ 12022/10 - 52/1	Maritz Bild Capper Cont	Non-Reporting	
15.00	12AAPAP1 ×		Non-Reporting	
				(if non-pickup):
17.5.8	THE PASS TO TYPE	- Donne Broom	Call OI: After call ltr to	OI:
11,5.6	THE I WAS TO TABLE	s) to Prepare Report.	- Name and Address of the Park	n Check List: Handler Typist
	-		Notification ltr	THE RESERVE OF THE PARTY OF THE
	DE	CEIVED 1 7 MAY 2018	After call ltr to	OI:
	1/1	DETVIEW THE COLO	Authorisation 7	
			Release Vouch Final Repair Bi	
			Car Rental Inv	
			Towing Invoice	
	RECEIVED	2 9 JUN 2018	LTA / GIA ;	V
			Medical Bill:	
			PIR:	ect Instruction:
			LOD	ect instruction.
				akdown Form:
PRELIMINARY ADVIC	E Date/Time:	Sent By:	Post-Repair P	hotos:
	P. (1911)	A. A.	Others:	
FINALIZATION Repair Cost:	Date/Time: 8.58 S \$\$1,400 (	Confirm with:	Confirm by:	Awk Email Call
FINAL SETTLEMENT	Date/Time: 22 - 6 - 1 8	Confirm with G904	Email Email	Call Call
Final Liability:		1 / Assessed) BOLA S/N No. : 15	If NO or B 28	
Repair Cost: w/6!	S\$1,498.00	O1 CHANG	D LAME TO THE LY.	3100-9100004110
Loss of Rental (LOR):	S\$ 304-79 (	3 days) x +108.93		DOW DENIST
Loss of Use (LOU): Loss of Income (LOI):		days)     days)	F	0000
LOR only LOU or		LOR + LOI [Tick only one]	1	DI Jarolis
GIA/LTA Search	S\$3.00	Marie Control of the		
Medical:	SS -	the second secon		us: Normal/Reject/Private Settle
Disbursement:	SS -	(e.g. Tow/ Independent )	2) Report For	
Legal Cost Total:	S\$ - S\$ 1,946,79	Global Sum SS:	3) Survey fee	7120
FINAL PAYMENT	Date/Time: 33-6-18	Confirm with: GARA	Email	Call
Payee 1:	S\$1,946.19	Name 1: PREMIER AUTOMOTIVE S		
Payee 2: (Strike if N.A.)	ss	Name 2:	->	
Payce 3: (Strike if N.A.)	SS	Name 3:		

(08/11/13)	REF:		11/
Quive un Kalvin	KCI.		
	ASSI	GNMENT	28
From:	Date:	Veh No: SHB 85	814 Yr Regn: Oct 1313
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van /	Lorry / Taxe / Prime Mover /
OD/TP/WS/TPRES/ODRE	S / EVA / INV / MV	Truck / Trailer or	1050
To Insped Vehicle No:	South Control of the	Make: KA opti	4a 0.0 /6Pm
at Workshop m/s		Colour Silver	A/C: Insured / Std / NI / NA
83639/8530 ** 6543168 0		Sp.Reading 675%61	T/Radio: Insered / Std / NI / NA
Insured:		Eng/No:	
Policy No.		C/No: CNAG.	M X/XAE 5 847832
Claims No.		Gen. Cond: Good Fair / Poor / Bu	rnt
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leak	ed / Burnt or
(Client's Record)	The state of the s	Brake: Inorder / Jammed / Leak	ed / Burnt or
Make of Veh;		Modi: Nil / S/Rim / STD ARim	
	100 000 000 000 000	Tyre Size; F: 2	201/65/16
(Policy Condition)		R:	۲,
Remark: The veh had commer	nced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZ	ZA / MIÇ / OHTSU / PIR / SUMI /
repair at the time of	inspection.	TOYO/YOKO or	Hankh
Bal. or Market Value:	10	Front	Rear 1
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. d mm	R/Balmm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. + mm	L/Bal. + mm
Est. Repairs: 3	days Res.: Yes or No	D.O.A. /4/4/-8	D.O.I. 23/x/-8
Lum Sum: 👆	% 3 Val.: Yes or No	Survey held at	fremis .
CA / REV / REP. / 241	HRS	Des. of Damages : Frt / Rear / O	
	Vehicle: IN / OUT		Froy,
	Contacted:	The U/C / Chassis frame / B	ody Structure affected due to collision.
Date / Time Action / Instr	uction		Longre
Ns. d	+11400 (RED:+1031.60 42/)		45
	¥)		
		1 1	
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:	
1)	: Final Report	Resurvey No. of Trip:	Survey Fee:
Date/Time, File Return to?			Transportation:
2)	Add Fee	[1]	)S+RS,SI
12		: Interview (\$	) Photos
Report Format :		: Tech. Invs (\$	) Others
Lump Sum / I.B.I: (\$	)	: Weekend (\$	)
			TOTAL



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation	nale Des Experts En Autom	nobile		
ONPAC INSURANCE	BHD	Ref : CC3/LPC18007	7554/K1ea3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date: 24-04-2018 Code: LPC2			
	Policy Particulars	:- THIRD PARTY CLAI	M		
Insured Veh.	SLP 4646J	Veh. Inspected	SHB 8581G		
Policy No.	Z/17/VP05/014399-001	Coverage (\$)	0.00		
Claim No.	17/18/18/VP05/020556	Excess (\$)	0.00		
Assign From		Assign Date	24/04/2018		
2.	Vehicle Parti	culars & Condition			
Make & Model		c.c	0		
Engine No.	HIDDEN	Year of Reg.			
Chassis No.		Colour			
Odometer	-	Steering			
Brakes	Brakes		Modification		
General					
3.	Condit	ions of Tyres			
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre			mm		
4.	Descript	ion of Damages			
5.	Genera	al Information			
Accident Date	19/04/2018	Inspection Date	23/04/2018		
Survey held at	PREMIER AUTOMOTIVE SER	VICES PTE LTD			
10 88	23 CHANGI SOUTH AVENUE	2 #01-02 SINGAPORE 48	6443		
5a.		Remarks			
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS, I	THOUT PREJUDICE" BA WE HAVE NOT AUTHORI	SIS. SED REPAIRS.		

### Mei Kwan (LKKAuto)

From:

ONG LI LI < llong@lonpac.com>

Sent:

Friday, 27 April, 2018 2:21 PM

To:

Mei Kwan (LKKAuto); MT\_Claim\_SG

Cc:

Asher Sng (LKKAuto); Joy Irene (LKKAuto); Admin A

Subject:

RE: Direct Settlement - Accident Involving SLP4646J (OI: LPC -

17/18/18/VP05/020556) AND SHB8581G (TP: LKK REF - CC3/LPC18007554/K1ea3)

on 19.04.2018

Attachments:

SLP4646J 190418.PDF

Follow Up Flag:

Follow up

Flag Status:

Completed

Categories:

**HMK** 

Hi Mei Kwan

Please see attached for our Insured's GIA report.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Friday, 27 April, 2018 10:51 AM

To: MT Claim SG

Cc: GERALD POH WEE BIN; ONG LI LI; ERIC WOO JUN KIAT; Asher Sng (LKKAuto); Joy Irene (LKKAuto); Admin A

Subject: Direct Settlement - Accident Involving SLP4646J (OI: LPC - TBA) AND SHB8581G (TP: LKK REF -

CC3/LPC18007554/K1ea3) on 19.04.2018

#### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHB 8581G at M/s Premier Automotive Services Pte Ltd - Changi.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- · Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

# REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1678298Z





DAWOOD BIN HAMID




INDIAN
Date of birth
16-05-1964
Country/Place of birth
SINGAPORE


1


S1678298Z



d1d 3 3140 HMAL ZHB 82818







YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor cars with unladen weight =< 3000kg with =< 7 18 Aug 200 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg

NP 428A





#### **Certificate of Insurance**

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: SHB8581G

Chassis Number

: KNAGM414ME5447832

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive\*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use\*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

#### This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: \$\$3,500

**INSURE WITH COE** 

: N/A

HIRE PURCHASE COMPANY

: N/A

SUM INSURED

N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

: 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

**Authorised Officer** 

Chief Executive

#### **Enquire Transaction History**

Transaction History Details

Log Date/Time:

28 Oct 2013 / 09:31:41

Receipt No.:

AACCK001-AX239-131028-000041

Asset Type:

Vehicle

Transaction Amount:

\$73,800.00

Asset ID:

SHB8581G

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

**Business Transaction** 

Reference No.:

20131028093141503838

01.02 Register New Vehicle (AA)

Vehicle No.:

SHB8581G

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2: Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 28 Oct 2013

Original Registration

28 Oct 2013

Date:

Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414ME5447832

Engine No.:

D4FDDH308109

Motor No.:

Trailer Chassis No.:

Propellant:

Diesel

Passenger Capacity: Engine Capacity:

4 1685

Power Rating:

Unladen Weight:

1584 2050

Maximum Laden

Weight: Primary Color:

Silver

Secondary Color:

Manufacturing Year:

2013

Open Market Value:

\$19,836.00 \$7,401.00

Minimum PARF Benefit:

Y

PARF Eligibility:

No. of Transfer:

Effective Ownership Date/Time:

28 Oct 2013 09:31:41

COE No .:

2013102801001072M

COE Expiry Date:

27 Oct 2021

COE Bid Category:

Actual QP/PQP Paid

Amount:

\$61,324.00

Lifespan Expiry Date:

27 Oct 2021

Owner ID Type:

Company

### **Enquire Transaction History**

Transaction History Details

Log Date/Time:

28 Oct 2013 / 09:31:41

Receipt No .:

AACCK001-AX239-131028-000041

Asset Type:

Vehicle

Transaction Amount:

\$73,800.00

Asset ID:

SHB8581G

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

**Business Transaction** Reference No.:

01.02 Register New Vehicle (AA)

20131028093141503838

Vehicle No.:

SHB8581G

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 28 Oct 2013

Original Registration

28 Oct 2013

Date: Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414ME5447832

Engine No.:

D4FDDH308109

Motor No.:

Trailer Chassis No.:

Propellant:

Passenger Capacity:

Engine Capacity:

4 1685

Diesel

Power Rating:

Unladen Weight:

1584

Maximum Laden Weight:

2050

Silver

Primary Color:

Secondary Color:

2013

Manufacturing Year: Open Market Value:

\$19,836.00

Minimum PARF

\$7,401.00

Benefit:

Y

PARF Eligibility:

No. of Transfer:

Effective Ownership

28 Oct 2013 09:31:41

Date/Time:

COE No .:

2013102801001072M

COE Expiry Date:

27 Oct 2021

COE Bid Category:

Actual QP/PQP Paid Amount:

\$61,324.00

Lifespan Expiry Date:

27 Oct 2021

Owner ID Type:

Company

## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

20-Apr-18

### ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8581 G

1 pc	Front bumper	s	531.00
1 pc	Front o/s bumper side bracket 🗶	\$	16.00
1 pc	Front bumper o/s fog lamp cover	\$	66.00
1 pc	Front bumper o/s protector 🔀	\$	51.00
1 pc	Front o/s fender	\$	384.00
1 pc	Front o/s fender inner shield	\$	120.00
1 pc	Wheel cover X	\$	116.00
	/2 -1	\$	1,284.00
	Less 10%	\$	128.40
		\$	1,155.60
S/nett			
1 set	Front bumper clips	\$	48.00
1 set	Front o/s fender inner shield clips —	\$	28.00
	Sundry	\$	50.00 20
	To check wheel alignment	\$	80.00 >
	To labour charge for dismantle and renew the accident damaged parts.	s	550.00
			360
	To putty and spray painting on front bumper, front o/s fender	\$	400.00
	To apply rustproofing on repair/replace panel	\$	120.00 20
		\$	2,431.60

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kakillley

1 23/x/-8 1020hs

3 hs,

4s Repair plh LKK Auto Consultants hence notify the Repairer of the following: To resurvey before lattle spray painting To display damages earlies through resurvey Parts prices are result in commation. • No illegal more sale into the sale and Supplemental: State of the supplemental and th Acknowledged by Repairer Signature:

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

20-Apr-18

#### ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8581 G

	Front bumper / Add		531.00
1 pc	Front bumper	\$	
1 pc	Front o/s bumper side bracket X	\$	16.00
1 pc	Front bumper o/s fog lamp cover	\$	66.00
1 pc	Front bumper o/s protector	S	51.00
1 pc	Front o/s fender	\$	384.00
1 pc	Front o/s fender inner shield	\$	120.00
1 pc	Wheel cover X	\$	116.00
	Sec.	\$	1,284.00
	Less 10%	\$	128.40
		\$	1,155.60
S/nett			
1 set	Front bumper clips	\$	48.00
1 set	Front o/s fender inner shield clips	\$	28.00
	Sundry V	S	50.00 20
	To check wheel alignment	\$	8000 200
	To labour charge for dismantle and renew the accident		
	damaged parts.	S	559:00
			2/.
	To putty and spray painting on front bumper, front o/s fender	\$	400.00
	To apply rustproofing on repair/replace panel	s	120.00 2
		s	2,431.60

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify

the Repairer of the following:

To resurvey before/after soray painting

To display dam start partials during resurvey

Parts prices are seen and to contimetion

Third party survey on a "Microst Prejudice" basis

No illegal modernation and went

Supplementary seen a make an essurveyed and

Supplementary seen and trom insurance Company is subject to final additional from insurance Company

Signature: Date: Kakillley

1 23/x/-8 1020hs

3 hs,

4s Repair phh

8/5/18 all 45\$140/36,



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Aut	omobile
ONPAC	INSURANCE	BHD	Ref : CC3/LPC180	07554/K1ea3n2
300 BEA \$17-04/0	CH ROAD 7 THE CONCO	DURSESINGAPORE 199555	Date: 03-07-2018 Code: LPC2	
		Policy Particulars	:- THIRD PARTY CL	AIM
Ins	ured Veh.	SLP 4646J	Veh. Inspected	SHB 8581G
Po	licy No.	Z/17/VP05/014399-001	Coverage (\$)	0.00
Cla	aim No.	17/18/18/VP05/020556	Excess (\$)	0.00
As	sign From		Assign Date	23/04/2018
2.		Vehicle Parti	culars & Condition	
Ma	ke & Model	KIA OPTIMA	c.c	1685
En	gine No.	HIDDEN	Year of Reg.	2013
Ch	assis No.	KNAGM414ME5447832	Colour	SILVER
Od	lometer	675469	Steering	IN ORDER
Br	akes	IN ORDER	Modification	STANDARD ALLOY RIM
Ge	eneral	GOOD		
3.		Condit	ions of Tyres	
		Size	Make	Balance
R/I	H Front Tyre	205/65 R16	HANKOOK	7 mm
LI	H Front Tyre	205/65 R16	HANKOOK	7 mm
R/	H Rear Tyre	205/65 R16	HANKOOK	7 mm
LI	H Rear Tyre	205/65 R16	HANKOOK	7 mm
4.		Descript	ion of Damages	
	IE VEHICLE SU	STAINED DAMAGES AT THE O/	S FRONT PORTION.	
5.			al Information	
	cident Date	19/04/2018	Inspection Date	23/04/2018
Si	urvey held at	PREMIER AUTOMOTIVE SER 23 CHANGI SOUTH AVENUE		486443
5a.			Remarks	
A	THE INSPECTION ACCORDAN	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS, V	THOUT PREJUDICE" E	BASIS. PRISED REPAIRS.
5b.		Estimate	e Days of Repair	

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8581G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			110
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT O/S BUMPER SIDE BRACKET	SERVICEABLE	16.00	157
1	FRONT BUMPER O/S FOG LAMP COVER	SERVICEABLE	66.00	
-1	FRONT BUMPER O/S PROTECTOR	SERVICEABLE	51.00	55
1	FRONT O/S FENDER	DENTED	384.00	384.00
1	FRONT O/S FENDER INNER SHIELD	TORN	120.00	120.00
1	WHEEL COVER	SERVICEABLE	116.00	
	LESS 10% DISCOUNT		-128.40	-103.50
			1,155.60	931.50
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
	50. 20		126.00	96.00
	LABOUR			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.		550.00	400.00
	TO APPLY RUSTPROOFING ON REPAIR/REPLACE PANEL .		120.00	G121-9-0135
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER .		400.00	360.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			1,150.00	780.00
	GRAND TOTAL		2,431.60	1,807.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	1,400.00
(TOTIS PRE-ACCIDENT CONDITION)	

Report Ref No. CC3/LPC18007554/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

Amorti.

HO LEONG CHUAN

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.