

ASS. REC. BY:

REF: CS/MS(18007561 / Utben

Special Instruction:

SUPERVISOR

Marcus

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSIH

Date/Time:

24/04/2018 2:03pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ 1981S

Insured:

GBB 5938C

at Workshop m/s

Precise Auto

Tel:

6745 7367

of

Blk 1 Kaki Bukit Ave 6 #01-34

Policy No:

A29076922 MKF

Claim No:

556083

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/04/2018

CA / REV / REP. / REV 24 HRS 'wp'

11-05-2018 @ 12pm

H.O.D. Endorsement:

Date/Time:

24/04/2018 3:29pm

Person Contacted:

Yan Hong

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GZ 1981S - NA / CTL 8107472 / ZH
	GBB 5938C - NA / TME 16004599 / d2
	insured's
	Mr K. K. Lau had viewed the video clips of insured's & damaged assessment of Mr Marcus Chua, opinion not consistent.

D.O.A: 18/04/2018

D.O.A: 09/03/2016

Mr K. K. Lau had viewed the video clips of insured's & damaged assessment of Mr Marcus Chua, opinion not consistent.

REF: MSH

ASSIGNMENT

From: _____ Date: 11-05-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GZ 1981S

at Workshop m/s: Precise Auto

of: Blk 1 Kaki Bukit Ave 6 #02-34

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: GZ 1981S Yr Regn: 1 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Dyne (M) C.C. 2986

Colour: Silver A/C Insured / Std / NI / NA

Sp. Reading: 451984 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFUF34 / 303011577

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or _____

Brake: In Order / Jammed / Leaked / Burnt or _____

Modif: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185-12 14
R: 155-12 12 Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Mestloke

Front _____ Rear _____

R/Bal. 5- mm R/Bal. 5/5 mm

L/Bal. _____ mm L/Bal. 5/5 mm

D.O.A. 18/5/18 D.O.I. 11/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS Body Panel. ?

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition) 12pm owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 18k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3-Val: Yes or No

CA / REV / REP. / 24 HRS 9962M

Date: _____ Person Contacted: 31/12/2020 Vehicle IN / OUT

6/8/18 47A 11822 for desc n/s only reporting report - according from OZ report and video footage NO accident involved. Summary. not consistent report

RECEIVED 13 SEP 2018

Date/Time. File Pass to? Prefi. Report

1) 1219 Typist Final Report

Date/Time. File Return to? _____

Report Format: TP

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 0

Resurvey No. of Trip: -

Survey Fee: 150

Transportation: _____

3 * P.S. \$ _____

Picass: _____

Others: _____

TOTAL: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

West-end (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Apr 2018		24 Apr 2018 14:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ORANGE CLOVE CATERING PTE LTD, Co. Reg. No.: 200809605R								
Main Claimant:	CASSEROLE CATERING SERVICES PTE LTD, Co. Reg. No.: 201530426E								
Vehicle Reg. No.:	GZ1981S	Date of Loss: 18/04/2018 09:00 - :59 [147 Months From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 556083	Policy/Cover Note No.: A29076922MKF (Comprehensive) Coverage: 01/04/2018 - 31/03/2019							
Vehicle Reg. No. (Insured):	GBB5938C	Policy No. (Claimant): Excess:							
Repairer:	Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/04/2018]								
Driver/Custodian (Insured):	KYAW MYO WIN (), NRIC: G3309963R, Tel: +6593835319								
Adj Asg. Remarks:	Please assign to Mr Adrian Ling. Thank you.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2018 16:25
Date Of Accident	18/04/2018 09:50
Exact Location Of Accident	JLN BOON LAY BEFORE JUNC INTERNATIONAL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ1981S
Insured/Policyholder	
Name Of Registered Owner	M/S CASSEROLE CATERING SERVICES PTE LTD
Co Reg No	201530426E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63236445
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150 D
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMCVSN3000861800
Cover Note Number	
Driver	
Name of Driver	NEO HOCK SIN
Passport No/FIN	G7753575L
Date Of Birth	27/07/1986
Occupation	OUTDOOR
Date Of Driving Pass	27/10/2017
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98399976
Fax Number	
Contact Number	OFFICE-98399976
Email Address	NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name NEO HOCK SIN
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? GZ1981S
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name CHONG WEI CHENG, JACKY
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? GZ1981S
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Police Report

Police Station Of Origin
 Bukit Batok N.P.C.
 21 Bukit Batok East Avenue 4 SINGAPORE
 869840
 Tel No: 1800-6859999

Report No: T201804182154

CONTINUATION OF REPORT

Name	NEO HOCK SIN		ID No.	G7753675L
Related Vehicle	GZ1981S (Lorry)		Contact No	98399978
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class 3.4 Date of Expiry NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	

Brief Details.

On 18/02/2018, at around 0950hrs, I was exiting my company at 17 Chin Bee Crescent on the company lorry GZ1981S with a passenger namely Chong Wei Cheng, Jacky (S9246265Z). We were driving on Jalan Boon Lay towards the direction of International Road. I was travelling on the 2nd lane of the 3 lane road of Jalan Boon Lay before the traffic light. After the traffic light before International Road, the 2nd and 3rd lane merges into a 2 lane road. After I successfully merged, I look at my side mirror and noticed a orange lorry (GBB5938C) driving at very high speeds with the driver appearing to be on the phone. The side of the said orange lorry then collided into the passenger side of my lorry. I immediately honked at the driver of the said orange lorry however he did not stop at all and drove on. I told my passenger to quickly snap a photo of the lorry and its driver. Both myself and my passenger went to see the doctors at Northeast (Bukit Batok) Medical Group and both of us received a 3 day MC for injuries due to myself hitting my head on the windscreen and my passenger suffering a sprain on his torso and left hand area.

I wish to add that my lorry has its passenger's door dented, left side mirror twisted and the left slide door having some scratches. There is no in-vehicle camera in my lorry.



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0426E
Vehicle Details	
Vehicle No.:	GZ1981S
Vehicle to be Exported:	No
Intended De-registration Date:	11 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	5L5633928
Chassis No.:	JTFUF34Y303011517
Maximum Power Output:	-
Open Market Value:	\$23,681.00
Original Registration Date:	18 Jan 2006
First Registration Date:	18 Jan 2006
Transfer Count:	3
Actual ARF Paid:	\$1,185.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,416.00
COE Rebate Amount:	\$11,822.00
Total Rebate Amount:	\$11,822.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 11 May 2018

OK

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more

SGCARMART CONNECT
BRIDGING BUYERS & SELLERS

Toyota Dyna Price Range Depreciation > 10 year(Vehicle Type Submit t Advanced Search

Home » Used Cars » Direct Owners » Toyota Dyna 150 (COE till 10/2020)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres

TNT

Toyota Dyna 150 (COE till 10/2020)

Overview Financial Accessories Similar Research Photos Map **DIRECT OWNER**

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$20,800	
Depreciation	\$8,590 /yr	?
Reg Date	12-Oct-2005 (2yrs 5mths COE left)	
Lifespan	11-Oct-2025	
Manufactured	2005	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,986 cc	
Curb Weight	1,500 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	1 Careful Owner, Regular Servicing, Just Pass Inspection, Tip Top Condition, 100% Loan At 4 %, Trade In Welcome.	
COE	\$23,992	?
OMV	\$23,690	?
ARF	\$1,185	?
Dereg Value	\$11,621 as of today (change)	?
No. of Owners	3	?
Type of Veh	Truck	
Category	COE Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER

Add to Shortlist Add to Compare Add a Note

Posted on: 01-May-2018 | Last Updated on: 01-May-2018
Tags: Toyota Dyna, 2005 Toyota Dyna, Toyota, Dyna, Used Toyota

Upfront Payment [» more Financial info](#)

Transfer Fee	\$25	?
Down Payment	\$2,080 (change)	Maximum 90% Loan ?
1st Instalment	\$716	?
Total Upfront Payment	\$2,821 (excluding insurance)	?

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.



100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER

Seller Information

Contact Person(s) Eric

Contact No. 91181690

Enquiry [Contact Seller](#)

USEFUL FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » M01

Instructions on how to complete a seller to end-consumer deal
Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.

Useful Services

Make sure of this car condition with STA Evaluation.
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.
Free Valuation

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

with Allowance
11/5/18
330?

30-07-18

Date Of Accident : 18-04-18

Marcus

OUR REF : GZ 1981S/T/18

Date in/out : 10/07/18 to 12/07/18

Casserole Catering Services Pte Ltd

17 Chin Bee Crescent

Singapore 619898

ESTIMATE BILL ON VEH. NO. : GZ 1981S

VEHICLE MODEL : TOYOTA DYNA

CHASSIS NO. : JTFUF34Y303011517

LIST ITEM

Front Door Assy 1 als	n/c 70	1,218.40 X
Front Door Weatherstripe als	17	219.00 X
		<hr/> 1,437.40
	Less Discount 25%:	<hr/> 359.35
		<hr/> 1,078.05

SPECIAL NETT ITEM

R.O.C Sticker als (30)	n/c	60.00 X
------------------------	-----	---------

LABOUR CHARGE

To Respray Affected Areas (200)	17	550.00 X
To Renew Damaged Parts, Straighten & Repair Front Bumper, (100) Door, Rear Pillar & Aligned All Parts	17	450.00 X

TOTAL :	<hr/> 2,138.05
GST 7%:	<hr/> 149.66
AMOUNT DUE :	<hr/> <hr/> 2,287.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Apr 2018		24 Apr 2018 14:03 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ORANGE CLOVE CATERING PTE LTD , Co. Reg. No.: 200809605R								
Main Claimant:	CASSEROLE CATERING SERVICES PTE LTD , Co. Reg. No.: 201530426E								
Vehicle Reg. No.:	GZ1981S	Date of Loss:	18/04/2018 09:00 - :59 [147 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556083	Policy/Cover Note No.:	A29076922MKF (Comprehensive) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	GBB5938C	Policy No. (Claimant):							
		Excess:							
Repairer:	Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 25/04/2018]								
Driver/Custodian (Insured):	KYAW MYO WIN (), NRIC: G3309963R, Tel: +6593835319								
Adj Asg. Remarks:	Please assign to Mr Adrian Ling. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GZ1981S (556083)**
[GBB5938C]

TP

CASSEROLE CATERING SERVICES PTE LTD

Apr 18 2018 9:00AM

[ORANGE CLOVE CATERING PTE LTD]

Precise Auto Services

Upload Documents Upload Photos Compose New Letter			View	View In Browser ▼	
Video			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/04/18 10:26	Video - Accident From: SC - Reg. No: GBB5938C, Claimant: ORANGE CLOVE CATERING PTE LTD	i	Load MP4	<input checked="" type="checkbox"/>
2	13/07/18 14:27	Video - Accident- OI vehicle front From: TP BI - Reg. No: GZ1981S, Claimant: CHONG WEI CHENG JACKY	i	Load MP4	<input checked="" type="checkbox"/>
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/04/18 10:26	Accident Statement From: SC - Reg. No: GBB5938C, Claimant: ORANGE CLOVE CATERING PTE LTD	i	Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/05/18 15:07	Chassis Number	i	Load JPG	<input checked="" type="checkbox"/>
2	11/05/18 15:08	Odometer Reading	i	Load JPG	<input checked="" type="checkbox"/>
3	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
4	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
5	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
6	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
7	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
8	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
9	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
10	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
11	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
12	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
13	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
14	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
15	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
16	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
17	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
18	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
19	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
20	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
21	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
22	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
23	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
24	11/05/18 15:08	General View	i	Load JPG	<input checked="" type="checkbox"/>
25	12/07/18 17:20	Reinspection Photo	i	Load JPG	<input checked="" type="checkbox"/>
26	12/07/18 17:20	Reinspection Photo	i	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
27	12/07/18 17:20	Reinspection Photo	Load JPG	✓
28	12/07/18 17:20	Reinspection Photo	Load JPG	✓
29	12/07/18 17:20	Reinspection Photo	Load JPG	✓
30	12/07/18 17:20	Reinspection Photo	Load JPG	✓
31	12/07/18 17:20	Reinspection Photo	Load JPG	✓
32	12/07/18 17:20	Reinspection Photo	Load JPG	✓
33	12/07/18 17:20	Reinspection Photo	Load JPG	✓
34	12/07/18 17:20	Reinspection Photo	Load JPG	✓

Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/04/18 10:26	GZ1981S E FILE REPORT From: SC - Reg. No: GBB5938C, Claimant: ORANGE CLOVE CATERING PTE LTD	Load PDF	
2	24/04/18 10:39	PRI Notice	Load PDF	
3	24/04/18 14:03	TP agree on SJE.	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007561/UTBS2
Date: 14/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29076922MKF
Claimant Vehicle No :	GZ1981S	Insured Vehicle No :	GBB5938C
Date of Loss:	18/04/2018	Nature of Claim:	TP
		Claim No:	556083

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ1981S	Engine No:	5L5633928
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFUF34Y303011517
Reg. Date:	18/01/2006 (Man. Year: 2005)	Odometer:	451984 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185 R14	Rear Tyre Size:	155 R12 (D)
Front Left Side:	West Lake 5 mm	Rear Left Side:	Falken 5/5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	Falken 5/5 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,138.05	0.00	1,138.05	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	0.00	1,000.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,138.05	0.00	2,138.05	100.00
+ GST 7.00/7.00% (S\$)	149.66	0.00	149.66	100.00
Nett Amount (S\$)	2,287.71	0.00	2,287.71	100.00

INSPECTION

Date of Assignment:	24/04/2018		
Date Inspected:	11/05/2018	Inspected At:	Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36 Singapore 417883
Estimated Period of Repair:	0.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Mr K.K.Lau had viewed the insured's video clips and damaged assessment of our Marcus Chua opinion not consistent.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Sep 2018)
Parts:	N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ1981S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR ASSY N/S	Not Consistent With The Impact	1,218.40 FL	*- FL	
2	1		*FRONT DOOR WEATHERSTRIPE N/S	Not Necessary	219.00 FL	*- FL	
3	1		*R.O.C STICKER N/S	Not Consistent With The Impact	60.00 FS	*- FS	
					Sub Total (\$\$)	1,497.40	0.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	359.35	0.00
					Total Parts (\$\$)	1,138.05	0.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY AFFECTED AREAS	New	550.00	-
2	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR FRONT BUMPER, DOOR, REAR PILLAR & ALIGNED ALL PARTS	New	450.00	-
Gross Labour Cost (\$\$)			1,000.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >