

Our Ref : T 0418 / SHD3460U / JW(st)
 Your ref : _____
 Date : 02-May-18

CDGE Taxi Claims Dept
 59 Loyang Drive 4th Flr
 Singapore 508969

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road Singapore 579701

Mainline +65 6383 6280
 Facsimilie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

EQ Insurance Company Limited
 5 Maxwell Road, MND Complex
 #17-00 Tower Block
 Singapore 069110

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHD3460U YOUR INSURED GR 7702J
 AND OTHER _____ ON 21.04.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHD3460U which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving GR 7702J we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	4,866.25
2	<u>4</u> days Loss of Rental @ <u>\$ 117.00</u> per day	\$	468.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$	-
4	LTA Search Fees	\$	7.49
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transportation Fees	-	-
Sub Total :		\$	5,341.74

HIRER'S CLAIM

7	<u>4</u> days Loss of Income @ <u>\$ 80.00</u> per day	\$	320.00
Total Claims:		\$	5,661.74

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 7 pcs.
- b) LTA search slip/s of : GR 7702J
- c) GIA / Police report/s of : SHD3460U
- d) Letter of authority from owner / hirer / operator

- () Witness statement/s () Towing/Medical bill/receipts () Certificate of Insurance
- (X) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Jim Wong

Deputy Manager

CDGE Claims Department

Tel : 6214 8374 Fax: 6214 1843 Email : jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.

Workshops

Braddell
 205 Braddell Road
 Singapore 579701

Loyang
 59 Loyang Drive
 Singapore 508969

Sin Ming
 383 Sin Ming Drive
 Singapore 575717

Pandan
 45 Pandan Road
 Singapore 609286

Ubi
 320 Ubi Road 3
 Singapore 408649

Senoko
 24 Senoko Loop
 Singapore 758156

Sungei Kadut
 7 Sungei Kadut Way
 Singapore 728791

Defu
 6 Defu Avenue 1
 Singapore 539537

Yishun
 501 Yishun Industrial Park A
 Singapore 768732

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****i 40 SHD3460U , GR7702J****ON 21-Apr-18 11:30****ALONG SOON LEE ROAD TWDS INTERNATIONAL RD, OUTSIDE SBS TRANSIT**

I / We

LAU FOOK YUEN(Hirer) NRIC No.: **S0149893B**

and/or

(Relief) NRIC No.:

Taxi Number

SHD3460U

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

22-Apr-2018

Name of Hirer

LAU FOOK YUEN

Hirer NRIC

S0149893B

Signature :



Address

**641 JURONG WEST STREET 61 #11-...
640641**

Contact No.

90699489

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 1

8010325

EQ INSURANCE COMPANY LIMITED

#17-00 5 MAXWELL ROAD TOWER BLOCK
SINGAPORE SG 069110

CONTACT NO: 62239433

VEHICLE NO
SHD3460U

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
18.08.2016

CHASSIS CODE
KMHLE41UMGU093321

INV. NO/DATE
91369803 27.04.2018

JOB NO.
305144702

ODOMETER READING

DATE/TIME IN
21.04.2018 14:50

Description : 3P 21.04.18

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART REQUISITION						
0001	04-01-0103-0577	I40VC PANREL ASSY-TRUNK LH	1	1,681.40	20.00	1,345.12
0002	04-01-0103-0800	I40VC SYMBOL MARK-TRUNK L	1	27.20	20.00	21.76
0003	04-01-0103-0787	I40VC EMBLEM-I40	1	41.00	20.00	32.80
0004	04-01-0103-0786	I40VC EMBLEM-CRDI	1	41.00	20.00	32.80
0005	28-01-0103-0005	(I40/SONATA)REAR BOOT LOG	1	20.00	0.00	20.00
0006	28-01-0103-0006	(I40/SONATA)REAR BOOT TEL	1	10.00	0.00	10.00
0007	04-01-0103-0579	I40VC COVER ASSY-RR BUMPER	1	603.60	20.00	482.88
0008	04-01-0103-0738	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0009	04-01-0103-0739	I40VC ABSORBER-RR BUMPER	1	143.40	20.00	114.72
0010	04-01-0103-0740	I40VC BEAM-RR BUMPER#	1	504.35	20.00	403.48
0011	04-01-0103-0742	I40VC STAY-RR BUMPER LH	1	180.00	20.00	144.00

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY OR NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010325	91369803	4,866.25	

GST REG. NO. M2-8921817-3

TAX INVOICE

8010325

EQ INSURANCE COMPANY LIMITED

#17-00 5 MAXWELL ROAD TOWER BLOCK
SINGAPORE SG 069110

CONTACT NO: 62239433

VEHICLE NO
SHD3460U

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
18.08.2016

CHASSIS CODE
KMHLE41UMGU093321

INV. NO/DATE
91369803 27.04.2018

JOB NO.
305144702

ODOMETER READING

DATE/TIME IN
21.04.2018 14:50

S/No	Part No.		Qty	Unit Price	%Disc	Net
0012	04-01-0103-0743	I40VC STAY-RR BUMPER RH	1	180.00	20.00	144.00
0013	04-01-0101-0111	HYUNDAI BUMPER COVER CLIP	10	2.20	20.00	17.60
0014	09-01-9999-0068	HYUNDAI REVERSE SENSOR AS	1	135.70	0.00	135.70
0015	04-01-0103-0695	I40VC CLAMP-SPARE TIRE	1	28.80	20.00	23.04
SUB-TOTAL						3,107.90

JOB NATURE

0001	20-05	RENEW ADVERTISEMENT REAR FENDER LH	100.00		100.00
0002	20-05	RENEW ADVERTISEMENT REAR FENDER RH	100.00		100.00
0003	L	PANEL BEATING	600.00		600.00
0004	L	SPRAY PAINTING CHARGE	600.00		600.00
0005	L	TUFF KOTE	20.00		20.00
0006	L	REMOVE/REFIX REVERSE SENSOR	20.00		20.00

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY OR NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010325	91369803	4,866.25	

Workshops

GST REG. NO. M2-8921817-3

TAX INVOICE

8010325
EQ INSURANCE COMPANY LIMITED

#17-00 5 MAXWELL ROAD TOWER BLOCK
SINGAPORE SG 069110

CONTACT NO: 62239433

VEHICLE NO SHD3460U	INV. NO/DATE 91369803 27.04.2018
MAKE HYUNDAI	JOB NO. 305144702
MODEL I-40	ODOMETER READING _____
DATE OF REG 18.08.2016	DATE/TIME IN 21.04.2018 14:50
CHASSIS CODE KMHLB41UMGU093321	

S/No	Part No.	Qty	Unit Price	%Disc	Net
------	----------	-----	------------	-------	-----

SUB-TOTAL	:	1,440.00
-----------	---	----------

Items total	4,547.90
Add GST @	7.000 % 318.35
Invoice amount	4,866.25

Issued by : KATHERINETAN 27.04.2018 14:18:54
Repair type : CL50/57/57
Payment Type/Term: /Credit 30 days

- 1) WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- 2) CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- 3) INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- 4) PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010325	91369803	4,866.25	

Our Ref: CT18040594

Date: 27 April 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 21/04/2018 @ 11:30 hrs
ALONG ALONG SOON LEE RD > INT'L RD OUTSIDE SBS
TRANSIT
INVOLVING GR7702J

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHD3460U** (the "Taxi"). The Taxi was hired to **LAU FOOK YUEN IC NO S0149893B** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$117.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

NG	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER	MILEAGE READING		MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
		FROM	TO			FROM	TO		FROM	TO
90	170	1120	2250		SHP 346001	182	280	262	1615	0045
08	318	0600	2050	21/04/18	SM			1N	0830	1450
50	144	0830	1610	21/04/18	Accident			001	1450	1500
17	264	1610	0030	24/4/18	Repair					
86	169	0630	1600							
55	269	1610	0030							
11	156	0630	1700							
12	200	1710	0020							
597	85	0700	1600							
264	272	1600	0055							
01	149	0630	1610							

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
GR7702J	21 Apr 2018 / 11:30:00	Successful	E04	EQ INSURANCE COMPANY LTD

Previous

OK

