

ASS. REC. BY:

REF: CS3 / ICS 1800 7573 / 62416d2

Special Instruction:

Survivor

ASSIGNMENT (Office)From (Person): Janice Goh of ICS Date/Time: 24042018 4:16pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 12252 Insured: SBU 3999Pat Workshop m/s Uni Automotiv Tel: 9798 1616of Blk 1 Kaki Bukit Ave 6 #01-94

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23042018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

26.042018 @ afternoon

Date/Time: 24042018 4:42pm Person Contacted: Alvin H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKR 12252 - X
	SBU 3999P - X
27/4/18	dismantled
30/4/18	After Repair

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKR 1225L Yr Regn: N2 V / 2014
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: BMW 3161c.c. 1598Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 64909

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA3A16050N537591Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 205 / 60 R 16R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 23042018D.O.I. 27042018 @ 12.28pmSurvey held at Uni Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Estimated repair range \$5,000 - \$6,000
Range + No. of days

30/7/18 Submit PRS Report.

[Signature]
27/7/2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format : PRB

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

) \$ + RS \$

) Photos

) Other

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Insp (\$)☐ Weekend (\$)

100

100

100

10

20

Catherine Chong (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Tuesday, 24 April, 2018 4:16 PM
To: Jennifer Guay; 'assignments'
Cc: 'Unimotor'; motorsurvey
Subject: RE: OUR REF: AW-INS-U7-SKR1225L-18.jgv & YR REF: SBU3999P

Without Prejudice

Dear Jennifer

Thank you for your email.
We are not agreeable with your surveyor list and we will appoint LKK for the PRI.

Aside to LKK

Please assist to arrange TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Jennifer Guay [mailto:jenniferguay@visionlawllc.com]
Sent: Tuesday, 24 April, 2018 2:11 PM
To: motorsurvey
Cc: 'Unimotor'
Subject: RE: OUR REF: AW-INS-U7-SKR1225L-18.jgv & YR REF: SBU3999P
Importance: High

CLAIMANT: ARLINA
ACCIDENT INVOLVING SKR 1225 L & SBU 3999 P ON 23 APRIL 2018 ALONG AYE TOWARDS JURONG TOWN HALL RD

Dear Sirs

Refer to your email of 24 April 2018 informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following
10 surveyors for your consideration:-

1. Alan Cheong	2. Willy Goh
3. BJ Loi	4. Marc
5. Oh Han Cheong	6 TT Rajan
7. Andrew How	8. Teo Hoon Tong
9. Lee Kok Weng	10. Lim Yong Tian Sebastian

You can inspect our client's vehicle as follows:

Workshop : Uni Automotive Pte Ltd
Blk 1 Kaki Bukit Ave 6 #01-94
Singapore 417883

Tel : 9798 1616 Alvin

Please reply within 2 working days.

Regards

Jennifer Guay

(Secretary)

VISION LAW LLC

133 New Bridge Road #18-01
Chinatown Point
Singapore 059413
Tel : 6534 2811 (Ext 116)
Fax : 6535 6802

From: motorsurvey [<mailto:motorsurvey@ecics.com.sg>]

Sent: Tuesday, 24 April, 2018 2:04 PM

To: Jennifer Guay; motorsurvey

Cc: 'Unimotor'

Subject: RE: OUR REF: AW-INS-U7-SKR1225L-18.jgv & YR REF: SBU3999P

Without prejudice

Dear Jennifer

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam

4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]
Sent: Tuesday, 24 April, 2018 1:19 PM
To: motorsurvey
Cc: 'Unimotor'
Subject: OUR REF: AW-INS-U7-SKR1225L-18.jgv & YR REF: SBU3999P
Importance: High

PRE - REPAIR SURVEY
CLAIMANT: ARLINA
ACCIDENT INVOLVING SKR 1225 L & SBU 3999 P ON 23 APRIL 2018 ALONG AYE TOWARDS JURONG TOWN HALL RD

Dear Sirs

We are instructed by **ARLINA** to notify you of a road accident on **23 APRIL 2018** at about 9.10hr **ALONG AYE TOWARDS JURONG TOWN HALL RD** involving our client's **SKR 1225 L & SBU 3999 P** driven by your driver at the material time.

As a result of the accident, our client's vehicle has been damage. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For Surveyor

Please initial here after completion of pre-repair survey.
Thank you.

Appointed Surveyor: _____
Name & Signature

Contact: _____

Date & Time: _____

Surveyor during repair: _____

Date & Time: _____

Surveyor after repair: _____

Date & Time: _____

Regards

Jennifer Guay

(Secretary)

VISION LAW LLC

133 New Bridge Road #18-01

Chinatown Point

Singapore 059413

Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2018 16:47
Date Of Accident	23/04/2018 09:10
Exact Location Of Accident	AYE TWDS JURONG TOWN HALL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR1225L
Insured/Policyholder	
Name Of Registered Owner	ARLINA
NRIC No	S8678968Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90103086
Alternative Phone No	OFFICE-90103086

Vehicle Particulars

Manufacturer	BMW
Model	316I
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700074896
Cover Note Number	

Driver

Name of Driver	ANTONI
NRIC No	S7975330J
Date Of Birth	08/04/1979
Occupation	INDOOR
Date Of Driving Pass	11/08/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96914395
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	770 BEDOK RESERVOIR RD #02-02
Postcode	479250
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG JURONG TOWN HALL ROAD FROM SECOND LANE CHANGING TO THIRD LANE AND MOVING IN STRAIGHT. A CAR (SBU3999P) AT HIGH SPEED FROM LANE 4 CUT INTO LANE 3 AND HIT ONTO MY VEHICLE FRONT LEFT HAND SIDE PORTION. MY IN CAR CCTV CAMERA TOOK DOWN THE ACCIDENT HAPPENED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TP WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBU3999P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature:
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG JURON TOWNHALL ROAD FROM ~~2nd~~ 2ND LANE CHANGING TO 3RD LANE AND WAS MOVING IN STRAIGHT. A CAR SBU 3999P AT HIGH SPEED FROM LANE 4 CUT INTO LANE 3 AND HIT ONTO MY VEHICLE FRONT LEFT HAND SIDE PORTION. IN MY CAR MY CCTV CAMERA TOOK DOWN THE ACCIDENT HAPPENED.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Driving License





CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Arina
 Period of Insurance : 28 Nov 2017 To 27 Nov 2018
 Engine No. : A391J794N13B16A
 Chassis No. : WBA3A16050NS37581

Vehicle No. : SKR1226L
 Policy No. : 1700074395
 Endorsement No. :
 Issued Date : 06 Nov 2017

ABOUT THE COVER

Make/Model : BMW 318IA4DR
 Engine Capacity/Tonnage : 1,596.00 CC
 Driver Restriction : NA

Sum Insured : Market Value
 Off Peak Car : No

First Year of Registration : 2014
 Insuring with COE/FAIRF : Yes

Person or Classes of Persons Entitled to Drive*

1. The Policyholder
 2. Any other person who is named on the Policyholder's motor vehicle licence/permit.
 This Policy will indemnify the Policyholder only if the driver is fully licensed in the relevant jurisdiction.
 *You have to pay an additional sum of \$2,500 for Young and/or inexperienced Driver excess (YED/IED) for each of your Authorized Driver named on the policy (under 25 years of age for Young and/or inexperienced drivers).

Age Condition : All Age Condition

Limitations on Use*

Use only for social, domestic and pleasure purposes and not for the Policyholder's business.
 The Policy does not cover use for hire or reward, driving in the street, racing, assembly, road testing or speed testing, the carrying of goods other than transport containers with any motor vehicle or use for any purpose inconsistent with Motor Traffic.

Legal Offence : Driving Without

*This clause is subject to the provisions of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 162) and Section 55 of the Road Transport Act, 1997 (Cap. 394), and the Motor Vehicle (Third Party Risks) Regulations.

EXCESS

Section 1

Excess : \$0. Own Damage : \$500. Theft : \$0. Road Damage : \$0.

Section 2

Excess : \$0.

Windscreen : \$100

Named Driver and Excess (per person/vehicle)

Arina

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres (ARC) and Authorized Repairers (AR) are listed on the back of the policy. You must use the services of the ARC and AR for repairs to the vehicle. Within the first 3 years of the first registration of the vehicle in Singapore, you have the option of sending the accident reports and claim to the ARC and AR's workshop.
 For more approved Reporting Centres (ARC) and repairers, please contact our 24-hour accident emergency hotline at +65 6520 0200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

This Policy is subject to the policy conditions and Certificate of Insurance which is issued in accordance with the provisions of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 162) Part IV of the Road Transport Act, 1997 (Cap. 394) and Motor Vehicle (Third Party Risks) Rules, 1999 (Malaysia).

5504860050

T&N JERRON

31 ALPINES GRANDE #05-29 A/A ALEXANDRA

SINGAPORE 526709 SF-000CH

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

JERRON T&N

[Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKR1225L		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	B.M.W.		
Vehicle Model :	316i 1.6 AT D/AB 4DR ABS HID		
Chassis No. :	WBA3A16050NS37591		
Propellant :	Petrol		
Engine No. :	A391J734N13B16A		
Engine Capacity :	1598 cc		
Maximum Power Output :	100.0 kW (134 bhp)		
Maximum Laden Weight :	1955 kg		
Unladen Weight :	1405 kg		
Year Of Manufacture :	2014		
Original Registration Date :	28 Nov 2014		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$71,300.00		
COE Expiry Date :	27 Nov 2024		
Road Tax Expiry Date :	27 Nov 2018		
PARF Eligibility Expiry Date :	27 Nov 2024		
Inspection Due Date :	27 Nov 2019		
Intended Transfer Date :	18 Jul 2018		
CO2 Emission :	137.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2018 08:59 Edit Reg		24 Apr 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured: -, Co. Reg. No.: -, Email: email@email.com

Main Claimant: -

Vehicle Reg. No.: SKR1225L	Date of Loss: 23/04/2018 00:00 - :59 [40 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type: TP	Policy/Cover Note No.:
Vehicle Reg. No. (Insured): SBU3999P	Policy No. (Claimant):
	Excess:

Repairer: **Uni Automotive Pte Ltd (HQ)** NO. 1 KAKI BUKIT AVE 6 #01-94 AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67482795

Handling Insurer: **ECICS Limited (HQ)** - Tel: 63374779 /6303 0178

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... [Final Rpt due 25/07/2018]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.






































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)












Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKR1225L**
[SBU3999P]
TP

-
Apr 23 2018 12:00AM
[-]
Uni Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/07/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/07/18 12:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/07/18 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	18/07/18 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	18/07/18 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	18/07/18 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18007573/GZ4BE2

Date: 31/07/2018

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SKR1225L

Insured Vehicle No :

SBU3999P

Date of Loss: 23/04/2018

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKR1225L

Make & Model: BMW 318i, 1.5 (A)

Engine No: A391J734N13B16A

Reg. Date: 28/11/2014 (Man. Year: 2014)

Chassis No: WBA3A16050NS37591

Colour: Black

Odometer: 64509 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/04/2018

Date Inspected: 27/04/2018 Inspected At:

 Uni Automotive Pte Ltd (HQ)
 NO. 1 KAKI BUKIT AVE 6 #01-94
 AUTOBAY@KAKI BUKIT
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2018)
Parts:	143	BMW 318I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1225L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >