

ASS. REC. BY:

REF: CS3 / FWD 18007574 / G24604 Special Instruction: /

Surveyor:

GR

ASSIGNMENT (Office)

From (Person):

Clara Li

of

FWD

Date/Time:

24/04/2018 2:24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 5160P

Insured:

SGA 4288m

at Workshop m/s

HS Motor

Tel:

6747 7755

of

Blk 2 Kalsi Bukit Ave 2 #01-15

Policy No:

Claim No:

1201800004946

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

25-04-2018

H.O.D. Endorsement:

Date/Time:

24/04/2018 4:40pm

Person Contacted:

Connie

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKM 5160P - X
	SGA 4288m - X.
26/4/18	Dismantled
28/4/18	After Repair

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKM 5160P Yr Regn: 2014 / Mar 11  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Hyundai Elantra 1.6 AT c.c. 1591Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 57897 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM1HDH41CMEU080664Gen. Cond: Good / Fair / Poor / BurntSteering: Insider / Jammed / Leaked / Burnt orBrake: Insider / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 55 ZR16 11WR: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 20-04-2018 D.O.I. 25-04-2018 @ 639pmSurvey held at H S AutomobileDes. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$8,500 - \$9,800

Range + No. of days.

30/7/18 Submit PRS report

[Signature]  
21/7/2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format : PRS

Lump Sum / I.B.I. (\$) \_\_\_\_\_

80

50

50

180

## Catherine Chong (LKK Auto)

---

**From:** motorclaims.sg@fwd.com  
**Sent:** Tuesday, 24 April, 2018 2:24 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Subject:** FW: Accident involving SKM5160P / SGQ4288M & others on 20-4-2018 at AYE  
Our Ref: 1201800004946  
**Attachments:** AL SKM5160P PRI.PDF

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	<b>Endowment Plan</b> Get the biggest guaranteed return for a 3 year plan available online. <b>Limited time offer!</b>	 <b>2.02% p.a.</b> fwd.com.sg <b>save now</b>
--	--	--

---

**From:** Motor Claims SG - SG Common

**Sent:** Tuesday, 24 April, 2018 2:23 PM

**To:** 'Atkins Law Corporation'

**Cc:** 'CONNIE CHANG'

**Subject:** RE: Accident involving SKM5160P / SGQ4288M & others on 20-4-2018 at AYE Our Ref: 1201800004946

**WITHOUT PREJUDICE**

Dear Sir/ Madam,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your

client's vehicle, SKM5160P. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

***\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.***

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E [clara.li@fwd.com](mailto:clara.li@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



	<b>Endowment Plan</b> Get the biggest guaranteed return for a 3 year plan available online. <b>Limited time offer!</b>		<b>2.02% p.a.</b> <a href="http://fwd.com.sg">fwd.com.sg</a> <b>save now</b>
--	--	--	--

---

**From:** Atkins Law Corporation [<mailto:atkinslawcorp@gmail.com>]

**Sent:** Tuesday, 24 April, 2018 2:10 PM

**To:** Motor Claims SG - SG Common

**Cc:** 'CONNIE CHANG'

**Subject:** RE: Accident involving SKM5160P / SGQ4288M & others on 20-4-2018 at AYE Our Ref: 1201800004946

Dear Sir,

We refer to your email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) PAR Automotive Consultancy,
- 2) SK Auto Consultants,
- 3) Chartered Auto Assessors,
- 4) LCW APPRAISER PTE LTD
- 5) Sincere Appraisal Services,
- 6) Pal's Appraisal Pte Ltd,
- 7) Mc-Coy Appraiser Pte Ltd,
- 8) CM Automotive Consultancy,

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

**H S Motor Engineering**

Blk 2 Kaki Bukit Avenue 2 #01-15

Kaki Bukit AutoHub,

Singapore 417921

Person In-Charge: Ms. Connie. Tel: 6747 2755

**\* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.**

Regards.

Atkins Law Corporation

---

**From:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com) [<mailto:motorclaims.sg@fwd.com>]

**Sent:** 24 April 2018 12:16

**To:** [atkinslawcorp@gmail.com](mailto:atkinslawcorp@gmail.com)

**Subject:** RE: Accident involving SKM5160P / SGQ4288M & others on 20-4-2018 at AYE Our Ref: 1201800004946

**WITHOUT PREJUDICE**

Dear Sir/ Madam,

We refer to your letter dated 24 April 2018 of the PRI Notice of your client's vehicle SKM5160P.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

***\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.***

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E [clara.li@fwd.com](mailto:clara.li@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



---

**From:** Atkins Law Corporation [mailto:[atkinslawcorp@gmail.com](mailto:atkinslawcorp@gmail.com)]  
**Sent:** Monday, 23 April, 2018 5:05 PM  
**To:** SG Corporate Contact  
**Subject:** Accident involving SKM5160P / SGQ4288M & others on 20-4-2018 at AYE

Dear Sir,

Please refer to the attached Notice of Accident.

Regards,

Atkins Law Corporation.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1372C
Vehicle Details	
Vehicle No.:	SKM5160P
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jul 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	G4FGDU224259
Chassis No.:	KMHDH41CMEU080664
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$13,299.00
Original Registration Date:	11 Mar 2014
First Registration Date:	11 Mar 2014
Transfer Count:	1
Actual ARF Paid:	\$13,299.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Mar 2024
PARF Rebate Amount:	\$9,974.00
Intended COE Rebate Details	
COE Expiry Date:	10 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,564.00
COE Rebate Amount:	\$40,334.00
Total Rebate Amount:	\$50,308.00

The information contained herein is correct as at 20 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/04/2018 12:24
Date Of Accident	20/04/2018 19:45
Exact Location Of Accident	AYE > TUAS BEFORE CLEMENTI RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM5160P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WONG PENG WOON (HUANG BINGWEN)
NRIC No	S7421372C
Email Address	ECV@ELITECARVENTURES.COM
Mobile Phone No	(LOCAL) +65-98892227
Alternative Phone No	OFFICE-98892227

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA340557/1
Cover Note Number	06/04/2018-05/04/2019

### Driver

Name of Driver	WONG PENG WOON (HUANG BINGWEN)
NRIC No	S7421372C
Date Of Birth	09/07/1974
Occupation	INDOOR
Date Of Driving Pass	19/01/2004
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98892227
Fax Number	
Contact Number	OFFICE-98892227
EMail Address	ECV@ELITECARVENTURES.COM



Address	BLK 987D JURONG WEST ST 93 #14-597
Postcode	644987
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGQ4288M
Vehicle Make/Model/Colour	B
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKP9935D
-----------------------------	----------

Vehicle Make/Model/Colour	C
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJN9420U
Vehicle Make/Model/Colour	D
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SKETCH PLAN

AYE towards Tuas  
Before Clementi Rd Exit



Vehicle A SKM 5160P  
Vehicle B SGQ 4288M  
Vehicle C SKP 9935D  
Vehicle D SJN 9420U

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On dated 00/04/2018 at around 19:45 hours.  
I was driving along AYE towards Tuas, just before  
Clementi Rd Exit. Suddenly I felt a strong impact  
from my rear and immediately I braked and caused  
my vehicle to hit slightly onto a vehicle in front of mine.  
After that, I alighted and realising there's four vehicle  
involved including mine. I took some photos and exchanged  
all particulars. My rear portion was badly damaged.  
My vehicle A (SKM 5160P), vehicle B (SGQ 4288M), vehicle C (SKP 9935D)  
vehicle D (SJN 9420U)

You had been advised by workshop that in the event that you wish to claim  
against your own policy (OD claim), there is a Fourteen (14) days clause  
whereby the claim must be made within the stipulated timeframe from  
the day of occurrence.

<input type="checkbox"/>	Reporting Only
<input type="checkbox"/>	Claim OD
<input type="checkbox"/>	Claim TP
<input checked="" type="checkbox"/>	Claim OD / TP at other workshop

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKM5160P [SGQ4288M] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)****1/159: General View****2/159: General View****3/159: General View**

• **SKM5160P [SGQ4288M] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)**13/159: **General View**14/159: **General View**15/159: **General View**






































### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jul 2018 <a href="#">Edit Reg</a>		24 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>Tan Kai Pin</b> , ID: S81036791									
Main Claimant: <b>WONG PENG WOON (HUANG BINGWEN)</b> , ID: S7421372C									
Vehicle Reg. No.: <b>SKM5160P</b>		Date of Loss: 20/04/2018 19:00 - :59 [49 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 1201800004946</b>		Policy/Cover Note No.: PNPV2017-00008128 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SGQ4288M</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Hs Automotive Services (HQ)</b> Blk 2 Kaki Bukit Avenue 2 #02-25, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel:									
Handling Insurer: <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Josey Loh</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 25/07/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































## Claim Documents
























**\*SKM5160P (1201800004946)**  
**[SGQ4288M]**  
**TP**  
**WONG PENG WOON (HUANG BINGWEN)**  
**Apr 20 2018 7:00PM**  
**[Tan Kai Pin]**  
**Hs Automotive Services**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	18/07/18 12:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
141	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
142	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
143	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
144	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
145	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
146	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
147	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
148	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
149	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
150	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
151	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
152	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
153	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
154	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
155	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
156	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
157	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
158	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
159	18/07/18 12:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	17/07/18 11:29	Insured GIA Report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div> <div></div> <div> ^ v </div> </div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18007574/GZ4BE2

Date: 31/07/2018

## REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00008128

Claimant Vehicle No: SKM5160P Insured Vehicle No: SGQ4288M

Date of Loss: 20/04/2018 Nature of Claim: TP Claim No: 1201800004946

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKM5160P**  
 Make & Model: HYUNDAI ELANTRA, 1.6 D/AB 2WD 4DR (A) Engine No: G4FGDU224259  
 Reg. Date: 11/03/2014 (Man. Year: 2014) Chassis No: KMHDH41CMEU080664  
 Colour: Silver Odometer: 57897 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16  
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm  
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 24/04/2018

Date Inspected: 25/04/2018 Inspected At:

Hs Automotive Services (HQ)  
 Blk 2 Kaki Bukit Avenue 2 #02-25, Kaki  
 Bukit AutoHub  
 Singapore 417921

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500.00 -\$9,800.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 31 Jul 2018)

**Parts:** 143      HYUNDAI ELANTRA 1.6 D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKM5160P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >