

ASS. REC. BY:

REF:

CS3 / MSC118007598 / GZ464

Special Instructions:

Surveyor

GR

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

NBA

Date/Time:

25/04/2018 12:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 3175X

Insured:

SLT 7817S

at Workshop m/s

Bluel

Tel:

of

Blk 1 Kaki Bukit Ave 6 #01-28

Policy No:

290504470MY

Claim No:

556340

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

25/04/2018 1:48pm

Person Contacted:

Sally

Vehicle IN / OUT

Date/Time

Action/Instruction (x) Estimate

SJR 3175X - X

SLT 7817S - NBA / MSC118007451 / Y

DFA: 23/04/18

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$24k.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJR 3175X Yr Regn: 18 Jun 2009

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic 20 1998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 155629 T/Radio: Insured / Std / NI / NA

Eng/No: FD 2140 2851

C/No: _____

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 25-04-18

Survey held at w/s 5pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$7000 - \$800
27/6/18	Submit PRS Report

Date/Time. File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time. File Return to?

2)

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		25 Apr 2018 12:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		AU YUEN KENG, ID: S1599172J [Created by insurer]							
Main Claimant:		LOY ZHI JUN DERRICK, ID: S8202698C							
Vehicle Reg. No.:	SJR3175X	Date of Loss:	23/04/2018 00:00 - :59 [106 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556340	Policy/Cover Note No.:	29050447QMY Coverage: 10/11/2017 - 09/11/2018						
Vehicle Reg. No. (Insured):	SLT78175	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/04/2018]								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.			View All	Compose Case Mail					
ALL ASSOCIATED TASKS									
<div> View All Search Tasks Create New Task Complete </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2018 12:33
Date Of Accident	23/04/2018 08:10
Exact Location Of Accident	AYE TWDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR3175X
Insured/Policyholder	
Name Of Registered Owner	LOY ZHI JUN DERRICK
NRIC No	S8202698C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96339165
Alternative Phone No	OFFICE-96339165

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01008516
Cover Note Number	

Driver

Name of Driver	LOY ZHI JUN DERRICK
NRIC No	S8202698C
Date Of Birth	05/02/1982
Occupation	INDOOR
Date Of Driving Pass	29/11/2002
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96339165
Fax Number	
Contact Number	OFFICE-96339165
Email Address	NOEMAIL

Address	BLK 28B DOVER CRESCENT #35-33
Postcode	132028
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : LOY RUI EN HEIDI
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 23/04/2018 AT ABOUT 8.07AM, I STOPPED MY VEHICLE AT THE SLIP ROAD WAITING TO ENTER INTO AYE. FEW SECONDS LATER, I FELT AN IMPACT AT THE REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT7817S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	AU YUEN KENG
NRIC/Passport Number	S1599172J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 23/4/18, 11am

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/4/18, 11am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Blawor

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/4/18 at about 8:07am, I stopped my vehicle at the slip road waiting to enter into AYE. Few seconds later, I felt an impact at the rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time: 23/4/18, 11am

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/4/18, 11am

23/4/18 11.33AM
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2698C
Vehicle Details	
Vehicle No.:	SJR3175X
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC TYPE-R 2.0 M
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	K20A5822937
Chassis No.:	FD21402851
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$29,224.00
Original Registration Date:	18 Jun 2009
First Registration Date:	18 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$29,224.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2019
PARF Rebate Amount:	\$14,612.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$14,840.00
COE Rebate Amount:	\$1,446.00
Total Rebate Amount:	\$16,058.00

The information contained herein is correct as at 27 Jun 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		25 Apr 2018 12:46 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AU YUEN KENG , ID: S1599172J								
Main Claimant:	LOY ZHI JUN DERRICK , ID: S8202698C								
Vehicle Reg. No.:	SJR3175X	Date of Loss:	23/04/2018 00:00 - :59 [106 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556340	Policy/Cover Note No.:	29050447QMY Coverage: 10/11/2017 - 09/11/2018						
Vehicle Reg. No. (Insured):	SLT7817S	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 26/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR3175X (556340)
[SLT7817S]
TP
LOY ZHI JUN DERRICK
Apr 23 2018 12:00AM
[AU YUEN KENG]
Bluwe! Automotive Service Pte Ltd

Upload Documents

Upload Photos





























Compose New Letter

View

View in Browser




Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/06/18 11:19	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/04/18 17:31	TP PRI & Sketch Plan	 Load PDF	
2	24/04/18 10:49	OI accident report	 Load PDF	
3	25/04/18 12:20	SJR3175X GIA Rpt	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18007598/GZ4BE2

Date: 27/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29050447QMY

Claimant Vehicle No: SJR3175X

Insured Vehicle No: SLT7817S

Date of Loss: 23/04/2018

Nature of Claim: TP

Claim No: 556340

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR3175X

Make & Model: HONDA CIVIC, 2.0 TYPE-R (M)

Engine No: K20A5822937

Reg. Date: 18/06/2009 (Man. Year: 2008)

Chassis No: FD21402851

Colour: Silver

Odometer: 155629 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/04/2018

Date Inspected: 25/04/2018 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts:	144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR3175X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >