

A.S. REC. BY:

REF:

CS/CTU18007636/TB6n2

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Treny

of

CIL

Date/Time: 25/04/2018 1.41pm

Estimated Cost:

Bill to:

OD / H / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 1893X

Insured:

SFW 3838M

at Workshop m/s

Volkswagen

Tel:

69223512

of

1 Kampung Ampet Off Macpherson Rd

Policy No:

DMPCLN301484841706

Claim No:

SNM18D02113C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/09/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

03.05.2018 C 2.30pm

H.O.D. Endorsement:

Date/Time:

25/04/2018 3.49pm

Person Contacted:

Shushi

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKF 1893X - X
	SFW 3838M - X
11/01/19	checked with Steven (repairer), pending liability from insurance. vehicle has not sent in for repair

Surinder
Nadimur

REF: CTL

ASSIGNMENT

From:

Date:

18/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKF 1853x

at Workshop m/s

Volkswagen

of

Kampong Ampet Off Mapheusson Rd

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

3:30pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKF1893x

Yr Regn:

2012 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Shivero

C.C.

1390

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

127596

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ13ZCVO31728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

R/Bal.

mm

Rear

6

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

03/5/18

Survey held at

VW 11g Ampet

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 14 JAN 2019

Date/Time, File Pass to?

14/01/19

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Prel.

Lump Sum / I.B.I: (\$

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		25 Apr 2018 14:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		[Created by insurer]							
Main Claimant:		SU HANWEI JEREMY							
Vehicle Reg. No.:		SKF1893X	Date of Loss:	07/09/2017 00:00 - :59					
Claim Type:		TP / SNM18D02113C02	Policy/Cover Note No.:	DMPCSN3014841706					
Vehicle Reg. No. (Insured):		SFW3838M	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		Volkswagen Group Singapore Pte Ltd (MacPherson) 1 Kampong Ampat, Singapore 368314, 368314 Macpherson - Tel: 63057299							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2018]							
Adj Asg. Remarks:		EST \$5190.61, CASE WITH SJE.							
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Tang, Shu Shi (VWG Singapore) <shushi.tang@vw.com.sg>
Sent: Friday, 11 January 2019 3:37 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR; Chee, Steven (VWG Singapore); Ong, Germaine (VWG Singapore)
Subject: RE: SKF 1893X (TP) SFW 3838M (OI) DOA - 07/09/2017

Hi,

We did not repair the vehicle, liability not clear.


Thank you.

Best Regards,

Tang Shu Shi
Insurance Service Advisor
Aftersales

Volkswagen Centre Singapore (Macpherson)
1 Kampong Ampat
Singapore 368314

DID: +65 6922-3502
Mobile: +65 9386-7833
Main Line : +65 6305-7299
Main Fax: +65 6285-8620
shushi.tang@vw.com.sg
<http://www.vw.com.sg>



From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 11 January, 2019 2:40 PM
To: Tang, Shu Shi (VWG Singapore)
Cc: SUR; Chee, Steven (VWG Singapore); Ong, Germaine (VWG Singapore)
Subject: SKF 1893X (TP) SFW 3838M (OI) DOA - 07/09/2017

Hi Shu Shi,

If vehicle has been repair, please finalisation with us.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/09/2017 10:35
Date Of Accident	07/09/2017 09:45
Exact Location Of Accident	BLK 108 HOUGANG AVE1 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF1893X
Insured/Policyholder	
Name Of Registered Owner	SU HANWEI JEREMY
NRIC No	S8430906J
Email Address	JEREMYSUHW1984@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94353990
Alternative Phone No	OFFICE-94353990

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SCIROCCO-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	PARKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80430643AVW
Cover Note Number	

Driver

Name of Driver	SU HANWEI JEREMY
NRIC No	S8430906J
Date Of Birth	16/10/1984
Occupation	INDOOR
Date Of Driving Pass	09/02/2004
Driving Experience	13 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94353990
Fax Number	
Contact Number	OFFICE-94353990
Email Address	JEREMYSUHW1984@GMAIL.COM

Address	BLK 236 HOUGANG AVE 1 #04-280
Postcode	530236
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFW3838M
Vehicle Make/Model/Colour	LAND ROVER
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time

[Signature]


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



81030002

Sketch Plan



Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

Refer to Police Report

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time





Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20170908/2127

1 of 3

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20170908/2127

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/09/2017 17:02		Vide Report No.:		Station Diary No.: 87	
Informant's Particulars					
Name of Informant: SU HANWEI, JEREMY			Address: APT BLK 236 HOUGANG AVENUE 1 #04-280 SINGAPORE 530236		
ID Type / ID No.: NRIC NO / S8430906J			Contact No.: Home/Office: Mobile: 94353990		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 32	Date of Birth: 16/10/1984	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: CUSTOMER ENGINEER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 07/09/2017 09:50	Type of Location: Car Park
Location: Along Road 1 HOUGANG AVENUE 1 open carpark at Blk 108 Hougang Ave 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKF1893X	Car	VOLKSWAGO N	SCIROCCO 1.4L AT TSI 1372Q5	White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKF1893X	MSIG INSURANCE (SINGAPORE) PTE. LTD.	A80430643AVW	07/05/2017	06/05/2018



**SINGAPORE
POLICE FORCE**



T/20170908/2127

2 of 3

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No: T/20170908/2127

CONTINUATION OF REPORT

Brief Details.

On 07/09/2017 at between 0945hours to 1015hours, I had parked my vehicle (SKF1893X) at one of the parking lots at Blk 108 Hougang Avenue 1 Open Carpark. On 08/09/2017 I discovered there are several scratches on the front right bumper of my vehicle. I then made a playback of my in-car camera which captured on 07/09/2017, one dark grey coloured SUV car had slid past my parked vehicle at Blk 108 Hougang Avenue 1 Open Carpark. The footage showed the vehicle plate number as SFW3838 and the last digit of the vehicle could not be seen clearly. The footage also reflected that the said vehicle "SFW3838" was parked in the lot next to mine on my right. When he moved off to his left, he made a left turn and caused a slight jerk to my vehicle. The driver had also stopped his vehicle for a short while after the movement was captured and then moved off again. I have the in-car camera footage available.



**SINGAPORE
POLICE FORCE**



T/20170908/2127

3 of 3

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20170908/2127

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 2 TEO MIN MIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 08/09/2017 17:02
Officer In Charge Of Case: TP / HRT / SSI 2 SOH PENG GUAN Contact No.: 65476171	Classification Of Case:

Authentication Stamp



Signature

Singapore Police Force



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6627 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

VW DRIVEEASY
Comprehensive

Certificate No. A 80430643 AVW

Excess : SGD1,000
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SKF1893X
2. Name of Policyholder
SU HANWEI JEREMY
3. Effective Date of the Commencement of Insurance for the purposes of the Act
07/05/2017
4. Date of Expiry of Insurance
06/05/2018
5. Persons or Classes of Persons entitled to drive*
SU HANWEI JEREMY
Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*
Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.



Signature / Date

Counter-Signatory:

Winner Consultancy Pte. Ltd.


MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Amy Ler
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

XWGPLSASX2017042114091008

Accident Sketch Plan Pg. 1



Taylor 97445749
- WP

3/5/18 E1440

03 days

Bring before paint

Car @ Iskandar.com

22/5/18

PDI TUAS

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

PDI TUAS

SU HANWEI, JEREMY
236 HOUGANG AVENUE 1
#04-280
Singapore, 530236
Singapore

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Service Quote

Customer No. CV018490
Quote No. SER/QUO/1701549
QuoteDate 11/09/17
Salesperson Sharon Aw
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	SCIROCCO 1.4 TSI+KL1	107,418	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SKF1893X	WVWZZZ13ZCV031728	07/05/12	Sharon Aw
Engine Code	Labor Type	Engine No.	Model Code
	1J	CAV 400011	1372Q5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	2	UNIT		840 1,680.00
P B&P MACP PAINT	SPRAY PAINT	2	UNIT		800 1,600.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		✓ 480.00
	Sum Labor				3,760.00
P 1K8807184B	RHF BUMPER BRACKET	1	Pieces		? 24.35
	Use Predecessor 1K8807184A				
P 1K8807217M GRU	FRONT BUMPER	1	Pieces		de 1,571.04
P 1K8853666C 9B9	RHS FOG LAMP GRILLE	1	Pieces		? 125.49
	Sum Item				1,720.88
Sum Labor					3,760.00
Sum Item					1,720.88
Total SGD					5,480.88
7% GST					5,480.88 383.67
Total SGD Incl. GST					5,864.54

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007636/T1SBN2

Date: 15/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3014841706
Claimant Vehicle No :	SKF1893X	Insured Vehicle No :	SFW3838M
Date of Loss:	07/09/2017	Nature of Claim:	TP
		Claim No:	SNM18D02113C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF1893X	Engine No:	CAV400011
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WWWZZZ13ZCV031728
Reg. Date:	07/05/2012 (Man. Year: 2012)	Odometer:	127596 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40R18	Rear Tyre Size:	235/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,720.88	1,571.04	149.84	8.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,120.00	1,640.00	43.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,480.88	3,691.04	1,789.84	32.66
+ GST 7.00/7.00% (\$\$)	383.66	258.37	125.29	32.66
Nett Amount (\$\$)	5,864.54	3,949.41	1,915.13	32.66

INSPECTION

Date of Assignment: 25/04/2018

Date Inspected: 03/05/2018 Inspected At:

Volkswagen Group Singapore Pte Ltd
(MacPherson)
1 Kampong Ampat, Singapore 368314
Singapore 368314

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$149.84 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2019)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF1893X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHF BUMPER BRACKET	*Check	24.35 FS	*- FS
2	1		*FRONT BUMPER	Deformed	1,571.04 FS	*1,571.04 FS
3	1		*RHS FOG LAMP GRILLE	*Check	125.49 FS	*- FS
				Total Parts (S\$)	1,720.88	1,571.04

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,680.00	840.00
2	SPRAY PAINT	New	1,600.00	800.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
Gross Labour Cost (\$\$)			3,760.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >