

|                                                                                                                                        |                                                                          |                 |                    |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|--------------------|-------------------------------------------------------------------------------------|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007662/K1vbn2                                                                      |                                                                          |                 |                    |                                                                                     |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556                                                                 |                                                                          |                 | Date: 08-05-2018   |  |
|                                                                                                                                        |                                                                          |                 | Code: INC4         |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                          |                 |                    |                                                                                     |
| Insured Veh.                                                                                                                           | SJN 8596C                                                                | Veh. Inspected  | SHA 3309R          |                                                                                     |
| Policy No.                                                                                                                             | 5094768470                                                               | Coverage (\$)   | 0.00               |                                                                                     |
| Claim No.                                                                                                                              | MT/0991977-003                                                           | Excess (\$)     | 0.00               |                                                                                     |
| Assign From                                                                                                                            |                                                                          | Assign Date     | 25/04/2018         |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                          |                 |                    |                                                                                     |
| Make & Model                                                                                                                           | HYUNDAI I40                                                              | c.c             | 1685               |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                   | Year of Reg.    | 2014               |                                                                                     |
| Chassis No.                                                                                                                            | KMHLB41UMEU052793                                                        | Colour          | BLUE               |                                                                                     |
| Odometer                                                                                                                               | 707070                                                                   | Steering        | IN ORDER           |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                 | Modification    | STANDARD ALLOY RIM |                                                                                     |
| General                                                                                                                                | FAIR                                                                     |                 |                    |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                          |                 |                    |                                                                                     |
|                                                                                                                                        | Size                                                                     | Make            | Balance            |                                                                                     |
| R/H Front Tyre                                                                                                                         | 205/60 R16                                                               | WEST LAKE       | 7 mm               |                                                                                     |
| L/H Front Tyre                                                                                                                         | 205/60 R16                                                               | WEST LAKE       | 7 mm               |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 205/60 R16                                                               | WEST LAKE       | 7 mm               |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 205/60 R16                                                               | WEST LAKE       | 7 mm               |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                          |                 |                    |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                          |                 |                    |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                          |                 |                    |                                                                                     |
| Accident Date                                                                                                                          | 25/04/2018                                                               | Inspection Date | 25/04/2018         |                                                                                     |
| Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |                    |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                          |                 |                    |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                 |                    |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                          |                 |                    |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                          | 4 Working Days  |                    |                                                                                     |