



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref : CC4/ASM18007670/Aea3q2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:ERNEST TAY	Date : 17-11-2020
	Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh. SJP 3239G	Veh. Inspected SLP 7225X
Policy No.	Coverage (\$) 0.00
Claim No. S8M00EXJ	Excess (\$) 0.00
Assign From	Assign Date 23/04/2018

2. Vehicle Particulars & Condition

Make & Model HONDA VEZEL	c.c 1496
Engine No. HIDDEN	Year of Reg. 2017
Chassis No. RU11206920	Colour SILVER
Odometer 38108	Steering IN ORDER
Brakes IN ORDER	Modification STANDARD ALLOY RIM
General GOOD	

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date 20/04/2018	Inspection Date 25/04/2018
Survey held at MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**