

IOD NO: FY 18/19/0003



Front View of MID 20563



Rear View of MID 20563



Left Side View of MID 20563



Right Side View of MID 20563



Zoomed In View of MID 20563

Damage Assessment: Scratches on the left step of MID 20563

