

22/03/2002

ASS. REC. BY:

REF: CS/CTU8007682 / Kv bez

Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

M/min

From (Person): Jawyn Tay of CTL Date/Time: 26/04/2018 10:47am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 6509E Insured: GBC 7023Z

at Workshop m/s Autoworx House Tel: 6452 8211

of 176 Sin ming Driv #D-01

Policy No: DMCVSN 3054141700 Claim No: SNM18D01078602

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 23/04/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp: \_\_\_\_\_ H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 26/04/2018 11:16am Person Contacted: Amanda Vehicle IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	<u>XD 6509E - X</u>
	<u>GBC 7023Z - 003/AU15015776 / Klygn2</u> <u>DVA 150918</u>
<u>5/9/18</u>	<u>@ 3:52pm Yuki will check</u>
<u>24/9/18</u>	<u>@ 4:23pm Yuki will check</u>
<u>7/11/18</u>	<u>Final fig \$300 confirmed by email (Ref 6364.05, 957)</u>

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Autwork

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: XD 6509E Yr Regn: 11, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mit FV c.c. 12882

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 365031 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RV51JJA 10002

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: 295/80R22.50

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 7 mm Rear R/Bal. 22 44 mm

L/Bal. 7 mm L/Bal. 22 44 mm

D.O.A. 23/4/18 D.O.I. 21/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rec cls

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>22/6</u>	<u>Take photo to Carhouse</u>

RECEIVED 07 NOV 2018

Date/Time, File Pass to?  : Prell. Report  : Final Report

1) \_\_\_\_\_  
2) 7/11 - typist

Days Of Repair: 1  
Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Survey Fee:	<u>220</u>
Transportation:	
S - RS, SI	
Photos	
Others	
TOTAL	<u>220</u>

Report Format: Merimen  
Lump Sum / I.B.I. (\$) 300/2

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Apr 2018		26 Apr 2018 10:47 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	YAHONG ENGINEERING PTE LTD		
Main Claimant:	HI-TACT LOGISTIC & TRADING PTE LTD, Co. Reg. No.: 200920990M		
Vehicle Reg. No.:	XD6509E	Date of Loss:	23/04/2018 09:00 - :59
Claim Type:	TP / SNM18D02078C02	Policy/Cover Note No.:	DMCVSN3054141700
Vehicle Reg. No. (Insured):	GBC7023Z	Policy No. (Claimant):	DMCFHQ17-000180
		Excess:	S\$0.00
Repairer:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/05/2018]		
Adj Asg. Remarks:	DEAR MARCUS/KALVN, PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/04/2018 13:38
Date Of Accident	23/04/2018 09:15
Exact Location Of Accident	OLD AIRPORT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD6509E
-----------------------------	---------

#### Insured/Policyholder

Name Of Registered Owner	HI-TACT LOGISTIC & TRADING PTE LTD
Co Reg No	200920990M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81640734
Alternative Phone No	OFFICE-81640734

#### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FV51JP-12.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCFHQ17-000180
Cover Note Number	

#### Driver

Name of Driver	TAN BAN SHA
NRIC No	S1322701B
Date Of Birth	12/06/1958
Occupation	OUTDOOR
Date Of Driving Pass	29/04/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81640734
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 201 TAMPINES ST 23 #03-52
Postcode	527201
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO ATTACHED WRITTEN STATEMENT.

**Attachment(s)**

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBC7023Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHOONG THIM CHOON
NRIC/Passport Number	F0080207R
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Accident Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 23/4/18



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along Old Airport Road toward Tai Seng Ave; on the extreme right lane. vehicles in front of me stopped, I stopped too. A lorry GBC 7023Z failed to stop in time, Collided into the rear of my vehicle with a hard impact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 23/4/18

Reporting Personnel's Signature  
Name:  
NRIC/FIN No.:

## Accident Sketch Plan Pg. 2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.






Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 23/4/18



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.



# AUTOWORX HOUSE

C/O176 SIN MING DRIVE #02-01 SINGAPORE 575721  
 TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

*Not Authored*

### HI-TACT LOGISTICS & TRADING

c/o 46 Lentor Plain  
 Singapore 786548

Date: 25/4/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE: MITSUBISHI FUSO FV51J / XD 6509 E</b>		
1pc	rear tail lamp assy	<i>Sm</i> 578.00 <i>X</i>
1pc	rear tail lamp housing panel	<i>R</i> 1,200.00 <i>X</i>
1pc	rear wheel housing panel	<i>R</i> 2,400.00 <i>X</i>
1pc	rear wheel mud flag	<i>Sm</i> 65.00 <i>X</i>
2 pcs	rear tail flap lock @ 475.00	<i>R</i> 950.00 <i>X</i>
	sub-total	5,193.00
	less 15%	778.95
	sub-total	4,414.05
	To remove replace the parts mentioned above, panel beat and realign the necessary affected areas.	<i>30d</i> 1,000.00
	To spray painting on affected areas.	<i>nn</i> 450.00 <i>X</i>
	To remove and install rear undercarriage parts to enable repair.	<i>nn</i> 800.00 <i>X</i>
	Total	6,664.05
<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer                      Signature:                      Date:</p>		

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 7 November 2018 12:10 PM  
**To:** 'admin@supreme.sg'; SUR  
**Subject:** RE: FINALISE-XD 6509E AND SKZ 8649J

Dear Yuki,

Noted with thanks.

Kindly send Final invoice and all supporting documents to CHINA TAIPING.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** admin@supreme.sg <admin@supreme.sg>  
**Sent:** Wednesday, 7 November 2018 12:00 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** RE: FINALISE-XD 6509E AND SKZ 8649J

Hi Veron,

Accept your offer of \$300.00 @ 1 day.

Thank you!

Best regards,  
Yuki Ho  
Supreme Auto Service Pte Ltd  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 64528211  
Fax: 64517423

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Monday, 5 November 2018 8:38 AM  
**To:** admin@supreme.sg  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: FINALISE-XD 6509E AND SKZ 8649J

Dear Yuki,

Check with surveyor.

Close at \$300/- @ 1 working day

Please confirm.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [admin@supreme.sg](mailto:admin@supreme.sg) <[admin@supreme.sg](mailto:admin@supreme.sg)>

**Sent:** Friday, 2 November 2018 4:58 PM

**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Subject:** RE: FINALISE-XD 6509E AND SKZ 8649J

Hi Veron,

Can we please finalise XD 6509 E at \$500/ 2 days?

Thank you very much.

Best regards,

Yuki Ho

Supreme Auto Service Pte Ltd

No.176 Sin Ming Drive

#02-01 Singapore 575721

Tel: 64528211

Fax: 64517423

---

**From:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Sent:** Monday, 29 October 2018 10:02 AM

**To:** 'admin@supreme.sg' <[admin@supreme.sg](mailto:admin@supreme.sg)>; 'Dylan Chew' <[dylan@supreme.sg](mailto:dylan@supreme.sg)>

**Subject:** FINALISE-XD 6509E AND SKZ 8649J

Dear Suki/Dylan,

WITHOUT PREJUDICE

SKZ 8649J-Offer Lump Sum \$1050/- @ 2 working days.

XD 6509E-Offer \$300/- @ 1 working day.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)

**Sent:** Monday, 22 October 2018 4:18 PM

**To:** 'admin@supreme.sg' <admin@supreme.sg>

**Subject:** CHECK VEHICLE STATUS

Dear Suki,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Vehicle	DOA
1) XD 6509E	23/4/2018 (CHINA TAIPING TP)
2) SKZ 8649J	2/5/2018 (MSIG TP)
3) SKZ 8638R	10/1/2018 (FIRST CAPITAL TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Apr 2018		26 Apr 2018 10:47 <a href="#">Edit Adj Rpt</a>	<b>S\$300.00</b> <a href="#">Edit Estimates</a>	<b>S\$300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured:	<b>YAHONG ENGINEERING PTE LTD</b> , Co. Reg. No.: 0								
Main Claimant:	<b>HI-TACT LOGISTIC &amp; TRADING PTE LTD</b> , Co. Reg. No.: 200920990M								
Vehicle Reg. No.:	<b>XD6509E</b>	Date of Loss:	23/04/2018 09:00 - :59 <b>[65 Months and 7 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / SNM18D02078C02</b>	Policy/Cover Note No.:	DMCVSN3054141700						
Vehicle Reg. No. (Insured):	<b>GBC7023Z</b>	Policy No. (Claimant):	DMCFHQ17-000180						
		Excess:	S\$0.00						
Repairer:	<b>Autoworx House - Sin Ming (HQ)</b> 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Jowyn Tay</b> - 6389 6174]								
Claimant's Insurer:	<b>EQ Insurance Company Ltd (HQ)</b> - Tel: 6223 9433								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 08/05/2018]</b>								
Adj Asg. Remarks:	DEAR MARCUS/KALVN, PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*XD6509E (SNM18D02078C02)  
[GBC7023Z]  
TP  
HI-TACT LOGISTIC & TRADING PTE LTD  
Apr 23 2018 9:00AM  
[YAHONG ENGINEERING PTE LTD]  
Autoworx House - Sin Ming

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser	
<b>Assessment Reports</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Supreme Auto Service Pte Ltd (HQ)				Thumbnail	Print	
1	23/04/18 14:18	<b>Accident Statement</b>				Load HTM		
<b>Photos/Images</b>							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Supreme Auto Service Pte Ltd (HQ)				Thumbnail	Print	
1	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
2	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
3	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
4	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
5	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
6	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
7	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
8	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
9	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
10	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
11	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
12	23/04/18 14:05	<b>Accident Photo</b> [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	07/11/18 12:14	<b>General View</b>				Load PDF		
<b>Documentation</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print	
1	26/04/18 10:49	<b>INSURED SAS REPORT GBC7023Z</b>				Load PDF		
2	26/04/18 10:49	<b>THIRD PARTY XD6509E -PRS EMAIL BTW CIC AND AUTOWORX HOUSE</b>				Load PDF		
3	26/04/18 10:49	<b>THIRD PARTY XD6509E -FROM AUTOWORZ HOUSE -PRS LTR</b>				Load PDF		
No	Finalized On	Supreme Auto Service Pte Ltd (HQ)				Thumbnail	Print	
1	23/04/18 14:01	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]				Load TIF		
2	23/04/18 14:01	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]				Load TIF		
3	23/04/18 14:01	<b>IC</b> [Linked Accident Report Documents]				Load TIF		

## Linked Accident Report Documents

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser	
<b>Assessment Reports</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Supreme Auto Service Pte Ltd (HQ)				Thumbnail	Print	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Supreme Auto Service Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 14:18	Accident Statement	Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Supreme Auto Service Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	23/04/18 14:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Supreme Auto Service Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 14:01	Accident Sketch Plan	Load TIF	<input checked="" type="checkbox"/>
2	23/04/18 14:01	Accident Sketch Plan	Load TIF	<input checked="" type="checkbox"/>
3	23/04/18 14:01	IC	Load TIF	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18007682/KVBE2

Date: 09/11/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3054141700  
 Claimant Vehicle No: XD6509E Insured Vehicle No: GBC7023Z  
 Date of Loss: 23/04/2018 Nature of Claim: TP Claim No: SNM18D02078C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: XD6509E  
 Make & Model: MITSUBISHI FV51JP, 12.9 D (M) Engine No: 6M70454296  
 Reg. Date: 16/11/2012 (Man. Year: 2012) Chassis No: FV51JJA10002  
 Colour: White Odometer: 365031 km  
 Engine Capacity: 12882 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5 (D/D)  
 Front Left Side: EFFI PLUS 7 mm Rear Left Side: Linglong 2/2/4/4 mm  
 Front Right Side: EFFI PLUS 7 mm Rear Right Side: Linglong 2/2/4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,414.05	0.00	4,414.05	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	300.00	1,950.00	86.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>6,664.05</b>	<b>300.00</b>	<b>6,364.05</b>	<b>95.50</b>

## INSPECTION

Date of Assignment: 26/04/2018  
 Date Inspected: 21/06/2018 Inspected At: Autoworx House - Sin Ming (HQ)  
 176 SIN MING DRIVE #02-01  
 Singapore 575721  
 Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 09 Nov 2018)	
<b>Parts:</b>	N/A	mitsubishi FV51JP 12.9 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XD6509E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAIL LAMP ASSY	Serviceable	578.00 FL	*- FL	
2	1		*REAR TAIL LAMP HOUSING PANEL	Repair	1,200.00 FL	*- FL	
3	1		*REAR WHEEL HOUSING PANEL	Repair	2,400.00 FL	*- FL	
4	1		*REAR WHEEL MUD FLAG	Serviceable	65.00 FL	*- FL	
5	2		*REAR TAIL FLAP LOCK	Repair	950.00 FL	*- FL	
					<b>Sub Total (S\$)</b>	<b>5,193.00</b>	<b>0.00</b>
					<b>- List Item Discount on L Items 15.00/15.00% (S\$)</b>	<b>778.95</b>	<b>0.00</b>
					<b>Total Parts (S\$)</b>	<b>4,414.05</b>	<b>0.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE REPLACE THE PARTS MENTIONED ABOVE,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,000.00	300.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	450.00	-
3	TO REMOVE AND INSTALL REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	800.00	-
<b>Gross Labour Cost (S\$)</b>			<b>2,250.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >