

ASS. REC. BY:

REF:

CS/CTU 8007691 / U536

Special Instruction:

SUNVALLEY
Mullman

ASSIGNMENT (Office)

From (Person):

Adeine Chng

of

CTU

Date/Time:

25042018 121pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBG 9865B

Insured:

SJS 3942T

at Workshop m/s

Bun Hock Hin

Tel:

6281 6520 X220

of

No. 6 Delta Lane 4

Policy No:

DMPCSN3071351701

Claim No:

SNM18 D0197902

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15042018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

Date/Time:

26042018 936am

Person Contacted:

Raymond

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBG 9865B - x

SJS 3942T - x

C71/
ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 266 98653at Workshop m/s 5/11

or _____

Insured: _____

Policy No. _____

Claims No _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

O/S / PR Seen: 2

Consistent? : Yes or No

Est. Repairs: 3

days

Res.: Yes or No

Lump Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

LTA 9154 yrs. Sal.1/5/18 confirmed L/S \$ 450 with Raymond.02/05/18 Red - 30%

RECEIVED 02 MAY 2018

Veh No: FB698653 Yr Regn: 1 / 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: YamahaYBR

C.C.

124Colour: Red

A/C:

Insured / Std / NI / NA

Sp. Reading: 84529

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: LBPKE1783D0009877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.75-18R: 90-90-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal: 6

mm

R/Bal: 6

mm

L/Bal: _____

mm

L/Bal: _____

mm

D.O.A. 15/4/18D.O.A. 26/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S, O/S Body.

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

02/05/18

Prel. Report

1) Typst

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3 daysResurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

\$ - \$5.00

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐

Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18007691/Us3b

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 3942T	Veh. Inspected	FBG 9865B
Policy No.	DMPCSN3071351701	Coverage (\$)	0.00
Claim No.	SNM18D01975C02	Excess (\$)	0.00
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	25/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/04/2018	Inspection Date	26/04/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		25 Apr 2018 16:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WAN KAM CHUEN								
Main Claimant:	BAN HOCK HIN CO PTE LTD, Co. Reg. No.: 197000288K								
Vehicle Reg. No.:	FBG9865B	Date of Loss:	15/04/2018 14:00 - :59						
Claim Type:	TP / SNM18D01975C02	Policy/Cover Note No.:	DMPC5N3071351701						
Vehicle Reg. No. (Insured):	SJ53942T	Policy No. (Claimant):	AVFMSB0000591702						
		Excess:	S\$0.00						
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2018]								
Adj Asg. Remarks:	DEAR MARCUS, PLEASE CONDUCT SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBG9865B		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	YBR 125 MANUAL		
Chassis No. :	LBPKE1783D0009877		
Propellant :	Petrol		
Engine No. :	E3J2E007830		
Engine Capacity :	124 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	285 kg		
Unladen Weight :	124 kg		
Year Of Manufacture :	2012		
Original Registration Date :	22 Jan 2013		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,933.00		
COE Expiry Date :	21 Jan 2023		
Road Tax Expiry Date :	21 Jan 2019		
Inspection Due Date :	21 Jan 2019		
Intended Transfer Date :	25 Apr 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0288K
Vehicle Details	
Vehicle No.:	FBG9865B
Vehicle to be Exported:	No
Intended De-registration Date:	26 Apr 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR 125 MANUAL
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	E3J2E007830
Chassis No.:	LBPKE1783D0009877
Maximum Power Output:	-
Open Market Value:	\$1,248.00
Original Registration Date:	22 Jan 2013
First Registration Date:	22 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$188.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,933.00
COE Rebate Amount:	\$915.00
Total Rebate Amount:	\$915.00

The information contained herein is correct as at 26 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2018 14:10
Date Of Accident	15/04/2018 14:30
Exact Location Of Accident	ALONG BLK 208 CHOA CHU KANG CENTRAL OPEN CP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG9865B
Insured/Policyholder	
Name Of Registered Owner	BAN HOCK HIN CO PTE LTD
Co Reg No	197000288K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67630401

Vehicle Particulars

Manufacturer	YAMAHA
Model	YBR 125
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	AVFMSB0000591702
Cover Note Number	

Driver

Name of Driver	CHEN DONG
NRIC No	G2839925T
Date Of Birth	20/08/1987
Occupation	OUTDOOR
Date Of Driving Pass	27/06/2016
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82650822
Fax Number	
Contact Number	
EMail Address	295636067@QQ.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CHOA CHU KANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180418/2044. ON 15/04/2018 AT 1430HRS, I WAS RIDING MY MOTORCYCLE BEARING FBG9865B AT THE OPEN CARPARK OF BLK 208 CHOA CHU KANG CENTRAL. I WAS RIDING TOWARDS THE MOTORCYCLE LOT. WHILE RIDING I NOTICED A CAR STOPPED AT THE SIDE OF THE PARKING LOTS. THE CAR WAS NOT PARKED IN THE LOT AND THE HAZARD LIGHT WAS NOT ON. WHILE I WAS APPROACHING THE MOTORCYCLE LOT, THE CAR SUDDENLY JUST TURNED OUT AND HIT MY MOTORCYCLE. I THEN FELT TO THE ROAD AND SUFFERED INJURIES ON MY LEFT ANKLE. I WAS THEN CONVEYED TO NG TENG FONG HOSPITAL AND WAS GIVEN 4 DAYS OF MEDICAL LEAVE. I HAD 05 STICHES ON MY LEFT ANKLE AREA. I THEN WENT TO CLINICAL ASSOCIATES MEDICAL CENTRE AND EXTENDED MY MEDICAL LEAVE FOR ANOTHER 05 DAYS. I AM LODGING THIS REPORT AS REQUESTED BY MCDONALD'S MANAGEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS3942T
Vehicle Make/Model/Colour	TOYOTA/COROLLA AXIO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

CHEN DONG

Approximate Age

Injuries Sustain

INJURIES ON LEFT ANKLE

Injured person in which vehicle?

FBG9865B

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

20/4/18
1:47pm

73.5


VERIFIED BY AJAX MARS
REPORTING OFFICER
THOMAS NG CHIN CHUN

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Police Report



**SINGAPORE
POLICE FORCE**



T/20180418/2044

1 of 3

Report No. T/20180418/2044

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/04/2018 12:48		Vide Report No.:		Station Diary No.: 12
Informant's Particulars				
Name of Informant: CHEN DONG		Address:		
ID Type / ID No.: FIN NO / G2839925T		Contact No.: Home/Office:		Mobile: 82650822
Nationality: CHINESE		Email:		
Sex: Male	Age: 30	Date of Birth: 20/08/1987	Type of Informant: Rider	
Race: Chinese		Language:	Institution / School Name:	
Occupation: MC DELIVERY RIDER		Driving Licence Information: Class: 2B,3C		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 15/04/2018 14:30	Type of Location: Car Park
Location: Along Road 1 CHOA CHU KANG CENTRAL				
Blk 208 Choa Chu Kang Central Open Carpark				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG9865B	Motorcycle				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20180418/2044

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999

2 of 3

Report No. T/20180418/2044

CONTINUATION OF REPORT

Rider			
Name	CHEN DONG	ID No.	G2839925T
Related Vehicle	FBG9865B (Motorcycle)	Contact No.	82650822
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3C Date of Expiry: NIL
Date Treatment	15/04/2018	Date Discharge	15/04/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Rider			
Name	CHEN DONG	ID No.	G2839925T
Related Vehicle	FBG9865B (Motorcycle)	Contact No.	82650822
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3C Date of Expiry: NIL
Date Treatment	18/04/2018	Date Discharge	18/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 15/04/2018 at 1430hrs, I was riding my motorcycle bearing FBG9865B at the open Carpark of Blk 208 Choa Chu Kang Central. I was riding towards the motorcycle lot. While riding I noticed a car stopped at the side of the parking lots. The car was not parked in the lot and the hazard light was not on. While I was approaching the motorcycle lot, the car suddenly just turned out and hit my motorcycle. I then felt to the road and suffered injuries on my left ankle. I was then conveyed to Ng Teng Fong Hospital and was given 4 days of medical leave. I had 05 stitches on my left ankle area. I then went to Clinical Associates Medical Centre and extended my medical leave for another 05 days. I am lodging this report as requested by MC Donald's management.

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Choa Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
680116
Tel No: 1800-7629999



T/20180418/2044

3 of 3

Report No. T/20180418/2044

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Staff Sgt IBRAHIM SHA S/O M'ABDUL RAHIM

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt MOHAMMAD ABDILLAH BIN PALIL

Contact No.: 65476246

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

18/04/2018 12:48

Classification Of Case:

CERTIFICATE OF INSURANCETHE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) OF THE REPUBLIC OF SINGAPORE
THE ROAD TRANSPORT ACT 1987 OF MALAYSIATHE AGREEMENT BETWEEN THE MINISTER FOR FINANCE (SINGAPORE) AND THE MOTOR INSURERS' BUREAU OF SINGAPORE DATED 22 FEBRUARY 1975
THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS' BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1968
ANY SUBSEQUENT REVISIONS TO THE ABOVE ACTS AND AGREEMENTS

CERTIFICATE No. AVFMSB0000591803 ChaNo: LBPKE1783D0009877

1. Index Mark and Registration Number of Vehicle FBG 9865 B

2. Name of Policyholder BAN HOCK HIN CO PTE LTD

3. Effective Date of Commencement of Insurance 10 April 2018
for the purposes of the Ordinance
09 April 2019

4. Date of Expiry of Insurance

5. Persons or Classes of Persons entitled to drive* (For certificate references MX1 and MX4, see overleaf)
ANY PERSON WHO IS UNDER THE POLICYHOLDER &/OR HIRER'S EMPLOYMENT AND IS DRIVING ON THEIR ORDER OR WITH THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use* (For certificate reference MX1, see overleaf)

USE ONLY FOR THE POLICYHOLDER &/OR HIRER'S BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER:

1. USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL, OR SPEED-TESTING.
2. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING (OTHER THAN FOR REWARD) OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.
3. USE FOR THE CARRIAGE OF PASSENGERS FOR HIRE OR REWARD BY ANY PERSON TO WHOM THE VEHICLE IS HIRED.

Type of Cover : Third Party

* Limitations rendered inoperative by Section 79 of the Road Traffic Ordinance 1958 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party Risks and Compensation) Ordinance 1960 (Republic of Singapore) are not to be included under the headings.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Republic of Singapore)



Approved Insurers

Examined By



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 32558

- Rev. 1

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#18-00 / 19-00

THE OCTAGON

S'PORE 069534

MOTOR CLAIMS DEPT

DATE : 24/04/2018

CLAIM NO. : 11132

POLICY NO. : AVFMSB0000591803

FROM : RAYMOND

VEHICLE NO. : FBG9865B

MAKE/MODEL : YAM / YBR125ESD

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 45301	REPLACE	1.00	\$48.00	Self 48.00 ✓
2	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	Self 195.00 ✓
3	GRIP HANDLE RH P/N: 45627	REPLACE	1.00	\$20.00	To. 1 20.00 ✓
4	HEADLAMP ASSY P/N: 43129	REPLACE	1.00	\$160.00	One 160.00 ✓
5	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	* Supply/Install	3.00	\$35.00	90 105.00 ✓
6	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$20.00	Self 20.00 ✓
7	PEDAL GEAR (SHORT) P/N: 45076	REPLACE	1.00	\$20.00	2 20.00 X
8	PROTECTOR MUFFLER (REAR) P/N: 46294	REPLACE	1.00	\$35.00	Self 35.00 ✓
9	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	* REPLACE	1.00	\$18.00	Self 18.00 ✓
10	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	* REPLACE	1.00	\$12.00	Self 12.00 10 ✓
11	TRANSPORT CHARGES P/N: 07169 - TOW BACK BIKE FOR ACCIDENT REPAIR.	* ✓	1.00	\$35.00	35.00 ✓
12	VISOR P/N: 43130	REPLACE	1.00	\$30.00	Self 30.00 ✓



P-508



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT. NO. 2000-1-0388
ISO 9001:2008

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$698.00
		GST @ 7 %			\$48.86
		GRAND TOTAL			\$746.86

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		25 Apr 2018 16:21 Edit Adj Rpt	S\$450.00 Edit Estimates	S\$450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WAN KAM CHUEN , ID: -								
Main Claimant:	BAN HOCK HIN CO PTE LTD , Co. Reg. No.: 197000288K								
Vehicle Reg. No.:	FBG9865B	Date of Loss:	15/04/2018 14:00 - :59 [62 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01975C02	Policy/Cover Note No.:	DMPCSN3071351701						
Vehicle Reg. No. (Insured):	SJS3942T	Policy No. (Claimant):	AVFMSB0000591702						
		Excess:	S\$0.00						
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/05/2018]								
Adj Asg. Remarks:	DEAR MARCUS, PLEASE CONDUCT SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBG9865B (SNM18D01975C02)
[SJS3942T]**































TP










































BAN HOCK HIN CO PTE LTD

Apr 15 2018 2:00PM

[WAN KAM CHUEN]

Ban Hock Hin Co. Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)				Thumbnail		Print	
1	20/04/18 14:26	Accident Statement						Load HTML	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)				Thumbnail		Print	
1	20/04/18 14:23	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
2	20/04/18 14:23	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
3	20/04/18 14:24	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
4	20/04/18 14:24	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
5	20/04/18 14:24	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
6	20/04/18 14:24	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
7	20/04/18 14:24	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
8	20/04/18 14:24	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
9	20/04/18 14:24	Accident Photo [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
10	20/04/18 14:24	Driving License [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
11	20/04/18 14:24	Driving License [Linked Accident Report Documents]						Load JPG <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	02/05/18 11:25	Chassis Number						Load JPG <input checked="" type="checkbox"/>	
2	02/05/18 11:25	Odometer Reading						Load JPG <input checked="" type="checkbox"/>	
3	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
4	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
5	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
6	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
7	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
8	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
9	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
10	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
11	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
12	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
13	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
14	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
15	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
16	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
17	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	
18	02/05/18 11:25	General View						Load JPG <input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
19	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/05/18 11:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/05/18 11:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	02/05/18 11:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	02/05/18 11:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	02/05/18 11:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	02/05/18 11:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	02/05/18 11:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/04/18 16:23	THIRD PARTY FBG9865B -PRS EMAIL BTW CIC AND BAN HOCK HIN CO	 Load PDF	
2	25/04/18 16:23	THIRD PARTY FBG9865B -FR BAN HOCK HIN CO -TP SAS REPORT AND ESTIMATE	 Load PDF	
3	25/04/18 16:23	INSURED SAS REPORT SJS3942T	 Load PDF	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	20/04/18 14:22	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	20/04/18 14:23	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	20/04/18 14:23	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	20/04/18 14:23	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	20/04/18 14:26	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	20/04/18 14:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/04/18 14:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/04/18 14:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/04/18 14:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/04/18 14:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/04/18 14:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	20/04/18 14:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	20/04/18 14:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	20/04/18 14:24	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	20/04/18 14:24	Driving License	 Load JPG	<input checked="" type="checkbox"/>
11	20/04/18 14:24	Driving License	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	20/04/18 14:22	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	20/04/18 14:23	Police Report	 Load JPG	<input checked="" type="checkbox"/>
3	20/04/18 14:23	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	20/04/18 14:23	Police Report	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007691/US3BQ2

Date: 04/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3071351701
Claimant Vehicle No :	FBG9865B	Insured Vehicle No :	SJS3942T
Date of Loss:	15/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01975C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG9865B	Engine No:	E3J2E007830
Make & Model:	YAMAHA Y125Z, 125cc (M)	Chassis No:	LBPKE1783D0009877
Reg. Date:	22/01/2013 (Man. Year: 2012)	Odometer:	84529 km
Colour:	Red		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	90-90-18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	558.00	485.20	72.80	13.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	140.00	125.00	15.00	10.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	698.00	610.20	87.80	12.58
Approved Total (Overridden) (S\$)		450.00		
(S\$)	698.00	450.00	248.00	35.53
+ GST 7.00/7.00% (S\$)	48.86	31.50	17.36	35.53
Nett Amount (S\$)	746.86	481.50	265.36	35.53

INSPECTION

Date of Assignment:	25/04/2018	
Date Inspected:	26/04/2018	Inspected At: Ban Hock Hin Co, Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 May 2018)

Parts: N/A YAMAHA Y125Z 125cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBG9865B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR HANDLE	Bent	48.00 F	*48.00 FL
2	1		*CRASH BAR	Bent	195.00 F	*195.00 FL
3	1		*GRIP HANDLE RH	Torn	20.00 F	*20.00 FL
4	1		*HEADLAMP ASSY	Cracked	160.00 F	*160.00 FL
5	1		*LEVER BRAKE	Scratched	20.00 F	*20.00 FL
6	1		*PEDAL GEAR (SHORT)	Repair	20.00 F	*- FL
7	1		*PROTECTOR MUFFLER (REAR)	Scratched	35.00 F	*35.00 FL
8	1		*STICKER (MCDONALDS) WINDSHIELD V2	Necessary	18.00 FS	*18.00 FS
9	1		*STICKER NUMBER PLATE FRONT (BLACK)STRAIGHT	Necessary	12.00 FS	*10.00 FS
10	1		*VISOR	Scratched	30.00 F	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	558.00	536.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	50.80

Total Parts (S\$)	558.00	485.20
-------------------	--------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	105.00	90.00
2	TRANSPORT CHARGES	New	35.00	35.00
Gross Labour Cost (\$\$)			140.00	125.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >