

ASS. REC. BY:

REF:

CS/CTLI8007692/Urb921

Special Instruction:

SUBV. ID

MURBY

ASSIGNMENT (Office)

From (Person):

McMinn

Jowyn Tay

of

CTI

Date/Time:

25042018 5:30pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 5908T

Insured:

SJT 9225K

at Workshop m/s

Vfix Auto

Tel:

6448 9268

of

60 Kaki Bukit Ave 6

Policy No:

DMHCSN 1670571600

Claim No:

SNM18D0203302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19042018

CA / REV / REP. / REV 24 HRS wpi

27042018 @ 10am

H.O.D. Endorsement:

Date/Time:

26042018 9:21am

Person Contacted:

Irene

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

XD 5908T - X

SJT 9225K - NA / CTI8007692/24

XN: 190418

SAFARI
MURIMBA

REF: C71

ASSIGNMENT

From: Date: 27/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: XD 5908T
at Workshop m/s Vix Auto
of 60 Kaki Bukit Ave 6

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 1Dam

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: XD 5908 T Yr Regn: 7 / 12
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLVO FMX370 cc 10837

Colour: Blue A/C Insured / Std / NI / NA

Sp Reading: 340290 T/Radio: Insured / Std / NI / NA

Eng/No

C/No: YV2JIE 1D4CA 724858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 315/80/22.5

R: 315/80/22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 19/4/18

Survey held at

Rear

R/Bal: 7/7 7/7 mm

L/Bal: 7/7 7/7 mm

D.O.I: 27.4.18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS Rf, Lf, Rd, O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/4/18 home video of workshop.
confirmed L/S at 1600 with Michael. (Red 2327.39, 5990)

RECEIVED 30 APR 2018

Date/Time. File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time. File Return to?

2) 30/4- typist

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation:

\$ + RS \$

Photos

Citizens

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: merimen

Lump Sum / I.B.I: (\$ 1600 p)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		25 Apr 2018 17:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SGRENTACAR PTE LTD, Co. Reg. No.: 201329402W								
Main Claimant:	EE HUP CONSTRUCTION PTE LTD, Co. Reg. No.: 197902194K								
Vehicle Reg. No.:	XD5908T	Date of Loss:	19/04/2018 14:00 - :59						
Claim Type:	TP / SNM18D02033C02	Policy/Cover Note No.:	DMHCSN1670571600 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJT9225K	Policy No. (Claimant):	5088299286-01 (PREF W/SHOP)						
		Excess:	S\$0.00						
Repairer:	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 64552957								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2018]								
Driver/Custodian (Insured):	TAN KOK LEONG (52 / Male), NRIC: S1690191A, Tel: +6590582813								
Adj Asg. Remarks:	NO EST, ASSIGN HENRY NG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2194K
Vehicle Details	
Vehicle No.:	XD5908T
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	VOLVO
Vehicle Model:	FMX370 64R SLEEPER CAB
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	D11243792
Chassis No.:	YV2J1E1D4CA724858
Maximum Power Output:	-
Open Market Value:	\$120,556.00
Original Registration Date:	20 Jul 2012
First Registration Date:	20 Jul 2012
Transfer Count:	1
Actual ARF Paid:	\$6,028.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,556.00
COE Rebate Amount:	\$23,432.00
Total Rebate Amount:	\$23,432.00

The information contained herein is correct as at 30 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2018 13:00
Date Of Accident	19/04/2018 14:45
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD5908T
Insured/Policyholder	
Name Of Registered Owner	EE HUP CONSTRUCTION PTE LTD
Co Reg No	197902194K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62954623

Vehicle Particulars

Manufacturer	VOLVO
Model	FMX370 64R SLEEPER CAB
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088299286-01 (PREF W/SHOP)
Cover Note Number	

Driver

Name of Driver	LIM KIM SONG
NRIC No	S0213751H
Date Of Birth	05/03/1954
Occupation	OUTDOOR
Date Of Driving Pass	22/09/1975
Driving Experience	42 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91709032
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 53 TEBAN GARDENS ROAD #11-605
Postcode	600053
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT9225K
Vehicle Make/Model/Colour	TOYOTA VIOS E AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KOK LEONG
NRIC/Passport Number	S1690191A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court order.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 20 APR 2018

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackbi@sinnnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

AS PER ENCLOSED SKETCH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/04/2018 at about 14:45 hrs. I was driving along PIE towards Changi. While I was changing lane, I felt an impact on my left. Then I realised vehicle B on my left also changed lane and collided with my truck.

No injury involved.

DECLARATION

I/We declare that foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20 APR 2018

IDAC KAKI BUKIT (VAC)


23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@sinonet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1

9-4-18 245 PM PIE → CHANGI

SKETCH PLAN



A) KD 5908T

B) SJT 9225K

M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claim Department

RE : VEHICLE NO :XD5908T VOLVO FMX

ESTIMATE

DATE : 21/04/2018
ACC DATE : 19/04/2018
REF NO. : VFIX-TP20180455
POLICY NO :

DESCRIPTION	AMOUNT S\$
1 1 GUARD PLATE FRONT	0.5 773.00
2 1 GUARD PLATE BAR	3.4 315.00
3 1 GUARD PLATE REAR	0.5 627.00
4 1 STEP PLATE	1.1 546.50
5 1 STEP GRILLE	1.2 435.60
	<u>2,697.10</u>
LESS 10%	269.71
	<u>\$ 2,427.39</u>

1715
15435

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten step board bracket replace new parts refit align into position with all necessary components attachmets	480 800.00
2 To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	1.1 700.00
	<u>\$ 1,500.00</u>

20235

GRAND TOTAL : \$ 3,927.39

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after repair/repairs
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SINGAPORE DOLLARS : THREE THOUSAND NINE HUNDRED TWENTY SEVEN & CENTS

THIRTY NINE ONLY

Vfix Auto Service Pte Ltd
Acknowledged by Repairer



Not Acknowledged
2/5 to 1600/c
27/4/18
The photo attached

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		25 Apr 2018 17:23 Edit Adj Rpt	\$51,600.00 Edit Estimates	\$51,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SGRENTACAR PTE LTD , Co. Reg. No.: 201329402W									
Main Claimant: EE HUP CONSTRUCTION PTE LTD , Co. Reg. No.: 197902194K									
Vehicle Reg. No.:	XD5908T	Date of Loss:	19/04/2018 14:00 - :59 [68 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02033C02	Policy/Cover Note No.:	DMHCSN1670571600 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJT9225K	Policy No. (Claimant):	5088299286-01 (PREF W/SHOP)						
		Excess:	\$0.00						
Repairer:	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 64552957								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd, (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/05/2018]								
Driver/Custodian (Insured):	TAN KOK LEONG (52 / Male), NRIC: S1690191A, Tel: +6590582813								
Adj Asg. Remarks:	NO EST, ASSIGN HENRY NG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD5908T (SNM18D02033C02)
[SJT9225K]
TP
EE HUP CONSTRUCTION PTE LTD
Apr 19 2018 2:00PM
[SGRENTACAR PTE LTD]
Vfix Auto Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page	☒	
No	Finalized On	VAC (Kaki Bukit)						Thumbnail	Print		
1	20/04/18 13:05	Accident Statement						Load HTM			
Photos/Images									3 per page	☒	
No	Finalized On	VAC (Kaki Bukit)						Thumbnail	Print		
1	20/04/18 13:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒		
2	20/04/18 13:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒		
3	20/04/18 13:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒		
4	20/04/18 13:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒		
5	20/04/18 13:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒		
6	20/04/18 13:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒		
7	20/04/18 13:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	30/04/18 11:27	General View						Load PDF			
Documentation									1 per page	☒	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	25/04/18 17:22	PRS						Load PDF			
2	25/04/18 17:22	OI GIA REPORT						Load PDF			
No	Finalized On	VAC (Kaki Bukit)						Thumbnail	Print		
1	20/04/18 13:05	Sketch Plan [Linked Accident Report Documents]						Load TIF			
2	20/04/18 13:05	Sketch Plan #2 [Linked Accident Report Documents]						Load TIF			
3	20/04/18 13:05	Sketch Plan #3 [Linked Accident Report Documents]						Load TIF			

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail Print
1	20/04/18 13:05	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	VAC (Kaki Bukit)		Thumbnail Print
1	20/04/18 13:05	Accident Photo		Load JPG ☒
2	20/04/18 13:05	Accident Photo		Load JPG ☒
3	20/04/18 13:05	Accident Photo		Load JPG ☒
4	20/04/18 13:05	Accident Photo		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
5	20/04/18 13:05	Accident Photo	 Load JPG	☒
6	20/04/18 13:05	Accident Photo	 Load JPG	☒
7	20/04/18 13:05	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	20/04/18 13:05	Sketch Plan	 Load TIF	
2	20/04/18 13:05	Sketch Plan #2	 Load TIF	
3	20/04/18 13:05	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007692/UVBQ2

Date: 04/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1670571600

Claimant Vehicle
No: XD5908TInsured Vehicle
No: SJT9225K

Date of Loss: 19/04/2018

Nature of Claim: TP

Claim
No: SNM18D02033C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD5908T

Make & Model: VOLVO FMX370, 10.8 D SLEEPER CAB (M)

Engine No: D11243792

Reg. Date: 20/07/2012 (Man. Year: 2011)

Chassis No: YV2J1E1D4CA724858

Colour: Blue

Odometer: 340290 km

Engine Capacity: 10837 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D/D)
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7/7/7/7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7/7/7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,427.39	1,543.50	883.89	36.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	480.00	1,020.00	68.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,927.39	2,023.50	1,903.89	48.48
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,927.39	1,600.00	2,327.39	59.26
+ GST 7.00/7.00% (S\$)	274.92	112.00	162.92	59.26
Nett Amount (S\$)	4,202.31	1,712.00	2,490.31	59.26

INSPECTION

Date of Assignment: 25/04/2018

Date Inspected: 27/04/2018 Inspected At:

Vfix Auto Service Pte Ltd (HQ)
60 Kaki Bukit Ave 6, ARK@KB
Singapore 417892

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 May 2018)	
Parts:	N/A	VOLVO FMX370 10.8 D SLEEPER CAB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD5908T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUARD PLATE FRONT	Distorted	773.00 FL	*773.00 FL
2	1		*GUARD PLATE BAR	Bent	315.00 FL	*315.00 FL
3	1		*GUARD PLATE REAR	Distorted	627.00 FL	*627.00 FL
4	1		*STEP PLATE	Not Necessary	546.50 FL	*- FL
5	1		*STEP GRILLE	Not Necessary	435.60 FL	*- FL
					Sub Total (S\$)	2,697.10
					- List Item Discount on L Items 10.00/10.00% (S\$)	269.71
					Total Parts (S\$)	2,427.39
						1,543.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN STEP BOARD BRACKET REPLACE NEW PARTS REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS ATTACHMENTS	New	800.00	480.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	700.00	0.00
Gross Labour Cost (S\$)			1,500.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >