

108/1143

Surrey Mr: Kevin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost _____

OD / TP / INS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work Stop nts _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 2078CYr Regn: 12 Aug 2010

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa FeC.C. 199Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 432862

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ICMHET4IVMAA786866

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxx

Front

Rear

R/Bal. 7

mm

R/Bal. 7

mm

L/Bal. 7

mm

L/Bal. 7

mm

D.O.A. 24/4/18D.O.I. 26/4/18Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

AXA
4 nts left c/s

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI _____

Photos _____

Other _____

Team: IN ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC No305145796

CUSTOMER

REGN NO:

SHC2078C

MILEAGE

NAME COMFORT TRANSPORTATION PTE LTD

MAKE:

HYUNDAI

FUEL

CUSTOMER NO 7010045

ADDRESS 383 SIN MING DRIVE

MODEL

SONATA

DATE/TIME IN 25.04.2018 14:15

Singapore SINGAPORE 575717

TEL (R) 65508755

(O)

YR OF MANU

12.08.2010

TARGET DATE

(P)

CHASSIS CODE

KMHET41VMAA786866

COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 24.04.2018

NATURE: 3P 24.04.2018

S/NO

LABOR CODE

DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

By:

Signature

Vehicle No.:

SHC2078C

CHIANG

Vehicle No.:

SHC2078C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard