

ASS. REC. BY:

REF:

CS/MSG18007702/R1/vb/v

Special Instruction:

SURVIVOR

RASH

ASSIGNMENT (Office)

MURIMEN

From (Person):

Kenly Ong

of

MSTH

Date/Time:

26042018 1:48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJD 8828L

Insured:

SLS 2190D

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Rd

Policy No.:

A29069766 MKF

Claim No.:

556393

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21042018

CA / REV / REP. / REV 24 HRS

27042018 @ 10am

H.O.D. Endorsement:

Date/Time:

26042018 2:18pm

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SJD 8828L - NSA / LLP 15008613 / Y

DA: 230515

SLS 2190D - x

30/4/18

Send preli revised by merimen

12/6/18

@ 1046am Gary said vehicle already done

20/6/18

Final fig \$ 3334.15 (Reel 3135.75, 48%) confirmed by email

REF: *Rasul*

REF: *MSEH*

9943F

ASSIGNMENT

From: \_\_\_\_\_ Date: *27/04/2018*

Estimated Cost: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SJD 8828L*

at Workshop mis *Performana*  
of *303 Alexandra Rd*

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: *Cozy*

(Policy Condition)

*100m  
owner waiting*



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *SJD 8828L* Yr Regn: *2014 / July*

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: *B.M.W M135I* c.c *2979*

Colour: *WHITE* A/C: Insured / Std / NI / NA

Sp. Reading: *38416* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *WPA 1B72030J 778482*

Gen. Cond: Good /  Fair / Poor / Burnt

Steering:  in order / Jammed / Leaked / Burnt or

Brake:  in order / Jammed / Leaked / Burnt or

Modl: Nil /  S/Rim / STD A/Rim or

Tyre Size: F: *245/352R18*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA /  MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: *6* mm

R/Bal: *6* mm

L/Bal: *6* mm

L/Bal: *6* mm

D.O.A: *21/04/18*

D.O.I: *27/04/18*

Survey held at: *PERFORMANCE*

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 JUN 2018

Date/Time: File Pass to?  : Prel. Report

1)  : Final Report

Date/Time: File Return to?

2) *2016 - typist*

Days Of Repair: *3*

Resurvey No. of Trip: *—*

Survey Fee:

Transportation: \_\_\_\_\_ \$ + RS. \_\_\_\_\_ \$

) Phone

) Other

TOTAL

Report Format: *melimen*

Lump Sum / I.B.I: (\$ *3334.15*)

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Apr 2018		26 Apr 2018 13:48 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>			[Created by insurer]						
Insured:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G								
Main Claimant:	<b>NG CHEH GEE</b> , ID: S6939943F								
Vehicle Reg. No.:	<b>SJD8828L</b>	Date of Loss:	21/04/2018 13:00 - :59 [44 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 556393</b>	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	<b>SLS2190D</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Keny Ong Thiam Beng</b> - 6643 1309]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Imm.Advice due 27/04/2018]								
Driver/Custodian (Insured):	TAN CHOCK SOON (), NRIC: S0192527Z								
<b>ASSOCIATED MAIL RECEIVED</b>			View All   Compose Case Mail						
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
View All   Search Tasks   Create New Task   Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Keny Ong Thiam Beng	
<b>Date:</b> 30 Apr 2018	
<h3><u>Preliminary Advice</u></h3>	

Insured Vehicle No	: SLS2190D		
TP Vehicle No	: SJD8828L	Accident Date	: 21/04/2018
Make	: BMW M3	Assignment Date	: 26/04/2018
Date of Inspection	: 27/04/2018	Est. Duration of Repair	: 3.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,389.90
Revised Amount	:S\$	3,191.20
Check Items (Estimated)	:S\$	2,217.70
<b>Total</b>	<b>:S\$</b>	<b>5,408.90</b>

Lump Sum Repair	:S\$	
-----------------	------	--

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

( )		The vehicle is economical/not economical for repair.
( X )		The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/04/2018 15:41
Date Of Accident	21/04/2018 13:00
Exact Location Of Accident	MOUNTBATTEN RD TWDS WILKINSON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD8828L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG CHEH GEE
NRIC No	S6939943F
Email Address	CHEHGEE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90222322
Alternative Phone No	OFFICE-90222322

### Vehicle Particulars

Manufacturer	BMW
Model	M135i
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1710474
Cover Note Number	

### Driver

Name of Driver	NG CHEH GEE
NRIC No	S6939943F
Date Of Birth	15/11/1969
Occupation	INDOOR
Date Of Driving Pass	11/11/1988
Driving Experience	29 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90222322
Fax Number	
Contact Number	OFFICE-90222322
Email Address	CHEHGEE@GMAIL.COM

Address	121 MEYER RD #11-06
Postcode	437932
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS2190D
Vehicle Make/Model/Colour	TOYOTA PRIUS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN CHOCK SOON
NRIC/Passport Number	S0192527Z
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	3

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBH2994C
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ONG AH HENG
NRIC/Passport Number	S1407479A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number	WB4747U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SENG KHENG GEE
NRIC/Passport Number	S0029938C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) in complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time: 23/4 12:00

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Mountbatten Road, about to turn left towards Wilkinson Road. I came to a stop before the zebra crossing as a pedestrian was waiting to cross the road.

Moments later, there was a loud bang. I got out of my car and realised the car behind had hit ~~my~~ <sup>the</sup> rear ~~bump~~ of my car.

It was a chain collision and there were 2 other vehicles behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time: 23/4 12:00

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

GAR  
Perfomants Autos Limited  
303 Aintree Dr Road  
Sims Darby Performance Centre  
En 29014 150644

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
MRC/FBI No:

23/4/18  
12:30

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



300, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

150, Kembangan Road  
East Coast Centre  
Singapore 438180  
Tel: 63190888 (AfterSales)  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190028 (AfterSales)  
63195523/530 (Motorrad)  
Fax: 64795501 (AfterSales)  
64795524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

23 APR 2018

Estimate No. : b1 46696 Page No. : 1 of 2  
Date Estimated : 23/04/2018  
Prepared By : Gary Poh Chai Hoon

**- ESTIMATE REPAIR FOR -**

Ng Cheh Gee  
121 Meyer Road  
#11-06

Singapore 437932

**- ACCOUNT - 40000**

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD8828L	J778482		135iA/5	0

DESCRIPTION

To replace rear bumper and attachment include knocking cause by the accident

painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

To supply rear emboss number plate

VALUE

✓ 850 ~~1,700.00~~  
✓ 934 ~~1,038.00~~  
✓ 150 ~~177.00~~  
✓ BA ~~83.00~~

Total Labour 1: 2,998.00

DESCRIPTION

REAR BUMPER CARRIER  
RR BUMPER CENTER GUIDE  
RR BUMPER CENTER GUIDE  
GUIDE FOR BUMPER SIDE LH (M)  
GUIDE FOR BUMPER SIDE RH (M)  
INSERT FOR BUMPER REAR (M)  
RR BUMPER FLAP TOWING EYE PRIMED (M)  
REAR BUMPER PANEL PRIMED (M)  
SET MOUNTS PDC SENSOR REAR (M)  
NUMBER PLATE LIGHT LED  
DECOUPLING RING PDC TORQUE CONVERTE  
RR PDC SENSOR ALPINWEISS (300)

QTY	PRIC	VALUE
1	385.25	385.25
1	56.85	56.85
1	56.85	56.85
1	57.40	57.40
1	57.40	57.40
1	225.60	225.60
1	45.60	45.60
1	902.20	902.20
1	62.95	62.95
2	23.20	46.40
4	5.05	20.20
4	368.80	1,475.20

xm } ?  
DE- ?  
xm ?  
DE- ?  
New ?  
CA ?  
xm } ?

Total Parts : 3,391.90

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197403183M GST Reg. No M2-0020081-X



302, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Bangkong Arany Road  
East Coast Centre  
Singapore 438189  
Tel. 63190688 (AfterSales)  
Fax. 63443773

313, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63150528 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64786611 (AfterSales)  
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 46696  
Date Estimated : 23/04/2018  
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD8828L	J778482		135iA/5	0

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Claim Code	3rd Party / Uninsured Losses / Direct Settlement
Regn No.	_____
Date/Time	27/04/18 @ 1100
Surveyor's Name	RASUL
Surveyor's Tel	90010068
Authorised Date	_____
Authorised Time	_____
RESURVEY PARTS PHOTO BY SURVEYOR	Yes / No
PML	Yes / No
Surveyor's E-mail	_____
No. of Working Days Requirement	3 days

*[Handwritten Signature]*  
24/4/18

6469.90

Labour 1	:	2,998.00
Parts	:	3,391.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	447.29
<b>Grand Total</b>	:	<b>6,837.19</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 46696  
Date Estimated : 23/04/2018  
Prepared By : Gary Poh Chai Hoon

Page No. :

**REPAIR FOR -**

Ng Cheh Gee  
121 Meyer Road  
#11-06

Singapore 437932

**- ACCOUNT - 66**

MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SJD8828L	J778482		135iA/5	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To supply rear emboss number plate	83.00		83.00	
Sundries	80.00		80.00	

(A)

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
INSERT FOR BUMPER REAR (M)	225.60	1.00		225.60
REAR BUMPER PANEL PRIMED (M)	902.20	1.00		902.20
SET MOUNTS PDC SENSOR REAR (M)	62.95	1.00		62.95
NUMBER PLATE LIGHT LED	23.20	2.00		46.40

# SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,237.15
Total Labour & Parts :	3,334.15
Deduction for Excess :	
Total Repair Costs less Excess:	3,334.15
GST @7%:	233.39
<b>Grand Total :</b>	<b>3,567.54</b>

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 20 June 2018 3:25 PM  
**To:** 'PBSP'; Rasul (LKKAuto); SUR  
**Subject:** RE: FINAL REPORT / SJD8828L

Dear Caroline,

WITHOUT PREJUDICE

Confirmed amount \$3,334.15 before GST

Repair days: 3 days

**Final invoice and all supporting documents sent over to MSIG**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP [mailto:pml-pbsp@simedarby.com.sg]  
**Sent:** Tuesday, 19 June 2018 2:27 PM  
**To:** Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINAL REPORT / SJD8828L

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,097.00

Total Parts : 1,237.15

Total Labour & Parts : 3,334.15

Repair days: 3

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Apr 2018		26 Apr 2018 13:48 <a href="#">Edit Adj Rpt</a>	<b>S\$3,334.15</b> <a href="#">Edit Estimates</a>	<b>S\$3,334.15</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G								
Main Claimant:	<b>NG CHEH GEE</b> , ID: S6939943F								
Vehicle Reg. No.:	<b>SJD8828L</b>	Date of Loss:	21/04/2018 13:00 - :59 [44 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 556393</b>	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	<b>SLS2190D</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Keny Ong Thiam Beng</b> - 6643 1309]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 26/05/2018]								
Driver/Custodian (Insured):	<b>TAN CHOCK SOON</b> (), NRIC: S01925272								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SJD8828L (556393)  
[SLS2190D]  
TP  
NG CHEH GEE  
Apr 21 2018 1:00PM  
[GRAB RENTALS PTE LTD]  
Performance Motors Limited

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View	View in Browser
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/04/18 11:02	<b>Accident Statement</b> From: SC - Reg. No: SLS2190D, Claimant: GRAB RENTALS PTE LTD	Load HTM	<input type="checkbox"/>
2	24/04/18 11:02	<b>Addendum Sheet</b> From: SC - Reg. No: SLS2190D, Claimant: GRAB RENTALS PTE LTD	Load TIFF	<input type="checkbox"/>
3	24/04/18 11:02	<b>Accident Statement Addm. #1</b> From: SC - Reg. No: SLS2190D, Claimant: GRAB RENTALS PTE LTD	Load HTM	<input type="checkbox"/>
4	24/04/18 11:02	<b>Addendum Sheet</b> From: SC - Reg. No: SLS2190D, Claimant: GRAB RENTALS PTE LTD	Load TIFF	<input type="checkbox"/>
5	24/04/18 11:02	<b>Accident Statement Addm. #2</b> From: SC - Reg. No: SLS2190D, Claimant: GRAB RENTALS PTE LTD	Load HTM	<input type="checkbox"/>
6	24/04/18 11:02	<b>Addendum Sheet</b> From: SC - Reg. No: SLS2190D, Claimant: GRAB RENTALS PTE LTD	Load TIFF	<input type="checkbox"/>
7	24/04/18 11:02	<b>Accident Statement Addm. #3</b> From: SC - Reg. No: SLS2190D, Claimant: GRAB RENTALS PTE LTD	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/18 11:55	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	30/04/18 11:56	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
24	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
25	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
26	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
27	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
28	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
29	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
30	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
31	30/04/18 11:56	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	24/04/18 11:00	<b>EST - SJD8828L.pdf</b>		Load PDF <input type="checkbox"/>
2	24/04/18 11:00	<b>TPD SJD8828L GIA REPORT.pdf</b>		Load PDF <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/06/18 08:28	<b>SUPPLEMENTARY PART</b>		Load PDF <input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG18007702/R1VBQ2

**Date:** 25/06/2018

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29069766MKF
Claimant Vehicle No : SJD8828L	Insured Vehicle No :	SLS2190D
Date of Loss: 21/04/2018	Nature of Claim:	TP <span style="float: right;">Claim No: 556393</span>

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD8828L	Engine No:	02708600N55B30A
Make & Model:	BMW M3, CABRIOLET SMG II	Chassis No:	WBA1B72030J778482
Reg. Date:	24/07/2014 (Man. Year: 2013)	Odometer:	38416 km
Colour:	White		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	245/35Z R18	Rear Tyre Size:	245/35Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,554.90	1,400.15	2,154.75	60.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,469.90</b>	<b>3,334.15</b>	<b>3,135.75</b>	<b>48.47</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>452.89</b>	<b>233.39</b>	<b>219.50</b>	<b>48.47</b>
<b>Nett Amount (S\$)</b>	<b>6,922.79</b>	<b>3,567.54</b>	<b>3,355.25</b>	<b>48.47</b>

#### INSPECTION

Date of Assignment:	26/04/2018	
Date Inspected:	27/04/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 25 Jun 2018)	
<b>Parts:</b>	N/A	BMW M3 CABRIOLET SMG II (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJD8828L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*REAR BUMPER CARRIER	Serviceable	385.25 FS	*- FS
3	1		*RR BUMPER CENTER GUIDE	Serviceable	56.85 FS	*- FS
4	1		*RR BUMPER CENTER GUIDE	Serviceable	56.85 FS	*- FS
5	1		*GUIDE FOR BUMPER SIDE LH (M)	Serviceable	57.40 FS	*- FS
6	1		*GUIDE FOR BUMPER SIDE RH (M)	Serviceable	57.40 FS	*- FS
7	1		*INSERT FOR BUMPER REAR (M)	Deformed	225.60 FS	*225.60 FS
8	1		*RR BUMPER FLAP TOWING EYE PRIMED (M)	Serviceable	45.60 FS	*- FS
9	1		*REAR BUMPER PANEL PRIMED (M)	Deformed	902.20 FS	*902.20 FS
10	1		*SET MOUNTS PDC SENSOR REAR (M)	Necessary	62.95 FS	*62.95 FS
11	2		*NUMBER PLATE LIGHT LED	Cracked	46.40 FS	*46.40 FS
12	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	20.20 FS	*- FS
13	4		*RR PDC SENSOR ALPINWEISS (300)	Serviceable	1,475.20 FS	*- FS
14	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>3,554.90</b>	<b>1,400.15</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	1,700.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,915.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >